

Effective: 17/04/2014 to 17/04/2016

Display Action Officer: Yes

Street: B2146 Compton Down To Harting Hill (7202504)

Street: B2146 Compton Down To Harting Hill (7202504)

Locality: Harting Ward, Harting, West Sussex

Area: HARTING

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Section:	9,999.00	Road No. - Locn.:		C/Way Type: Whole Street Feature			Area: HARTING	
Batch: 408316 - Inspection Batch				Route: Ad Hoc Prog Mangmnt		Officer: Curtis Bloxham (AIP)		Date: 21/10/2014
20008400	Pothole 1sqm by 120mm depth to be repaired with side sawn and sealed DBM. Located on the southbound side of carriageway opposite a gully. Marked on site.	21/10/2014	Approx 150m north of the property of south lodge b2146.	Potholes	Internal		Committed	6004977
Batch: 387804 - Ad Hoc Inspection Batch				Route: Ad-Hoc Northern2		Officer: Chichester District		Date: 20/11/2015
3074381	Repair Pothole - DEEP (Over 10 cm) WIDE (60cm/24ins) ()	20/11/2015	Just North of South Lodge	WS Obst flood,spill,tree,hedge	Internal		Committed	957151
Batch: 162914 - Inspection Batch	No actionable defects found			Route: Monthly Driven Northwest		Officer: Paul Moore (HS-Arun)		Date: 29/03/2016
Batch: 161624 - Ad Hoc Inspection Batch				Route: Ad-Hoc Western		Officer: Chichester Pothole Stack		Date: 24/02/2016
10142081	approximate dimension are: 100cm by 75cm by 15cm deep ()	24/02/2016	from South Harting to Uppark House on the B2146;	Potholes	Internal		Committed	723966
Batch: 161608 - Inspection Batch	No actionable defects found			Route: Monthly Driven Northwest		Officer: Paul Moore (HS-Arun)		Date: 24/02/2016
Batch: 160175 - Inspection Batch	No actionable defects found			Route: Monthly Driven Northwest		Officer: Paul Moore (HS-Arun)		Date: 26/01/2016
Batch: 158693 - Inspection Batch	No actionable defects found			Route: Monthly Driven Northwest		Officer: Paul Moore (HS-Arun)		Date: 22/12/2015
Batch: 157613 - Inspection Batch	No actionable defects found			Route: Monthly Driven Northwest		Officer: Paul Moore (HS-Arun)		Date: 27/11/2015
Batch: 156579 - Inspection Batch	No actionable defects found			Route: Monthly Driven Northwest		Officer: Paul Moore (HS-Arun)		Date: 29/10/2015
Batch: 154981 - Inspection Batch	No actionable defects found			Route: Monthly Driven Northwest		Officer: Paul Moore (HS-Arun)		Date: 25/09/2015
Batch: 153472 - Inspection Batch	No actionable defects found			Route: Monthly Driven Northwest		Officer: Paul Moore (HS-Arun)		Date: 24/08/2015
Batch: 152332 - Inspection Batch	No actionable defects found			Route: Monthly Driven Northwest		Officer: Paul Moore (HS-Arun)		Date: 27/07/2015
Batch: 151315 - Inspection Batch				Route: Monthly Driven Northwest		Officer: Paul Moore (HS-Arun)		Date: 24/06/2015
10136530	c/w pothole pls patch 1 m2 to incorporate pothole 0.8x0.7x50mm	23/06/2015	50m north of Nat trust pull in area 400m south of southern entrance Uppark house northbound - verge	Potholes	Internal		Committed	718354
10136531	c/w pothole pls patch 0.5m2 to incorporate pothole 0.2x0.25x40mm	23/06/2015	50m north of Nat trust pull in area 400m south of southern entrance Uppark house northbound - verge	Potholes	Internal		Committed	718355

Effective: 17/04/2014 to 17/04/2016

Display Action Officer: Yes

Street: B2146 Compton Down To Harting Hill (7202504)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Section: 9,999.00	Road No. - Locn.:			C/Way Type: Whole Street Feature			Area: HARTING	
Batch: 151315 - Inspection Batch				Route: Monthly Driven Northwest	Officer: Paul Moore (HS-Arun)		Date: 24/06/2015	
10136532	c/w pothole pls patch 2.0x1.0m to incorporate pothole 1.7x0.7x60mm	23/06/2015	50m north of Nat trust pull in area 400m south of southern entrance Uppark house northbound - verge	Potholes	Internal		Committed	718353
Batch: 150087 - Inspection Batch	No actionable defects found			Route: Monthly Driven Northwest	Officer: Paul Moore (HS-Arun)		Date: 22/05/2015	
Batch: 149220 - Inspection Batch	No actionable defects found			Route: Monthly Driven Northwest	Officer: Paul Moore (HS-Arun)		Date: 01/05/2015	
Batch: 148238 - Ad Hoc Inspection Batch				Route: Ad-Hoc Western	Officer: Chichester District		Date: 09/04/2015	
10135163	Report of tree fallen and is propped up on the cables, approx 1ft off ground Size approx 20 foot high	09/04/2015	just near to junction with B2141	WS Obst flood,spill,tree,hedge	Internal		Committed	716952
Batch: 147604 - Inspection Batch	No actionable defects found			Route: Monthly Driven Northwest	Officer: Paul Moore (HS-Arun)		Date: 24/03/2015	
Batch: 146171 - Inspection Batch				Route: Monthly Driven Northwest	Officer: Paul Moore (HS-Arun)		Date: 19/02/2015	
10134212	c/w pothole pls infill 2.2x0.8x75mm	18/02/2015	B2146 Compton down to Harting hill Harting 20m north of Deerkeepers cottage 150m south of West Harting down Nat. Trust pull in area - northbound - by verge	Potholes	Internal		Committed	716001
10134211	c/w pothole pls infill 0.8x0.4x40mm	18/02/2015	B2146 Compton down to Harting hill Harting 100m north of Deerkeepers cottage 50m south of West Harting down Nat. Trust pull in area northbound - by verge	Potholes	Internal		Committed	716003
10134210	c/w pothole pls infill 2.1x0.8x50mm	18/02/2015	B2146 Compton down to Harting hill Harting 100m north of Deerkeepers cottage 50m south of West Harting down Nat. Trust pull in area northbound -by verge	Potholes	Internal		Committed	716002
Batch: 144996 - Inspection Batch	No actionable defects found			Route: Monthly Driven Northwest	Officer: Paul Moore (HS-Arun)		Date: 25/01/2015	
Batch: 144117 - Inspection Batch				Route: Monthly Driven Northwest	Officer: Paul Moore (HS-Arun)		Date: 31/12/2014	
10133028	Edge erosion pls infill 3.5x1.0x70mm	30/12/2014	B2146 Compton down to Harting hill section 100m east of Hucksholt farm southbound- bend - verge	Edge deterioration / breakout	Internal		Committed	714830
10133027	Edge erosion pls infill 2.5x1.0x75mm	30/12/2014	B2146 Compton down to Harting hill section 100m east of Hucksholt farm southbound - bend - verge	Edge deterioration / breakout	Internal		Committed	714831
Batch: 142466 - Inspection Batch	No actionable defects found			Route: Monthly Driven Northwest	Officer: Paul Moore (HS-Arun)		Date: 23/11/2014	

Effective: 17/04/2014 to 17/04/2016

Display Action Officer: Yes

Street: B2146 Compton Down To Harting Hill (7202504)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Section:	9,999.00	Road No. - Locn.:		C/Way Type:	Whole Street Feature		Area: HARTING	
Batch: 141409 - Inspection Batch	No actionable defects found			Route: Monthly Driven Northwest		Officer: Paul Moore (HS-Arun)		Date: 29/10/2014
Batch: 140165 - Inspection Batch	No actionable defects found			Route: Monthly Driven Northwest		Officer: Paul Moore (HS-Arun)		Date: 26/09/2014
Batch: 138718 - Inspection Batch	No actionable defects found			Route: Monthly Driven Northwest		Officer: Paul Moore (HS-Arun)		Date: 27/08/2014
Batch: 137623 - Inspection Batch				Route: Monthly Driven Northwest		Officer: Paul Moore (HS-Arun)		Date: 25/07/2014
10130008	c/w pothole pls infill 2.5x0.6x60mm - by verge	23/07/2014	B2146 Compton Down rd to Harting Hill section 400m south of southern entrance to Upark house northbound c/w - (50m north of Nat. Trust pull in area)	Potholes	Internal		Committed	711811
10130010	c/w pothole pls infill 3.0x0.8x70mm - by verge	23/07/2014	B2146 Compton Down rd to Harting Hill section 400m south of southern entrance to Upark house- northbound c/w (50m north of Nat. Trust pull in area)	Potholes	Internal		Committed	711810
10130009	c/w pothole pls infill 2.0x0.7x50mm- by verge	23/07/2014	B2146 Compton Down rd to Harting Hill section 400m south of southern entrance to Upark house northbound c/w (50m north of Nat. Trust pull in area)	Potholes	Internal		Committed	711812
Batch: 136633 - Inspection Batch				Route: Monthly Driven Northwest		Officer: Paul Moore (HS-Arun)		Date: 25/06/2014
10129312	c/w pothole pls infill 0.8x0.4x50mm	24/06/2014	B2146 Compton Down to Harting hill 400m south of southern entrance to Upark house - verge - northbound c/w	Potholes	Internal		Committed	711118
Batch: 135562 - Inspection Batch	No actionable defects found			Route: Monthly Driven Northwest		Officer: Paul Moore (HS-Arun)		Date: 22/05/2014
Batch: 134478 - Inspection Batch	No actionable defects found			Route: Monthly Driven Northwest		Officer: Paul Moore (HS-Arun)		Date: 25/04/2014
Batch: 68844 - Inspection Batch				Route: Ad-Hoc Northern		Officer: Steve Hodd (HS-Chichester)		Date: 13/04/2016
158851	Fill edge erosion / pothole with stone and IDBM 3 .5 Sqm u at depth of 100 MM bend in proximity 2 of 2	13/04/2016	Near access road to bucksholt farm southbound	Edge deterioration / breakout	Internal		Committed	99071
Batch: 68843 - Inspection Batch				Route: Ad-Hoc Northern		Officer: Steve Hodd (HS-Chichester)		Date: 13/04/2016
158850	Fill edge erosion / pothole with stone and DBM 3 Sqm at depth of 100 MM bend in proximity 1 of 2	13/04/2016	Approx 75 m north of access road to buckshot farm southbound carriageway	Edge deterioration / breakout	Internal		Committed	99070
Batch: 67588 - Ad Hoc Inspection Batch				Route: Ad-Hoc Northern		Officer: Chichester Pothole Stack		Date: 18/02/2016
157595	Potholes #DEEP 4-10 cm #WIDE 30-60cm ()	18/02/2016	South of south harting. 0.2 miles from where the b2141 and b2146 join. Nearside edge of road	Potholes	Internal		Committed	97806

Effective: 17/04/2014 to 17/04/2016

Display Action Officer: Yes

Street: B2146 Compton Down To Harting Hill (7202504)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Section: 9,999.00	Road No. - Locn.:			C/Way Type: Whole Street Feature			Area: HARTING	
Batch: 66922 - Ad Hoc Inspection Batch				Route: Ad-Hoc Northern		Officer: Jane Richards		Date: 25/01/2016
156922	Obstruction - Dead Deer [REDACTED]	25/01/2016	B2146 South Harting Right hand Lane nr to where the speed limit ends	WS Obst flood,spill,tree,hedge	Internal		Committed	97109
Batch: 65007 - Ad Hoc Inspection Batch				Route: Ad-Hoc Northern		Officer: Jane Richards		Date: 24/07/2015
155005	Trees - tree down across both lanes of carriageway [REDACTED]	24/07/2015	b2146 south harting towards compton south of south hartington village	WS Obst flood,spill,tree,hedge	Internal		Committed	95165
Batch: 63603 - Inspection Batch				Route: Ad-Hoc Northern		Officer: Steve Hodd (HS-Chichester)		Date: 09/03/2015
153594	Fill pothole with DBM 1 sqm at depth of 100 mm bend in proximity 1 of 2	09/03/2015	Approx 100 m north of access road to hicks holt farm	Potholes	Internal		Committed	93692
Batch: 63602 - Inspection Batch				Route: Ad-Hoc Northern		Officer: Steve Hodd (HS-Chichester)		Date: 09/03/2015
153593	Fill pothole / erosion with sTone and DBM 2 sqm at depth of 100 mm bend in proximity	09/03/2015	Approx 100 m north of road to hicks holt farm	Edge deterioration / breakout	Internal		Committed	93691
Batch: 61141 - Inspection Batch				Route: Ad-Hoc Northern		Officer: Matt Meechan		Date: 14/06/2014
151132	Tree blocking carriageway, police on site Police ref. 31514062014	14/06/2014	Between compton and south harting	WS Obst flood,spill,tree,hedge	Internal		Committed	91158
Batch: 60963 - Inspection Batch				Route: Ad-Hoc Northern		Officer: Gary Mawson		Date: 24/05/2014
150954	Tree across the C/Way blocking the Whole road Police on site. Police ref=259245	24/05/2014	Entrance to Up Park, National Trust park	WS Obst flood,spill,tree,hedge	Internal		Committed	90978

Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
Section: 9,999.00	Road No. - Locn.:				C/Way Type: Whole Street Feature		Area: HARTING	
90978	Tree across the C/Way blocking the Whole road Police on site. Police ref=259245 (WS Obst flood,spill,tree,hedge)	Entrance to Up Park, National Trust park	Emergency Response	Wes 2 Hours - BB	Works Closed	24/05/2014	24/05/2014	Act. BB01/50516
91158	Tree blocking carriageway, police on site Police ref. 31514062014 (WS Obst flood,spill,tree,hedge)	Between compton and south harting	Emergency Response	Wes 2 Hours - BB	Works Closed	14/06/2014	14/06/2014	Act. BB01/50662
93691	Fill pothole / erosion with sTone and DBM 2 sqm at depth of 100 mm bend in proximity (Edge deterioration / breakout)	Approx 100 m north of road to hicks holt farm	Steve Hodd (HS-Chicheste	28 Days - BB	Works Closed	09/03/2015	10/03/2015	Act. BB01/52921
93692	Fill pothole with DBM 1 sqm at depth of 100 mm bend in proximity 1 of 2 (Potholes)	Approx 100 m north of access road to hicks holt farm	Steve Hodd (HS-Chicheste	5 Days - BB	Works Closed	09/03/2015	10/03/2015	Act. BB01/52922
95165	Trees - tree down across both lanes of carriageway [REDACTED] (WS Obst flood,spill,tree,hedge)	b2146 south harting towards compton south of south hartington village	Emergency Response	Wes 2 Hours - BB	Works Closed	24/07/2015	24/07/2015	Act. BB01/54261

Effective: 17/04/2014 to 17/04/2016

Display Action Officer: Yes

Street: B2146 Compton Down To Harting Hill (7202504)

Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
Section:	9,999.00	Road No. - Locn.:			C/Way Type:	Whole Street Feature	Area:	HARTING
97109	Obstruction - Dead Deer WS Obst flood,spill,tree,hedge)	B2146 South Harting Right hand Lane nr to where the speed limit ends	Emergency Response	Wes 2 Hours - BB	Works Closed	25/01/2016	25/01/2016	Act. BB01/56079
97806	Potholes #DEEP 4-10 cm #WIDE 30-60cm (Potholes)	South of south harting. 0.2 miles from where the b2141 and b2146 join. Nearside edge of road	Chichester Pothole Stack	28 Days - BB	Works Closed	18/02/2016	29/02/2016	Act. BB01/56768
99070	Fill edge erosion / pothole with stone and DBM 3 Sqm at depth of 100 MM bend in proximity 1 of 2 (Edge deterioration / breakout)	Approx 75 m north of access road to buckshot farm southbound carriageway	Steve Hodd (HS-Chicheste	28 Days - BB	Works Closed	13/04/2016	22/04/2016	Act. BB01/58004
99071	Fill edge erosion / pothole with stone and IDBM 3 .5 Sqm u at depth of 100 MM bend in proximity 2 of 2 (Edge deterioration / breakout)	Near access road to bucksholt farm southbound	Steve Hodd (HS-Chicheste	28 Days - BB	Works Closed	13/04/2016	22/04/2016	Act. BB01/58005
121070	New 2m post for signs. Pass to RB. Entering late as info from previous insp wiped/missing had to re do. Insp 24/04/06 JJ/BW. (Signs/bollards)	Just S of where S Downs Way joins on W side.	Jackie Jenner-Jones (WAC	zzPassed to Traffic Engineer	Passed to Traffic Engineer	31/05/2006		
711118	c/w pothole pls infill 0.8x0.4x50mm (Potholes)	B2146 Compton Down to Harting hill 400m south of southern entrance to Upark house - verge - northbound c/w	Paul Moore (HS-Arun)	28 Days - BB	Works Closed	25/06/2014	27/06/2014	Act. BB01/306810
711810	c/w pothole pls infill 3.0x0.8x70mm - by verge (Potholes)	B2146 Compton Down rd to Harting Hill section 400m south of southern entrance to Upark house- northbound c/w (50m north of Nat. Trust pull in area)	Paul Moore (HS-Arun)	28 Days - BB	Works Closed	25/07/2014	29/07/2014	Act. BB01/307143
711811	c/w pothole pls infill 2.5x0.6x60mm - by verge (Potholes)	B2146 Compton Down rd to Harting Hill section 400m south of southern entrance to Upark house northbound c/w - (50m north of Nat. Trust pull in area)	Paul Moore (HS-Arun)	28 Days - BB	Works Closed	25/07/2014	29/07/2014	Act. BB01/307143
711812	c/w pothole pls infill 2.0x0.7x50mm- by verge (Potholes)	B2146 Compton Down rd to Harting Hill section 400m south of southern entrance to Upark house northbound c/w (50m north of Nat. Trust pull in area)	Paul Moore (HS-Arun)	28 Days - BB	Works Closed	25/07/2014	29/07/2014	Act. BB01/307143
714830	Edge erosion pls infill 3.5x1.0x70mm (Edge deterioration / breakout)	B2146 Compton down to Harting hill section 100m east of Hucksholt farm southbound- bend - verge	Paul Moore (HS-Arun)	28 Days - BB	Works Closed	31/12/2014	10/03/2015	Act. BB01/308642
714831	Edge erosion pls infill 2.5x1.0x75mm (Edge deterioration / breakout)	B2146 Compton down to Harting hill section 100m east of Hucksholt farm southbound - bend - verge	Paul Moore (HS-Arun)	28 Days - BB	Works Closed	31/12/2014	10/03/2015	Act. BB01/308642

Effective: 17/04/2014 to 17/04/2016

Display Action Officer: Yes

Street: B2146 Compton Down To Harting Hill (7202504)

Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
Section:	9,999.00	Road No. - Locn.:			C/Way Type: Whole Street Feature		Area: HARTING	
716001	c/w pothole pls infill 2.2x0.8x75mm (Potholes)	B2146 Compton down to Harting hill Harting 20m north of Deerkeepers cottage 150m south of West Harting down Nat. Trust pull in area - northbound - by verge	Paul Moore (HS-Arun)	28 Days - BB	Works Closed	19/02/2015	17/03/2015	Act. BB01/309312
716002	c/w pothole pls infill 2.1x0.8x50mm (Potholes)	B2146 Compton down to Harting hill Harting 100m north of Deerkeepers cottage 50m south of West Harting down Nat. Trust pull in area northbound -by verge	Paul Moore (HS-Arun)	28 Days - BB	Works Closed	19/02/2015	17/03/2015	Act. BB01/309312
716003	c/w pothole pls infill 0.8x0.4x40mm (Potholes)	B2146 Compton down to Harting hill Harting 100m north of Deerkeepers cottage 50m south of West Harting down Nat. Trust pull in area northbound - by verge	Paul Moore (HS-Arun)	28 Days - BB	Works Closed	19/02/2015	17/03/2015	Act. BB01/309312
716952	Report of tree fallen and is propped up on the cables, approx 1ft off ground Size approx 20 foot high (WS Obst flood,spill,tree,hedge)	just near to junction with B2141	Chichester District	2 Hours - BB	Works Closed	09/04/2015	09/04/2015	Act. BB01/309886
718353	c/w pothole pls patch 2.0x1.0m to incorporate pothole 1.7x0.7x60mm (Potholes)	50m north of Nat trust pull in area 400m south of southern entrance Uppark house northbound - verge	Paul Moore (HS-Arun)	28 Days - BB	Works Closed	24/06/2015	29/06/2015	Act. BB01/310686
718354	c/w pothole pls patch 1 m2 to incorporate pothole 0.8x0.7x50mm (Potholes)	50m north of Nat trust pull in area 400m south of southern entrance Uppark house northbound - verge	Paul Moore (HS-Arun)	28 Days - BB	Works Closed	24/06/2015	29/06/2015	Act. BB01/310686
718355	c/w pothole pls patch 0.5m2 to incorporate pothole 0.2x0.25x40mm (Potholes)	50m north of Nat trust pull in area 400m south of southern entrance Uppark house northbound - verge	Paul Moore (HS-Arun)	28 Days - BB	Works Closed	24/06/2015	29/06/2015	Act. BB01/310686
723966	approximate dimension are: 100cm by 75cm by 15cm deep (2089706) (Potholes)	from South Harting to Uppark House on the B2146;	Chichester Pothole Stack	5 Days - BB	Works Closed	24/02/2016	29/02/2016	Act. BB01/313723
957151	Repair Pothole - DEEP (Over 10 cm) WIDE (60cm/24ins) (WS Obst flood,spill,tree,hedge)	Just North of South Lodge	Chichester District	2 Hours - BB	Works Closed	20/11/2015	20/11/2015	Act. BB01/917139

Effective: 17/04/2014 to 17/04/2016

Display Action Officer: Yes

Street: B2146 Compton Down To Harting Hill (7202504)

Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
	Section: 9,999.00	Road No. - Locn.:			C/Way Type: Whole Street Feature		Area: HARTING	
6004977	Pothole 1sqm by 120mm depth to be repaired with side sawn and sealed DBM. Located on the southbound side of carriageway opposite a gully. Marked on site. (Potholes)	Approx 150m north of the property of south lodge b2146.	Curtis Bloxham (AIP)	5 Days - BB	Works Closed	21/10/2014	24/10/2014 Act.	BB01/1503950