Effective: 01/02/2016 to 25/05/2018

Street: APPLEDRAM LANE SOUTH (7200545)

Street: APPLEDRAM	LANE SO	UTH (7200545)		Locality: F	ISHBOURN	E, WEST SUSSEX			Area: FISHBO	JRNE
Condition Survey										
Defect No: Description			Log Date	Location		Defect Type	Clas	s. Organisation	Status	Job No.
Section: 9,999	.00	Road No Locn.:				C/Way Type: \	Whole Street	t Feature	Area: FISHBO	DURNE
Batch: 621074 - Ir	nspection	Batch			Route: Ad-l	Hoc Western	Officer:	Mark Bishop (HS-	Chichester)	Date: 06/04/2018
10164816 1.5m x 350 m Site constrain		Depth 100 mm	06/04/2018	East edge of road just sou north of Church Farm and Appledram centre.		Potholes	Inter	rnal	Committed	747254
Batch: 198675 - Ir	nspection	Batch			Route: Ad-l	Hoc Western	Officer:	Mark Bishop (HS-	Chichester)	Date: 28/02/2018
10163260 350MM depth bend nearby	40 MM \$	Site constraints:	28/02/2018	West edge of road approx between sewage plant and the east		Potholes	Inter	nal	Committed	745643
Batch: 198674 - Ir	nspection	Batch			Route: Ad-l	Hoc Western	Officer:	Mark Bishop (HS-	Chichester)	Date: 28/02/2018
10163259 300m MM dep bend nearby	oth 60MM	Site constraints:	28/02/2018	West edge of the road just bend, south of the sewage	north of the plant	Potholes	Inter	nal	Committed	745642
Batch: 198673 - Ir	nspection	Batch			Route: Ad-l	Hoc Western	Officer:	Mark Bishop (HS-	Chichester)	Date: 28/02/2018
10163258 300i MM dept bend nearby	h 40 MM	Site constraints:	28/02/2018	West edge of road just not bend south of sewage plan		Potholes	Inter	nal	Committed	745641
Batch: 197427 - Ir	nspection	Batch			Route: 6 M	onthly Driven Feb/August	Officer:	Paul Moore (HS-A	run)	Date: 12/02/2018
No actionable	defects f	ound								
Batch: 197224 - A	d Hoc Ins	pection Batch			Route: Ad-l	Hoc Western	Officer:	Chichester Pothol	e Stack	Date: 07/02/2018
10162380 Kerbside wid than 10cm (cm depth more	07/02/2018	Near Calafrana number 10	1	Potholes	Inter	nal	Committed	744730
Batch: 197090 - A	d Hoc Ins	pection Batch			Route: Ad-l	Hoc Western	Officer:	Chichester Pothol	e Stack	Date: 06/02/2018
10162247 Driving lane videpth more th			06/02/2018	about 100 metres from jun Fishbourne Road West.	ction with	Potholes	Inter	rnal	Committed	744597
Batch: 195589 - Ir	nspection	Batch			Route: Ann	ual Bosham,Fishbourne	Officer:	Paul Moore (HS-A	run)	Date: 17/01/2018
No actionable	defects f	ound								
Batch: 187346 - Ir	nspection	Batch			Route: 6 M	onthly Driven Feb/August	Officer:	Paul Moore (HS-A	run)	Date: 05/08/2017
No actionable	defects f	ound								
Batch: 186262 - Ir	nspection	Batch			Route: Ad-l	Hoc Western	Officer:	James Strachan (App) [BL]	Date: 14/07/2017
10156426 Reinstate carr DBM	riageway	2m x 0.5m x 50mm	14/07/2017	apuldram lane south chich		Potholes	Inter	nal	Committed	738638
Batch: 186261 - Ir	nspection	Batch			Route: Ad-l	Hoc Western	Officer:	James Strachan (App) [BL]	Date: 14/07/2017
10156425 Reinstate pot	hole 0.4sc	m x 40mm DBM	14/07/2017	apuldram lane south chich		Potholes	Inter		Committed	738637
Batch: 186260 - Ir	nspection	Batch			Route: Ad-	Hoc Western	Officer:	James Strachan (App) [BL]	Date: 14/07/2017
10156424 Reinstate pot		•	14/07/2017	apuldram lane south chich		Potholes	Inter		Committed	738636
Batch: 186259 - Ir	nspection	Batch			Route: Ad-	Hoc Western	Officer:	James Strachan (App) [BL]	Date: 14/07/2017
10156423 Reinstate potl DBM	hole 1m x	0.5m x 60mm	14/07/2017	apuldram lane south chich	ester	Potholes	Inter	rnal	Committed	738635

Defect No: Description	Log Date	Location	Defect Type	Clas	s. Organisation	Status	Job No
Section: 9,999.00 Road No Locn.:			C/Way Type: W	/hole Stree	t Feature	Area: FISHB	OURNE
Batch: 186258 - Inspection Batch		Route:	Ad-Hoc Western	Officer:	James Strachan (A	App) [BL]	Date: 14/07/2017
10156422 Reinstate carriageway 0.6sqm x 50mm DBM	14/07/2017	apuldram lane south chichester out	side Potholes	Inte	rnal	Committed	738634
Batch: 185662 - Ad Hoc Inspection Batch		Route:	Ad-Hoc Western	Officer:	Chichester Potholo	e Stack	Date: 29/06/2017
10156097 Repair potholes in carriageway. Approx depth 4-10 cm and approx width 15-30cm/6-12ins (Enquiry)	29/06/2017	Just North of sewage works by the bridge. In carriageway.	Potholes	Inte	rnal	Committed	738306
Batch: 184161 - Ad Hoc Inspection Batch		Route:	Ad-Hoc Western	Officer:	Chichester Pothole	e Stack	Date: 31/05/2017
10155284 Pothole width is 300-600mm and depth is over 100mm	31/05/2017	Approx 40m from junction with Fishbourne Road West	Potholes	Inte	rnal	Committed	737484
Batch: 184001 - Ad Hoc Inspection Batch		Route:	Ad-Hoc Western	Officer:	Chichester Pothole	e Stack	Date: 30/05/2017
10155241 width 30-60cm depth more than 10cm (Enquiry)	30/05/2017	approx 20/30mtre from the approacthe A259 Near Larkspur	h to Potholes	Inte	rnal	Committed	737442
Batch: 181248 - Ad Hoc Inspection Batch		Route:	Ad-Hoc Western	Officer:	Chichester Pothole	e Stack	Date: 10/04/2017
10153767 Kerbside Southbound side width 30-60cm depth more than 10cm (Enquiry	10/04/2017	Treatment Works	Potholes	Inte	rnal	Committed	735950
Batch: 179123 - Inspection Batch		Route:	Ad-Hoc Western	Officer:	Mark Bishop (HS-	Chichester)	Date: 02/03/2017
10152410 300 MM dia. Depth 70 MM. No photo due to location	02/03/2017	On inside of bend where the small parking layby is, approx 120 m sout the sewage plant	Potholes h of	Inte	rnal	Committed	734519
Batch: 177617 - Inspection Batch		Route:	6 Monthly Driven Feb/August	Officer:	Paul Moore (HS-A	run)	Date: 09/02/2017
No actionable defects found							
Batch: 176274 - Inspection Batch			Annual Bosham,Fishbourne	Officer:	Teresa Wright (HS	-Chichester)	Date: 17/01/2017
10150544 Please f/w patch approx 0.3m2 around proud (approx 20mm) concrete surround (22cm * 22cm) with metal water stop cock cover in near back of western fw 10150543 Please lift & reset loose/rocking kerb (91cm * 12cm) front of southwestern tarmac f/w & may need additional tarmac for f/w behind, suggest attending in quiet period &/or stop & go	17/01/2017 17/01/2017	C106/2 o/s 22 Tradewind & approx 2.75m north of 24 Russet - opp Haylands & opp & approx 4m south green street light column no 9 C103/2 o/s 32 & approx 2.25m northwest of The Lodge (1st proper north of Southern Water Sewage/Wastewater Treatment Wo	of F/W hazard trip/depression y	Inte		Committed	732613 732614
Batch: 169545 - Inspection Batch		Route:	Ad-Hoc Western	Officer:	Mark Bishop (HS-	Chichester)	Date: 26/08/2016
10146877 500 x 250 MM patch depth 50 MM (no photo due to equipment failure)	26/08/2016	West edge of road approx 30 m nor the sharp bend located south of the sewage plant	th of Potholes	Inte		Committed	728870
Batch: 169544 - Inspection Batch			Ad-Hoc Western	Officer:	Mark Bishop (HS-	Chichester)	Date: 26/08/2016
10146876 500 x 200 MM patch depth 50 MM (no photo due to equipment failure)	26/08/2016	North edge of road just west of the sharp bend located to the east of property Rymans	Potholes	Inte	rnal	Committed	728869

Condition	Survey
-----------	--------

Defect No: Description	Log Date	Location	Defect Type	Clas	s. Organisation	Status	Job No
Section: 9,999.00 Road No Locn.:			C/Way Type: W	/hole Stree	t Feature	Area: FISHB	OURNE
Batch: 169543 - Inspection Batch		Route:	Ad-Hoc Western	Officer:	Mark Bishop (HS-	Chichester)	Date: 26/08/2016
10146875 500 x 250 MM patch depth 50 MM (no photo due to equipment failure)	26/08/2016	Appledram Lane South, south edgroad approx mid-way between prop Rymans and the sharp bend to the	erty	Inter	nal	Committed	72886
Batch: 168935 - Inspection Batch		Route:	6 Monthly Driven Feb/August	Officer:	Paul Moore (HS-A	Arun)	Date: 09/08/2016
No actionable defects found							
Batch: 168898 - Inspection Batch		Route:	Ad-Hoc Western	Officer:	Mark Bishop (HS-	Chichester)	Date: 09/08/2016
10146338 Trim back vegetation along footway adj to small layby	09/08/2016	West side footway adj to small lay-l just north of Manor Barn	y WS Obst flood,spill,tree,hed	dge Inte	nal	Committed	72832
Batch: 166290 - Inspection Batch		Route:	Ad-Hoc Western	Officer:	Mark Bishop (HS-	Chichester)	Date: 07/06/2016
10144845 500 mm x 200 mm patch depth 80 mm On a bend	07/06/2016	Outside of bend South East of the sewage plant, (where the gravel a in front of double metal gates is located)	Potholes ea	Inte	rnal	Committed	72680
Batch: 164281 - Inspection Batch		Route:	Ad-Hoc Western	Officer:	Mark Bishop (HS-	Chichester)	Date: 25/04/2016
10143831 250 mm dia depth 40 mm Site constraints: entrance to sewage plant: bend nearby	25/04/2016	Edge of road at entrance to sewage plant	Potholes	Inter	rnal	Committed	72572
Batch: 164280 - Inspection Batch		Route:	Ad-Hoc Western	Officer:	Mark Bishop (HS-	Chichester)	Date: 25/04/2016
10143830 2 sqm patch depth 100 mm Bend	25/04/2016	Inside of bend located approx 80 m North of church farm (bend with gra area and gate)	Potholes avel	Inte	nal	Committed	72572
Batch: 164279 - Inspection Batch		Route:	Ad-Hoc Western	Officer:	Mark Bishop (HS-	Chichester)	Date: 25/04/2016
10143829 250 mm dia depth 60 mm Bend	25/04/2016	Outside edge of bend approx 80 m North of church farm	Potholes	Inte	nal	Committed	72572
Batch: 164264 - Inspection Batch		Route:	Ad-Hoc Western	Officer:	Mark Bishop (HS-	Chichester)	Date: 25/04/2016
10143814 350 mm dia depth 100 mm	25/04/2016	Southbound lane just north of Chur-Farm	ch Potholes	Inte	rnal	Committed	72570
Batch: 162362 - Ad Hoc Inspection Batch		Route:	Ad-Hoc Western	Officer:	Chichester Distric	t	Date: 09/03/2016
10142541 Clear large branch, blocking 3/4 of the carriagway. Size tree or branch: Too large to be moved.	09/03/2016	Near the junction with Fishbourne Road.	WS Obst flood,spill,tree,hed	dge Inte	rnal	Archived	72442
Batch: 160709 - Inspection Batch		Route:	6 Monthly Driven Feb/August	Officer:	Paul Moore (HS-A	Arun)	Date: 04/02/2016
No actionable defects found							
Section: 1,009,999.00 Road No Locn.:			C/Way Type: ₩	/hole Site S	Species	Area: FISHB	OURNE
Batch: 1108906 - Ad Hoc Inspection Batch		Route:	Adhoc Inspection	Officer:	Mark Warwick (Tr	ee Team)	Date: 16/11/2016
845153 .	16/11/2016		ARB - Internal Tree Defect	Inter	nal	Committed	5003559

aintenance Management							
b No. Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
Section: 9,999.00 Road	No Locn.:			C/Way Type: Whole Street Feature		Area: FISHBOUR	NE
188075 (Added to June 2012 CCTV Batch) Investigate possible break in pipe.	O/s 34 the Lodge.	Drainage Strategy Team	Planned Works - Prog.	Forward Asset Mgmt Team only	18/05/2012	17/05/2019 Est.	
725705 350 mm dia depth 100 mm (Potholes)	Southbound lane just north of Church Farm	Mark Bishop (HS-Chicheste	5 Days - BB	Works Closed	25/04/2016	26/04/2016 Act.	BB01/314778
725720 250 mm dia depth 60 mm Bend (Potholes)	Outside edge of bend approx 80 m North of church farm	Mark Bishop (HS-Chicheste	28 Days - BB	Works Closed	25/04/2016	26/04/2016 Act.	BB01/314793
725721 2 sqm patch depth 100 mm Bend (Potholes)	Inside of bend located approx 80 m North of church farm (bend with gravel area and gate)	Mark Bishop (HS-Chicheste	5 Days - BB	Works Closed	25/04/2016	26/04/2016 Act.	BB01/314794
725722 250 mm dia depth 40 mm Site constraints: entrance to sewage plant: bend nearby (Potholes)	Edge of road at entrance to sewage plant	Mark Bishop (HS-Chicheste	28 Days - BB	Works Closed	25/04/2016	26/04/2016 Act.	BB01/314795
726800 500 mm x 200 mm patch depth 80 mm On a bend (Potholes)	Outside of bend South East of the sewage plant , (where the gravel area in front of double metal gates is located)	Mark Bishop (HS-Chicheste	28 Days - BB	Works Closed	07/06/2016	17/06/2016 Act.	BB01/315364
728328 Trim back vegetation along footway adj to small layby (WS Obst flood,spill,tree,hedge)	West side footway adj to small lay-by just north of Manor Barn	Mark Bishop (HS-Chicheste	28 Days - BB	Works Closed	09/08/2016	02/09/2016 Act.	BB01/316176
728868 500 x 250 MM patch depth 50 MM (no photo due to equipment failure) (Potholes)	Appledram Lane South, south edge of road approx mid-way between property Rymans and the sharp bend to the east	Mark Bishop (HS-Chicheste	28 Days - BB	Works Closed	26/08/2016	21/09/2016 Act.	BB01/316419
728869 500 x 200 MM patch depth 50 MM (no photo due to equipment failure) (Potholes)	North edge of road just west of the sharp bend located to the east of property Rymans	Mark Bishop (HS-Chicheste	28 Days - BB	Works Closed	26/08/2016	21/09/2016 Act.	BB01/316420
728870 500 x 250 MM patch depth 50 MM (no photo due to equipment failure) (Potholes)	West edge of road approx 30 m north of the sharp bend located south of the sewage plant	Mark Bishop (HS-Chicheste	28 Days - BB	Works Closed	26/08/2016	21/09/2016 Act.	BB01/316421
732613 Please f/w patch approx 0.3m2 around proud (approx 20mm) concrete surround (22cm * 22cm) with metal water stop cock cover in near back of western fw (F/W hazard trip/depression)	C106/2 o/s 22 Tradewind & approx 2.75m north of 24 Russet - opp Haylands & opp & approx 4m south of green street light column no 9	Teresa Wright (HS-Chiches	·	Works Closed		26/01/2017 Act.	
732614 Please lift & reset loose/rocking kerb (91cm * 12cm) front of southwestern tarmac f/w & may need additional tarmac for f/w behind, suggest attending in quiet period &/or stop & go (F/W hazard trip/depression)	C103/2 o/s 32 & approx 2.25m northwest of The Lodge (1st property north of Southern Water Sewage/Wastewater Treatment Works)	Teresa Wright (HS-Chiches	28 Days - BB	Works Closed	17/01/2017	23/11/2017 Act.	BB01/318582
734519 300 MM dia. Depth 70 MM. No photo due to location (Potholes)	On inside of bend where the small parking layby is, approx 120 m south of the sewage plant	Mark Bishop (HS-Chicheste	:28 Days - BB	Works Closed	02/03/2017	16/05/2017 Act.	BB01/319958

Mainte	nance Management							
Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
	·	d No Locn.:			C/Way Type: Whole Street Feature		Area: FISHBOUR	
73595	60 Kerbside Southbound side width 30-60cm depth more than 10cm (Enquiry (Potholes)	Treatment Works	Chichester Pothole Stack	5 Days - BB	Works Closed	10/04/2017	11/04/2017 Act.	BB01/321099
73744	2 width 30-60cm depth more than 10cm (Enquiry) (Potholes)	n approx 20/30mtre from the approach to the A259 Near Larkspur	Chichester Pothole Stack	5 Days - BB	Job Cancelled - No action req.	30/05/2017	30/05/2017 Est.	BB01/322129
73748	4 Pothole width is 300-600mm and depth is over 100mm (Potholes)	• • • • • • • • • • • • • • • • • • • •	Chichester Pothole Stack	5 Days - BB	Works Closed	31/05/2017	05/06/2017 Act.	BB01/322157
73830	Repair potholes in carriageway. Approx depth 4-10 cm and approx width 15-30cm/6-12ins (Enquiry (Potholes)	Just North of sewage works by the bridge. In carriageway.	Chichester Pothole Stack	28 Days - BB	Works Closed	29/06/2017	24/07/2017 Act.	BB01/322785
73863	4 Reinstate carriageway 0.6sqm x 50mm DBM (Potholes)	apuldram lane south chichester outside farm shop	James Strachan (App) [BL]	28 Days - BB	Works Closed	14/07/2017	07/08/2017 Act.	BB01/323045
73863	5 Reinstate pothole 1m x 0.5m x 60mm DBM (Potholes)	apuldram lane south chichester	James Strachan (App) [BL]	28 Days - BB	Works Closed	14/07/2017	07/08/2017 Act.	BB01/323046
73863	66 Reinstate pothole 0.4sqm x 50mm DBM (Potholes)	apuldram lane south chichester	James Strachan (App) [BL]	28 Days - BB	Works Closed	14/07/2017	07/08/2017 Act.	BB01/323047
73863	7 Reinstate pothole 0.4sqm x 40mm DBM (Potholes)	apuldram lane south chichester	James Strachan (App) [BL]	28 Days - BB	Works Closed	14/07/2017	07/08/2017 Act.	BB01/32304
73863	8 Reinstate carriageway 2m x 0.5r x 50mm DBM (Potholes)	m apuldram lane south chichester	James Strachan (App) [BL]	28 Days - BB	Works Closed	14/07/2017	07/08/2017 Act.	BB01/323049
74459	77 Driving lane width of the pothole 15-30cm depth more than 10cm (Enquiry (Potholes)	e about 100 metres from junction with Fishbourne Road West.	Chichester Pothole Stack	5 Days - BB	Works Closed	06/02/2018	08/02/2018 Act.	BB01/32763
74473	60 Kerbside width 30-60cm depth more than 10cm (Enquiry (Potholes)	h Near Calafrana number 10	Chichester Pothole Stack	5 Days - BB	Works Closed	07/02/2018	08/02/2018 Act.	BB01/327683
74564	1 300i MM depth 40 MM Site constraints: bend nearby (Potholes)	West edge of road just north of the bend south of sewage plant	Mark Bishop (HS-Chicheste	28 Days - BB	Works Closed	28/02/2018	21/03/2018 Act.	BB01/328344
74564	2 300m MM depth 60MM Site constraints: bend nearby (Potholes)	West edge of the road just north of the bend, south of the sewage plant	Mark Bishop (HS-Chicheste	28 Days - BB	Works Closed	28/02/2018	21/03/2018 Act.	BB01/328345
74564	3 350MM depth 40 MM Site constraints: bend nearby (Potholes)	West edge of road approx mid-way between sewage plant and the bend to the east	Mark Bishop (HS-Chicheste	28 Days - BB	Works Closed	28/02/2018	21/03/2018 Act.	BB01/32834
74725	4 1.5m x 350 mm patch. Depth 10 mm Site constraints: bend (Potholes)		Mark Bishop (HS-Chicheste	5 Days - BB	Works Closed	06/04/2018	25/04/2018 Act.	BB01/329692
040181	Undertake seek and find pothole repairs with hot material as agreed		John Bowyer [JB]	28 Days - BB	Job Cancelled - No action req.	17/02/2017	17/02/2017 Est.	BB04/201076

Maintenance Management										
Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order		
	Section: 1,009,999.00	Road No Locn.:		C/	Way Type: Whole Site Species		Area: FISHBOUR	NE		
5003559	95 STREET LIGHTING	LC1 (W side of road, immed. S of j/w Fishbourne Road West (A259)).	Mark Warwick (Tree Team)	TR: 05 High 3 Mon	ths Scheduled	16/11/2016	25/04/2018 Est.	BB06/11112		