

## **Health and Safety Executive: RIDDOR Report**

Report Number: 96B53A7C5B Date Submitted: 22/06/2017 Current Authority: East and South East - 08

Luton

About you and your organisation:

Name:

Job Title:

Phone Number:

Organisation:

Address:

Town:

County:

Post Code:

Fax Number:

E-Mail:

Did the Dangerous Occurrence happen at the above

Which authority is responsible where the Dangerous

**Operations Manager** 

**Whippet Coaches** 

2 Rowles Way

**Buckingway Business Park** 

Swavesey **CAMBRIDGE** 

Cambs

**CB24 4UG** 

@whippet.uk.com

ves

**HSE** 

Occurrence happened?

About where the Dangerous Occurrence happened:

Where did Dangerous Occurrence happen:

Organisation:

2 Rowles Way

Address:

**Buckingway Business Park** 

The incident happened at the notifier address

Swavesey **CAMBRIDGE** 

Town:

County:

Post Code:

Cambs **CB24 4UG** 

Details of where (address unknown):

**About the Dangerous Occurrence** 

Dangerous Occurrence date:

Dangerous Occurrence time:

21/06/2017

15:47

Country:

Which LA did the Dangerous Occurrence occur in?

Geographic Area:

Local Authority:

England

Cambridgeshire

In which department or where on premises did Dangerous Occurrence happen?

On the guided busway

What type of work was being carried out?

Main Industry:

Manufacture machinery, vehicle, transport

Main Activity:

Other transport equipment

Sub Activity:

Other transport equipment nec

About the kind of Dangerous Occurrence

Type of Dangerous Occurrence:

Collision of trains other than those reportable to ORR

Describe what happened:

Our guided bus BT66MVE was entering the track at Station Place en-route to Addenbrookes Hospital and the driver misjudged the track, mounted it and collided with a wall. No known injuries at this time but it was a dangerous incident.