

HSE Health and Safety Executive: RIDDOR Report

Report Number: 73F26C1FEE Date Submitted: 19/07/2017 Current Authority: East and South East - 08

Luton

About you and your organisation:

Name:

Job Title:

Phone Number:

Organisation:

Address:

Town:

County: Post Code:

Fax Number:

E-Mail:

Did the incident happen at the above address?

Which authority is responsible for monitoring H & S

where the incident happened?

PArk & Ride / Guided Busway Team Leader

Cambridgeshire County Council ET 1026 Trumpington Park & Ride

43 Hauxton Road **CAMBRIDGE**

Cambridgeshire CB2 9FT

no

HSE

01223 845791

@cambridgeshire.gov.uk

About where the incident happened:

Where did Incident happen:

The incident happened elsewhere in my organisation

Cambridgeshire County Council

Unknown

Address:

Town:

Organisation:

Unknown Unknown

HISTON

County: Post Code:

Details of where (address unknown):

Cambridgeshire UNKNOWN

Cambridgeshire Guided Busway, approximately 1 km north of its

junction with Station Road, Histon, Cambridgeshire

About the incident

Incident date:

Incident time:

15/07/2017

13:30

Which LA did incident occur in?

Country:

Geographic Area:

Local Authority:

England

Cambridgeshire

Cambridge

In which department or where on premises did incident happen?

Cambridgeshire Guided Busway

What type of work was being carried out?

Main Industry: Main Activity:

Transportation and Storage Land, pipeline transport

Sub Activity:

Other passenger land transport

About the kind of accident

Kind of accident that described incident:

Slip, trip, fall same level

How high was fall?

0 metres

Work process involved:

Movement, including aboard transport

Main factor involved:

Being caught or carried away by something (or by momentum)

Describe what happened:

A young male cyclist was travelling north on the maintenance track adjacent to the guideway when he and his bicycle fell into the guideway. A bus, travelling in the same direction, was approaching the location and the driver noticed the hazards and applied the bus's brakes. The action was sufficient to bring the bus to a halt a few feet short of the stricken cyclist, although a passenger was thrown from their seat near the front of the bus as a result of the braking. An ambulance response was mobilised for the bus passenger who, it was thought, had sustained back injuries after being thrown from their seat. The male cyclist reportedly sustained only minor injuries, and left the scene shortly afterwards. The injured passenger was initially treated on the bus for their injuries, before the bus was taken up the track to the next road junction where the injured passenger was transferred to a waiting ambulance for onward transportation to the nearest hospital

About the injured person

Name:

Address:

Town:

County:

Post Code: Phone Number:

Gender:

Age:

Injured person's employment status

What was the person's occupation or job title?

What was the person's work status?

Details if on training scheme / employed by someone else



Male

Member of the public - Job title not applicable

The injured person was a member of the public

About the injured person's injuries

Injured person's injuries: Part of body affected:

What was the severity of the injury?

Multiple injuries

Back

Member of the public - taken directly to hospital