

**Feature ID:** UY975/B

**Street:** Under Rainow

Road (09101268)

**Locality:** Congleton, Cheshire

**Area:** Congleton

**Report Period:** 17/05/08 to 17/05/10

### Ad Hoc Defects

Batch ID	Defect ID	Date	Description	Location	Officer
6503385	6503472	26/01/2010	Pot hole in c/way make safe	1100m before weathercock lane	CJ

### S58 Inspections

Batch ID	Officer	Date	Method	Type
14350	PAA	27/05/2008	Driven	Normal
15305	PAA	25/09/2008	Walked	Normal
16561	PAA	16/02/2009	Walked	Normal
7100324	PAA	27/05/2009	Walked	Normal
7101402	PAA	24/09/2009	Walked	Normal
7102570	PAA	27/01/2010	Driven	Normal

## S58 Defects



**Inspector:** PAA  
**Road Name:** Under Rainow Road  
**Chainage:** 290  
**Defect Number:** 128625  
**Description:** Flex/Cwy Pothole  
**Location:** opp brookhouse lane jct  
**XSP:** Permanent Right Lane 1  
**Time:** 2008-05-27 10:18:00

**Length:** 0.4  
**Surface Type:** Bitmac  
**Text:** .05  
**Width:** 0.4



**Inspector:** PAA  
**Road Name:** Under Rainow Road  
**Chainage:** 267  
**Defect Number:** 128637  
**Description:** Flex/Cwy Edge Deteriation  
**Location:** 20m before brookhouse lane jct  
**XSP:** Permanent Left Lane 1  
**Time:** 2008-05-27 10:17:00

**Length:** 3  
**Surface Type:** Bitmac  
**Text:** .1  
**Width:** 0.25



**Inspector:** PAA  
**Road Name:** Under Rainow Road  
**Chainage:** 25  
**Defect Number:** 7133122  
**Description:** Flex/Cwy Patch Diff in Level  
**Location:** approx 40m past rainbow farm  
**XSP:** Permanent Right Lane 1  
**Time:** 2010-01-27 09:34:00

**Length:** 0.5  
**Surface Type:** Bitmac  
**Text:** .04  
**Width:** 0.5



**Inspector:** PAA  
**Road Name:** Under Rainow  
Road  
**Chainage:** 765  
**Defect Number:** 7133123  
**Description:** Flex/Cwy  
Pothole  
**Location:** os birchwood  
**XSP:** Permanent Left  
Lane 1  
**Time:** 2010-01-27 09:38:00

**Length:** 1  
**Surface Type:** Bitmac  
**Text:** .05  
**Width:** 1

## Jobs

Job Number	Location	Officer Name	Entry Date	Notes	Current Status
1112787	20m before brookhouse lane jct	PAA	27/05/2008	Patch - no excavation & b	S58 Defect Made Safe
		Status Date	Status	Notes	Officer
Job Number	Location	Officer Name	Entry Date	Notes	Current Status
1112788	20m before brookhouse lane jct	RC	27/05/2008	Patch - no excavation & b - .1	Job to be Cancelled
		Status Date	Status	Notes	Officer
Job Number	Location	Officer Name	Entry Date	Notes	Current Status
1112789	Opp brookhouse lane jct	PAA	27/05/2008	Patch - no excavation & b	S58 Defect Made Safe
		Status Date	Status	Notes	Officer
Job Number	Location	Officer Name	Entry Date	Notes	Current Status
1112790	Opp brookhouse lane jct	RC	27/05/2008	Patch - no excavation & b - .05	Job to be Cancelled
		Status Date	Status	Notes	Officer
Job Number	Location	Officer Name	Entry Date	Notes	Current Status
6004234	On under rainow rainow road each side of its jcn with brookhouse lane.	JWH	11/01/2010	Install advance "no through road" signs	Awaiting Check for CDM
		Status Date	Status	Notes	Officer
Job Number	Location	Officer Name	Entry Date	Notes	Current Status
6004775	1100m before weathercock lane	RC	26/01/2010	Pot hole in c/way make safe	Job Closed - Sleeping
		Status Date	Status	Notes	Officer
		28/01/2010	Job Received by Contractor	Status update -	CJ

		16/02/2010	Work Complete on site	Status update - record created automatically by digital pen interface processing application.	CJ
		16/02/2010	Work started on site	Status update - record created automatically by digital pen interface processing application.	CJ
Job Number	Location	Officer Name	Entry Date	Notes	Current Status
7133719	Approx 40m past rainbow farm	RC	27/01/2010	Patch - edge key & bitmac - .04	Job Closed - Sleeping
		Status Date	Status	Notes	Officer
		28/01/2010	Job Received by Contractor	Status update -	CONG
		03/02/2010	Work started on site	Status update - record created automatically by digital pen interface processing application.	CONG
		03/02/2010	Work Complete on site	Status update -	CONG
Job Number	Location	Officer Name	Entry Date	Notes	Current Status
7133720	Os birchwood	RC	27/01/2010	Patch - no excavation & b - .05	Job Closed - Sleeping
		Status Date	Status	Notes	Officer
		28/01/2010	Job Received by Contractor	Status update -	CONG
		03/02/2010	Work started on site	Status update - record created automatically by digital pen interface processing application.	CONG
		03/02/2010	Work Complete on site	Status update - record created automatically by digital pen interface processing application.	CONG

**Enquiries on Road Section UY975/B**

**No Enquiries**

## Enquiries on Street Number 09101268

Number	Logged Time	Service	Subject	Description	Address
4303548	17/07/2008	Traffic & Transportation	planning applications	Planning app.	Smithy fold, under rainbow road, timbersbrook, congleton.
		Status Date	Status	Notes	Officer
		17/07/2008	Passed to Officer		JTW
		18/07/2008	Passed to Officer		NC
		13/08/2008	Resolved no action	No highway imp	NC
Number	Logged Time	Service	Subject	Description	Address
3023712	22/07/2008	Highway Maintenance	road works	Wants to know if the road will be closed?	
		Status Date	Status	Notes	Officer
		22/07/2008	Resolved		SMT
		22/07/2008	Resolved	Site amended - old : under rainow road (09101268) new : reades lane (09101014)	EM
		22/07/2008	Passed to Officer	Subject amended - old : road works (rwk) new : surface treatment (sur)	CS
		22/07/2008	Passed to Officer	Advised weather dependant and may not take 4 days - [REDACTED] not too happy	SS
		22/07/2008	Resolved	Site amended - old : reades lane (09101014) new : under rainow road (09101268). subject amended - old : surface treatment (sur) new : road works (rwk)	SMT
Number	Logged Time	Service	Subject	Description	Address
3051418	26/01/2009	Highway Maintenance	other	Interested in doing traffic surveys work	
		Status Date	Status	Notes	Officer

26/01/2009	Enquiry Received		MBO
26/01/2009	Passed to Officer		MBO
26/01/2009	Passed to Officer	Please call [REDACTED] on [REDACTED]	MBO
26/01/2009	Resolved	Please call [REDACTED] on [REDACTED] spoke to [REDACTED] to inform no jobs going to look on cheahire web site	MBO

Number	Logged Time	Service	Subject	Description	Address
3074711	28/07/2009	Highway Maintenance	Pothole	Caller states large potholes x2 in the area stated, states are very large but due to area and speed in road dose not have sizes.. pls inspect.	From the coach and horses pub along past the farm by the grid.
		Status Date	Status	Notes	Officer
	28/07/2009		Enquiry Received		MBO
	28/07/2009		Passed to Officer		MBO
	28/07/2009		Passed to Officer	Rang through to a/h/o	MBO
	28/07/2009		Passed to Officer	Rang through to a/h/o. i have phoned throught to [REDACTED] to look at, [REDACTED]	MBO
	28/07/2009		Passed to Officer	Rang through to a/h/o. i have phoned throught to mark to look at, julie phoned through to maint crew i was tied up with jetting crew 28/7/09 11.00	MBO
	28/07/2009		Resolved	Rang through to a/h/o. i have phoned throught to [REDACTED] to look at, [REDACTED] phoned through to maint crew i was tied up with jetting crew 28/7/09 11.00 inspected pm and found the maint crew had fill old reinstatement	MBO
	29/07/2009		Work passed to contractor	Job 6001809 - committed	MBO
	29/07/2009		101-Work Complete	Job progressed	MBO



		29/07/2009	101-Work Complete	Job progressed	MBO
		18/09/2009	101-Work Complete	Job 6001809 - qs complete	RC
Number	Logged Time	Service	Subject	Description	Address
2501658	17/08/2009	Traffic & Transportation	planning applications	Vc planning permission application	Smithy fold, under rainow road, timbersbrook, congleton, cheshire, cw12 3pn
		Status Date	Status	Notes	Officer
		17/08/2009	Passed to Officer		MMC
		17/08/2009	Passed to Officer		NC
		19/10/2009	Resolved		NC
Number	Logged Time	Service	Subject	Description	Address
2502409	09/10/2009	Traffic & Transportation	planning applications	Wants to reposition the vehicular access of under rainow road	Smithy fold under rainow road timbersbrook congleton
		Status Date	Status	Notes	Officer
		09/10/2009	Passed to Officer	9/10/09 > application was recieved	MMC
		12/10/2009	Passed to Officer		NC
		19/10/2009	Resolved		NC
Number	Logged Time	Service	Subject	Description	Address
3090792	17/11/2009	Street Lighting	light out	Col no 2, light out	Congleton
		Status Date	Status	Notes	Officer
		17/11/2009	Passed to Officer		JPO

		17/11/2009	Work passed to Job 3005751 - committed contractor		JPO
		02/12/2009	101-Work Complete	Job progressed	JPO
		25/01/2010	101-Work Complete	Job 3005751 - authorize payment	JPO
Number	Logged Time	Service	Subject	Description	Address
3094937	11/12/2009	Highway Maintenance	Temporary Traffic Lights	Please call re work nxt wed for central networks that require 3 way temp traf lights	Rd works spring bank farm, under rainow road, timbersbrook cw12 3pn
		Status Date	Status	Notes	Officer
		11/12/2009	Enquiry Received		AS
		11/12/2009	Passed to Officer		AS
		14/12/2009	Passed to Officer		PM
		14/12/2009	Passed to Officer	Site amended - old : rainow road (24101919) new : under rainow road (09101268)	CJ
		17/12/2009	Resolved	Approved	CJ
Number	Logged Time	Service	Subject	Description	Address
3095114	14/12/2009	Highway Maintenance	Temporary Traffic Lights	Caller requests to erect some temp traffic lights in order to complete some tree work. caller states that lights would be there for 1 day from 9:30am-4pm on wednesday 16th december, caller works on behalf of central networks.	Spring bank farm on junction brookhouse lane.
		Status Date	Status	Notes	Officer
		14/12/2009	Enquiry Received		CJ
		14/12/2009	Passed to Officer		CONG
		14/12/2009	Passed to Officer	** phoned through to aho	CONG

		14/12/2009	Resolved	** phoned through to aho there is already a enquiry on this	CONG
		14/12/2009	Passed to Officer	Subject amended - old : road opening licence (lc02) new : temporary traffic lights (ttl). ** phoned through to aho please approve	CJ
		17/12/2009	Resolved	Approved	CJ
Number	Logged Time	Service	Subject	Description	Address
3102360	28/01/2010	Highway Maintenance	Pothole	Caller rang to report that his wife hit a pothole in their car last night (27/01/10) 9pm and says this has damaged a tyre and dented an alloy wheel. says there are 2 potholes approx 3-4 inches deep. rang aho.	Cw12 3pn, 100 yards past stone cottages going towards the cloud.
		Status Date	Status	Notes	Officer
		28/01/2010	Passed to Officer		CJ
		28/01/2010	Passed to Officer	Rang through to [REDACTED] on his mobile - jh	CJ
		29/01/2010	Resolved	Have been filled in	CJ
		16/02/2010	Resolved	Have been filled in. letter of claim recieved 16/2/10	CJ
		19/02/2010	Passed to Officer	19.2.2010> first notification of claim sent to [REDACTED], inc invoices and photos, form 2 pls/krl	CJ
Number	Logged Time	Service	Subject	Description	Address
3102987	02/02/2010	Highway Maintenance	Pothole	Incident @ 09.30am 03.02.10- caller has no idea to size of pothole but its damaged the car tyre and tracking and caller wants to claim.	Near to joining with tunstall road, out of congleton towards tunstall road, 300yds before the crossroads of weathercock lane and tunstall road, caller did...
		Status Date	Status	Notes	Officer
		02/02/2010	Passed to Officer		CJ


		02/02/2010	Passed to Officer	Site amended - old : under rainow road (09101268) CJ new : under rainow road (09101268). subject amended - old : pothole (poth) new : pothole (poth)	
		03/02/2010	Passed to Officer	Rang through to aho	CJ
		03/02/2010	Passed to Officer	Rang through to aho passed to cj	CJ
		19/02/2010	Resolved	Filled in	CJ
Number	Logged Time	Service	Subject	Description	Address
3104636	12/02/2010	Highway Maintenance	other	Caller reports that stone wall has knocked through after a car crashed through it. caller states that wall stops livestock from entering road. caller states council repaired last time, please inspect and resolve. thankyou	Going towards roundabout on rainow road, near the old tenbursy cafe, near bus shelter.
		Status Date	Status	Notes	Officer
		12/02/2010	Passed to Officer		AS
		12/02/2010	Passed to Officer	** phoned through to aho	AS
		12/02/2010	Passed to Officer	** unable to contact aho	AS
		12/02/2010	Passed to Officer	Site amended - old : rainow road (24101919) new : under rainow road (09101268). ** unable to contact aho	CJ
Number	Logged Time	Service	Subject	Description	Address
3111557	16/04/2010	Street Lighting	light on during the day	Caller adamant light is on brookhouse lane, from his old ref it is rainow road. saying light is still on all the time	Near to the old factory and bath vale
		Status Date	Status	Notes	Officer
		16/04/2010	Enquiry Received		JPO

16/04/2010	Enquiry Received	Site amended - old : brookhouse lane (09100176) new : under rainow road (09101268)	JPO
16/04/2010	Enquiry Received	Job raised	JPO
19/04/2010	Passed to Officer		JPO
19/04/2010	Passed to Officer	Job raised	JPO
19/04/2010	Work passed to contractor	Job 3007141 - committed, updating job status to committed	JPO
20/04/2010	101-Work Complete	Job progressed	JPO

## Street Work Sites on 09101268

**Header Number:** 226135  
**Version Number:** 2  
**Site Number:** 1  
**Organisation:** BT  
**Start Date:** 23/05/2008  
**Est End Date:** 28/05/2008  
**End Date:** 28/05/2008

**Description:** DIG TO EXPOSE  
BURIED BT CABLE  
FIT NEW BT  
PREFABRICATED  
PLASTIC  
INSPECTION  
CHAMBER, per BT...  
**Notice Type:** EToN3: Section  
74  
**Works Name:** EToN3: Urgent  
**Works Ref:** EP2060000003056  
2348  
**Site Location:** ADJ NO 1 SPRING  
BANK COTTAGES,  
UNDER RAINOW  
ROAD,  
CONGLETON,  
CHESHIRE  
**Depth:** Up To 1.5  
Metres of Cover  
**Length:** 1  
**Width:** 0.6  
**Site Status:** Site Closed  
**Works Status:** Works Closed



**Header Number:** 239284  
**Version Number:** 3  
**Site Number:** 1  
**Organisation:** BT  
**Start Date:** 18/12/2008  
**Est End Date:** 22/12/2008  
**End Date:** 22/12/2008

**Description:** EXCAVATE ON  
BURIED BT CABLE  
IN THE FOOTWAY  
TO 350MM OF  
COVER APPROX 1M  
SQUARE.  
CABLE/JOINTING...

**Notice Type:** Registration of  
Reinstatement -  
Full

**Works Name:** EToN 4:  
Immediate -  
Urgent

**Works Ref:** EP206W000003198  
5673

**Site Location:** BETWEEN  
BIRCHWOOD AND  
SMITHY, UNDER  
RAINOW ROAD  
CONGLETON  
CHESHIRE

**Depth:** Up To 1.5  
Metres of Cover

**Length:** 1.2

**Width:** 0.4

**Site Status:** A Permanent  
Reinstatement

**Works Status:** Works Stopped



**Header Number:** 245792  
**Version Number:** 3  
**Site Number:** 1  
**Organisation:** West Midlands  
Network WMLDZ  
**Start Date:** 01/04/2009  
**Est End Date:** 09/04/2009  
**End Date:** 06/04/2009

**Description:** Trace, then  
excavate to  
repair gas  
escape and  
reinstate where  
possible

**Notice Type:** Registration of  
Reinstatement -  
Full

**Works Name:** EToN 4:  
Immediate -  
Emergency

**Works Ref:** 9563022

**Site Location:** O/S No 2

**Depth:** Up To 1.5  
Metres of Cover

**Length:** 1.25

**Width:** 0.8

**Site Status:** A Permanent  
Reinstatement


**Works Status:** Works Stopped





**Header Number:** 20003662  
**Version Number:** 3  
**Site Number:** 1  
**Organisation:** United Utilities  
PLC - MorganEST  
- CLEAN WATER  
MINO  
**Start Date:** 14/05/2009  
**Est End Date:** 26/05/2009  
**End Date:** 26/05/2009

**Description:** GANG REQUIRED  
TO REPAIR  
LEAKING SERVICE  
**Notice Type:** Registration of  
Reinstatement -  
Full  
**Works Name:** EToN 4:  
Immediate -  
Urgent  
**Works Ref:** 521223440010  
**Site Location:** UNDER RAINOW  
STREET Jnc OF  
WEATHERCOCK  
LANE  
**Depth:** Up To 1.5  
Metres of Cover  
**Length:** 1  
**Width:** 1  
**Site Status:** A Permanent  
Reinstatement  
**Works Status:** Works Stopped



**Header Number:** 20003972  
**Version Number:** 4  
**Site Number:** 1  
**Organisation:** United Utilities  
 PLC - MorganEST  
 - CLEAN WATER  
 MINO  
**Start Date:** 04/06/2009  
**Est End Date:** 15/06/2009  
**End Date:** 05/06/2009



**Header Number:** 20016459  
**Version Number:** 1  
**Site Number:** 1  
**Organisation:** Stoke  
**Start Date:** 16/12/2009  
**Est End Date:** 16/12/2009  
**End Date:** 16/12/2009

**Description:** DEFECTIVE --  
 GANG REQUIRED  
 TO REPLACE STOP  
 TAP

**Notice Type:** Registration of  
 Reinstatement -  
 Full

**Works Name:** EToN 4:  
 Standard

**Works Ref:** 521207541006

**Site Location:** O/S SMITHY ----  
 50METERS FROM  
 SMITHY HOUSE

**Depth:** Up To 1.5  
 Metres of Cover

**Length:** 1.5

**Width:** 1

**Site Status:** A Permanent  
 Reinstatement

**Works Status:** Works Stopped

**Description:** 40m of tree  
 cutting on side  
 of road

**Notice Type:** Works Stop

**Works Name:** EToN 4: Minor

**Works Ref:** \89645

**Site Location:** Outside Spring  
 Bank


**Depth:** No Excavation

**Length:** 0

**Width:** 0

**Site Status:** Site of  
 Proposed Street  
 Works

**Works Status:** Works Stopped



**Header Number:** 20016969  
**Version Number:** 2  
**Site Number:** 1  
**Organisation:** Stoke  
**Start Date:** 20/12/2009  
**Est End Date:** 26/12/2009  
**End Date:** 22/12/2009

**Description:** LV Fault -  
Excavate and  
locate the low  
voltage fault  
to repair and  
reinstate.

**Notice Type:** Works Stop

**Works Name:** ETON 4:  
Immediate -  
Urgent

**Works Ref:** \90867

**Site Location:** OPPST COACH-  
HORSES JNCT OF  
UNDER RAINOW RD  
AND READS LN

**Depth:** No Excavation

**Length:** 0

**Width:** 0

**Site Status:** Site of  
Proposed Street  
Works

**Works Status:** Works Stopped