

Selective Licensing Scheme - Netherfield Ward

Tom Southam

Senior Environmental Health Officer

Background

Scheme

Designated 1st October 2018

Netherfield Ward

All private rented dwellings to be Licensed



<u>Team</u>

One Environmental Health Officer

Two Housing Improvement and Enforcement Officers

One Student Placement Officer



Update On Applications

- 700 Applications Received
- 41 Applications withdrawn or subsequently found to be exempt from licensing
- 582 Licenses Issued
- 315 Properties Inspected (Inspections temporarily suspended due to Covid-19)
- Civil Penalty Notices served in relation to 13 dwellings for failing to licence (total fines £14,551)



Hazards Identified

 85% of properties identified as requiring remedial works following property inspection

 35 Properties identified as having disrepair presenting imminent risk to occupants safety (11%)




Advantages to the scheme

- Increase in property inspections
 - More hazards identified
 - More problems rectified
- Tenants, Agents and Landlords more aware now of what is expected and required
 - Tenants do not have to complain to the Council in order for an inspection to be carried out
 - Advice provided by officers on relevant legislative requirements, responsibilities and rights
 - 85% of properties had issues identified as requiring improvement.
- Licence conditions ensure effective management of property
 - Prescribed set of rules Licence Holders bound by
 - Increase in powers available to Council if conditions not adhered to




Before and After







Common hazards – Electrical








Disrepair to plug sockets and light fittings

Bare live wires





Common hazards – Damp and Mould







Defective damp proofing

Water leak


Defect to the fabric of the building allowing moisture ingress

Inadequate heating provision

Common hazards – Excess Cold













Disrepair to windows



Common hazards – Falls on Stairs/between levels








Disrepair to stairs

Inadequate guarding



Missing handrails Gedling **