

## Kings Park Site Visit 17/03/2020




View from the north looking south towards the 3 trees left for breeding birds. Fencing was in place around them. Diggers were moving about in the vicinity which was noisy but I am unsure if this would be enough to disturb the birds.



Tree to be retained in the north west of the site next to the access road. Fencing in place.



Protective fencing in place around trees on the eastern boundary of the site.



Two pigeons sitting on a nest in the tree belt on the east of the site.





View of the eastern part of the site looking north. Protective fencing in around the trees and the site boundary.



View of the site from the south looking north west. Showing the work around the trees left for breeding birds.



The south side of the site looking west. This looks like a pipe going in. I wasn't aware of this work but they have blocked off access from Clive Road. When I asked one of the workmen about it he advised that it was temporary, at least 2 weeks whilst the pipe was laid.