

# Freedom of Information Request

NSG Number:	17600055	*
Road Section:	C615/115	*
Reference:	Mr Paul Ellis	*
Period:	01/01/2015 to present	*

Road: STANE STREET, BILLINGSHURST

- |  |   |
|--|---|
| 1. Inspection Details  | Attached  |
| 2. Defect Details  | Attached  |
| 3. Inspection Frequency  | STANE STREET, BILLINGSHURST is subjected to a 6 monthly driven and a annually walked inspection<br><br>The driven inspection is carried out 6 monthly and the walked inspection annually                            |
| 4. Inspection Procedure  | Driven carriageway inspections are carried out in a County Council inspection vehicle specifically designed for this purpose, the vehicle is 'double manned'.<br>The maximum speed for driven inspections is 30 mph |
| 5. Complaint Details   | Attached  |
| 6. Road Hierarchy  | 4b  |
| 7. Road/Section Number   | C615/115  |
| 8. Defect Intervention Criteria:   | < 40mm: Low Impact<br>40 > < 99mm: Medium Impact<br>> 99mm: High Impact   |
| 9. Response Times:   | Low Impact: Observation<br>Medium Impact: 28 Days<br>High Impact: 5 Working Days  |
| 10. West Sussex County Council has taken guidance from 'Well Maintained Highways' A Code of Practice, July 2005. |   |