

Effective: 01/03/2014 to 04/04/2014

Batch Descrip. Contains: inspection batch

DisplayAction Officer: Yes

Street: Worksop Road, Mastin Moor (7101297)

Street: Worksop Road, Mastin Moor (7101297)

Locality: Chesterfield, Derbyshire

Area: Chesterfield Borough

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Section:	1,000.00	Road No. - Locn.:	MH - Worksop Rd, Mastin Moor	C/Way Type:	Highway Inspection		Area:	Chesterfield Borough
Batch:	3007524 - Inspection Batch			Route:	028C - Mntly Hwy - Staveley	Officer:	Peter Kleesh	Date: 17/03/2014
3022406		17/03/2014	at bus shelter just before Norbriggs Rd - eastbound	f/way trip hazard	Internal		Committed	2022639

Customer Services

Enquiry No: [REDACTED] **Logged by:** Suzanne Cross **on:** 19/03/2014 09:48 **Officer:** Performance Team
Service: Member or MP enquiry **Subject:** Member Enquiry H/ways **Classification:** service request **Enquiry Ref:** LAB/500.1
Desc.: Members Casework Enquiry: [REDACTED] has reported this twice via Contact Centre. Someone has been out and cut back the grass that was growing over the pavement but not repaired the pavement. [REDACTED] have both tripped on the uneven surface. See email attached for further background information. Please draft a response for Cllr Western to send [REDACTED]
Location: Pavement outside 390 Worksop Road, Mastin Moor **Contact:**

Enquiry No: [REDACTED] **Logged by:** Corinne O'Neill **on:** 25/03/2014 07:51 **Officer:** Street Lighting Admin
Service: SL - Street Light **Subject:** column damaged **Classification:** Street Lighting **Enquiry Ref:** INC 64 25/03/2014
Desc.: damaged after RTC, reported to be hanging over
Location: o/s 40a Worksop Road Maston Moor Col No 19399 **Contact:**

Enquiry No: [REDACTED] **Logged by:** System Agent 2 **on:** 19/03/2014 12:13 **Officer:** Nikki Hopkinson
Service: Maintenance Damage/Defect **Subject:** Manhole cover missing/damaged **Classification:** Rapid Response Teams
Desc.: caller reporting the manhole/gully has dropped caller said it is dangerous as lorries are bouncing about and the items they are carrying are getting thrown off into the road, she said a motor cyclist nearly came off at the weekend as something fell into the road, it is on Worksop Rd outside number 20 just before the traffic lights, it is a very busy road call back requiredNo is an insurance claim possible please obtain photographsNo
Location: Worksop Rd outside number 20 just before the traffic lights **Contact:**

Plot Number: 1,000.00

Feature Id - Location: MH - Worksop Rd, Mastin Moor

Feature Type: Highway Inspection

Job Number: 240509

Effective: 01/03/2014 to 04/04/2014

Batch Descrip. Contains: inspection batch

DisplayAction Officer: Yes

Street: Worksop Road, Mastin Moor (7101297)

Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
Section: 1,000.00		Road No. - Locn.: MH - Worksop Rd, Mastin Moor		C/Way Type: Highway Inspection		Area: Chesterfield Borough		
240509	Manhole cover missing/damaged - caller reporting the manhole/gully has dropped caller said it is dangerous as lorries are bouncing about and the items they are carrying are getting thrown off into the road, she said a motor cyclist nearly came off at the weekend as something fell into the road, it is on Worksop Rd outside number 20 just before the traffic lights, it is a very busy road call back requiredNo is an insurance claim possible please obtain photographsNo (Enquiry	Worksop Rd outside number 20 just before the traffic lights	Nikki Hopkinson	** 32 hours	Job Committed	20/03/2014	21/03/2014	Est. RM14/298586
2017549	5 x p/hs (carriageway pothole)	just before Lansbury Ave travelling downhill opposite lamp 19374 CDM Type - Low Risk Suggested Traffic Control - Give and Take Potential Hazards – Repair material to be used - Viafix Also identified for patch - YES	Stonegravels 1	** 32 hours	Job fully completed	13/02/2014	06/03/2014	Act. RM14/295069
2017550	2 x p/hs (carriageway pothole)	travelling towards Staveley just before Staveley Bridge CDM Type - Low Risk Suggested Traffic Control - Stop and Go Potential Hazards – Repair material to be used - Viafix Also identified for patch - YES	Stonegravels 1	** 32 hours	Job fully completed	13/02/2014	06/03/2014	Act. RM14/295070
2017715	f/way trip hazard	at bus stand near traffic lights at Norbriggs Rd junc CDM Type - Low Risk Suggested Traffic Control - Not required	Stonegravels 1	** 32 hours	Job fully completed	13/02/2014	06/03/2014	Act. RM14/295098
2017716	f/way trip hazard	opposite Norbriggs Road rear of A619 signs CDM Type - Low Risk Suggested Traffic Control - Not required Potential Hazards – pedestrians	Stonegravels 1	** 32 hours	Job fully completed	13/02/2014	06/03/2014	Act. RM14/295099

Effective: 01/03/2014 to 04/04/2014

Batch Descrip. Contains: inspection batch

DisplayAction Officer: Yes

Street: Worksop Road, Mastin Moor (7101297)

Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
Section: 1,000.00		Road No. - Locn.: MH - Worksop Rd, Mastin Moor		C/Way Type: Highway Inspection		Area: Chesterfield Borough		
2017717	carriageway pothole	outside 24 CDM Type - Low Risk	Stonegravels 1	** 32 hours	Job fully completed	13/02/2014	06/03/2014	Act. RM14/295100
		Suggested Traffic Control - Give and Take						
		Potential Hazards –						
		Repair material to be used -						
		Viafix						
2022639	f/way trip hazard	Also identified for patch - YES	Stonegravels 7	** 32 hours	Job passed to ACM	17/03/2014	18/03/2014	Est. RM14/298084
		at bus shelter just before						
		Norbriggs Rd - eastbound CDM						
		Type - Low Risk						
		Suggested Traffic Control - Give and Take						
		Potential Hazards – pedestrians						
Section: 5,027.00		Road No. - Locn.:		C/Way Type: ~DR Gully		Area: Chesterfield Borough		
1500914	FULL OF TARMAC. SEE MAP (dr-Gully dig out required)	0	Rob Marceniuk	xGully Contract	Job Raised	14/02/2013		
2022789	FULL OF TARMAC. See map - dr-gully dig out required		Rob Marceniuk	xGully Contract	Job Raised	18/03/2014	17/06/2014	Est.
Section: 5,061.00		Road No. - Locn.:		C/Way Type: ~DR Gully		Area: Chesterfield Borough		
1500913	FULL OF CEMENT. OS 2A (dr-Gully dig out required)	0	Rob Marceniuk	xGully Contract	Job fully completed	14/02/2013	20/03/2014	Act.
2022790	FULL OF CEMENT. Os 2a - dr-gully dig out required		Rob Marceniuk	xGully Contract	Job Raised	18/03/2014	17/06/2014	Est.