

Streetcare Reports for Potholes on the Croydon Flyover 09 December 2019 to 30 November 2020

Report ID	Title	Detail	Category	Subcategory	Created	Status	Borough	Easting	Northing	Report URL
1890036	Two pot holes on the flyover . This is a danger to cars, motocyclists and cyclists.	Called 111 aand advised on Friday.	Road, Cycleway and Footway Defects	Pothole	2019-12-16T09:18:41	fixed - council	Croydon	532463	165242	https://streetcare.tfl.gov.uk/report/1890036
1892133	slip road going off Croydon Flyover from Duppas Hill onto the A212 roundabout. This is a safety issue for the cars	Pothole found on the slip road going off Croydon Flyover from Duppas Hill onto the A212 roundabout. This is a safety issue for the cars	Road, Cycleway and Footway Defects	Pothole	2019-12-17T09:35:54	fixed - council	Croydon	531792	164919	https://streetcare.tfl.gov.uk/report/1892133
1892428	Pothole found on the slip road	Pothole found on the slip road going off Croydon Flyover from Duppas Hill onto the A212 roundabout. This is a safety issue for the cars	Road, Cycleway and Footway Defects	Pothole	2019-12-17T11:22:42	fixed - council	Croydon	532568	165249	https://streetcare.tfl.gov.uk/report/1892428
1926001	The road is worn and potholes forming	Croydon Flyover , Croydon - as you enter the junction of Park Lane and the flyover, the road is worn and potholes are forming	Road, Cycleway and Footway Defects	Pothole	2020-01-08T15:18:24	fixed - council	Croydon	532559	165244	https://streetcare.tfl.gov.uk/report/1926001
1942984	Deep pothole. On Croydon Flyover West just before exit slip to A236 kerbside	cause damage to vehicles. It's about time this was repaired properly. It had a temporary repair 12 months ago which didn't last. Located within 1.5m of the kerb and I estimate the depth as 800mm	Road, Cycleway and Footway Defects	Pothole (minor)	2020-01-16T17:04:41	fixed - council	Croydon	532323	165216	https://streetcare.tfl.gov.uk/report/1942984
1952554	Large pothole on Croydon Flyover near Croydon Jobcentre	very large and dangerous pot hole on the Croydon Flyover A232 heading towards WADDON from Croydon. On Wednesday 15th January 2020 I drove my vehicle over the pothole with my passenger side wheel damaging my RIM. The pot hole was covered with water. When I drove over it my car made a loud noise. I pulled over off the dual carriage way and saw the damage to my vehicle RIM I returned to take pictures of the pot hole, it was very dangerous to do as it was a dual carriage way I have attached photos for you to see.	Road, Cycleway and Footway Defects	Pothole	2020-01-21T13:27:07	duplicate	Croydon	531757	164920	https://streetcare.tfl.gov.uk/report/1952554
2053510	Potholes	Exact Location: 110 The Croydon Flyover , Croydon CR0 4BE, UK Latitude: 51.36798088375825 Longitude: -0.10579367678222429	Road, Cycleway and Footway Defects	Pothole (minor)	2020-03-10T18:35:58	fixed - council	Croydon	532008	164945	https://streetcare.tfl.gov.uk/report/2053510
2059348	Pothole	The pothole was somewhere in the location as indicated on the attached. It was as we left the flyover near where the up ramp merges with the A232.	Road, Cycleway and Footway Defects	Pothole (minor)	2020-03-13T11:08:19	fixed - council	Croydon	532265	165205	https://streetcare.tfl.gov.uk/report/2059348
2135608	Croydon Flyover Road Surface	Road surface on much of Duppas Hill Road and The Croydon Flyover is in a really poor state of repair. Please seriously consider a full re-surface and clean-up.	Road, Cycleway and Footway Defects	Pothole (minor)	2020-05-30T23:24:55	fixed - council	Croydon	531887	164905	https://streetcare.tfl.gov.uk/report/2135608
2329554	Large pothole on Croydon flyover just before the exit for the A236	Right before the exit to the A236 on Croydon Flyover . Hard to avoid and dangerous to try and avoid if exiting at this turning and there is a car on the outside lane.	Road, Cycleway and Footway Defects	Pothole	2020-10-07T09:29:53	fixed - council	Croydon	532332	165218	https://streetcare.tfl.gov.uk/report/2329554