

Effective: 17/02/2016 to 17/02/2018  
Street: FOREST ROAD (17600308)

Display Action Officer: Yes

Street: FOREST ROAD (17600308)

Locality: HORSHAM, WEST SUSSEX

Area: NORTH HORSHAM

### Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Section:</b>	9,999.00	<b>Road No. - Locn.:</b>		<b>C/Way Type:</b>	Whole Street Feature		<b>Area:</b>	NORTH HORSHAM
<b>Batch:</b>	688299 - Inspection Batch No actionable defects found			<b>Route:</b>	Horsham 3 Mthly Driven Urban	<b>Officer:</b>	Ian Brett (HS-Mid Sussex)	<b>Date:</b> 29/01/2018
<b>Batch:</b>	683746 - Inspection Batch No actionable defects found			<b>Route:</b>	Horsham 3 Mthly Driven Urban	<b>Officer:</b>	Ian Brett (HS-Mid Sussex)	<b>Date:</b> 30/10/2017
<b>Batch:</b>	680156 - Ad Hoc Inspection Batch			<b>Route:</b>	Ad-Hoc Northern2	<b>Officer:</b>	Horsham District	<b>Date:</b> 17/08/2017
3092018	Please sand and clear oil spillage on road after 2 car RTC. Police on site currently. 2m worth of oil.	17/08/2017	Outside property called Roffeyhurst Cottage	WS Obst flood,spill,tree,hedge	Internal		Committed	975165
<b>Batch:</b>	679138 - Inspection Batch No actionable defects found			<b>Route:</b>	Horsham 3 Mthly Driven Urban	<b>Officer:</b>	Ian Brett (HS-Mid Sussex)	<b>Date:</b> 26/07/2017
<b>Batch:</b>	676214 - Inspection Batch No actionable defects found			<b>Route:</b>	North Horsham Annual Walked	<b>Officer:</b>	Ian Brett (HS-Mid Sussex)	<b>Date:</b> 07/06/2017
<b>Batch:</b>	674631 - Inspection Batch No actionable defects found			<b>Route:</b>	Horsham 3 Mthly Driven Urban	<b>Officer:</b>	Mick Norris (HS-Horsham)	<b>Date:</b> 02/05/2017
<b>Batch:</b>	670129 - Inspection Batch No actionable defects found			<b>Route:</b>	Horsham 3 Mthly Driven Urban	<b>Officer:</b>	Ian Brett (HS-Mid Sussex)	<b>Date:</b> 31/01/2017
<b>Batch:</b>	635447 - Inspection Batch No actionable defects found			<b>Route:</b>	Horsham 3 Mthly Driven Urban	<b>Officer:</b>	Mick Norris (HS-Horsham)	<b>Date:</b> 28/10/2016
<b>Batch:</b>	630593 - Inspection Batch No actionable defects found			<b>Route:</b>	Horsham 3 Mthly Driven Urban	<b>Officer:</b>	Ian Brett (HS-Mid Sussex)	<b>Date:</b> 03/08/2016
<b>Batch:</b>	611987 - Ad Hoc Inspection Batch			<b>Route:</b>	Ad-Hoc Northern	<b>Officer:</b>	Jane Richards	<b>Date:</b> 09/08/2017
20202004	Trees - Tree had falling onto a car but been removed and chopped up by residents but left in Rd ( )	09/08/2017	Forest Road Horsham	WS Obst flood,spill,tree,hedge	Internal		Committed	60402562
<b>Batch:</b>	611632 - Ad Hoc Inspection Batch			<b>Route:</b>	Ad-Hoc Northern	<b>Officer:</b>	Jane Richards	<b>Date:</b> 27/04/2017
20201649	Rubbish and spillages - RTI damaged road sign and oil spillage (needs about 4 bags of sand )	27/04/2017	Forest Road B2195 Horsham (Near junction with Harwood Road	WS Obst flood,spill,tree,hedge	Internal		Committed	60402207
<b>Batch:</b>	397114 - Inspection Batch			<b>Route:</b>	North Horsham Annual Walked	<b>Officer:</b>	Ian Brett (HS-Mid Sussex)	<b>Date:</b> 03/06/2016
3080254	patch 0.15 x 0.15m lorry support leg depression in footway	03/06/2016	Outside nos.28-30	F/W hazard trip/depression	Internal		Committed	963126
3080253	cut square, excavate 50mm, reset 1 x loose buff tactile paver & patch 1.0 x 0.4m old sunken reinstatement in footway alongside tactile paved crossing point to west side of roundabout	03/06/2016	Alongside no.1 Beech Road	F/W hazard trip/depression	Internal		Committed	963127
<b>Batch:</b>	395779 - Inspection Batch No actionable defects found			<b>Route:</b>	Horsham 3 Mthly Driven Urban	<b>Officer:</b>	Mick Norris (HS-Horsham)	<b>Date:</b> 04/05/2016

Effective: 17/02/2016 to 17/02/2018  
Street: FOREST ROAD (17600308)

Display Action Officer: Yes

### Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Section:</b> 1,000,001.00	<b>Road No. - Locn.:</b> Opposite Forest Lodge			<b>C/Way Type:</b> Aesculus hippocastanum			<b>Area:</b> NORTH HORSHAM	
<b>Batch:</b> 1119595 - Inspection Batch	No actionable defects found			<b>Route:</b> Forest Road		<b>Officer:</b> Jake Farrington		<b>Date:</b> 19/01/2018
<b>Batch:</b> 1116828 - Inspection Batch				<b>Route:</b> Adhoc Inspection		<b>Officer:</b> Mark Warwick (Tree Team)		<b>Date:</b> 21/08/2017
848126		21/08/2017	Opposite Forest Lodge	ARB - Internal Tree Defect	Internal		Committed	50038252
<b>Section:</b> 1,000,002.00	<b>Road No. - Locn.:</b> opp 7			<b>C/Way Type:</b> Tilia x europaea			<b>Area:</b> NORTH HORSHAM	
<b>Batch:</b> 1119590 - Inspection Batch	No actionable defects found			<b>Route:</b> Forest Road		<b>Officer:</b> Jake Farrington		<b>Date:</b> 19/01/2018
<b>Section:</b> 1,000,003.00	<b>Road No. - Locn.:</b> OPP 5			<b>C/Way Type:</b> Tilia x europaea			<b>Area:</b> NORTH HORSHAM	
<b>Batch:</b> 1119591 - Inspection Batch	No actionable defects found			<b>Route:</b> Forest Road		<b>Officer:</b> Jake Farrington		<b>Date:</b> 19/01/2018
<b>Section:</b> 1,000,004.00	<b>Road No. - Locn.:</b> OPP 5			<b>C/Way Type:</b> Tilia x europaea			<b>Area:</b> NORTH HORSHAM	
<b>Batch:</b> 1119592 - Inspection Batch	No actionable defects found			<b>Route:</b> Forest Road		<b>Officer:</b> Jake Farrington		<b>Date:</b> 19/01/2018
<b>Section:</b> 1,000,005.00	<b>Road No. - Locn.:</b> OPP forest Lodge			<b>C/Way Type:</b> Tilia x europaea			<b>Area:</b> NORTH HORSHAM	
<b>Batch:</b> 1119593 - Inspection Batch	No actionable defects found			<b>Route:</b> Forest Road		<b>Officer:</b> Jake Farrington		<b>Date:</b> 19/01/2018
<b>Section:</b> 1,000,006.00	<b>Road No. - Locn.:</b> OPP forest Lodge			<b>C/Way Type:</b> Tilia x europaea			<b>Area:</b> NORTH HORSHAM	
<b>Batch:</b> 1119594 - Inspection Batch	No actionable defects found			<b>Route:</b> Forest Road		<b>Officer:</b> Jake Farrington		<b>Date:</b> 19/01/2018
<b>Section:</b> 1,000,007.00	<b>Road No. - Locn.:</b> opp. no. 66 and rear south of no. 8, Rowan Close			<b>C/Way Type:</b> Quercus robur			<b>Area:</b> NORTH HORSHAM	
<b>Batch:</b> 1119596 - Inspection Batch	No actionable defects found			<b>Route:</b> Forest Road		<b>Officer:</b> Jake Farrington		<b>Date:</b> 19/01/2018

### Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
<b>Section:</b> 1.00	<b>Road No. - Locn.:</b> C49/110				<b>C/Way Type:</b> Single 2-Lane Carriageway		<b>Area:</b> NORTH HORSHAM	
417052	cpo / minor fretting.	cpo / outside 5 in layby	Nick De Sousa (TE-Mid Sx)	ZZZZP3	Z Works Incomplete	11/02/2003	05/08/2003	Est.
417053	ft / kerb missing, no immediate danger	ft / opposite 16	Nick De Sousa (TE-Mid Sx)	ZZZZP3	Z Works Incomplete	11/02/2003	05/08/2003	Est.
429801	gnn /	0	Nick De Sousa (TE-Mid Sx)	ZZZGNI	Z No code allocated	13/08/2003	06/02/2004	Est.
<b>Section:</b> 2.00	<b>Road No. - Locn.:</b> C49/115				<b>C/Way Type:</b> Single 2-Lane Carriageway		<b>Area:</b> NORTH HORSHAM	
63396			Drainage Strategy Team	28 Days - BB	Job is part of wider scheme	02/12/2011	30/12/2011	Est.
429800	gnn /	0	Nick De Sousa (TE-Mid Sx)	ZZZGNI	Z No code allocated	13/08/2003	06/02/2004	Est.
<b>Section:</b> 2.25	<b>Road No. - Locn.:</b> C49/118				<b>C/Way Type:</b> Single 2-Lane Carriageway		<b>Area:</b> NORTH HORSHAM	
328865	Replace centre and edge line	Bend near Rowan House	Nigel Dewey	zz - Do not use old Cat 3	Job is part of wider scheme	08/09/2006	07/09/2008	Est.
417054	see section 1		Nick De Sousa (TE-Mid Sx)	ZZZZP3	Z Works Incomplete	11/02/2003	05/08/2003	Est.

Effective: 17/02/2016 to 17/02/2018  
Street: FOREST ROAD (17600308)

Display Action Officer: Yes

### Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
<b>Section:</b> 2.25		<b>Road No. - Locn.:</b> C49/118		<b>C/Way Type:</b> Single 2-Lane Carriageway		<b>Area:</b> NORTH HORSHAM		
429802	gnn /	0	Nick De Sousa (TE-Mid Sx)	ZZZGNI	Z No code allocated	13/08/2003	06/02/2004	Est.
<b>Section:</b> 3.50		<b>Road No. - Locn.:</b> C49/208		<b>C/Way Type:</b> Single 1-Lane Cway (one-way)		<b>Area:</b> NORTH HORSHAM		
407056	pothole at manholecover	c/w outside 27 at b/t cover	Richard Nicholson (NAO)	ZZZZN2	Z Works Incomplete	18/07/2002	05/12/2002	Est.
429799	gnn /	0	Nick De Sousa (TE-Mid Sx)	ZZZGNI	Z No code allocated	13/08/2003	06/02/2004	Est.
<b>Section:</b> 9,999.00		<b>Road No. - Locn.:</b>		<b>C/Way Type:</b> Whole Street Feature		<b>Area:</b> NORTH HORSHAM		
95651	2015/16 FOOTWAY SMALL WORKS BATCH 1. SEE MASTER JOB 943452 FOR BATCH INFORMATION - Replace stick on tactile paving with new tactile paving slabs	Junction with Harwood Road. 519629, 131939 - 519648, 131975	Chris Whiting (Structural)	[k 2 Weeks Contractor Assessment	Works Closed	29/09/2015	22/06/2016	Act.
316084	ft / root damage 2x3m patch & depression 0.5x4m (FW tripping hazard)	ft / roffey lites end, near tree on verge & alongside 1 beech rd	Steve Bicknell (HE-Crwly)	[ ZZZ 3 - 6 Monthly - 6 Months	Passed to Contractor	18/08/2005	09/02/2006	Est.
324429	FTR - root damage. (Trip)	FTR - As marked on map. Between Roffey lights jnc & Forest Road slip road.	Nick De Sousa (TE-Mid Sx)	zz- Do not use old Cat 2-6	Job Cancelled	08/06/2006	03/12/2006	Est.
360894	jetting required,previous investigation not completed /flooding 28/03/08	slip road at roffey lights	John Bowyer [JB]	zz- Do not use old Cat 2-6	Job is part of wider scheme	31/03/2008	25/09/2008	Est.
374065	debris from RTA includes posts and chevron require renewing (Safety Sign, Barrier, Ped Rail)	junction of Forest grange (private road)	Charlie West (Routine Mair z	Fix required within 3 months	Job is part of wider scheme	30/03/2009	27/06/2009	Est.
374066	Reported by Sussex Police serial [REDACTED] Rta accident has knocked down chevrons and posts (Safety Sign, Barrier, Ped Rail)	Junction Forest Grange (private Road)	Charlie West (Routine Mair	zzPassed to Traffic Engineer	Passed to Traffic Engineer	30/03/2009	30/03/2011	Est.
430884	SSM / Chevron sign struck by vehicle. Needs replacing but not obstruction to carriageway. Damage to posts & sign. SPH/JU	SSM / Forest road on Forest Grange triangle heading towards horsham.	Nick De Sousa (TE-Mid Sx)	ZZZZN2	Z Works Incomplete	04/09/2003	26/01/2004	Est.
963126	patch 0.15 x 0.15m lorry support leg depression in footway (F/W hazard trip/depression)	Outside nos.28-30	Ian Brett (HS-Mid Sussex)	28 Days - BB	Works Closed	03/06/2016	20/06/2016	Act. BB01/921468
963127	cut square, excavate 50mm, reset 1 x loose buff tactile paver & patch 1.0 x 0.4m old sunken reinstatement in footway alongside tactile paved crossing point to west side of roundabout (F/W hazard trip/depression)	Alongside no.1 Beech Road	Ian Brett (HS-Mid Sussex)	28 Days - BB	Works Closed	03/06/2016	21/06/2016	Act. BB01/921468

Effective: 17/02/2016 to 17/02/2018  
Street: FOREST ROAD (17600308)

Display Action Officer: Yes

### Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
Section:	9,999.00	Road No. - Locn.:			C/Way Type: Whole Street Feature		Area: NORTH HORSHAM	
975165	Please sand and clear oil spillage on road after 2 car RTC. Police on site currently. 2m worth of oil. (WS Obst flood,spill,tree,hedge)	Outside property called Roffeyhurst Cottage	Emergency Response	Nort 2 Hours - BB	Works Closed	17/08/2017	17/08/2017	Act. BB01/930005
6000574	Programme Year 2014/15 Carriageway Surface Dressing (PSD Patching 6002629) (Planned Carriageway Works) MASTER JOB - Refer to Dummy JN 6002904	(B2195) Harwood Road to Grouse Road 519617,131977 to 520750, 132333 (CD: B2195 Harwood Road to Forest Grange EN: 519615, 131977 to 520763, 132333)	Asset Management Team	[ Planned Works - Forward Prog.	Passed To Contractor To Start	09/12/2013	07/12/2020	Est.
6002629	MASTER JOB - Refer to Dummy JN 6002907 Programme Year 2014/15 Carriageway PSD Patching (Surface Dressing JN 6000574) (Planned Carriageway Works)	(B2195) Harwood Road to Grouse Road 519617,131977 to 520750, 132333 (CD: B2195 Harwood Road to Forest Grange EN: 519615, 131977 to 520763, 132333)	Asset Management Team	[ Planned Works - Forward Prog.	Passed To Contractor To Start	19/03/2014	17/03/2021	Est.
6004967	Drainage - water from blocked drain flowing yet again across into callers garden. #Extent of obstruction : Slip road is described as a river. Frequent flooding is now undermining her garden wall. Very unhappy that thisw flooding problem repeats three or four times every year. #Is it causing an obstruction? : No #Call Back Reason : Wants to know when the problem will be solved, not just occasional rodding. #Is there anything else? : Very anxious for a final solution to the problem. Call back requested with date for work to be done. (Call Back Requested)	rear of 14, by Forest Road slip road.	John Bowyer [JB]	28 Days - BB	Job is part of wider scheme	21/10/2014	12/11/2014	Est.
60402207	Rubbish and spillages - RTI damaged road sign and oil spillage (needs about 4 bags of sand [REDACTED]) (WS Obst flood,spill,tree,hedge)	Forest Road B2195 Horsham (Near junction with Harwood Road	Emergency Response	Nort 2 Hours - BB	Works Closed	27/04/2017	27/04/2017	Act. BB01/60510
60402562	Trees - Tree had falling onto a car but been removed and chopped up by residents but left in Rd [REDACTED]) (WS Obst flood,spill,tree,hedge)	Forest Road Horsham	Emergency Response	Nort 2 Hours - BB	Works Closed	09/08/2017	09/08/2017	Act. BB01/60853

Effective: 17/02/2016 to 17/02/2018  
 Street: FOREST ROAD (17600308)

Display Action Officer: Yes

**Maintenance Management**

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
<b>Section:</b> 1,000,001.00		<b>Road No. - Locn.:</b> Opposite Forest Lodge			<b>C/Way Type:</b> Aesculus hippocastanum		<b>Area:</b> NORTH HORSHAM	
50038252	1 of 1 job	Opposite Forest Lodge	Mark Warwick (Tree Team)	TR: 04 High   6 Weeks	Works Completed	21/08/2017	12/10/2017	Act. BB06/13869