

Health Safety & Security Tool Kit

VRA026 RRV BMW i3



Potential Hazard	Potential injury caused and how	Current Controls	Risk Score			Additional controls required	Completion date and by who
			C	L	Risk		
Access to communication equipment	Manual handling injury to NWAS engineers	All staff are instructed in manual handling techniques. Access to the communications equipment located under the boot area has been designed to minimise manual handling injuries. The central partition can be quickly unscrewed and is hinged to drop down onto the boot base which can then be removed. The cage for the communications equipment is provided with handles to aid being lifted out of the car.	2	2	4	None	

Vehicle LJ67 DZY associated photos available in s:/Medical/Risk and Safety/HSS/Risk Assessments/3 Vehicles/BMW i3 RRV Photos Oct 2017

NWAS:	Page:	7 Of 7
Author: Health, Safety and Safety	Version:	V2
Date: May 2019	Status:	Approved
Date of issue: May 2019	Date of review:	May 2020