Enquiry Trace Form

07/09/2011			inquity trace rol	1111		
Enquiry: 1710140	08	Logged by:	Jennifer Pow		on 28/01/2010 14:00	
Service: Traffic a	and Parking		Classifica	ation: Request for Service		
Subject: Hgv/Lar	ge Vehicle Issue	es				
	s exceed the 7.5 rate the road.	tn limit and al	vays go through the village	despite the restrictions and s	signs, the lorries thunder pass	
Street: WYE R	OAD (1301977),	WYE WITH H	IINXHILL, KENT			
Street Address: WYE Ro	OAD			Area: Ashford		
Location: from ker	mps corner to A	251		Ward: Wye		
Customer: 1710126	63	Time: 28/01/2010 14:00 Method: Telephone		•		
Name:	-	Telephone:				
Address:					- con-control	
Current Status:						
No. Effective	Status		Officer		w up Date	
6 10/02/2010 12:04:26 Notes: job raised	-	•	James Pronge			
Status history:	by sarah elicoc	k to repair poti	10:63		mana Anthe-Fr	
No. Effective	Status		Officer	Note	s	
5 09/02/2010 14:05	ENQ - Enquir	y Acknowledg	ed James Pronge	· · · · · ·		
4 08/02/2010 16:02 3 28/01/2010 15:09	ENQ - Enquir	y Reassigned	James Pronge	Phon today with I there in Wy Corn Also compin Octose inspec	the back of and explained situ tegard to lorry use. Ithen reported that are lots of pot holes are lots of pot holes are lots of contages. It is a contage to the contage of	
2 28/01/2010 14:00	ENQ - P2 En			limit : the vi restri lorrie	cles exceed the 7.5tn and always go through illage despite the ctions and signs, the s thunder pass and le the road.	
1 28/01/2010 14:00 Revised Status:	ENQ - P2 En	quiry Received	T&D ASHFORI	limit : the vi restri lorrie:	cles exceed the 7.5tn and always go through illage despite the ctions and signs, the s thunder pass and te the road.	
Mevised Status:						

Name :	Signed :	Date :	Time: