



Customer Enquiry X Site Report Inspection Batch Inspection Batch Feature X

1 of 1 Activities

Inspection Batch 12061301 Inspection Batch

Site CHINNOR ROAD 45500215

Asset Id B4009 Locn

Asset Number 1.00 HW: SECONDARY DISTRIBUTION

Measurement 1,149.08 Metre

Officer LWHT Lewis White

Inspected 05/01/2017 12:15:48 Expiry Date 00/00/0000 00:00:00

Due Date 29/01/2017 00:00:00

Conditions

Defects

Observation Type	Grade	Score	Defects
HW: Defect Observations	Defect found	.0000	0
HW: Driver	Not Assessed	.0000	0
HW: Road Condition	Dry	.0000	0
HW: Weather	Sunny	.0000	0

Observe Type HW: Defect Observations HDEF

Grade Defect found Score .0000

Notes P3 order raised for gully and setts to be repaired on 7/11/16, now an immediate safety risk, order raised for next working

New

Delete

Defect

SOR Items		Status Log	Child Jobs
Job Item No.	SOR Item Code	SOR Item Name	Item Quantity
1	HWPOTD	HW: Pothole Dimensions	1.00

[Detail](#)

Job		Additional		Current Status	
Job Number	5045402	Placed on W.O.	TFB09/65044288	Committed	Parent Job
Site	CHINNOR ROAD		45500215		
	BLEDLOW, BUCKINGHAMSHIRE				
Asset Id	B4009		Location		
Asset No	1.00	HW: SECONDARY DISTRIBUTOR			
Area	LAT Area 9 (HWHX)		Ward	Ridgeway West	
Description	please make a full repair To defect as marked using 10mm hot material		Work Location	Out side maplewood	
Job Type	12	Notice/Permit Required No Exc (Semi Auto)		Estimated Value	
Hazard Type	Highways Attributes				
Priority	HW P2 (NWD)		Price Factor	Standard Rates & Activities	
Cost Code	R07Pothole	R07Pothole		Partial Payments	
Customer	BCC		Est. Start Date	06/01/2017 12:32:00	
Customer Reference			Actual Start Date	06/01/2017 12:30:44	
Pref. Contr.	TFB09	Transport for Buckinghamshire	Est. Completion	06/01/2017 13:17:00	
Status	J350	Job Complete (COMPLETED)	Target Completion	06/01/2017 12:16:02	
Officer	LWHT	Lewis White	Actual Completion	06/01/2017 12:31:06	

SOR Items		Status Log	Child Jobs
Job Item No.	SOR Item Code	SOR Item Name	Item Quantity
1	HWFOTD	HW: Pothole Dimensions	1.00

[Detail](#)

SOR Items		Status Log	Child Jobs
Job Item No.	SOR Item Code	SOR Item Name	Item Quantity
1	HWPOTD	HW: Pothole Dimensions	1.00

[Detail](#)



Customer Enquiry X Site Report Inspection Batch Inspection Batch Feature X

1 of 1 Activities

Inspection Batch 12066208 Inspection Batch

Site CHINNOR ROAD 45500215 ...

Asset Id B4009 ... Locn

Asset Number 1.00 HW: SECONDARY DISTRIBUTION

Measurement 1,149.08 Metre

Officer MKES Lee Meakes ...

Inspected 20/02/2017 13:55:28 Expiry Date 00/00/0000 00:00:00

Due Date 28/02/2017 00:00:00

Conditions

Defects

Observation Type	Grade	Score	Defects
HW: Defect Observations	Nothing found	.0000	0
HW: Driver	Not Assessed	.0000	0
HW: Road Condition	Dry	.0000	0
HW: Weather	Cloudy	.0000	0

Observe Type HW: Defect Observations HDEF ...

Grade Nothing found Score .0000

Notes

New

Delete

Defect

File Edit Shortcuts Window Help



Customer Enquiry X Site Report Inspection Batch Inspection Batch Feature X

1 of 1 Activities

Inspection Batch 12068135 Inspection Batch

Site CHINNOR ROAD 45500215 ...

Asset Id B4009 ... Locn

Asset Number 1.00 HW: SECONDARY DISTRIBUTION

Measurement 1,149.08 Metre

Officer LWHT Lewis White ...

Inspected 09/03/2017 13:09:18 Expiry Date 00/00/0000 00:00:00

Due Date 28/04/2017 00:00:00

Conditions

Defects

Observation Type	Grade	Score	Defects
HW: Defect Observations	Defect found	.0000	0
HW: Driver	Not Assessed	.0000	0
HW: Road Condition	Dry	.0000	0
HW: Weather	Sunny	.0000	0

Observe Type HW: Defect Observations HDEF ...

Grade Defect found Score .0000

Notes

New

Delete

Defect

Ready

Job		Additional		Current Status	
Job Number	5051336	Placed on W.O.	TFB09/65050193	Committed	Parent Job
Site	CHINNOR ROAD		45500215		
	BLEDLOW, BUCKINGHAMSHIRE				
Asset Id	B4009		Location		
Asset No	1.00	HW: SECONDARY DISTRIBUTOR			
Area	LAT Area 9 (HWHX)		Ward	Ridgeway West	
Description	Please make a full repair to defect as marked using 10mm hot material		Work Location	Out side garage called platinum autos	
Job Type	12	Notice/Permit Required No Exc (Semi Auto)		Estimated Value	
Hazard Type	Highways Attributes				
Priority	HW P2 (NWD)		Price Factor	Standard Rates & Activities	
Cost Code	R07Pothole	R07Pothole		Partial Payments	
Customer	BCC		Est. Start Date	10/03/2017 15:10:00	
Customer Reference			Actual Start Date	10/03/2017 12:51:39	
Pref. Contr.	TFB09	Transport for Buckinghamshire	Est. Completion	10/03/2017 15:55:00	
Status	J350	Job Complete (COMPLETED)	Target Completion	10/03/2017 13:09:35	
Officer	LWHT	Lewis White	Actual Completion	10/03/2017 13:26:38	

SOR Items		Status Log	Child Jobs
Job Item No.	SOR Item Code	SOR Item Name	Item Quantity
1	HWPOTD	HW: Pothole Dimensions	1.00

[Detail](#)

Job		Additional		Current Status	
Job Number	5051337	Placed on W.O.	TFB09/65050195	Committed	Parent Job
Site	CHINNOR ROAD		45500215		
	BLEDLOW, BUCKINGHAMSHIRE				
Asset Id	B4009		Location		
Asset No	1.00	HW: SECONDARY DISTRIBUTOR			
Area	LAT Area 9 (HWHX)		Ward	Ridgeway West	
Description	Please make a full repair to defect as marked using 10mm hot material		Work Location	Out side garage called platinum autos	
Job Type	12	Notice/Permit Required No Exc (Semi Auto)		Estimated Value	
Hazard Type	Highways Attributes				
Priority	HW P2 (NWD)		Price Factor	Standard Rates & Activities	
Cost Code	R07Pothole	R07Pothole		Partial Payments	
Customer	BCC		Est. Start Date	10/03/2017 15:55:00	
Customer Reference			Actual Start Date	10/03/2017 12:52:07	
Pref. Contr.	TFB09	Transport for Buckinghamshire	Est. Completion	10/03/2017 16:40:00	
Status	J350	Job Complete (COMPLETED)	Target Completion	10/03/2017 13:09:35	
Officer	LWHT	Lewis White	Actual Completion	10/03/2017 13:27:10	

SOR Items		Status Log	Child Jobs
Job Item No.	SOR Item Code	SOR Item Name	Item Quantity
1	HWPOTD	HW: Pothole Dimensions	1.00

[Detail](#)

Job		Additional		Current Status	
Job Number	5051338	Placed on W.O.	TFB09/65050194	Committed	Parent Job
Site	CHINNOR ROAD		45500215		
	BLEDLOW, BUCKINGHAMSHIRE				
Asset Id	B4009		Location		
Asset No	1.00	HW: SECONDARY DISTRIBUTOR			
Area	LAT Area 9 (HWHX)		Ward	Ridgeway West	
Description	Please make a full repair to defect as marked using 10mm hot material		Work Location	On junction of west lane	
Job Type	12	Notice/Permit Required No Exc (Semi Auto)		Estimated Value	
Hazard Type	Highways Attributes				
Priority	HW P2 (NWD)		Price Factor	Standard Rates & Activities	
Cost Code	R07Pothole	R07Pothole		Partial Payments	
Customer	BCC		Est. Start Date	10/03/2017 16:41:00	
Customer Reference			Actual Start Date	10/03/2017 12:21:20	
Pref. Contr.	TFB09	Transport for Buckinghamshire	Est. Completion	10/03/2017 17:26:00	
Status	J350	Job Complete (COMPLETED)	Target Completion	10/03/2017 13:09:35	
Officer	LWHT	Lewis White	Actual Completion	10/03/2017 12:46:12	

SOR Items		Status Log	Child Jobs
Job Item No.	SOR Item Code	SOR Item Name	Item Quantity
1	HWPOTD	HW: Pothole Dimensions	1.00

[Detail](#)



Customer Enquiry X Site Report Inspection Batch Inspection Batch Feature X

1 of 1 Activities

Inspection Batch 12072780 Inspection Batch

Site CHINNOR ROAD 45500215

Asset Id B4009 Locn

Asset Number 1.00 HW: SECONDARY DISTRIBUTION

Measurement 1,149.08 Metre

Officer MKES Lee Meakes

Inspected 24/04/2017 11:49:25 Expiry Date 00/00/0000 00:00:00

Due Date 28/05/2017 00:00:00

Conditions

Defects

Observation Type	Grade	Score	Defects
HW: Defect Observations	Nothing found	.0000	0
HW: Driver	Not Assessed	.0000	0
HW: Road Condition	Dry	.0000	0
HW: Weather	Cloudy	.0000	0

Observe Type HW: Defect Observations HDEF

Grade Nothing found Score .0000

Notes

New

Delete

Defect

File Edit Shortcuts Window Help



Customer Enquiry X Site Report Inspection Batch Inspection Batch Feature X

1 of 1 Activities

Inspection Batch 12073576 Inspection Batch

Site CHINNOR ROAD 45500215

Asset Id B4009 Locn

Asset Number 1.00 HW: SECONDARY DISTRIBUTION

Measurement 1,149.08 Metre

Officer MKES Lee Meakes

Inspected 03/05/2017 12:21:52 Expiry Date 00/00/0000 00:00:00

Due Date 28/06/2017 00:00:00

Conditions

Defects

Observation Type	Grade	Score	Defects
HW: Defect Observations	Nothing found	.0000	0
HW: Driver	Not Assessed	.0000	0
HW: Road Condition	Dry	.0000	0
HW: Weather	Cloudy	.0000	0

Observe Type HW: Defect Observations HDEF

Grade Nothing found Score .0000

Notes

New

Delete

Defect

Ready

File Edit Shortcuts Window Help



Customer Enquiry X Site Report Inspection Batch Inspection Batch Feature X

1 of 1 | Activities

Inspection Batch 12076528 Inspection Batch

Site CHINNOR ROAD 45500215 ...
 Asset Id B4009 ... Locn
 Asset Number 1.00 HW: SECONDARY DISTRIBUTION
 Measurement 1,149.08 Metre
 Officer MKES Lee Meakes ...
 Inspected 07/06/2017 11:18:11 Expiry Date 00/00/0000 00:00:00
 Due Date 28/07/2017 00:00:00

Conditions		Defects	
Observation Type	Grade	Score	Defects
HW: Defect Observations	Defect found	.0000	0
HW: Driver	Not Assessed	.0000	0
HW: Road Condition	Dry	.0000	0
HW: Weather	Cloudy	.0000	0

Observe Type	HW: Defect Observations	HDEF	...
Grade	Defect found	Score	.0000
Notes			

New

Delete

Defect

Job		Additional		Current Status	
Job Number	5058835	Placed on W.O.	TFB09/65057632	Committed	Parent Job
Site	CHINNOR ROAD		45500215		
	BLEDLOW, BUCKINGHAMSHIRE				
Asset Id	B4009		Location		
Asset No	1.00	HW: SECONDARY DISTRIBUTOR			
Area	LAT Area 9 (HWHX)		Ward	Ridgeway West	
Description	Please make a full repair to the pothole as marked Tm stop and go (C/way surfacing - pothole)		Work Location	Junction with skittle green	
Job Type	16	Notice/Permit Required With Exc (Semi-Auto)		Estimated Value	
Hazard Type	New Defect Attributes 2017				
Priority	Category 1 - 2 Working days		Price Factor	Standard Rates & Activities	
Cost Code	R07ROUTINEMAIN	R07 Routinemaint		Partial Payments	
Customer	BCC		Est. Start Date	08/06/2017 10:55:00	
Customer Reference			Actual Start Date	08/06/2017 09:19:02	
Pref. Contr.	TFB09	Transport for Buckinghamshire	Est. Completion	08/06/2017 11:40:00	
Status	J350	Job Complete (COMPLETED)	Target Completion	09/06/2017 12:16:00	
Officer	MKES	Lee Meakes	Actual Completion	08/06/2017 09:20:05	

SOR Items		Status Log	Child Jobs
Job Item No.	SOR Item Code	SOR Item Name	Item Quantity
1	MAIND1	Maintenance: Attend and Repair	1.00

[Detail](#)