

# **Inspection Defect Summary Report**







#### D81106/00105

#### STOKES AVENUE WIMBORNE ROAD TATNAM ROAD

Defect Reference	Item Type	Item Detail	Defect Category	Defect Date	Current Status	Actual Completion Date	Location Description
Reactive Defect Reco BOP1043356 Please repair pothole	rded 01/02/2010 16: CARRIAGEWAY	51:42 by jjgrahamd Pothole	Cat 2.1 - 7d	01/02/2010 16:51:42	Completed	16/02/2010 13:20:00	Stokes Avenue near L/C1
BOP1043357 Please reset loose wh	FOOTWAYS ite block	Slab rocking	Cat 2 - 24h	01/02/2010 16:56:01	Completed	02/02/2010 16:00:00	High Street near L/C58 (o/s Leighton's)
Reactive Defect Reco BOP1043697 Please repair three po	CARRIAGEWAY	43:58 by jjgrahamd Pothole	Cat 2.1 - 7d	26/02/2010 09:43:58	Completed	25/05/2010 16:00:00	Stokes Ave o/s 30, 40, & 48
Reactive Defect Reco BOP1043804 Please repair three po	CARRIAGEWAY	26:11 by jjgrahamd Pothole	Cat 2.1 - 7d	04/03/2010 16:26:11	Completed	25/05/2010 16:00:00	Stokes Avenue o/s 60
Reactive Defect Reco BOP1044476 Please fill potholes.	rded 22/04/2010 10: CARRIAGEWAY	27:40 by jjgrahamd Pothole	Cat 2 - 24h	22/04/2010 10:27:40	Completed	22/04/2010 09:20:00	Stokes Avenue- various locations
Reactive Defect Reco BOP1045179 Please repair several	CARRIAGEWAY	<b>45:28 by jjgrahamd</b> Pothole	Cat 2.1 - 7d	01/06/2010 16:45:28	Completed	08/06/2010 16:00:00	Stokes Ave, see comments.

### of Area\_2\_local\_roads\_(4b\_Dec\_05) on 14 June 2010 by GD (Six Monthly Safety, Safety Inspection)

This section was inspected on 14/06/2010 16:54:00 and no defects were found.

### of Area\_2\_local\_roads\_(4b\_Dec\_05) on 15 December 2010 by NY (Yearly Detailed, Safety Inspection)

This section was inspected on 15/12/2010 12:56:00 and no defects were found.

### of Area\_2\_local\_roads\_(4b\_Dec\_05) on 15 December 2010 by NY (Six Monthly Safety, Safety Inspection)

This section was inspected on 15/12/2010 12:55:00 and no defects were found.

Reactive Defect Recorded 23/02/2011 10:02:28 by jjnigely

BOP1148641 CARRIAGEWAY Pothole Cat 1 - 2h 23/02/2011 10:02:28 Completed 22/02/2011 13:30:00

of Area\_2\_local\_roads\_(4b\_Dec\_05) on 06 June 2011 by NE (Six Monthly Safety, Safety Inspection)

13/02/2019 Page 1 of 7

### STOKES AVENUE WIMBORNE ROAD TATNAM ROAD

Defect Reference	Item Type	Item Detail	Defect Category	Defect Date	Current Status	Actual Completion Date	Location Description
AR29125-2	FOOTWAYS	Blacktop : extensive cracking	Cat 2.2 - 28d	06/06/2011 16:35:00	Completed	30/08/2011 16:00:00	Two jobs -o/s 66 & o/s 70 on the f/w.
Two lots of work close	e together - one 3 sqm	, the other 3,5 sqr	n, both marked separa	ately o/s numbers 66 & 70.			
nventory of adhoc_	defects on 22 Janu	ary 2014 by (In	ventory, Inventory	Inspection)			
HT29260-65	C/w Planned less than 15m	Pothole	Cat 2.3 - 3m	21/09/2011 13:14:00	Completed	23/09/2011 16:00:00	STOKES AVENUE, CENTRE C/W, O/S O 60.
POTHOLE & CRACK	ING						
nventory of adhoc_	defects on 22 Janu	ary 2014 by (In	ventory, Inventory	Inspection)			
HT29260-123	C/w Planned less than 15m	Pothole	Cat 2.3 - 3m	29/11/2011 09:49:00	Completed	01/03/2012 16:00:00	STOKES AVE, 5M FROM LAMPCOL1.
DEEP BREAKING O	JT.						
HT29260-124	C/w Planned less than 15m	Pothole	Cat 2.3 - 3m	29/11/2011 09:54:00	Completed	13/01/2012 16:00:00	STOKES AVE, C/W O/S NO 30
ONE POTHOLE							
HT29260-125	C/w Planned less than 15m	Pothole	Cat 2.3 - 3m	29/11/2011 09:57:00	Completed	29/02/2012 16:00:00	STOKES AVE C/W O/S NO 5. (NEW EXTENSION BEING BUILT).
OLD PATCHES PLUS	S POTHOLES.						

13/02/2019

### Six Monthly Safety of Area\_2\_local\_roads\_(4b\_Dec\_05) on 07 December 2011 by NE (Six Monthly Safety, Safety Inspection)

This section was inspected on 07/12/2011 12:43:53 and no defects were found.

# STOKES AVENUE WIMBORNE ROAD TATNAM ROAD

Defect Reference	Item Type	Item Detail	Defect Category	Defect Date	Current Status	Actual Completion Date	Location Description
Yearly Detailed of A	rea_2_local_roads_	(4b_Dec_05) on 07	December 2011	by NE (Yearly Detailed	, Safety Inspect	ion)	
HT29644-4	F/w Planned less than 15m	Blacktop : fretting	Cat 2.3 - 3m	07/12/2011 11:13:00	Completed	10/01/2012 14:00:00	F/W O/S 74 STOKES AVE
LONG THIN DEGRAI	DED AREA.						
HT29644-5	C/w Planned less than 15m	Pothole	Cat 2.3 - 3m	07/12/2011 11:19:00	Completed	13/01/2012 16:00:00	STOKES AVE C/W O/S 30.
PLS CANCEL IF ALR	READY ON LIST.						
HT29644-6	F/w Planned less than 15m	Pothole	Cat 2.3 - 3m	07/12/2011 11:21:00	Completed	10/01/2012 13:30:00	F/W O/S NO 26 STOKES AVE.
AT DROPPED KERB							
HT29644-7	C/w Planned less than 15m	Pothole	Cat 2.3 - 3m	07/12/2011 11:26:00	Completed	13/01/2012 16:00:00	C/W BY LAMPCOL 1, STOKES AVE.
PLS CANCEL IF ON	SCHEDULE.						
HT29644-8	C/w Planned less than 15m	Pothole	Cat 2.3 - 3m	07/12/2011 11:28:00	Completed	13/01/2012 16:00:00	C/W OPP NO 6 STOKES AVE
PLS CANCEL IF ALR	READY ON SCHEDULE	Ξ.					
nventory of adhoc_	defects on 22 Janu	ary 2014 by (Inver	ntory, Inventory I	nspection)			
HT29260-294	C/w Planned less than 15m	Pothole	Cat 2.2 - 28d	02/05/2012 09:25:00	Completed	08/03/2012 16:00:00	STOKES AVE OPP NO8
SURFACE BREAKIN	G						
Six Monthly Safety	of Area_2_local_roa	ds_(4b_Dec_05) o	n 20 June 2012 k	y NE (Six Monthly Safe	ety, Safety Inspe	ection)	
This section was insp	ected on 20/06/2012	08:34:00 and no defe	cts were found.				
Six Monthly Safety	of Area_2_local_roa	ds_(4b_Dec_05) o	n 10 December 2	2012 by NE (Six Monthly	y Safety, Safety	Inspection)	
This section was insp	ected on 10/12/2012	11:45:28 and no defe	cts were found.				
early Detailed of A	rea_2_local_roads_	(4b_Dec_05) on 10	December 2012	by NE (Yearly Detailed	, Safety Inspect	ion)	
HT210621-2	C/w Planned less than 15m	Pothole	Cat 2.1 - 7d	10/12/2012 09:50:00	Completed	11/12/2012 09:00:00	STOKES AVE OS NO 48
WEARING COURSE	ONLY OVER POTHO	LE					
HT210621-3	C/w Planned less than 15m	Pothole	Cat 2.1 - 7d	10/12/2012 10:08:00	Completed	11/12/2012 09:00:00	STOKES AVE OS NO5
CENTRE OF CW							

13/02/2019

### STOKES AVENUE WIMBORNE ROAD TATNAM ROAD

Defect Reference	Item Type	Item Detail	Defect Category	Defect Date	Current Status	Actual Completion Date	Location Description
nventory of adhoc_	_defects on 22 Janu	ary 2014 by (Inver	ntory, Inventory I	nspection)			
HT29260-568	C/w Planned less than 15m	Pothole	Cat 2.2 - 28d	18/02/2013 15:31:00	Completed	19/03/2013 09:00:00	STOKES AVE CW OS & OPP 30
SURFACE OVER ST	ONE						
HT29260-570	C/w Planned less than 15m	Pothole	Cat 2.2 - 28d	18/02/2013 15:36:00	Completed	19/03/2013 09:00:00	STOKES AVE CW OS NO 76
TWO IN SAME BIG I	PATCH PLS						
Six Monthly Safety	of Area_2_local_roa	ds_(4b_Dec_05) o	n 10 June 2013 b	y NE (Six Monthly Safe	ty, Safety Inspec	tion)	
HT211125-4	F/w Planned less than 15m	Blacktop : extensive cracking	Cat 2.2 - 28d	10/06/2013 12:21:00	Completed	15/07/2013 16:00:00	74 STOKES AVENUE
AT DRIVEWAY		or a orang					
Six Monthly Safety	of Area_2_local_roa	ds_(4b_Dec_05) o	n 05 December 2	013 by NE (Six Monthly	/ Safety, Safety II	nspection)	
This section was insp	pected on 05/12/2013	11:13:50 and no defe	cts were found.				
Yearly Detailed of A	rea_2_local_roads_	(4b_Dec_05) on 05	December 2013	by NE (Yearly Detailed	, Safety Inspectio	on)	
HT211606-1	F/w Planned less than 15m	Blacktop : fretting	Cat 2.2 - 28d	05/12/2013 10:15:00	Completed	14/01/2014 09:00:00	4 STOKES AVE
AT DRIVEWAY							
nventory of adhoc_	_defects ( Awaiting	Return ) by (Invent	tory, Inventory Ir	spection)			
HT211758-15 POTHOLE, ONE OF	CARRIAGEWAY SEVERAL PLS STA	Pothole RT HERE & GO ALO	Cat 2.2 - 28d NG MAKING REPA	04/02/2014 15:53:00 AIRS WITH 10MM PLUG.	Completed	29/04/2014 11:00:00	5 STOKES AVENUE & ALONG.
nventory of adhoc	defects ( Awaiting	Return ) by (Invent	tory, Inventory Ir	nspection)			
HT211758-77	CARRIAGEWAY	Pothole	Cat 2.1 - 7d	20/03/2014 09:53:00	Completed	28/03/2014 13:01:00	STOKES AVE BTWN WIMBORNE RD & HAYNES AVENUE
PLEASE PLUG POT	HOLES						

This section was inspected on 05/06/2014 12:46:00 and no defects were found.

Reactive Defect Recorded 14/08/2014 13:42:08 by jjnick

BOP14304185 Vehicle Access None Cat 2.2 - 28d 14/08/2014 13:42:08 Completed 09/09/2014 16:00:00 42 Stokes Avenue

Driveway works commence about mid to late October 2014. Please liaise with Mr Garnett on 01202 674705 or 07809757075 to synchronise footway modifications.

# STOKES AVENUE WIMBORNE ROAD TATNAM ROAD

Defect Reference	Item Type	Item Detail	Defect Category	Defect Date	Current Status	Actual Completion  Date	Location Description
Inventory of adhoc_	_defects ( Awaiting	Return ) by (Inve	ntory, Inventory I	nspection)			
HT211758-210	F/w Planned less than 15m	Pothole	Cat 2.2 - 28d	04/09/2014 09:58:00	Completed	17/09/2014 12:00:00	FW OPP 58 STOKES AVENUE
CRAZING/SMALL H	OLES DEVELOPING. F	PLS CUT & FILL.					
Six Monthly Safety	of Area_2_local_roa	ads_(4b_Dec_05)	on 04 December 2	2014 by NE (Six Monthly	y Safety, Safety I	nspection)	
	pected on 04/12/2014						
Reactive Defect Rec BOP15318274	corded 25/02/2015 09: CARRIAGEWAY		Actionable on site	25/02/2015 09:36:49			40 Stokes Avenue
Small pothole plugge	ed post lagan 668343.	NB Wessex blue ma	arks by water box in	c/w.			
Six Monthly Safety	of Area_2_local_roa	ads_(4b_Dec_05)	on 02 June 2015 I	by NE (Six Monthly Safe	ety, Safety Inspec	ction)	
HT212948-1	C/w Planned less than 15m	Pothole	Cat 2.2 - 28d	02/06/2015 10:49:00	Completed	30/06/2015 16:00:00	STOKES AVE, ALL!
pls fill holes							
Six Monthly Safety	of Central_Area_loc	cal_roads_(4b_De	c_05) on 09 Dece	mber 2015 by RB (Six N	Ionthly Safety, S	afety Inspection)	
This section was insp	pected on 09/12/2015	11:30:00 and no de	fects were found.	,	•		
Inventory of adhoc_	_defects on 17 June	2016 by SH (Inve	entory, Inventory I	Inspection)			
HT213338-73	CARRIAGEWAY	Patch - loss of material	Cat 2.1 - 7d	25/02/2016 13:37:00	Completed	29/04/2016 16:00:00	STOKES AVENUE
PATCH AND REPAIR	R ALL MARKED AREAS	3					
Inventory of adhoc	defects on 17 June	2016 by SH (Inve	entory, Inventory I	Inspection)			
HT213338-116	CARRIAGEWAY	Pothole	Actionable on site	29/03/2016 10:39:00	Completed	29/03/2016 10:40:58	70 STOKES AVE
TEMARY FILLED PO	OT HOLE WORKSORD	ER ALREADY CRE	ATED TO PATCH N	REAIR			
HT213338-117	FOOTWAYS	Block profile	Cat 2 - 24h	29/03/2016 14:46:00	Completed	30/03/2016 16:00:00	OUT SIDE MUNCHIES NEW ORCHARD NR HIGH STREET
RE LAY PAVING SLA	AB OUT SIDE MUNCH	IES TAKE AWAY SH	OP NEW ORCHAR	D NR HIGH STREET			

### STOKES AVENUE WIMBORNE ROAD TATNAM ROAD

Defect Reference	Item Type	Item Detail	Defect Category	Defect Date	Current Status	Actual Completion Date	Location Description
Six Monthly Safety of	f Central_Area_loc	al_roads_(4b_Dec	c_05) on 08 June	2016 by RB (Six Month	ly Safety, Safety I	nspection)	
HT213809-2	Cleansing Grading	Grade B	Non Actionable - comment only	08/06/2016 11:51:00	Completed	08/06/2016 11:51:35	
В			·				
HT213809-3	Cleansing Grading	Grade B	Non Actionable - comment only	08/06/2016 11:52:00	Completed	08/06/2016 11:52:29	
В			,				
Six Monthly Safety of	f Central_Area_loc	cal_roads_(4b_Dec	c_05) on 08 Dece	mber 2016 by RB (Six N	lonthly Safety, Sa	fety Inspection)	
HT214212-1 FILL ALL POTHOLES	CARRIAGEWAY	Pothole	Cat 2.1 - 7d	08/12/2016 14:45:00	Completed	14/12/2016 16:00:00	STOKES AVENUE AND HAYNES AV
Six Monthly Safety of	f Central_Area_loc	cal_roads_(4b_Dec	c_05) on 08 June	2017 by RB (Six Month	ly Safety, Safety I	nspection)	
This section was inspe	cted on 08/06/2017	14:57:00 and no defe	ects were found.				
Inventory of adhoc_d	lefects on 20 April	2017 by RB (Inve	ntory, Inventory I	nspection)			
HT213901-473	CARRIAGEWAY	Pothole	Cat 2.1 - 7d	11/08/2017 11:27:00	Job Closed superseeded by following inspection	01/01/9999 00:00:00	POTHOLES IN STOKES AVE ANDHAYES AVE ROAD N FOOTPATH PAH OUT SIDE OF 3 33 66 OPP 54
FILL MULTIPUL POTO	LE ON ROD AND O	OT ATHS			7		
HT213901-474	KERB	Kerb/channel block alignment	Cat 2.1 - 7d	11/08/2017 11:29:00	Completed	18/08/2017 13:00:00	3 STOKESAVE
RESET SUNKEN CUR	RB	J					
nventory of adhoc_d	lefects on 20 April	2017 by RB (Inve	ntory, Inventory I	nspection)			
HT213901-579 FILL POTHOLES X3	CARRIAGEWAY	Pothole	Cat 2 - 24h	23/10/2017 12:05:00	Completed	24/10/2017 16:00:00	O/S 2 /26/78 STOKES AVENUE
Inventory of adhoc_d	lefects on 04 Octo	ber 2018 by SH (Ir	ventory, Invento	ry Inspection)			
CA14940-15	FOOTWAYS	Blacktop : extensive cracking	Cat 2.1 - 7d	22/11/2017 11:12:00	Completed	05/01/2018 16:00:00	STOKES AV 0/31/33/72
PATCH AND REPAIR 7	7 MTRS OF SEPERA	•					
Oir Mandala Orfota and				b 0047 b - DD (05- 1			

Six Monthly Safety of Central\_Area\_local\_roads\_(4b\_Dec\_05) on 14 December 2017 by RB (Six Monthly Safety, Safety Inspection)

This section was inspected on 14/12/2017 14:29:00 and no defects were found.



# STOKES AVENUE WIMBORNE ROAD TATNAM ROAD

Defect Reference	Item Type	Item Detail	Defect Category	Defect Date	Current Status	Actual Completion Date	Location Description			
Inventory of adhoc	ventory of adhoc_defects on 04 October 2018 by SH (Inventory, Inventory Inspection)									
CA14940-80	CARRIAGEWAY	Pothole	Actionable on site	08/01/2018 10:59:00	Completed	08/01/2018 10:59:28	O/S 40 STOCKES AV			
POHOLE FILLED ON	NSITE X2									
Inventory of adhoc	_defects on 04 Octo	ber 2018 by SH (Ir	ventory, Inventor	y Inspection)						
CA14940-161 PLEASE PLUG ALL	CARRIAGEWAY POTHOLES	Pothole	Cat 2.1 - 7d	13/02/2018 13:42:00	Completed	14/02/2018 16:00:00	STOKES AVENUE			
Inventory of adhoc	_defects on 04 Octo	ber 2018 by SH (Ir	ventory, Inventor	y Inspection)						
CA14940-282 FILL POTHOLE	CARRIAGEWAY	Pothole	Cat 2.1 - 7d	04/04/2018 11:59:00	Completed	18/04/2018 16:00:00	OUTSIDE 5 STOKES AVE			
Reactive Defect Rec	corded 01/05/2018 08:	18:14 by russell.ben	nett							
BOP18458623 contact jim buchan 0	Vehicle Access 1202252153	None	Cat 2.2 - 28d	01/05/2018 08:18:14	Completed	11/06/2018 16:00:00	25 stokes avenue			
Six Monthly Safety	Six Monthly Safety of Central_Area_local_roads_(4b_Dec_05) on 15 June 2018 by RB (Six Monthly Safety, Safety Inspection)									
This section was ins	pected on 15/06/2018	14:31:33 and no defe	ects were found.							
Inventory of adhoc	nventory of adhoc_defects on 04 October 2018 by SH (Inventory, Inventory Inspection)									
CA14940-537 fill all pot holes	CARRIAGEWAY	Pothole	Cat 2.1 - 7d	31/07/2018 15:17:00	Completed	01/08/2018 16:00:00	stokes av and haze av			