

# Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/01/2010 and 13/02/2019, and defects raised outside of inspections on the same Section(s) during this period.

Road Uid = Hobbs Road

**D83483/00105**

**HOBBS ROAD TRINIDAD CRESCENT WORRELL DRIVE**

Defect Reference	Item Type	Item Detail	Defect Category	Defect Date	Current Status	Actual Completion Date	Location Description
<b>Reactive Defect Recorded 25/02/2010 15:21:14 by jjjohnw</b>							
BOP1043688	CARRIAGEWAY	Pothole	Cat 2.1 - 7d	25/02/2010 15:21:14	Completed	22/04/2010 16:00:00	Hobbs road o/s 11
c/way potholes x 2, 1.0 x 1.0 x 2. MCD							
<b>of Area_1_local_roads_(4b_Sep_03) on 23 March 2010 by JW (Six Monthly Safety, Safety Inspection)</b>							
<i>This section was inspected on 23/03/2010 12:02:00 and no defects were found.</i>							
<b>Reactive Defect Recorded 23/07/2010 16:45:21 by jjjohnw</b>							
BOP1045968	CARRIAGEWAY	Pothole	Cat 2.1 - 7d	23/07/2010 16:45:21	Completed	30/07/2010 16:00:00	HOBBS ROAD O/S 13
C/WAY POTHOLE 1.0 X 1.0 IN 10 MM.							
<b>of Area_1_local_roads_(4b_Sep_03) on 06 September 2010 by JW (Yearly Detailed, Safety Inspection)</b>							
<i>This section was inspected on 08/09/2010 17:10:00 and no defects were found.</i>							
<b>of Area_1_local_roads_(4b_Sep_03) on 06 September 2010 by JW (Six Monthly Safety, Safety Inspection)</b>							
<i>This section was inspected on 08/09/2010 17:12:00 and no defects were found.</i>							
<b>of Area_1_local_roads_(4b_Sep_03) on 11 March 2011 by JW (Six Monthly Safety, Safety Inspection)</b>							
<i>This section was inspected on 11/03/2011 14:37:00 and no defects were found.</i>							
<b>Reactive Defect Recorded 06/09/2011 15:47:57 by jjjohnw</b>							
BOP1152073	F/w Planned less than 15m	Blacktop : extensive cracking	Cat 2.3 - 3m	06/09/2011 15:47:57	Completed	09/09/2011 12:00:00	HOBBS ROAD O/S 7B
F/WAY FRETTEING 1.4 X 0.8							
<b>Yearly Detailed of Area_1_local_roads_(4b_Sep_03) on 07 September 2011 by JW (Yearly Detailed, Safety Inspection)</b>							
<i>This section was inspected on 09/09/2011 14:36:17 and no defects were found.</i>							
<b>Six Monthly Safety of Area_1_local_roads_(4b_Sep_03) on 09 September 2011 by JW (Six Monthly Safety, Safety Inspection)</b>							
<i>This section was inspected on 09/09/2011 14:36:52 and no defects were found.</i>							
<b>Six Monthly Safety of Area_1_local_roads_(4b_Sep_03) on 13 March 2012 by JW (Six Monthly Safety, Safety Inspection)</b>							
HT19865-1	C/w Planned less than 15m	Pothole	Cat 2.2 - 28d	13/03/2012 13:40:00	Completed	10/04/2012 16:00:00	HOBBS ROAD O/S 5 & 13
C/WAY POTHOLE X 3 , 1.5 X 1.0 IN TOTAL							



D83483/00105

## HOBBS ROAD TRINIDAD CRESCENT WORRELL DRIVE

Defect Reference	Item Type	Item Detail	Defect Category	Defect Date	Current Status	Actual Completion Date	Location Description
<b>Six Monthly Safety of Area_1_local_roads_(4b_Sep_03) on 12 September 2012 by JW (Six Monthly Safety, Safety Inspection)</b>							
<i>This section was inspected on 12/09/2012 13:08:37 and no defects were found.</i>							
<b>Yearly Detailed of Area_1_local_roads_(4b_Sep_03) on 12 September 2012 by JW (Yearly Detailed, Safety Inspection)</b>							
HT110367-4	ROAD MARKING	Wear	Cat 2.2 - 28d	12/09/2012 12:36:00	Completed	05/02/2013 16:00:00	HOBBS ROAD JCT WORRELL DRIVE TO RE-PAINT JUNCTION LINES
HT110367-5	C/w Planned less than 15m	Pothole	Cat 2.2 - 28d	12/09/2012 12:39:00	Completed	25/09/2012 16:00:00	HOBBS ROAD NEAR 13 & O/P 7A C/WAY POTHOLE X 3 AS MARKED 1.0 X 1.0 X 3.
<b>Six Monthly Safety of Area_1_local_roads_(4b_Sep_03) on 11 March 2013 by JW (Six Monthly Safety, Safety Inspection)</b>							
HT110904-1	Carriageway Planned	Pothole	Cat 2.1 - 7d	11/03/2013 15:36:00	Completed	15/03/2013 16:00:00	HOBBS ROAD O/S 6A. C/WAY POTHOLE 1.2 X 1.2.
<b>Reactive Defect Recorded 18/06/2013 16:12:06 by jjjohnw</b>							
BOP13201674	F/w Planned less than 15m	Pothole	Cat 2.1 - 7d	18/06/2013 16:12:06	Completed	21/06/2013 16:00:00	HOBBS ROAD C/WAY POTHOLE
<b>Six Monthly Safety of Area_1_local_roads_(4b_Sep_03) on 06 September 2013 by JW (Six Monthly Safety, Safety Inspection)</b>							
<i>This section was inspected on 12/09/2013 15:49:23 and no defects were found.</i>							
<b>Yearly Detailed of Area_1_local_roads_(4b_Sep_03) on 06 September 2013 by JW (Yearly Detailed, Safety Inspection)</b>							
HT111384-9	Footway Planned	Pothole	Cat 2.2 - 28d	12/09/2013 15:27:00	Completed	24/09/2013 09:00:00	HOBBS ROAD O/P 3. F/WAY POTHOLE 1.0 X 1.0.
HT111384-8	C/w Planned less than 15m	Pothole	Cat 2.2 - 28d	12/09/2013 15:26:00	Completed	20/09/2013 16:00:00	HOBBS ROAD O/S 15. C/WAY POTHOLE 1.0 X 1.0.
<b>Six Monthly Safety of Area_1_local_roads_(4b_Sep_03) on 14 March 2014 by JW (Six Monthly Safety, Safety Inspection)</b>							
<i>This section was inspected on 14/03/2014 11:57:17 and no defects were found.</i>							
<b>Six Monthly Safety of Area_1_local_roads_(4b_Sep_03) on 03 September 2014 by JW (Six Monthly Safety, Safety Inspection)</b>							
<i>This section was inspected on 03/09/2014 12:56:57 and no defects were found.</i>							
<b>Inventory of adhoc_defects on 27 February 2015 by JW (Inventory, Inventory Inspection)</b>							
SS112469-34	CARRIAGEWAY	Pothole	Actionable on site	20/01/2015 11:01:00	Completed	20/01/2015 15:14:06	HOBBS ROAD O/S 6 & 5. PLUGGED 2 C/WAY POTHOLE WITH VIAFIX.



D83483/00105

## HOBBS ROAD TRINIDAD CRESCENT WORRELL DRIVE

Defect Reference	Item Type	Item Detail	Defect Category	Defect Date	Current Status	Actual Completion Date	Location Description
<b>Six Monthly Safety of Area_1_local_roads_(4b_Sep_03) on 10 March 2015 by JW (Six Monthly Safety, Safety Inspection)</b>							
SS112777-3	Carriageway Planned	Pothole	Cat 2.1 - 7d	10/03/2015 09:44:00	Completed	12/03/2015 10:30:00	HOBBS ROAD O/S 12 & 3
C/WAY POTHOLAS X 3 AS MARKED. 2.0 X 1.0.							
SS112777-5	CARRIAGEWAY	Pothole	Cat 2 - 24h	10/03/2015 09:54:00	Completed	11/03/2015 09:00:00	HOBBS ROAD
TO PLUG ALL C/WAY POTHOLAS							
<b>Six Monthly Safety of South_Area_local_roads_(4b_Sep_03) on 04 September 2015 by JW (Six Monthly Safety, Safety Inspection)</b>							
SS113170-2	C/w Planned less than 15m	Pothole	Cat 2.2 - 28d	04/09/2015 13:55:00	Completed	17/09/2015 16:00:00	HOBBS ROAD O/S 15
C/WAY POTHOLE 1.2 X 1.0							
<b>Six Monthly Safety of South_Area_local_roads_(4b_Sep_03) on 15 March 2016 by JW (Six Monthly Safety, Safety Inspection)</b>							
This section was inspected on 15/03/2016 15:07:50 and no defects were found.							
<b>Six Monthly Safety of South_Area_local_roads_(4b_Sep_03) on 09 September 2016 by JW (Six Monthly Safety, Safety Inspection)</b>							
SS114037-1	CARRIAGEWAY	Refer to engineer	Non Actionable - comment only	09/09/2016 11:25:00	Completed	09/09/2016 11:25:53	HOBBS ROAD
C/WAY NEEDS RE-SURFACING.							
<b>Six Monthly Safety of South_Area_local_roads_(4b_Sep_03) on 06 March 2017 by JW (Six Monthly Safety, Safety Inspection)</b>							
SS114442-6	CARRIAGEWAY	Pothole	Actionable on site	06/03/2017 11:41:00	Completed	06/03/2017 11:41:13	HOBBS ROAD O/S 5 & 13
C/WAY POTHOLAS X 2 PLUGGED.							
<b>Six Monthly Safety of South_Area_local_roads_(4b_Sep_03) on 21 September 2017 by RP (Six Monthly Safety, Safety Inspection)</b>							
This section was inspected on 21/09/2017 11:30:27 and no defects were found.							
<b>Inventory of South_Area_adhoc_defects on 21 March 2018 by RP (Inventory, Inventory Inspection)</b>							
SS114852-82	CARRIAGEWAY	Pothole	Cat 2.1 - 7d	03/01/2018 10:26:00	Completed	04/01/2018 16:00:00	OUTSIDE 11 HOBBS ROAD
LARGE POTHOLE TO REPAIR							
<b>Inventory of adhoc_defects on 04 October 2018 by SH (Inventory, Inventory Inspection)</b>							
CA14940-205	CARRIAGEWAY	Pothole	Actionable on site	07/03/2018 14:19:00	Completed	07/03/2018 14:19:41	HOBBS ROAD
4X POTHOLE NEEDS PLUGGING							



**D83483/00105****HOBBS ROAD TRINIDAD CRESCENT WORRELL DRIVE**

Defect Reference	Item Type	Item Detail	Defect Category	Defect Date	Current Status	Actual Completion Date	Location Description
<b>Reactive Defect Recorded 20/03/2018 09:36:06 by jjbarry</b>							
BOP18448970	Vehicle Access	None	Cat 2.2 - 28d	20/03/2018 09:36:06	Completed	23/05/2018 16:00:00	9A Hobbs Road
instral drop crossing DC 17368BS Mr Gierkowski 07598 248821							
<b>Six Monthly Safety of South_Area_local_roads_(4b_Sep_03) on 29 March 2018 by RP (Six Monthly Safety, Safety Inspection)</b>							
<i>This section was inspected on 29/03/2018 13:37:00 and no defects were found.</i>							
<b>Inventory of South_Area_adhoc_defects on 25 July 2018 by SS (Inventory, Inventory Inspection)</b>							
SS115405-81	CARRIAGEWAY	Other	Cat 2.1 - 7d	02/07/2018 15:04:00	Completed	03/07/2018 16:00:00	HOBBS ROAD FROM JCT WORRELL TO TOP OF ROAD
PLEASE PLUG ALL POTHOLE.							
<b>Reactive Defect Recorded 18/09/2018 08:04:06 by eescotts</b>							
BOP18504283	Vehicle Access	None	Cat 2.2 - 28d	18/09/2018 08:04:06	Completed	20/09/2018 16:00:00	DKC 6a Hobbs Road
Contact Amy Alderman 07817554926							
<b>Six Monthly Safety of South_Area_local_roads_(4b_Sep_03) on 25 September 2018 by SS (Six Monthly Safety, Safety Inspection)</b>							
SS115684-21	Cleansing Grading	Grade B	Non Actionable - comment only	25/09/2018 11:08:00	Completed	25/09/2018 11:08:37	