

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/01/2010 and 13/02/2019, and defects raised outside of inspections on the same Section(s) during this period.

Road Uid = B3061

Section Code = B3061/00805

B3061/00805

SEA VIEW ROAD RINGWOOD ROAD TO VIEWPOINT ROUNDABOUT

Defect Reference	Item Type	Item Detail	Defect Category	Defect Date	Current Status	Actual Completion Date	Location Description
of Area_1_secondary_dis_(3b_03) on 25 January 2010 by JW (Monthly Safety, Safety Inspection)							
<i>This section was inspected on 25/01/2010 10:14:00 and no defects were found.</i>							
of Area_1_secondary_dis_(3b_03) on 04 February 2010 by JW (Monthly Safety, Safety Inspection)							
<i>This section was inspected on 04/02/2010 11:53:00 and no defects were found.</i>							
of Area_1_secondary_dis_(3b_03) on 10 March 2010 by JW (Monthly Safety, Safety Inspection)							
AR17856-1	GULLY	Blockage	Cat 2.1 - 7d	12/03/2010 10:50:00	Completed	04/06/2010 07:30:00	Seaview road between grove road & 58
To clear the ducting channel on the footway o/s the shop fronts							
of Area_1_secondary_dis_(3b_03) on 10 March 2010 by JW (Yearly Detailed, Safety Inspection)							
AR17857-5	GULLY	Blockage	Cat 2.1 - 7d	12/03/2010 11:05:00	Completed	04/06/2010 06:30:00	Seaview road o/s 6 & 2 on f/way
To clear the ducting channel on the f/way o/s 6 & 2							
AR17857-6	FOOTWAYS	Blacktop : potholes>25mm	Cat 2.1 - 7d	12/03/2010 11:08:00	Completed	27/04/2010 12:00:00	Seaview road o/s the Sea view public house
to repair pothole as marked 1.0 x 1.0 .							
AR17857-8	ROAD MARKING	Wear	Cat 2.2 - 28d	12/03/2010 11:16:00	Completed	15/07/2011 16:00:00	Sea view road jct Ringwood road
TO RE-PAINT ALL JUNCTION LINES YELLOWS & ALL OTHER MARKINGS WHERE NECESSARY							
Reactive Defect Recorded 25/03/2010 15:35:26 by jjjohnw							
BOP1044056	SIGN	Other	Cat 1 - 2h	25/03/2010 15:35:26	Completed	25/03/2010 12:20:00	Sea View road between ashley rd & ringwood rd & ashley rd jct Kipling rd
To put out chapter 8 signs & fill in pothole in ashley road							
BOP1044057	SIGN	Other	Cat 1 - 2h	25/03/2010 15:39:30	Completed	24/03/2010 15:00:00	Seaview road between ashley road & ringwood rd
To put out no waiting cones , cones & arrow boards in centre of road							
Reactive Defect Recorded 26/03/2010 15:48:18 by jjjohnw							
BOP1044070	CARRIAGEWAY	Trench RI - difference in level	Cat 2.1 - 7d	26/03/2010 15:48:18	Completed	06/04/2010 12:00:00	Sea view road o/s 33
C/WAY DEPRESSION AS MARKED .To do an investigative dig on the depression that has appeared in the centre of the road as marked. 5 metres x 1.3 metres x 4 paw							



B3061/00805

SEA VIEW ROAD RINGWOOD ROAD TO VIEWPOINT ROUNDABOUT

Defect Reference	Item Type	Item Detail	Defect Category	Defect Date	Current Status	Actual Completion Date	Location Description
of Area_1_secondary_dis_(3b_03) on 20 April 2010 by JW (Monthly Safety, Safety Inspection)							
<i>This section was inspected on 20/04/2010 16:38:00 and no defects were found.</i>							
of Area_1_secondary_dis_(3b_03) on 25 May 2010 by JW (Monthly Safety, Safety Inspection)							
<i>This section was inspected on 25/05/2010 16:01:00 and no defects were found.</i>							
of Area_1_secondary_dis_(3b_03) on 15 June 2010 by JW (Monthly Safety, Safety Inspection)							
AR18107-1	FOOTWAYS	Blacktop : potholes>25mm	Cat 2.1 - 7d	15/06/2010 16:13:00	Completed	19/07/2010 16:00:00	SEA VIEW RD JCT RINGWOOD RD ON CENTRAL RESERVATION & OLD POST STUMP O/S 74
F/WAY POTHOLE X 2 , 1.2 X 1.2							
of Area_1_secondary_dis_(3b_03) on 15 June 2010 by JW (Monthly Safety, Safety Inspection)							
AR18107-4	CARRIAGEWAY	Patch - difference in level	Cat 2.2 - 28d	24/06/2010 13:47:00			SEA VIEW ROAD O/S 29
C/WAY DEPRESSION 5 X 1 X 4 PAW							
of Area_1_secondary_dis_(3b_03) on 23 July 2010 by JW (Monthly Safety, Safety Inspection)							
AR18219-1	CARRIAGEWAY	Pothole	Cat 2.1 - 7d	23/07/2010 15:52:00	Completed	08/09/2010 16:00:00	SEA VIEW ROAD O/P 72
C/WAY POTHOLE 1.8 X 1.0 X 4 PAW							
AR18219-2	CARRIAGEWAY	Pothole	Cat 2.1 - 7d	23/07/2010 15:54:00	Completed	08/09/2010 16:00:00	SEA VIEW ROAD JCT RINGWOOD ROAD ON TRAFFIC LIGHTS
C/WAY POTHOLE 6.2 X 0.7 X 4 PAW							
of Area_1_secondary_dis_(3b_03) on 24 August 2010 by JW (Monthly Safety, Safety Inspection)							
<i>This section was inspected on 24/08/2010 14:00:00 and no defects were found.</i>							
Reactive Defect Recorded 25/08/2010 11:46:53 by jjjohnw							
BOP1046353	BOLLARD	Missing	Cat 2.1 - 7d	25/08/2010 11:46:53			Grove Road junction Sea View road op/s Premier convenience store.
To install 3 New style Bendy Bollards on the markings BB .Stats required. ONE OF THE BOLLARDS TO CHARGE ON JOB ORDER JCO847 FROM ST JOHNS							
BOP1046354	BOLLARD	Missing	Cat 2.2 - 28d	25/08/2010 12:11:53	Completed	07/09/2010 10:00:00	Sea Road View jct Grove road o/s Premier Convenience store.
To install 3 new style Bendy bollards as marked with BB . Stats required							
of Area_1_secondary_dis_(3b_03) on 27 September 2010 by JW (Monthly Safety, Safety Inspection)							
<i>This section was inspected on 27/09/2010 16:16:00 and no defects were found.</i>							
of Area_1_secondary_dis_(3b_03) on 19 October 2010 by JW (Monthly Safety, Safety Inspection)							
<i>This section was inspected on 28/10/2010 15:21:00 and no defects were found.</i>							

B3061/00805

SEA VIEW ROAD RINGWOOD ROAD TO VIEWPOINT ROUNDABOU

Defect Reference	Item Type	Item Detail	Defect Category	Defect Date	Current Status	Actual Completion Date	Location Description
of Area_1_secondary_dis_(3b_03) on 16 November 2010 by JW (Monthly Safety, Safety Inspection)							
AR18530-5	SIGN	Remove TO REMOVE POST ON FOOTWAY AS MARKED.	Cat 2.2 - 28d	26/11/2010 12:24:00	Completed	17/03/2011 16:00:00	SEA VIEW ROAD O/S 89
AR18530-6	FOOTWAYS	Blacktop : potholes>25mm FOOTWAY POTHOLE 1.0 X 1.0	Cat 2.1 - 7d	26/11/2010 12:26:00	Completed	01/01/9999 00:00:00	SEA VIEW ROAD O/S 68 SEA VIEW NEWS.
of Area_1_secondary_dis_(3b_03) on 22 December 2010 by JW (Monthly Safety, Safety Inspection)							
<i>This section was inspected on 23/12/2010 14:20:00 and no defects were found.</i>							
of Area_1_secondary_dis_(3b_03) on 21 January 2011 by JW (Monthly Safety, Safety Inspection)							
AR18701-10	CARRIAGEWAY	Pothole C/WAY POTHOLE 5.0 X 0.6 X 4 PAW	Cat 2.1 - 7d	27/01/2011 15:58:00	Completed	03/02/2011 12:00:00	SEA VIEW RD JCT RINGWOOD ROAD ON THE TRAFFIC LIGHT JUNCTION .
of Area_1_secondary_dis_(3b_03) on 18 February 2011 by JW (Monthly Safety, Safety Inspection)							
AR18773-4	GULLY	Blockage BLOCKED PAVEMENT GULLY TO CLEAR & JET LATERAL	Cat 2.1 - 7d	22/02/2011 15:32:00	Completed	25/02/2011 11:00:00	SEA VIEW ROAD O/S 57A
of Area_1_secondary_dis_(3b_03) on 03 March 2011 by JW (Monthly Safety, Safety Inspection)							
<i>This section was inspected on 08/03/2011 17:04:00 and no defects were found.</i>							
of Area_1_secondary_dis_(3b_03) on 03 March 2011 by JW (Yearly Detailed, Safety Inspection)							
AR18841-10	CARRIAGEWAY	Patch - loss of material C/WAY DEPRESSION AS MARKED .1.6 X 1.0 X 4 PAW , NO WAITING CONES REQUIRED.	Cat 2.1 - 7d	08/03/2011 16:52:00	Completed	15/03/2011 16:00:00	SEA-VIEW ROAD O/S 35
AR18841-11	Carriageway Planned	Blacktop : fretting C/WAY DEPRESSION WHERE TRAFFIC HAS MADE A RUT X 2 DEFECTS . 7.0 X 1.3 , 7.6 X 1.8 X 4 PAW & REINSTATE TRAFFIC LIGHT SENSORS WHEN COMPLETE	Cat 2.3 - 3m	08/03/2011 16:58:00	Completed	01/01/9999 00:00:00	SEAVIEW ROAD O/P 72 NR TRAFFIC LIGHTS T/MANAGEMENT REQUIRED
AR18841-12	CARRIAGEWAY	Pothole C/WAY POTHOLE 1.0 X 1.0 X 4 PAW	Cat 2.1 - 7d	08/03/2011 17:00:00	Completed	15/03/2011 16:00:00	SEA-VIEW ROAD JCT GROVE ROAD
AR18841-13	FOOTWAYS	Blacktop : potholes>25mm F/WAY POTHOLE 1.2 X 1.2	Cat 2.1 - 7d	08/03/2011 17:02:00	Completed	17/03/2011 16:00:00	SEA VIEW ROAD O/S SEA VIEW ROAD NEWS 68
of Area_1_secondary_dis_(3b_03) on 27 April 2011 by JW (Monthly Safety, Safety Inspection)							
<i>This section was inspected on 27/04/2011 17:32:00 and no defects were found.</i>							

B3061/00805**SEA VIEW ROAD RINGWOOD ROAD TO VIEWPOINT ROUNDABOU**

Defect Reference	Item Type	Item Detail	Defect Category	Defect Date	Current Status	Actual Completion Date	Location Description
of Area_1_secondary_dis_(3b_03) on 24 May 2011 by JW (Monthly Safety, Safety Inspection)							
<i>This section was inspected on 27/05/2011 15:08:00 and no defects were found.</i>							
of Area_1_secondary_dis_(3b_03) on 14 June 2011 by JW (Monthly Safety, Safety Inspection)							
AR19110-1	FOOTWAYS	Other	Cat 2.2 - 28d	14/06/2011 15:12:00	Completed	24/08/2011 16:00:00	SEA VIEW ROAD ON THE TRAFFIC ISLAND O/P 74 AROUND L/C
F/WAY POTHOLE 1.5 X 0.8							
Monthly Safety of Area_1_secondary_dis_(3b_03) on 19 July 2011 by JW (Monthly Safety, Safety Inspection)							
<i>This section was inspected on 22/07/2011 15:51:30 and no defects were found.</i>							
Monthly Safety of Area_1_secondary_dis_(3b_03) on 25 August 2011 by JW (Monthly Safety, Safety Inspection)							
<i>This section was inspected on 25/08/2011 13:38:00 and no defects were found.</i>							
Monthly Safety of Area_1_secondary_dis_(3b_03) on 28 September 2011 by JW (Monthly Safety, Safety Inspection)							
<i>This section was inspected on 28/09/2011 16:01:00 and no defects were found.</i>							
Monthly Safety of Area_1_secondary_dis_(3b_03) on 24 October 2011 by JW (Monthly Safety, Safety Inspection)							
<i>This section was inspected on 25/10/2011 13:49:00 and no defects were found.</i>							
Monthly Safety of Area_1_secondary_dis_(3b_03) on 11 November 2011 by JW (Monthly Safety, Safety Inspection)							
<i>This section was inspected on 24/11/2011 13:51:00 and no defects were found.</i>							
Monthly Safety of Area_1_secondary_dis_(3b_03) on 15 December 2011 by JW (Monthly Safety, Safety Inspection)							
<i>This section was inspected on 15/12/2011 14:44:28 and no defects were found.</i>							
Monthly Safety of Area_1_secondary_dis_(3b_03) on 18 January 2012 by JW (Monthly Safety, Safety Inspection)							
<i>This section was inspected on 18/01/2012 13:50:00 and no defects were found.</i>							
Monthly Safety of Area_1_secondary_dis_(3b_03) on 21 February 2012 by JW (Monthly Safety, Safety Inspection)							
HT19814-3	GULLY	Blockage	Cat 2.1 - 7d	27/02/2012 12:18:00	Completed	29/02/2012 14:00:00	SEA VIEW ROAD O/S 3, 5, 7, 15 X 2, 39 & 57A
TO CLEAR 7 BLOCKED PAVEMENT GULLIES							
HT19814-4	GULLY	Blockage	Cat 2.1 - 7d	27/02/2012 12:19:00	Completed	29/02/2012 15:00:00	SEA VIEW ROAD O/P 105
BLOCKED PAVEMENT GULLIES X 3 TO CLEAR .							
Monthly Safety of Area_1_secondary_dis_(3b_03) on 19 March 2012 by JW (Monthly Safety, Safety Inspection)							
<i>This section was inspected on 19/03/2012 14:10:00 and no defects were found.</i>							
Yearly Detailed of Area_1_secondary_dis_(3b_03) on 19 March 2012 by JW (Yearly Detailed, Safety Inspection)							
<i>This section was inspected on 19/03/2012 14:09:00 and no defects were found.</i>							

B3061/00805**SEA VIEW ROAD RINGWOOD ROAD TO VIEWPOINT ROUNDABOU**

Defect Reference	Item Type	Item Detail	Defect Category	Defect Date	Current Status	Actual Completion Date	Location Description
Monthly Safety of Area_1_secondary_dis_(3b_03) on 24 April 2012 by JW (Monthly Safety, Safety Inspection)							
<i>This section was inspected on 24/04/2012 15:00:00 and no defects were found.</i>							
Monthly Safety of Area_1_secondary_dis_(3b_03) on 25 May 2012 by JW (Monthly Safety, Safety Inspection)							
HT110011-1	Footway Planned	Pothole	Cat 2.2 - 28d	25/05/2012 14:16:00	Completed	18/06/2012 16:00:00	SEAVIEW ROAD O/S SEA VIEW PUB
F/WAY POTHOLE 1.0 X 1.0							
Reactive Defect Recorded 31/05/2012 13:50:14 by jjjohnw							
BOP1285145	F/w Planned less than 15m	Other	Cat 2.1 - 7d	31/05/2012 13:50:14	Completed	06/06/2012 14:30:00	RINGWOOD ROAD JCT SEA VIEW ROAD O/S 161
TO MAKE SAFE VOID IN F/WAY.							
BOP1285146	F/w Planned less than 15m	Other	Cat 2.1 - 7d	31/05/2012 13:53:29	Completed	31/05/2012 16:00:00	RINGWOOD ROAD JCT SEA VIEW ROAD O/S 161.
TO EXCAVATE VOID IN F/WAY , STONE UP & RESURFACE , 2.0 X 2.0							
Monthly Safety of Area_1_secondary_dis_(3b_03) on 27 June 2012 by JW (Monthly Safety, Safety Inspection)							
<i>This section was inspected on 27/06/2012 16:19:00 and no defects were found.</i>							
Monthly Safety of Area_1_secondary_dis_(3b_03) on 26 July 2012 by JW (Monthly Safety, Safety Inspection)							
<i>This section was inspected on 26/07/2012 11:18:54 and no defects were found.</i>							
Reactive Defect Recorded 03/08/2012 11:51:35 by jjjohnw							
BOP12102671	FOOTWAYS	Failed patch : loss of material	Cat 1 - 2h	03/08/2012 11:51:35	Completed	03/08/2012 13:20:00	SEAVIEW ROAD JCT RINGWOOD ROAD
TO MAKE SAFE VOID IN F/WAY							
BOP12102673	FOOTWAYS	Failed patch : difference in level	Cat 2.1 - 7d	03/08/2012 12:00:46	Completed	09/08/2012 14:20:00	SEA VIEW ROAD JCT RINGWOOD ROAD
TO INVESTIGATE VOID IN F/WAY 1.5 X 1.5							
Monthly Safety of Area_1_secondary_dis_(3b_03) on 21 August 2012 by TS (Monthly Safety, Safety Inspection)							
<i>This section was inspected on 21/08/2012 09:05:00 and no defects were found.</i>							
Monthly Safety of Area_1_secondary_dis_(3b_03) on 25 September 2012 by JW (Monthly Safety, Safety Inspection)							
<i>This section was inspected on 25/09/2012 11:30:00 and no defects were found.</i>							
Monthly Safety of Area_1_secondary_dis_(3b_03) on 25 October 2012 by JW (Monthly Safety, Safety Inspection)							
<i>This section was inspected on 25/10/2012 10:50:00 and no defects were found.</i>							
Monthly Safety of Area_1_secondary_dis_(3b_03) on 13 December 2012 by JW (Monthly Safety, Safety Inspection)							
<i>This section was inspected on 13/12/2012 13:52:00 and no defects were found.</i>							

B3061/00805

SEA VIEW ROAD RINGWOOD ROAD TO VIEWPOINT ROUNDABOUT

Defect Reference	Item Type	Item Detail	Defect Category	Defect Date	Current Status	Actual Completion Date	Location Description
Monthly Safety of Area_1_secondary_dis_(3b_03) on 16 January 2013 by JW (Monthly Safety, Safety Inspection)							
<i>This section was inspected on 24/01/2013 13:40:54 and no defects were found.</i>							
Reactive Defect Recorded 05/02/2013 08:58:07 by jjjohnw							
BOP13143300	SIGN	Accident damage	Cat 1 - 2h	05/02/2013 08:58:07	Completed	28/01/2013 21:00:00	SEA VIEW ROAD JCT CONSTITUTION HILL ROAD
TO RE-SET ALL SIGNS ON ROUNDABOUT.							
Monthly Safety of Area_1_secondary_dis_(3b_03) on 07 February 2013 by JW (Monthly Safety, Safety Inspection)							
HT110826-1	GULLY	Blockage	Cat 2.1 - 7d	07/02/2013 15:30:00	Completed	08/02/2013 10:30:00	SEA VIEW ROAD O/S 57A
TO CLEAR F/WAY GULLY & LATERAL.							
HT110826-2	Footway Planned	Pothole	Cat 2.2 - 28d	07/02/2013 15:31:00	Completed	02/03/2013 13:00:00	SEA VIEW ROAD O/S 57A
F/WAY POTHOLE 1.0 X 1.0							
Monthly Safety of Area_1_secondary_dis_(3b_03) on 07 February 2013 by JW (Monthly Safety, Safety Inspection)							
HT110826-3	C/w Planned less than 15m	Pothole	Cat 2.2 - 28d	18/02/2013 13:38:00	Completed	18/03/2013 15:00:00	SEAVIEW ROAD O/S 55 & 57.
TO REPLACE WORN WEARING COURSE AS MARKED . 10.0 X 1.0 T/M REQUIRED.							
Monthly Safety of Area_1_secondary_dis_(3b_03) on 05 March 2013 by JW (Monthly Safety, Safety Inspection)							
<i>This section was inspected on 05/03/2013 13:20:30 and no defects were found.</i>							
Yearly Detailed of Area_1_secondary_dis_(3b_03) on 05 March 2013 by JW (Yearly Detailed, Safety Inspection)							
HT110912-1	Footway Planned	Pothole	Cat 2.2 - 28d	05/03/2013 13:04:00	Completed	03/04/2013 13:30:00	SEA VIEW ROAD O/S 27.
F/WAY POTHOLE 1.0 X 1.0.							
HT110912-2	C/w Planned less than 15m	Pothole	Cat 2.2 - 28d	05/03/2013 13:06:00	Completed	02/04/2013 16:00:00	SEAVIEW ROAD O/P 105.
C/WAY POTHOLE 1.0 X 1.0 X 4 PAW.							
HT110912-3	C/w Planned less than 15m	Pothole	Cat 2.2 - 28d	05/03/2013 13:11:00	Completed	02/04/2013 16:00:00	SEA VIEW ROAD O/S 58.
C/WAY POTHOLE 1.2 X 1.0 X 4 PAW.							
HT110912-4	Footway Planned	Pothole	Cat 2.2 - 28d	05/03/2013 13:13:00	Completed	03/04/2013 14:30:00	SEA VIEW ROAD O/P 45.
F/WAY POTHOLE 1.0 X 1.0.							
HT110912-5	Footway Planned	Pothole	Cat 2.2 - 28d	05/03/2013 13:15:00	Completed	03/04/2013 14:00:00	SEA VIEW ROAD O/P 31.
F/WAY POTHOLE 1.2 X 1.0							
HT110912-6	Footway Planned	Pothole	Cat 2.2 - 28d	05/03/2013 13:18:00	Completed	03/04/2013 13:00:00	SEA VIEW ROAD O/S 10 & 8.
F/WAY POTHOLAS X 3. 3.0 X 1.0 IN TOTAL.							



B3061/00805

SEA VIEW ROAD RINGWOOD ROAD TO VIEWPOINT ROUNDABOU

Defect Reference	Item Type	Item Detail	Defect Category	Defect Date	Current Status	Actual Completion Date	Location Description
Monthly Safety of Area_1_secondary_dis_(3b_03) on 19 April 2013 by JW (Monthly Safety, Safety Inspection)							
<i>This section was inspected on 23/04/2013 13:24:00 and no defects were found.</i>							
Monthly Safety of Area_1_secondary_dis_(3b_03) on 02 May 2013 by JW (Monthly Safety, Safety Inspection)							
HT111082-1	Carriageway Planned	Other	Cat 2.1 - 7d	02/05/2013 13:44:00	Completed	17/05/2013 16:00:00	SEAVIEW ROAD O/S 55.
C/WAY DEPRESSION TO EXCAVATE , STONE UP & RE-SURFACE 1.5 X 1.5 X 4 PAW. STOP/GO.							
Reactive Defect Recorded 09/05/2013 14:45:24 by jjjohnw BOP13182803	CARRIAGEWAY	Patch - loss of material	Cat 1 - 2h	09/05/2013 14:45:24	Completed	03/05/2013 10:00:00	SEA VIEW ROAD O/S 55.
TO PLUG C/WAY DEPRESSION.							
Reactive Defect Recorded 14/05/2013 09:49:06 by jjbarry BOP13184899	Carriageway Planned	Other	Cat 2.3 - 3m	14/05/2013 09:49:06			test
test							
Monthly Safety of Area_1_secondary_dis_(3b_03) on 02 May 2013 by JW (Monthly Safety, Safety Inspection)							
HT111082-2	C/w Planned less than 15m	Pothole	Cat 2.2 - 28d	22/05/2013 11:52:00	Completed	30/07/2013 09:00:00	SEA VIEW ROAD O/S 27 & 35.
C/WAY DEPRESSIONX X 2 & STONE UP. 2.0 X 1.0 X 4 PAW . T/M REQUIRED.							
Reactive Defect Recorded 21/06/2013 14:49:28 by jjjohnw BOP13203157	CHANNEL	Kerb/channel block alignment	Cat 2.1 - 7d	21/06/2013 14:49:28	Completed	25/06/2013 12:30:00	SEA VIEW ROAD NEAR 66A PREMIER SHOP.
TO RE-SET CONCRETE CHANNEL ON FOOTWAY AS MARKED AND LEVEL UP OTHERS.							
Monthly Safety of Area_1_secondary_dis_(3b_03) on 26 June 2013 by JW (Monthly Safety, Safety Inspection)							
<i>This section was inspected on 26/06/2013 10:49:00 and no defects were found.</i>							
Monthly Safety of Area_1_secondary_dis_(3b_03) on 22 July 2013 by JW (Monthly Safety, Safety Inspection)							
<i>This section was inspected on 22/07/2013 14:21:00 and no defects were found.</i>							
Reactive Defect Recorded 02/08/2013 15:49:40 by jjjohnw BOP13212081	GULLY	Blockage	Cat 2.2 - 28d	02/08/2013 15:49:40	Completed	14/08/2013 11:40:00	SEA VIEW ROAD ON FOOTPATH TO RIGHT OF 103 NEAR VISI-RAILS
BLOCKED F/WAY GULLY AND LIFT MANHOLE COVER AND CLEAR							
Monthly Safety of Area_1_secondary_dis_(3b_03) on 15 August 2013 by JW (Monthly Safety, Safety Inspection)							
<i>This section was inspected on 15/08/2013 16:06:00 and no defects were found.</i>							

B3061/00805

SEA VIEW ROAD RINGWOOD ROAD TO VIEWPOINT ROUNDABOU

Defect Reference	Item Type	Item Detail	Defect Category	Defect Date	Current Status	Actual Completion Date	Location Description
Monthly Safety of Area_1_secondary_dis_(3b_03) on 26 September 2013 by JW (Monthly Safety, Safety Inspection)							
HT111408-5	Footway Planned	Pothole	Cat 2.2 - 28d	27/09/2013 10:30:00	Completed	04/10/2013 09:00:00	SEA VIEW ROAD O/S 2.
F/WAY POTHOLE 1.0 X 1.0.							
HT111408-2	Footway Planned	Pothole	Cat 2.2 - 28d	27/09/2013 10:25:00	Completed	04/10/2013 09:00:00	SEA VIEW ROAD O/P 16, O/S 39, 43 & 45.
F/WAY POTHOLE X 4 .4.5 X 1.0 IN TOTAL.							
HT111408-3	C/w Planned less than 15m	Pothole	Cat 2.2 - 28d	27/09/2013 10:26:00	Completed	04/10/2013 16:00:00	SEA VIEW ROAD O/S 87.
C/WAY POTHOLE 1.0 X 1.0 X4 PAW.							
HT111408-4	C/w Planned less than 15m	Pothole	Cat 2.2 - 28d	27/09/2013 10:28:00	Completed	04/10/2013 09:00:00	ASHLEY ROAD O/S 38.
C/WAY POTHOLE 1.2 X 1.0 X 4 PAW.							
Monthly Safety of Area_1_secondary_dis_(3b_03) on 16 October 2013 by JW (Monthly Safety, Safety Inspection)							
HT111502-1	Footway Planned	Slab profile : uneven/trips/gap	Cat 2.1 - 7d	16/10/2013 15:17:00	Completed	24/10/2013 16:00:00	SEA VIEW ROAD TO RIGHT OF 103.
TO REPLACE EDGING KERB AS MARKED TO PREVENT TRIP 1.0 X 1.0 F/WAY.							
Monthly Safety of Area_1_secondary_dis_(3b_03) on 08 November 2013 by JW (Monthly Safety, Safety Inspection)							
HT111579-2	C/w Planned less than 15m	Pothole	Cat 2.2 - 28d	27/11/2013 10:02:00	Completed	23/12/2013 09:00:00	SEAVIEW ROAD O/S 83.
C/WAY POTHOLE X 2. 2.2 X 1.0 X 4 PAW.							
Monthly Safety of Area_1_secondary_dis_(3b_03) on 17 December 2013 by JW (Monthly Safety, Safety Inspection)							
This section was inspected on 17/12/2013 13:20:00 and no defects were found.							
Reactive Defect Recorded 21/01/2014 09:39:11 by jjjohnw							
BOP14289124	GULLY	Blockage	Cat 1 - 2h	21/01/2014 09:39:11	Completed	31/12/2013 14:00:00	SEA VIEW ROAD
BLOCKED GULLIES.							

B3061/00805

SEA VIEW ROAD RINGWOOD ROAD TO VIEWPOINT ROUNDABOU

Defect Reference	Item Type	Item Detail	Defect Category	Defect Date	Current Status	Actual Completion Date	Location Description
Monthly Safety of Area_1_secondary_dis_(3b_03) on 10 January 2014 by JW (Monthly Safety, Safety Inspection)							
HT111730-5	GULLY	Blockage	Cat 2.1 - 7d	22/01/2014 09:48:00	Completed	10/02/2014 16:00:00	SEA VIEW ROAD O/S 57A
TO CLEAR F/WAY GULLY							
HT111730-4	GULLY	Blockage	Cat 2.1 - 7d	22/01/2014 09:44:00	Completed	10/02/2014 15:00:00	SEAVIEW ROAD FROM 1 TO O/S SEAVIEW SHAVERS.
TO CLEAR BLOCKED F/WAY GULLIES & JET LATERALS.							
HT111730-6	Footway Planned	Pothole	Cat 2.2 - 28d	22/01/2014 09:52:00	Completed	10/02/2014 12:01:00	SEA VIEW ROAD O/S 85.
F/WAY DEPRESSION/PUDDLING. 2.0 X 1.0 BY BUS STOP.							
HT111730-7	FOOTWAYS	Other	Cat 2.1 - 7d	22/01/2014 09:58:00	Completed	11/03/2014 08:01:00	SEA VIEW ROAD O/P 72
TO REPAIR KERB ON CETRAL RESERVATION WITH RAPID CEMENT.							
HT111730-8	C/w Planned less than 15m	Pothole	Cat 2.2 - 28d	22/01/2014 10:03:00	Completed	05/03/2014 16:00:00	SEA VIEW ROAD JCT GROVE ROAD.
C/WAY POTHOLE 3.5 X 1.0 X 4 PAW.							
HT111730-9	C/w Planned less than 15m	Pothole	Cat 2.2 - 28d	22/01/2014 10:10:00	Completed	05/03/2014 16:00:00	SEA VIEW ROAD JCT CROFT ROAD.
C/WAY POTHOLAS X 2. 1.5 X 1.0 X 4 PAW.							
HT111730-10	FOOTWAYS	Slab rocking	Cat 2.1 - 7d	22/01/2014 10:15:00	Completed	12/03/2014 08:01:00	SEA VIEW ROAD TO RIGHT OF M&K STORES
TO RE-SET TWO SMALL SQUIRE ROCKING SLABS.							
Reactive Defect Recorded 06/02/2014 15:05:33 by jjjohnw							
BOP14291987	GULLY	Blockage	Cat 1 - 2h	06/02/2014 15:05:33	Completed	07/02/2014 13:00:00	SEA VIEW ROAD O/S 1-11
TO CLEAR ALL F/WAY GULLIES							
Inventory of adhoc_defects (Awaiting Return) by (Inventory, Inventory Inspection)							
HT211758-35	C/w Planned less than 15m	Pothole	Cat 2 - 24h	18/02/2014 11:22:00	Completed	19/02/2014 12:00:00	SEA VIEW RD - ALL, BUT MAINLY UP FROM JCN RINGWOOD RD.
WEARING COURSE REPAIR, PLS. SEVERAL BUT MAIN ONE AT JCN GROVE RD							

B3061/00805

SEA VIEW ROAD RINGWOOD ROAD TO VIEWPOINT ROUNDABOUT

Defect Reference	Item Type	Item Detail	Defect Category	Defect Date	Current Status	Actual Completion Date	Location Description
Monthly Safety of Area_1_secondary_dis_(3b_03) on 13 February 2014 by JW (Monthly Safety, Safety Inspection)							
HT111829-4	GULLY	Rocking under load	Cat 2.1 - 7d	26/02/2014 12:15:00	Completed	12/03/2014 08:01:00	SEA VIEW ROAD O/S 38.
GULLY COVER TO RE SET AS MARKED.							
HT111829-2	FENCES AND BARRIERS	Other	Cat 2.1 - 7d	26/02/2014 12:11:00	Completed	12/05/2014 10:00:00	SEA VIEW ROAD TO RIGHT OF 103 NR COASTLINE CARS.
TO RE-SET TWO LOOSE VISIRAILS IN FOOTPATH BETWEEN SEA VIEW ROAD AND RINGWOOD ROAD.							
HT111829-3	C/w Planned less than 15m	Pothole	Cat 2.1 - 7d	26/02/2014 12:13:00	Completed	15/03/2014 08:01:00	SEA VIEW ROAD O/S COASTLINE CARS.
C/WAY POTHOLE SURFACE COURSE ONLY SQUARE OFF PATCH BEFORE. 4.0 X 1.0							
Yearly Detailed of Area_1_secondary_dis_(3b_03) on 11 March 2014 by JW (Yearly Detailed, Safety Inspection)							
HT111901-5	Road Name Plates	Accident damage	Cat 2.2 - 28d	19/03/2014 11:37:00	Completed	10/04/2014 11:50:00	SEA VIEW ROAD JCT RINGWOOD ROAD O/P 161 UNDER OTHER NEW SIGN.
TO REPLACE FADED STREET NAME PLATE WITH NEW ONE ON GRASS VERGE.							
Monthly Safety of Area_1_secondary_dis_(3b_03) on 11 March 2014 by JW (Monthly Safety, Safety Inspection)							
This section was inspected on 19/03/2014 11:38:00 and no defects were found.							
Monthly Safety of Area_1_secondary_dis_(3b_03) on 28 April 2014 by JW (Monthly Safety, Safety Inspection)							
This section was inspected on 28/04/2014 14:41:00 and no defects were found.							
Reactive Defect Recorded 16/05/2014 10:00:54 by jjbarry							
BOP14298640	Pothole Funding 2014-15	Pothole	3 month	16/05/2014 10:00:54	Completed	16/08/2014 16:00:00	Sea View Road Between Ringwood Road and Ashley Road
8 no Patches to be planed out to depth of 40mm and reinstated							
Monthly Safety of Area_1_secondary_dis_(3b_03) on 21 May 2014 by JW (Monthly Safety, Safety Inspection)							
This section was inspected on 28/05/2014 10:48:00 and no defects were found.							
Monthly Safety of Area_1_secondary_dis_(3b_03) on 20 June 2014 by JW (Monthly Safety, Safety Inspection)							
This section was inspected on 20/06/2014 13:16:00 and no defects were found.							
Monthly Safety of Area_1_secondary_dis_(3b_03) on 24 July 2014 by JW (Monthly Safety, Safety Inspection)							
This section was inspected on 24/07/2014 07:27:00 and no defects were found.							

B3061/00805

SEA VIEW ROAD RINGWOOD ROAD TO VIEWPOINT ROUNDABOU

Defect Reference	Item Type	Item Detail	Defect Category	Defect Date	Current Status	Actual Completion Date	Location Description
Monthly Safety of Area_1_secondary_dis_(3b_03) on 20 August 2014 by JW (Monthly Safety, Safety Inspection)							
HT112265-1	Footway Planned	Pothole	Cat 2.2 - 28d	20/08/2014 09:11:00	Completed	11/11/2014 16:00:00	SEA VIEW ROAD O/S 37.
F/WAY POTHOLE 1.0 X 1.0.							
HT112265-2	Footway Planned	Pothole	Cat 2.2 - 28d	20/08/2014 09:14:00	Completed	27/11/2014 16:00:00	SEA VIEW ROAD O/S SEA VIEW NEWS JCT GROVE ROAD.
F/WAY POTHOLE 1.5 X 1.5.							
Monthly Safety of Area_1_secondary_dis_(3b_03) on 17 September 2014 by JW (Monthly Safety, Safety Inspection)							
This section was inspected on 17/09/2014 13:07:00 and no defects were found.							
Monthly Safety of Area_1_secondary_dis_(3b_03) on 16 October 2014 by TS (Monthly Safety, Safety Inspection)							
This section was inspected on 16/10/2014 11:12:00 and no defects were found.							
Monthly Safety of Area_1_secondary_dis_(3b_03) on 25 November 2014 by JW (Monthly Safety, Safety Inspection)							
HT112460-1	GULLY	Blockage	Cat 2.2 - 28d	27/11/2014 13:13:00	Completed	27/03/2015 11:00:00	SEA VIEW ROAD O/S 57A.
BLOCKED FOOTWAY GULLY.							
Monthly Safety of Area_1_secondary_dis_(3b_03) on 18 December 2014 by JW (Monthly Safety, Safety Inspection)							
This section was inspected on 18/12/2014 11:02:00 and no defects were found.							
Monthly Safety of Area_1_secondary_dis_(3b_03) on 20 January 2015 by JW (Monthly Safety, Safety Inspection)							
This section was inspected on 27/01/2015 11:46:57 and no defects were found.							
Inventory of adhoc_defects on 27 February 2015 by JW (Inventory, Inventory Inspection)							
HT312469-52	GULLY	Blockage	Cat 2.2 - 28d	20/02/2015 12:12:00	Completed	26/03/2015 12:00:00	SEA VIEW ROAD - O/S 57A
1X BLOCKED F/WAY GULLY - PLEASE CLEAR							
Monthly Safety of Area_1_secondary_dis_(3b_03) on 27 February 2015 by JW (Monthly Safety, Safety Inspection)							
This section was inspected on 27/02/2015 10:07:00 and no defects were found.							
Monthly Safety of Area_1_secondary_dis_(3b_03) on 24 March 2015 by JW (Monthly Safety, Safety Inspection)							
This section was inspected on 24/03/2015 10:21:00 and no defects were found.							
Monthly Safety of Area_1_secondary_dis_(3b_03) on 23 April 2015 by JW (Monthly Safety, Safety Inspection)							
This section was inspected on 23/04/2015 11:58:00 and no defects were found.							
Monthly Safety of Area_1_secondary_dis_(3b_03) on 27 May 2015 by JW (Monthly Safety, Safety Inspection)							
This section was inspected on 27/05/2015 11:05:00 and no defects were found.							
Reactive Defect Recorded 08/06/2015 16:08:25 by jjjohnw							
BOP15321099	CARRIAGEWAY	Pothole	Cat 2 - 24h	08/06/2015 16:08:25	Completed	09/06/2015 09:00:00	SEA VIEW ROAD JCT GROVE ROAD
TO PLUG ALL C/WAY POTHOLE.							



SEA VIEW ROAD RINGWOOD ROAD TO VIEWPOINT ROUNDABOUT

Defect Reference	Item Type	Item Detail	Defect Category	Defect Date	Current Status	Actual Completion Date	Location Description
Monthly Safety of Area_1_secondary_dis_(3b_03) on 26 June 2015 by JW (Monthly Safety, Safety Inspection)							
SS112965-1	Footway Planned	Pothole	Cat 2.2 - 28d	26/06/2015 09:16:00	Job closed down no work carried out	01/01/9999 00:00:00	SEA VIEW ROAD O/S 37
F/WAY POTHOLE X 2. 2.0 X 1.0 IN TOTAL.							
SS112965-2	C/w Planned less than 15m	Pothole	Cat 2.2 - 28d	26/06/2015 09:18:00	Completed	01/07/2015 01:00:00	SEA VIEW ROAD O/S 59
C/WAY SURFACE COURSE TO SQUARE OFF AND RE-SURFACE 1.0 X 1.0.							
SS112965-3	Footway Planned	Pothole	Cat 2.2 - 28d	26/06/2015 09:19:00	Completed	26/08/2015 16:00:00	SEA VIEW ROAD O/S 63
F/WAY POTHOLE 1.0 X 1.0							
SS112965-4	C/w Planned less than 15m	Pothole	Cat 2.2 - 28d	26/06/2015 09:23:00	Job closed down no work carried out	01/01/9999 00:00:00	SEA VIEW ROAD O/S 64, 62, 60 AND 58
C/WAY O/LAY TO SQUARE OFF AND RE-SURFACE X 4. 9.0 X 0.5 IN TOTAL. NO WAITING CONES							
SS112965-5	Road Name Plates	Accident damage	Cat 2.2 - 28d	26/06/2015 09:24:00	Completed	01/10/2015 16:00:00	SEA VIEW ROAD JCT RINGWOOD ROAD
TO REPLACE DAMAGED STREET NAME PLATE ON GRASS VERGE AS MARKED.							
Monthly Safety of Area_1_secondary_dis_(3b_03) on 21 July 2015 by JW (Monthly Safety, Safety Inspection)							
This section was inspected on 28/07/2015 10:33:00 and no defects were found.							
Monthly Safety of South_Area_secondary_dis_(3b_03) on 14 August 2015 by JW (Monthly Safety, Safety Inspection)							
This section was inspected on 19/08/2015 12:06:43 and no defects were found.							
Monthly Safety of South_Area_Pedestrianised_(Pe) on 25 September 2015 by JW (Monthly Safety, Safety Inspection)							
SS113175-2	Footway Planned	Pothole	Cat 2.1 - 7d	25/09/2015 09:28:00	Completed	23/09/2015 16:00:00	SEA VIEW ROAD O/S SEA VIEW NEWS.
F/WAY POTHOLE AS MARKED 1.0 X 1.0 IN TOTAL							
Monthly Safety of South_Area_secondary_dis_(3b_03) on 15 September 2015 by JW (Monthly Safety, Safety Inspection)							
This section was inspected on 25/09/2015 10:21:00 and no defects were found.							

SEA VIEW ROAD RINGWOOD ROAD TO VIEWPOINT ROUNDABOUT

Defect Reference	Item Type	Item Detail	Defect Category	Defect Date	Current Status	Actual Completion Date	Location Description
Monthly Safety of South_Area_secondary_dis_(3b_03) on 15 October 2015 by JW (Monthly Safety, Safety Inspection)							
SS113252-1	Footway Planned	Pothole	Cat 2.2 - 28d	27/10/2015 10:42:00	Completed	26/11/2015 16:00:00	SEA VIEW ROAD O/S 35.
F/WAY POTHOLES X 2. 1.2 X 1.0 IN TOTAL.							
SS113252-2	Footway Planned	Pothole	Cat 2.2 - 28d	27/10/2015 10:44:00	Completed	26/11/2015 12:00:00	SEA VIEW ROAD O/S 47.
F/WAY POTHOLE 1.0 X 1.0.							
SS113252-3	Footway Planned	Pothole	Cat 2.2 - 28d	27/10/2015 10:45:00	Completed	26/11/2015 12:00:00	SEA VIEW ROAD O/S 81.
F/WAY POTHOLE 1.0 X 1.0							
SS113252-4	C/w Planned less than 15m	Blacktop : extensive cracking	Cat 2.2 - 28d	27/10/2015 10:48:00	Completed	26/11/2015 12:00:00	SEA VIEW ROAD O/S 58-64.
C/WAY TO O/LAY SURFACE COURSE AS MARKED, 7.0 X 1.0 IN TOTAL. NO WAITING CONES.							
SS113252-5	SIGN	Accident damage	Cat 2.2 - 28d	27/10/2015 10:51:00	Completed	23/11/2015 16:00:00	SEA VIEW ROAD O/S 12 NEAR KITCHEN SHOP
TO RE-INSTALL MISSING 50 X 50 POST AS MARKED AND REPLACE SIGN TAKEN BACK TO SIGN SHOP.							
Monthly Safety of South_Area_secondary_dis_(3b_03) on 17 November 2015 by JW (Monthly Safety, Safety Inspection)							
SS113307-1	Footway Planned	Pothole	Cat 2.2 - 28d	18/11/2015 15:37:00	Completed	27/02/2016 12:00:00	SEA VIEW ROAD O/S 157
F/WAY DEPRESSION 2.0 X 1.2							
Reactive Defect Recorded 30/11/2015 14:44:30 by jjjohnw							
BOP15330694	KERB	Damaged	Cat 2.1 - 7d	30/11/2015 14:44:30	Completed	20/02/2016 12:00:00	SEA VIEW ROAD O/S 99
TO RE-SET RAISED MARKED KERB.							
Monthly Safety of South_Area_secondary_dis_(3b_03) on 09 December 2015 by JW (Monthly Safety, Safety Inspection)							
This section was inspected on 18/12/2015 09:55:00 and no defects were found.							

B3061/00805

SEA VIEW ROAD RINGWOOD ROAD TO VIEWPOINT ROUNDABOUT

Defect Reference	Item Type	Item Detail	Defect Category	Defect Date	Current Status	Actual Completion Date	Location Description
Monthly Safety of South_Area_secondary_dis_(3b_03) on 20 January 2016 by JW (Monthly Safety, Safety Inspection)							
SS113455-10	Cleansing Grading	Grade D	Non Actionable - comment only	25/01/2016 15:57:00	Completed	25/01/2016 15:57:57	SEA VIEW ROAD FROM VIEWPOINT ROUNABOUT TO RINGWOOD ROAD.
FOOTWAY COVERED IN CIGARETTE BUTTS, DOG FOULING AND BENCHES AND CORNERS NEED SWEEPING OUT. PARKING BAYS NEED SWEEPING AND LITTER PICKING.AS WELL AS WEEDING BACK LINE OF FOOTWAY.							
SS113455-11	GULLY	Blockage	Cat 2.1 - 7d	25/01/2016 15:59:00	Job closed down no work carried out	01/01/9999 00:00:00	SEA VIEW ROAD BETWEEN 3 & 15.
TO CLEAR ALL FOOTWAY GULLIES							
SS113455-15	CARRIAGEWAY	Pothole	Cat 2 - 24h	25/01/2016 16:14:00	Completed	26/01/2016 16:00:00	SEA VIEW ROAD
TO PLUG ALL C/WAY POTHLES							
SS113455-12	CARRIAGEWAY	Blacktop : fretting	Cat 2.1 - 7d	25/01/2016 16:01:00	Job closed down no work carried out	01/01/9999 00:00:00	SEA VIEW ROAD FROM RINGWOOD ROAD TO VIEWPOINT ROUNABOUT.
TO RE-SURFACE ALL OF THE FAILED SURFACE COURSE POTHLES							
Monthly Safety of Central_Area_Pedestrianised_(Pe) on 25 January 2016 by SH (Monthly Safety, Safety Inspection)							
HT213480-15	GULLY	Blockage	Cat 1 - 2h	27/01/2016 11:12:00	Completed	27/01/2016 11:14:02	OUTSIDE3 N 5 SEAVIEW RD
2 X GULLY TO CLEAN							
HT213480-16	CARRIAGEWAY	Pothole	Cat 2.1 - 7d	27/01/2016 11:20:00	Completed	28/01/2016 16:00:00	OUTSIDE 55 AND34 SEAVIEW ROAD
FILL POTHLESX2							
Reactive Defect Recorded 09/02/2016 10:07:09 by jjjohnw							
BOP16335379	GULLY	Blockage	Cat 2 - 24h	09/02/2016 10:07:09	Completed	12/02/2016 16:00:00	SEA VIEW ROAD BETWEEN 1 & 15
TO CLEAR AND JET ALL FOOTWAY GULLIES							
Monthly Safety of South_Area_secondary_dis_(3b_03) on 15 February 2016 by JW (Monthly Safety, Safety Inspection)							
SS113527-3	CARRIAGEWAY	Blacktop : fretting	Cat 2 - 24h	19/02/2016 10:58:00	Completed	20/02/2016 16:00:00	SEA VIEW ROAD WHOLE LENGTH.
TO PLUG ALL C/WAY POTHLES ALONG WHOLE STRETCH.							
SS113527-4	SIGN	Accident damage	Cat 2.2 - 28d	19/02/2016 11:00:00	Completed	04/05/2016 16:00:00	SEA VIEW ROAD O/S 38.
TO REPLACE 50 X 50 POST AS MARKED.							
SS113527-5	SIGN	Accident damage	Cat 2.2 - 28d	19/02/2016 11:01:00	Completed	04/05/2016 16:00:00	SEA VIEW ROAD O/S 8.
TO INSTALL NEW 50 X 50 POST.							

B3061/00805

SEA VIEW ROAD RINGWOOD ROAD TO VIEWPOINT ROUNDABOUT

Defect Reference	Item Type	Item Detail	Defect Category	Defect Date	Current Status	Actual Completion Date	Location Description
Monthly Safety of South_Area_secondary_dis_(3b_03) on 07 March 2016 by RP (Monthly Safety, Safety Inspection)							
SS113593-3	Cleansing Grading	Grade B	Non Actionable - comment only	07/03/2016 11:42:00	Completed	07/03/2016 11:42:54	
Inventory of adhoc_defects on 17 June 2016 by SH (Inventory, Inventory Inspection)							
HT213338-90	CARRIAGEWAY	Pothole	Cat 2.1 - 7d	09/03/2016 11:34:00	Completed	02/04/2016 12:00:00	UOTSIDE 53A SEAVIEW RD
PATCH AND REPAIR 1X1 PATCH							
Reactive Defect Recorded 22/03/2016 14:34:24 by jjjohnw							
BOP16337915	CARRIAGEWAY	Pothole	Cat 2 - 24h	22/03/2016 14:34:24	Completed	24/03/2016 16:00:00	SEA VIEW ROAD O/S 53A AND OTHER SECTIONS.
TO PLUG ALL POTHOLES AND REPAIR THE MARK ED SECTION O/S 53A							
Monthly Safety of South_Area_secondary_dis_(3b_03) on 25 April 2016 by JW (Monthly Safety, Safety Inspection)							
SS113657-1	CARRIAGEWAY	Pothole	Cat 2.1 - 7d	25/04/2016 14:13:00	Completed	27/04/2016 16:00:00	SEA VIEW ROAD FROM RINGWOOD RAD TO VIEWPOINT ROUNDABOUT.
TO PLUG ALL C/WAY POTHOLES.							
Reactive Defect Recorded 04/05/2016 10:34:39 by jjjohnw							
BOP16340932	CARRIAGEWAY	Pothole	Cat 2 - 24h	04/05/2016 10:34:39	Completed	05/05/2016 16:00:00	SEA VIEW ROAD WHOLE LENGTH ESPECIAL AT THE JUNCTION OF GROVE ROAD
TO PLUG ALL C/WAY POTHOLES							
Monthly Safety of South_Area_secondary_dis_(3b_03) on 25 May 2016 by JW (Monthly Safety, Safety Inspection)							
SS113723-6	Cleansing Grading	Grade E	Non Actionable - comment only	26/05/2016 11:07:00	Completed	26/05/2016 11:07:55	SEA VIEW ROAD FROM VIEWPOINT RAB TO RINGWOOD ROAD.
BACK LINES, BUS STOPS LITTERED WITH LEAF DEBRIS WEEDS, CIGARETTE BUTS CANS BOTTLES, ETC NEEDS A HAND SWEEP							
Monthly Safety of South_Area_secondary_dis_(3b_03) on 14 June 2016 by JW (Monthly Safety, Safety Inspection)							
SS113796-1	Cleansing Grading	Grade E	Non Actionable - comment only	28/06/2016 10:25:00	Completed	28/06/2016 10:25:34	SEA VIEW ROAD FROM RINGWOOD ROAD TO SEA VIEW ROAD RAB
TO SWEEP AROUND ALL OBSTACLES, BENCHES/POSTS ETC & WEEDING. A LOT OF SILT DEBRIS ON FOOTWAY TO SHOVEL UP AND CHANNELS TO CLEAR.							
SS113796-2	GULLY	Blockage	Cat 2.1 - 7d	28/06/2016 10:26:00	Completed	08/07/2016 16:00:00	SEA VIEW ROAD O/P 107 - 111.
TO CLEAR BLOCKED F/WAY GULLIES							

SEA VIEW ROAD RINGWOOD ROAD TO VIEWPOINT ROUNDABOUT

Defect Reference	Item Type	Item Detail	Defect Category	Defect Date	Current Status	Actual Completion Date	Location Description
Monthly Safety of South_Area_secondary_dis_(3b_03) on 19 July 2016 by JW (Monthly Safety, Safety Inspection)							
SS113869-6	Cleansing Grading	Grade E	Non Actionable - comment only	27/07/2016 09:53:00	Completed	27/07/2016 09:53:19	SEA VIEW ROAD FROM RINGWOOD ROAD TO VIEWPOINT ROUNDABOUT.
PAVEMENTS NEED LITTER PICKING AND SWEEPING, WEEDS NEED CLEARING, DOG FOULING.BENCHES NEEDS SWEEPING OUT CIGARETTE BUTTS ALL OVER THE PLACE.							
Monthly Safety of South_Area_secondary_dis_(3b_03) on 10 August 2016 by JW (Monthly Safety, Safety Inspection)							
SS113939-3	CARRIAGEWAY	Pothole	Cat 2.1 - 7d	10/08/2016 15:47:00	Completed	12/08/2016 09:00:00	SEA VIEW ROAD JCT GROVE ROAD
TO REPAIR/PLUG ALL WEARING COURSE AT THIS JUNCTION, CYCLE HAZARD							
Monthly Safety of South_Area_secondary_dis_(3b_03) on 10 August 2016 by JW (Monthly Safety, Safety Inspection)							
SS113939-4	CARRIAGEWAY	Pothole	Cat 2.1 - 7d	31/08/2016 10:11:00	Completed	02/03/2017 16:00:00	SEA VIEW ROAD O/S 69/71
C/WAY SURFACE TO OVERLAY 2.0 X 1.0							
Monthly Safety of South_Area_secondary_dis_(3b_03) on 13 September 2016 by JW (Monthly Safety, Safety Inspection)							
SS114035-3	Cleansing Grading	Grade C	Non Actionable - comment only	28/09/2016 15:02:00	Completed	28/09/2016 15:02:15	SEA VIEW ROAD FROM VIEWPOINT TO RINGWOOD ROAD.
NEEDS A PAVEMENT SWEEPER AND OPERATIVE WITH A CART TO CARRY OUT A MANUAL SWEEP IN AND AROUND BENCHES, SHOPS BUS STOPS ETC.							
Monthly Safety of South_Area_secondary_dis_(3b_03) on 21 October 2016 by JW (Monthly Safety, Safety Inspection)							
SS114078-10	CARRIAGEWAY	Pothole	Cat 2 - 24h	25/10/2016 12:08:00	Completed	24/01/2017 11:20:00	SEA VIEW ROAD O/S 69, JCT GROVE ROAD AND OTHER SECTIONS.
C/WAY POTHOLE TO PLUG							
SS114078-9	CARRIAGEWAY	Patch - difference in level	Cat 2.1 - 7d	25/10/2016 12:06:00	Completed	09/02/2017 15:30:00	SEA VIEW ROAD O/S 45
C/WAY DEPRESSION AS MARKED. 4.0 X 1.0. STOP/GO.							
Monthly Safety of South_Area_secondary_dis_(3b_03) on 25 November 2016 by JW (Monthly Safety, Safety Inspection)							
SS114145-1	Cleansing Grading	Grade B	Non Actionable - comment only	29/11/2016 11:23:00	Completed	29/11/2016 11:23:38	
Monthly Safety of South_Area_secondary_dis_(3b_03) on 13 December 2016 by JW (Monthly Safety, Safety Inspection)							
SS114225-1	Cleansing Grading	Grade B	Non Actionable - comment only	20/12/2016 15:22:00	Completed	20/12/2016 15:22:49	

B3061/00805

SEA VIEW ROAD RINGWOOD ROAD TO VIEWPOINT ROUNDABOU

Defect Reference	Item Type	Item Detail	Defect Category	Defect Date	Current Status	Actual Completion Date	Location Description
Reactive Defect Recorded 17/01/2017 09:20:36 by jjjohnw BOP17360983	CARRIAGEWAY	Pothole	Cat 2.1 - 7d	17/01/2017 09:20:36	Job closed down no work carried out	01/01/9999 00:00:00	SEA VIEW ROAD FROM WAYNE ROAD TO RINGWOOD ROAD
TO PLUG ALL C/WAY POTHOLES							
Monthly Safety of South_Area_secondary_dis_(3b_03) on 18 January 2017 by JW (Monthly Safety, Safety Inspection)							
This section was inspected on 25/01/2017 13:57:03 and no defects were found.							
Monthly Safety of South_Area_secondary_dis_(3b_03) on 22 February 2017 by JW (Monthly Safety, Safety Inspection)							
SS114357-1	CARRIAGEWAY	Patch - loss of material	Cat 2.1 - 7d	22/02/2017 11:55:00	Completed	12/07/2017 16:00:00	SEA VIEW ROAD WHOLE LENGTH.
TO RE- SURFACE WEARING COURSE PATCHES ALONG WHOLE LENGTH							
Monthly Safety of South_Area_secondary_dis_(3b_03) on 23 March 2017 by JW (Monthly Safety, Safety Inspection)							
SS114454-7	Cleansing Grading	Grade B	Non Actionable - comment only	28/03/2017 10:43:00	Completed	28/03/2017 10:43:42	
Monthly Safety of South_Area_secondary_dis_(3b_03) on 20 April 2017 by JW (Monthly Safety, Safety Inspection)							
SS114497-7	CARRIAGEWAY	Pothole	Cat 2 - 24h	27/04/2017 11:13:00	Completed	28/04/2017 11:00:00	SEA VIEW ROAD
TO PLUG ALL C/WAY POTHOLES WITH HOT MATERIAL.							
Monthly Safety of South_Area_secondary_dis_(3b_03) on 20 April 2017 by JW (Monthly Safety, Safety Inspection)							
SS114497-9	Cleansing Grading	Grade B	Non Actionable - comment only	28/04/2017 08:58:00	Completed	28/04/2017 08:59:06	
Monthly Safety of South_Area_secondary_dis_(3b_03) on 23 May 2017 by JW (Monthly Safety, Safety Inspection)							
SS114563-6	CARRIAGEWAY	Pothole	Cat 2.1 - 7d	25/05/2017 09:28:00	Completed	26/05/2017 10:00:00	SEA VIEW ROAD.
C/WAY POTHOLES TO PLUG							
SS114563-7	Cleansing Grading	Grade D	Non Actionable - comment only	25/05/2017 09:29:00	Completed	25/05/2017 09:29:28	
Monthly Safety of South_Area_secondary_dis_(3b_03) on 20 June 2017 by JW (Monthly Safety, Safety Inspection)							
SS114653-6	Cleansing Grading	Grade B	Non Actionable - comment only	27/06/2017 11:14:00	Completed	27/06/2017 11:14:37	

B3061/00805

SEA VIEW ROAD RINGWOOD ROAD TO VIEWPOINT ROUNDABOU

Defect Reference	Item Type	Item Detail	Defect Category	Defect Date	Current Status	Actual Completion Date	Location Description
Monthly Safety of South_Area_secondary_dis_(3b_03) on 21 July 2017 by JW (Monthly Safety, Safety Inspection)							
SS114728-7	Cleansing Grading	Grade C	Non Actionable - comment only	25/07/2017 09:26:00	Completed	25/07/2017 09:26:12	
Monthly Safety of South_Area_secondary_dis_(3b_03) on 18 August 2017 by JW (Monthly Safety, Safety Inspection)							
SS114772-6	Cleansing Grading	Grade B	Non Actionable - comment only	22/08/2017 09:51:00	Completed	22/08/2017 09:51:18	
Monthly Safety of South_Area_secondary_dis_(3b_03) on 20 September 2017 by RP (Monthly Safety, Safety Inspection)							
<i>This section was inspected on 20/09/2017 12:31:00 and no defects were found.</i>							
Monthly Safety of South_Area_secondary_dis_(3b_03) on 03 October 2017 by RP (Monthly Safety, Safety Inspection)							
<i>This section was inspected on 03/10/2017 11:27:00 and no defects were found.</i>							
Monthly Safety of South_Area_secondary_dis_(3b_03) on 13 November 2017 by RP (Monthly Safety, Safety Inspection)							
<i>This section was inspected on 30/11/2017 06:46:00 and no defects were found.</i>							
Monthly Safety of South_Area_secondary_dis_(3b_03) on 13 December 2017 by RP (Monthly Safety, Safety Inspection)							
<i>This section was inspected on 13/12/2017 09:08:00 and no defects were found.</i>							
Monthly Safety of South_Area_secondary_dis_(3b_03) on 16 January 2018 by RP (Monthly Safety, Safety Inspection)							
<i>This section was inspected on 16/01/2018 13:33:00 and no defects were found.</i>							
Inventory of adhoc_defects on 04 October 2018 by RB (Inventory, Inventory Inspection)							
NA14940-74	CARRIAGEWAY	Pothole	Cat 2.1 - 7d	29/01/2018 14:04:00	Completed	06/03/2018 16:00:00	SEA VIEW ROAD
PLEASE PLUG ALL HOLES IN WEARING COURSE - APPROX 12							
Monthly Safety of South_Area_secondary_dis_(3b_03) on 20 February 2018 by RP (Monthly Safety, Safety Inspection)							
<i>This section was inspected on 20/02/2018 11:43:00 and no defects were found.</i>							
Monthly Safety of South_Area_secondary_dis_(3b_03) on 15 March 2018 by RP (Monthly Safety, Safety Inspection)							
<i>This section was inspected on 15/03/2018 10:30:00 and no defects were found.</i>							
Reactive Defect Recorded 11/04/2018 13:24:10 by jjbarry							
BOP18453678	CARRIAGEWAY	Pothole	Cat 2.2 - 28d	11/04/2018 13:24:10	Completed	17/04/2018 16:00:00	Sea View Road
Fill all potholes with HRA							
Monthly Safety of South_Area_secondary_dis_(3b_03) on 30 April 2018 by TS (Monthly Safety, Safety Inspection)							
<i>This section was inspected on 30/04/2018 10:39:00 and no defects were found.</i>							

SEA VIEW ROAD RINGWOOD ROAD TO VIEWPOINT ROUNDABOUT

Defect Reference	Item Type	Item Detail	Defect Category	Defect Date	Current Status	Actual Completion Date	Location Description
Monthly Safety of South_Area_secondary_dis_(3b_03) on 22 May 2018 by SS (Monthly Safety, Safety Inspection)							
SS115398-1	Cleansing Grading	Grade B	Non Actionable - comment only	22/05/2018 10:38:00	Completed	22/05/2018 10:38:49	
Monthly Safety of South_Area_secondary_dis_(3b_03) on 26 June 2018 by SS (Monthly Safety, Safety Inspection)							
<i>This section was inspected on 26/06/2018 13:04:00 and no defects were found.</i>							
Monthly Safety of South_Area_secondary_dis_(3b_03) on 24 July 2018 by SS (Monthly Safety, Safety Inspection)							
SS115563-8	Cleansing Grading	Grade C	Non Actionable - comment only	24/07/2018 14:01:00	Completed	24/07/2018 14:01:40	
Monthly Safety of South_Area_secondary_dis_(3b_03) on 21 August 2018 by RP (Monthly Safety, Safety Inspection)							
<i>This section was inspected on 21/08/2018 10:53:00 and no defects were found.</i>							
Monthly Safety of South_Area_secondary_dis_(3b_03) on 18 September 2018 by SS (Monthly Safety, Safety Inspection)							
SS115698-1	CARRIAGEWAY	Patch - difference in level	Cat 2.2 - 28d	18/09/2018 09:34:00	Completed	21/09/2018 16:00:00	ZEBRA CROSSING SEAVIEW/ASHLEY RD
SURFACE SINKING AGAIN. PLEASE REPAIR							
SS115698-2	Cleansing Grading	Grade B	Non Actionable - comment only	18/09/2018 09:35:00	Completed	18/09/2018 09:35:19	
Monthly Safety of South_Area_secondary_dis_(3b_03) on 16 October 2018 by SS (Monthly Safety, Safety Inspection)							
SS115758-5	CARRIAGEWAY	Pothole	Cat 2.1 - 7d	16/10/2018 11:40:00	Completed	30/10/2018 16:00:00	OPP 6 SEAVIEW ROAD
PLEASE PLUG HOLE							
SS115758-6	Section 81 defect	Other	Actionable on site	16/10/2018 11:45:00	Completed	16/10/2018 11:46:30	O/S SALVATION ARMY HALL
BT CHAMBER LID DAMAGED.							
SS115758-7	Cleansing Grading	Grade B	Non Actionable - comment only	16/10/2018 11:47:00	Completed	16/10/2018 11:47:27	