

Glasgow City Council
Land and Environmental Services
Freedom of Information Requests:



Safety Inspection Reports

Date Range **From 03January11 to 03January13**
Street **Dalmarnock Road**

Reference	Asset	Report	Defect Category	Date Recorded
03_LR_02				
Safety Inspection -3 Month of 03_LR_02 Calton E Ctre link route 2 - Bridgeton on 18 January 2011				
Dalmarnock Road				
SF11891-1	FOOTWAY	POTHLES (40mm-100mm)	Cat 2 High	17-Jan-2011
AT DUNN ST JUNCTION 100MM X 200MM AREA POTTED/UNEVEN ON C/WAY ON PED CROSSING				
SF11891-2	ROAD MARKING	WORN OR STRIPPING	Cat 3	17-Jan-2011
AT DUNN ST JUNCTION MARKINGS AT TRAFFIC LIGHTS				
SF11891-3	CARRIAGEWAY	POTHLES (40mm-100mm)	Cat 2 High	17-Jan-2011
8 M WEST OF DUNN ST VARIOUS P/HOLES / SURFACE UNEVEN OVER A 1.5 M X 8M AREA				
SF11891-4	ROAD MARKING	WORN OR STRIPPING	Cat 3	17-Jan-2011
AT 189 MARKINGS AT PED CROSSING				
SF11891-5	CARRIAGEWAY	POTHLES (40mm-100mm)	Cat 2 High	17-Jan-2011
AT QUEEN MARY ST JUNCTION POTTED AREA ROUND MANHOLE FITTMENT				
SF11891-6	KERB	DAMAGE CAUSING DANGER	Cat 1a - Fast Track	17-Jan-2011
OPP QUEEN MARY ST JUNCTION SECTIONOF KERB DISLODGED AT SCHOOL CROSSING AREA				
SF11891-7	CARRIAGEWAY	POTHLES (40mm-100mm)	Cat 2 High	17-Jan-2011
OPP 129 VARIOUS P/HOLES AND SURFACE PUSHED AND RAISED OVER A 300MM X 5 M AREA AT BUS STOP				
SF11891-8	ROAD MARKING	WORN OR STRIPPING	Cat 3	17-Jan-2011
AT COL R 13 LOOKS LIKE SCHOOL ZONE				
SF11891-9	TRAFFIC SIGNS	RE-ORIENTATE	Cat 3	17-Jan-2011
AT COL R 13 SCHOOL SIGN				

Reference	Asset	Report	Defect Category	Date Recorded
SF11891-10	TRAFFIC SIGNS	MISSING (NOT STOP OR LOW BRIDGE)	Cat 3	17-Jan-2011
5 M EAST OF QUEEN MARY ST				
SF11891-11	FOOTWAY	DEBRIS / OBSTRUCTION	Cat 1a - Fast Track	17-Jan-2011
AT 176 RUBBISH BIN FALLEN OFF OF POLE				
SF11891-12	FOOTWAY	INSPECTION AREA OBSCURED BY SKIP/SCAFFOLD/UTILITY	Cat 3	17-Jan-2011
26m from 150 Old Dalmarnock Road DALMARNOCK RD /SECTION FROM DUNN ST TO BRIDGE AT CLYDE NOT INSPECTED ON THIS INSPECTION AS IT IS ON A STRATIGIC 11 / 15 ROUTE				
SF11891-13	CARRIAGEWAY	POTHOLES (40mm-100mm)	Cat 2 High	18-Jan-2011
10 M EAST OF COL R 6 POTTED AREA ROUND IRONWORK				
SF11891-14	KERB	DAMAGE - NO IMMEDIATE DANGER	Cat 2 Low	18-Jan-2011
8 M WEST OF 93 SECTION OF KERB MISSING				
SF11891-15	FOOTWAY	POTHOLES (40mm-100mm)	Cat 2 High	18-Jan-2011
10 M WEST OF 93 100MM X 600MM AREA POTTED/UNEVEN				
SF11891-16	CARRIAGEWAY	POTHOLES (40mm-100mm)	Cat 2 High	18-Jan-2011
OPP MEGAN ST JUNCTION 400MM X 300MM				
SF11891-17	TRAFFIC SIGNS	RE-ALIGN POLE	Cat 3	18-Jan-2011
OPP 34				
SF11891-18	TRAFFIC SIGNS	RE-ALIGN POLE	Cat 3	18-Jan-2011
OPP 14				
SF11891-19	KERB	DAMAGE - NO IMMEDIATE DANGER	Cat 2 Low	18-Jan-2011
OPP 14 SECTION OF KERB CHIPPED				
SF11891-20	FOOTWAY	POTHOLES (40mm-100mm)	Cat 2 High	18-Jan-2011
6 M EAST OF 48 POTTED AREA/UNEVEN ROUND 2 TOBY FITTMENTS				
SF11891-21	DISTRIBUTION UNIT	Door Off/Missing	Cat 1a - Fast Track	18-Jan-2011
AT 48 DOOR OFF JUNCTION BOX WIRES EXPOSED /PHONED RALF NO 3333426				
SF11891-29	DISTRIBUTION UNIT	Door Off/Missing	Cat 1a - Fast Track	18-Jan-2011
OPP MEGAN ST JUNCTION JUNCTION BOX AT SIDE OF F/WAY DAMAGED CABELS STICKING OUT OF GROUND /PHONED RALF NO 333432				

Reference	Asset	Report	Defect Category	Date Recorded
-----------	-------	--------	-----------------	---------------

Reference	Asset	Report	Defect Category	Date Recorded
03_HP_05				
Safety Inspection - HP Footways of 03_HP_05 Calton E Centre ped route 5 - Dalmarnock on 01 February 2011				
Dalmarnock Road				
SF11912-6	FOOTWAY	INSPECTION AREA OBSCURED BY SKIP/SCAFFOLD/UTILITY	Cat 3	01-Feb-2011
22m from 367 Dalmarnock Road AREA BLOCKED OFF / BUILDING WORKS				

Reference	Asset	Report	Defect Category	Date Recorded
03_HP_06				
Safety Inspection - HP Footways of 03_HP_06 Calton E Centre ped route 6 - Bridgeton on 01 February 2011				
Dalmarnock Road				
SF11913-14	KERB	DAMAGE - NO IMMEDIATE DANGER	Cat 2 Low	02-Feb-2011
OPP 12 KERB CHIPPED /BROKEN				
SF11913-15	FOOTWAY	POTHoles (40mm-100mm)	Cat 2 High	02-Feb-2011
OPP 48 /AT FISH AND CHICKEN BAR 400MMX 400MM AREA POTTED/UNEVEN				
SF11913-16	CARRIAGEWAY	PONDING	Cat 2 Low	02-Feb-2011
OPP COL R 3				
SF11913-17	FOOTWAY	POTHoles (40mm-100mm)	Cat 2 High	02-Feb-2011
5 M EAST OF 48 LOW TAR ROUND 2 TOBYS /NEEDING LEVELLED OFF				
SF11913-18	FOOTWAY	INSPECTION AREA OBSCURED BY SKIP/SCAFFOLD/UTILITY	Cat 3	02-Feb-2011
AREA AT 48 SECTION OF F/WAY COVERED DUE TO WORKS				

Reference	Asset	Report	Defect Category	Date Recorded
11_015				
Safety Inspection - Strategic Even of 11_015 A749 - Dalmarnock Rd on 02 March 2011				
Dalmarnock Road				
SF12118-1	CARRIAGEWAY	INSPECTION AREA OBSCURED BY SKIP/SCAFFOLD/UTILITY	Cat 3	02-Mar-2011
FROM BARTHOMENLOW ST TO ESSO GARAGE ROAD SHUT DUE TO WORKS				
SF12118-2	CARRIAGEWAY	INSPECTION AREA OBSCURED BY SKIP/SCAFFOLD/UTILITY	Cat 3	02-Mar-2011
FROM ESSO GARAGE TO JUST WEST OF COL R 38 SECTIONS OF F/WAY AND C/WAY COVERED DUE TO WORKS				
SF12118-3	ROAD MARKING	WORN OR STRIPPING	Cat 3	02-Mar-2011
JUST EAST OF COL R 38 MARKINGS AT PED LIGHTS				
SF12118-4	ROAD MARKING	WORN OR STRIPPING	Cat 3	02-Mar-2011
AT SPRINGFIELD RD JUNCTION MARKINGS AT TRAFFIC LIGHTS				
SF12118-5	ROAD MARKING	WORN OR STRIPPING	Cat 3	02-Mar-2011
JUST WEST OF 789 MARKINGS AT PED LIGHTS				

Reference	Asset	Report	Defect Category	Date Recorded
03_HP_05				
Safety Inspection - HP Footways of 03_HP_05 Calton E Centre ped route 5 - Dalmarnock on 20 June 2011				
Dalmarnock Road				
SF12356-7	FOOTWAY	INSPECTION AREA OBSCURED BY SKIP/SCAFFOLD/UTILITY	Cat 3	20-Jun-2011
26m from 367 Dalmarnock Road THIS SECTION OF F/WAY SHUT OFF				

Reference	Asset	Report	Defect Category	Date Recorded
03_HP_06				
Safety Inspection - HP Footways of 03_HP_06 Calton E Centre ped route 6 - Bridgeton on 17 June 2011				
Dalmarnock Road				
SF12357-20	FOOTWAY	POTHLES (40mm-100mm)	Cat 2 High	20-Jun-2011
6 M EAST OF 48 AREA ROUND 2 TOBY FITTMENTS SUNKEN /UNEVEN /NEEDING LEVELLED OFF				
SF12357-21	FOOTWAY	INSPECTION AREA OBSCURED BY SKIP/SCAFFOLD/UTILITY	Cat 3	20-Jun-2011
FROM OPP MEGAN ST TO 23 SCAFFOLDING ON NORTH F/WAY DUE TO WORKS				

Reference	Asset	Report	Defect Category	Date Recorded
11_015				
Safety Inspection - Statagic of 11_015 A749 - Dalmarnock Rd on 17 August 2012				
Dalmarnock Road				
SF12475-1	ROAD MARKING	WORN OR STRIPPING	Cat 3	26-Aug-2011
AT 614 MARKINGS AT PED CROSSING				
SF12475-2	ROAD MARKING	WORN OR STRIPPING	Cat 3	26-Aug-2011
AT SPRINGFIELD RD JUNCTION ALL MARKINGS AT TRAFFIC LIGHTS				
SF12475-3	CARRIAGEWAY	INSPECTION AREA OBSCURED BY SKIP/SCAFFOLD/UTILITY	Cat 3	26-Aug-2011
19m from 367 Dalmarnock Road AREA WEST OF ESSO GARAGE BLOCK OFF /WORKS /BUT EXTREME WEST SECTION OF INSPECTION AT DUNN ST AREA INSPECTED				
SF12475-4	KERB	DAMAGE - NO IMMEDIATE DANGER	Cat 2 Low	26-Aug-2011
AT SPRINGFIELD RD JUNCTION KERB DISLODGED ON ISLAND				
SF12475-5	ROAD MARKING	WORN OR STRIPPING	Cat 3	26-Aug-2011
AT 789 MARKINGS AT PED CROSSING				
LA12475-1	CARRIAGEWAY	POTHOLE RESTRICTED ACCESS	Cat 2 High	17-Aug-2012
BUS STOP (BESIDE ESSO GARAGE 300MM\200MM POTHOLE				
LA12475-2	CARRIAGEWAY	GREEN - CONDITION GOOD	Cat 3	17-Aug-2012
11m from 558 Dalmarnock Road CARRIAGEWAY & FOOTWAY REASONABLY GOOD CONDITION				

Reference	Asset	Report	Defect Category	Date Recorded
03_LR_02				
Safety Inspection -3 Month of 03_LR_02 Calton E Ctre link route 2 - Bridgeton on 12 August 2011				
Dalmarnock Road				
SF12632-32	CARRIAGEWAY	INSPECTION AREA OBSCURED BY SKIP/SCAFFOLD/UTILITY	Cat 3	15-Aug-2011
24m from 150 Old Dalmarnock Road RD INSPECTED FROM DUNN ST TO BRIDGETON X ONLY /THE OTHER PART IS INSPECTED ON ROUTE 11 . 15				
SF12632-33	ROAD MARKING	WORN OR STRIPPING	Cat 3	15-Aug-2011
AT 104 SCHOOL ZONE MARKINGS				
SF12632-34	CARRIAGEWAY	POTHOLES (40mm-100mm)	Cat 2 High	15-Aug-2011
AT OPP 129 1.5 X 400MM AREA POTTED AND PUSHED AND RAISED AT BUS STOP				
SF12632-35	FOOTWAY	POTHOLES (40mm-100mm)	Cat 2 High	15-Aug-2011
OPP 133 /AT BUS STOP AREA ROUND CUT DOWN POLE NEEDING FILLED/LEVELLED OFF				
SF12632-36	CARRIAGEWAY	POTHOLES (40mm-100mm)	Cat 2 High	15-Aug-2011
AT MUSLIN ST JUNCTION POTTED AREA NEXT TO MANHOLE				
SF12632-37	CARRIAGEWAY	POTHOLES (40mm-100mm)	Cat 2 High	15-Aug-2011
AT 8 M EAST OF COL R 6 POTTED AREA ROUND IRONWORK				
SF12632-38	FOOTWAY	POTHOLES (40mm-100mm)	Cat 2 High	15-Aug-2011
AT 6 M WEST OF 60 AREA ROUND 2 TOBY FITTMENTS NEEDING FILLED /LEVELED OFF				
SF12632-45	CARRIAGEWAY	POTHOLES (40mm-100mm)	Cat 2 High	15-Aug-2011
AT 12 300MM X 300M IN PARKING BAY				
SF12632-46	TRAFFIC SIGNS	RE-ALIGN POLE	Cat 3	15-Aug-2011
AT 25				
SF12632-47	KERB	DAMAGE - NO IMMEDIATE DANGER	Cat 2 Low	15-Aug-2011
AT JUST WEST OF 25 SECTIONS OF KERB CHIPPED AWAY AT F/WAY CROSSOVER POINT				
SF12632-48	FOOTWAY	INSPECTION AREA OBSCURED BY SKIP/SCAFFOLD/UTILITY	Cat 3	15-Aug-2011
AREA FROM 25 TO OPP MEGAN ST JUNCTION SCAFFOLDING				
SF12632-49	KERB	DAMAGE - NO IMMEDIATE DANGER	Cat 2 Low	15-Aug-2011
AT 6 M WEST OF 93 SECTION OF KERB MISSING				

Reference	Asset	Report	Defect Category	Date Recorded
SF12632-50	KERB	DAMAGE - NO IMMEDIATE DANGER	Cat 2 Low	15-Aug-2011
AT 3 M EAST OF 93 KERB DISLODGED NEXT TO IRONWORK				
SF12632-51	FOOTWAY	TACTILE SLAB DEFECTIVE	Cat 2 Low	15-Aug-2011
AT 189 VARIOUS TACTILE TILES MISSING				
SF12632-52	ROAD MARKING	WORN OR STRIPPING	Cat 3	15-Aug-2011
AT DUNN ST JUNCTION MARKINGS AT TRAFFIC LIGHTS				

Reference	Asset	Report	Defect Category	Date Recorded
03_HP_05				
Safety Inspection - HP Footways of 03_HP_05 Calton E Centre ped route 5 - Dalmarnock on 24 October 2011				
Dalmarnock Road				
SF12894-15	FOOTWAY	INSPECTION AREA OBSCURED BY SKIP/SCAFFOLD/UTILITY	?	24-Oct-2011
THS SECTION BLOCKED OFF /BEING WORKED ON				

Reference	Asset	Report	Defect Category	Date Recorded
03_HP_06				
Safety Inspection - HP Footways of 03_HP_06 Calton E Centre ped route 6 - Bridgeton on 24 October 2011				
Dalmarnock Road				
LA12895-2	CARRIAGEWAY	POTHoles (40mm-100mm)	?	24-Oct-2011
OPPOSITE NUMBER 42, AT COLUMN R2				
LA12895-5	TRAFFIC SIGNS	OBSCURED	?	24-Oct-2011
OPPOSITE NUMBER 13				
NO ENTRY SIGN X 2, BADLY FADED				

Reference	Asset	Report	Defect Category	Date Recorded
11_015				
Safety Inspection - Strategic Even of 11_015 A749 - Dalmarnock Rd on 28 October 2011				
Dalmarnock Road				
SF12920-1	ROAD MARKING	WORN OR STRIPPING	?	28-Oct-2011
AT SPRINGFIELD RD JUNCTION MARKINGS AT TRAFFIC LIGHTS				
SF12920-2	ROAD MARKING	WORN OR STRIPPING	?	28-Oct-2011
AT 783 MARKINGS AT PED LIGHTS				
SF12920-3	CARRIAGEWAY	POTHoles	Cat 1a - Fast Track	28-Oct-2011
AT OPP 799 POTTED AREA ROUND TOBY FITTMENT ON C/WAY				
SF12920-4	CARRIAGEWAY	INSPECTION AREA OBSCURED BY SKIP/SCAFFOLD/UTILITY	?	28-Oct-2011
VARIOUS SECTIONS OF C./ WAY AND F/WAY COVERED DUE TO WORKS ON FULL LENGTH OF RD				

Reference	Asset	Report	Defect Category	Date Recorded
03_LR_02				
Safety Inspection -3 Month of 03_LR_02 Calton E Ctre link route 2 - Bridgeton on 25 November 2011				
Dalmarnock Road				
LA13312-18	CARRIAGEWAY	POTHLES	Remote/ Non Perm Harm < 1m	28-Nov-2011
BETWEEN ALLAN ST & STRATHCLYDE ST VERIOUS 300MM\200MM POTHOLE				
LA13312-19	FOOTWAY	POTHLES	Cat 2 Low	28-Nov-2011
DALMARNOCK RD \ DUNN ST 200MM\200MM POTHOLE (PED CROSSING COLUMN R26				
LA13312-20	CARRIAGEWAY	POTHLES	Remote/ Non Perm Harm < 1m	28-Nov-2011
OP BUILDING NO 206 500MM\400MM & 300MM\300MM POTHLES (TRAFFIC LIGHTS				

Reference	Asset	Report	Defect Category	Date Recorded
03_HP_05				
Safety Inspection - HP Footways of 03_HP_05 Calton E Centre ped route 5 - Dalmarnock on 20 January 2012				
Dalmarnock Road				
SF13423-4	FOOTWAY	INSPECTION AREA OBSCURED BY SKIP/SCAFFOLD/UTILITY	Cat 3	20-Jan-2012
26m from 367 Dalmarnock Road AREA BLOCKED OFF				

Reference	Asset	Report	Defect Category	Date Recorded
03_HP_06				
Safety Inspection - HP Footways of 03_HP_06 Calton E Centre ped route 6 - Bridgeton on 20 January 2012				
Dalmarnock Road				
SF13424-2	CARRIAGEWAY	PONDING	Possible / No Obvious Harm	20-Jan-2012
AT 60				
SF13424-3	FOOTWAY	POTHLES	Cat 2 Low	20-Jan-2012
AT 6 M WEST OF 60 AREA ROUND 2 TOBYS SUNKEN/UNEVEN				
SF13424-4	FOOTWAY	INSPECTION AREA OBSCURED BY SKIP/SCAFFOLD/UTILITY	Cat 3	20-Jan-2012
FROM 23 TO 47 SCAFFOLDING /WORKS				
SF13424-5	KERB	DAMAGE - NO IMMEDIATE DANGER	Cat 2 Low	20-Jan-2012
AT 23 /AT ENTRANCE TO LANE SECTIONS OF KERB CHIPPED				
SF13424-6	FOOTWAY	POTHLES	Cat 2 High	20-Jan-2012
AT COL R 2 200MM X 800MM AREA OF GRANO SURFACE BROKEN				

Reference	Asset	Report	Defect Category	Date Recorded
03_LR_02				
Safety Inspection -3 Month of 03_LR_02 Calton E Ctre link route 2 - Bridgeton on 26 January 2012				
Dalmarnock Road				
SF13452-24	CARRIAGEWAY	POTHLES	Possible / No Obvious Harm	26-Jan-2012
AT 5 M WEST OF DUNN ST VARIOUS P/HOLES // SURFACE UNEVEN OVER 3 M X 10 M AREA AT TRAFFIC LIGHTS				
SF13452-25	TRAFFIC SIGNS	MISSING (NOT STOP OR LOW BRIDGE)	Cat 3	26-Jan-2012
AT FAIRBAIRN PATH JUNCTION				
SF13452-26	GULLY	BLOCKED GULLY	Cat 2 Low	26-Jan-2012
AT 201				
SF13452-27	FOOTWAY	TACTILE SLAB DEFECTIVE	Cat 2 Low	26-Jan-2012
AT 189 3 TACTIL TILES MISSING				
SF13452-28	CARRIAGEWAY	POTHLES	Possible / No Obvious Harm	26-Jan-2012
AT MUSLIN ST JUNCTION POTTED AREA ROUND MANHOLE				
SF13452-29	ROAD MARKING	WORN OR STRIPPING	Cat 3	26-Jan-2012
AT 104 SCHOOL ZONE				
SF13452-30	CARRIAGEWAY	PONDING	Possible / No Obvious Harm	26-Jan-2012
AT 140				
SF13452-31	CARRIAGEWAY	PONDING	Possible / No Obvious Harm	26-Jan-2012
AT 158				
SF13452-32	CARRIAGEWAY	PONDING	Possible / No Obvious Harm	27-Jan-2012
AT 60				
SF13452-43	KERB	DAMAGE - NO IMMEDIATE DANGER	Cat 2 Low	27-Jan-2012
AT 7 M NORTH OF 93 SECTION OF KERB MISSING				
SF13452-44	ROAD MARKING	WORN OR STRIPPING	Cat 3	27-Jan-2012
AT 93 SCHOOL ZONE				
SF13452-45	KERB	DAMAGE - NO IMMEDIATE DANGER	Cat 2 Low	27-Jan-2012
AT 5 M SOUTH OF 93 SECTION OF KERB DISLODGED NEXT TO IRONWORK				

Reference	Asset	Report	Defect Category	Date Recorded
11_015				
Safety Inspection - Statagic of 11_015 A749 - Dalmarnock Rd on 16 January 2012				
Dalmarnock Road				
LA13491-1	CARRIAGEWAY	POTHLES	Remote/ Non Perm Harm < 1m	16-Jan-2012
BETWEEN WOODHALL ST & STRATHCLYDE ST THREE 400MM\300MM POTHOLE(TRAFFIC LIGHTS) & VERIOUS 300MM\200MM POTHLES				
LA13491-2	CARRIAGEWAY	POTHLES	Remote/ Non Perm Harm < 1m	16-Jan-2012
OP BIRKWOOD ST TWO 400MM\300MM POTHLES (BESIDE PED CROSSING				

Reference	Asset	Report	Defect Category	Date Recorded
11_015				
Safety Inspection - Statagic of 11_015 A749 - Dalmarnock Rd on 12 March 2012				
Dalmarnock Road				
LA13698-1	CARRIAGEWAY	AMBER - CONDITION DETERIORATING - END	Cat 3	12-Mar-2012
BETWEEN DUNN ST TO SWANSTON ST CARRIAGEWAY UNDER CONSTRUCTION				
LA13698-2	CARRIAGEWAY	AMBER - CONDITION DETERIORATING - END	Cat 3	12-Mar-2012
BETWEEN BIRKWOOD ST & BRIDGE CARRIAGEWAY UNDER CONSTRUCTION				

Reference	Asset	Report	Defect Category	Date Recorded
03_HP_06				
Safety Inspection - HP Footways of 03_HP_06 Calton E Centre ped route 6 - Bridgeton on 19 April 2012				
Dalmarnock Road				
LA13880-1	FOOTWAY	POTHLES	Cat 2 Low	19-Apr-2012
BUILDING NO 60 (BESIDE MEGAN ST VERIOUS 300MM\300MM POTHLES (BESIDE KERB				

Reference	Asset	Report	Defect Category	Date Recorded
11_015				
Safety Inspection - Statagic of 11_015 A749 - Dalmarnock Rd on 04 April 2012				
Dalmarnock Road				
LA13948-1	CARRIAGEWAY	POTHLES	Remote/ Non Perm Harm < 1m	04-Apr-2012
DALMARNOCK RD \ BIRKWOOD ST THREE 400MM\400MM POTHLES (BETWEEN FW				
LA13948-2	CARRIAGEWAY	POTHLES	Remote/ Non Perm Harm < 1m	04-Apr-2012
BUS STOP (BESIDE ESSO GARAGE 500MM\500MM POTHOLE (BUS STOP				

Reference	Asset	Report	Defect Category	Date Recorded
03_HP_05				
Safety Inspection - HP Footways of 03_HP_05 Calton E Centre ped route 5 - Dalmarnock on 22 May 2012				
Dalmarnock Road				
SK14117-7	FOOTWAY	GREEN - CONDITION GOOD	Cat 3	22-May-2012
21m from 367 Dalmarnock Road				

Reference	Asset	Report	Defect Category	Date Recorded
03_HP_06				
Safety Inspection - HP Footways of 03_HP_06 Calton E Centre ped route 6 - Bridgeton on 22 May 2012				
Dalmarnock Road				
SK14118-10	FOOTWAY	GREEN - CONDITION GOOD	Cat 3	22-May-2012
8m from 14 Dalmarnock Road				

Reference	Asset	Report	Defect Category	Date Recorded
11_015				
Safety Inspection - Statagic of 11_015 A749 - Dalmarnock Rd on 10 May 2012				
Dalmarnock Road				
LA14168-1	KERB	DAMAGE - NO IMMEDIATE DANGER	Cat 2 Low	10-May-2012
DALMARNOCK RD & SPRINGFIELD RD DISLODGED CORNER STONE (TRAFFIC LIGHTS)				
LA14168-2	CARRIAGEWAY	POTHLES	Remote/ Semi Perm Harm < 1yr	10-May-2012
BETWEEN ESSO GARAGE & SRINGFIELD RD 600MM\500MM POTHOLE (BUS STOP (COLUMN R35				
LA14168-3	CARRIAGEWAY	GREEN - CONDITION GOOD	Cat 3	10-May-2012
15m from 274 Dalmarnock Road CARRIAGEWAY & FOOTWAY REASONABLY GOOD CONDITION				

Reference	Asset	Report	Defect Category	Date Recorded
03_LR_02				
Safety Inspection -3 Month of 03_LR_02 Calton E Ctre link route 2 - Bridgeton on 15 May 2012				
Dalmarnock Road				
SK14311-13	CARRIAGEWAY	POTHLES	Liikely / No Obvious Harm	16-May-2012
OPPOSITE FLAT NUMBER 206 VARIOUS POTHLES				
SK14311-14	CARRIAGEWAY	INSPECTION AREA OBSCURED BY SKIP/SCAFFOLD/UTILITY	Cat 3	16-May-2012
46m from 3 Birkwood Street SECTION BETWEEN NUNEATON STREET AND BIRKOD STREET JUNCTIONS NOT INSPECTED AS COVERED BY OTHER MONTHLY "11" ROUTE				
SK14311-15	FOOTWAY	GREEN - CONDITION GOOD	Cat 3	16-May-2012
27m from 257 Dalmarnock Road				
SK14311-16	CARRIAGEWAY	GREEN - CONDITION GOOD	Cat 3	16-May-2012
28m from 257 Dalmarnock Road				

Reference	Asset	Report	Defect Category	Date Recorded
03_HP_06				
Safety Inspection - HP Footways of 03_HP_06 Calton E Centre ped route 6 - Bridgeton on 09 July 2012				
Dalmarnock Road				
SK14552-5	FOOTWAY	GREEN - CONDITION GOOD	Cat 3	09-Jul-2012
7m from 35 Dalmarnock Road				

Reference	Asset	Report	Defect Category	Date Recorded
11_015				
Safety Inspection - Statagic of 11_015 A749 - Dalmarnock Rd on 27 July 2012				
Dalmarnock Road				
SK14666-1	FOOTWAY	POLE REMAINS	Cat 2 Low	27-Jul-2012
AT JUNCTION WITH BARTHOLOMEW STREET				
SK14666-2	FOOTWAY	TREE OVERHANGING GCC	Cat 2 Low	27-Jul-2012
AT COLUMN R40 20M NORTH OF JUNCTION WITH SUMMERFIELD STREET				
SK14666-3	FOOTWAY	GREEN - CONDITION GOOD	Cat 3	27-Jul-2012
32m from 819 Dalmarnock Road				
SK14666-4	CARRIAGEWAY	GREEN - CONDITION GOOD	Cat 3	27-Jul-2012
20m from 819 Dalmarnock Road				

Reference	Asset	Report	Defect Category	Date Recorded
03_HP_05				
Safety Inspection - HP Footways of 03_HP_05 Calton E Centre ped route 5 - Dalmarnock on 03 September 2012				
Dalmarnock Road				
SH14867-10	FOOTWAY	INSPECTION AREA OBSCURED BY SKIP/SCAFFOLD/UTILITY	Cat 3	04-Sep-2012
25m from 367 Dalmarnock Road INSPECTION RESTRECTED DUE TO WORKS				

Reference	Asset	Report	Defect Category	Date Recorded
03_HP_06				
Safety Inspection - HP Footways of 03_HP_06 Calton E Centre ped route 6 - Bridgeton on 04 September 2012				
Dalmarnock Road				
SH14868-18	FOOTWAY	POTHLES	Cat 2 Low	04-Sep-2012
AT 60 AREA NEXT TO KERB POTTED OVER A 5 M LENGTH				
SH14868-19	FOOTWAY	POTHLES	Cat 2 Low	04-Sep-2012
AT 7 M WEST OF 60 AREA SUNKEN ROUND 2 TOBY FITTMENTS				
SH14868-23	FOOTWAY	POTHLES	Cat 2 Low	04-Sep-2012
AT COL R 2 200MM X 1 M AREA OF GRANO SURFACE BROKEN/PART MISSING				
SH14868-24	FOOTWAY	GREEN - CONDITION GOOD	Cat 3	04-Sep-2012
10m from 21 Dalmarnock Road				

Reference	Asset	Report	Defect Category	Date Recorded
03_LR_02				
Safety Inspection -3 Month of 03_LR_02 Calton E Ctre link route 2 - Bridgeton on 24 August 2012				
Dalmarnock Road				
SH14875-1	CARRIAGEWAY	INSPECTION AREA OBSCURED BY SKIP/SCAFFOLD/UTILITY	Cat 3	24-Aug-2012
AREA FROM DUNN ST TO BRIDGE OVER RIVER NOT INSPECTED AS THIS IS DONE ON ROUT NO 11 15				
SH14875-2	ROAD MARKING	WORN OR STRIPPING	Cat 3	24-Aug-2012
AT 93 SCHOOL ZONE				
SH14875-3	FOOTWAY	POTHoles	Cat 2 Low	24-Aug-2012
AT 60 3 M X100MM AREA NEXT TO KERB POTTED				
SH14875-4	FOOTWAY	POTHoles	Cat 2 Low	24-Aug-2012
AT 5 M WEST OF 60 AREA ROUND 2 TOBYS NEEDING LEVELLED OFF				
SH14875-21	FOOTWAY	POTHoles	Cat 2 Low	24-Aug-2012
AT COL R 2 /AT SHOPSMART 100MM X 700MM AREA OF GRANO SURFACE POTTED				
SH14875-22	KERB	DAMAGE - NO IMMEDIATE DANGER	Cat 2 Low	24-Aug-2012
AT 8 M WEST OF 93 SECTION OF KERB MISSING AND SECTION DISLODGED				
SH14875-23	FOOTWAY	SUBSIDENCE	Cat 1a - Fast Track	24-Aug-2012
AT 141 200MM X 200MM HOLE ON F/WAY /CONE ALREADY ON IT				
SH14875-24	ROAD MARKING	WORN OR STRIPPING	Cat 3	24-Aug-2012
AT 189 MARKINGS AT PED LIGHTS				
SH14875-25	ROAD MARKING	WORN OR STRIPPING	Cat 3	24-Aug-2012
AT DUNN ST MARKING AT TRAFFIC LIGHTS				
SH14875-26	ROAD MARKING	WORN OR STRIPPING	Cat 3	24-Aug-2012
AT 104 SCHOOL ZONE				
SH14875-27	TRAFFIC SIGNS	RE-ORIENTATE	Cat 3	24-Aug-2012
AT 100 PATROL SIGN				
SH14875-28	CARRIAGEWAY	POTHoles	Possible / No Obvious Harm	24-Aug-2012
AT 15 M NORTH OF 100 1 M X 200MM AREA PUSHED AND RAISED AT BUS STOP				

Reference	Asset	Report	Defect Category	Date Recorded
SH14875-29	CARRIAGEWAY	GREEN - CONDITION GOOD	Cat 3	24-Aug-2012
23m from 5 Old Dalmarnock Road				
SH14875-30	FOOTWAY	GREEN - CONDITION GOOD	Cat 3	24-Aug-2012
28m from 129 Dalmarnock Road				

Reference	Asset	Report	Defect Category	Date Recorded
11_015				
Safety Inspection - Statagic of 11_015 A749 - Dalmarnock Rd on 20 August 2012				
Dalmarnock Road				
LA14939-1	CARRIAGEWAY	POTHLES	Remote/ Non Perm Harm < 1m	20-Aug-2012
BUS STOP (BESIDE ESSO GARAGE 300MM\300MM POTHOLE				
LA14939-2	CARRIAGEWAY	GREEN - CONDITION GOOD	Cat 3	20-Aug-2012
13m from 558 Dalmarnock Road CARRIAGEWAY & FOOTWAY REASONABLY GOOD CONDITION				

Reference	Asset	Report	Defect Category	Date Recorded
11_015				
Safety Inspection - Statagic of 11_015 A749 - Dalmarnock Rd on 24 October 2012				
Dalmarnock Road				
SA15077-1	CARRIAGEWAY	POTHLES (40mm-100mm)	?	24-Oct-2012
JUNCTION DUNN ST POTHLES				
SA15077-2	CARRIAGEWAY	OPEN JOINTS	Unlikely / Non Perm Harm < 1m	24-Oct-2012
FROM DUNN ST TO NEW JUNCTION NO POLE NUMBERS POTHLES				
SA15077-3	CARRIAGEWAY	POTHLES (40mm-100mm)	?	24-Oct-2012
BUS STOP BEFORE SPRINGFIELD RD HEADING OUT OF CITY POTHLES				
SA15077-4	IRONWORK	DAMAGE - NO IMMEDIATE DANGER	Cat 3	24-Oct-2012
NO 14 LOW IRONWORK				
SA15077-5	CARRIAGEWAY	POTHLES	Unlikely / Semi Perm Harm <1yr	24-Oct-2012
JUNCTION SUMMERFIELD ST POTHLES				
SA15077-6	CARRIAGEWAY	POTHLES (40mm-100mm)	?	24-Oct-2012
ACROSS FROM NO 799 POTHOLE @ IRONWORK				
SA15077-7	CARRIAGEWAY	POTHLES	Unlikely / Non Perm Harm < 1m	24-Oct-2012
ACROSS FROM 779 POTHLES @ BUS STOP				
SA15077-8	CARRIAGEWAY	POTHLES (40mm-100mm)	?	24-Oct-2012
JUNCTION SPRINGFIELD RD POTHOLE AT TRAFFIC LIGHTS				
SA15077-9	CARRIAGEWAY	POTHLES (40mm-100mm)	?	24-Oct-2012
JUNCTION SPRINGFIELD RD POTHLES				

Reference	Asset	Report	Defect Category	Date Recorded
03_HP_05				
Safety Inspection - HP Footways of 03_HP_05 Calton E Centre ped route 5 - Dalmarnock on 22 October 2012				
Dalmarnock Road				
SH15151-6	FOOTWAY	INSPECTION AREA OBSCURED BY SKIP/SCAFFOLD/UTILITY	Cat 3	22-Oct-2012
25m from 367 Dalmarnock Road F/WAY SHUT OFF DUE TO WORKS				

Reference	Asset	Report	Defect Category	Date Recorded
03_HP_06				
Safety Inspection - HP Footways of 03_HP_06 Calton E Centre ped route 6 - Bridgeton on 23 October 2012				
Dalmarnock Road				
SH15152-1	FOOTWAY	POTHLES	Cat 2 Low	23-Oct-2012
AT 6 M WEST OF 60 SUNKEN AREA ROUND 2 TOBY FITMENTS				
SH15152-2	FOOTWAY	POTHLES	Cat 2 Low	23-Oct-2012
AT 60 POTTED AREA NEXT TO KERB OVER A 6 M LENGTH				
SH15152-3	FOOTWAY	POTHLES	Cat 2 High	23-Oct-2012
AT COL R 2 /AT SHOPSMART 1.5 M X 300MM AREA OF GRANO SURFACE POTTED/BROKEN				
SH15152-4	FOOTWAY	INSPECTION AREA OBSCURED BY SKIP/SCAFFOLD/UTILITY	Cat 3	23-Oct-2012
FROM 23 TO 47 VARIOUS SECTIONS OF F/WAY COVERED DUE TO WORKS				
SH15152-5	FOOTWAY	GREEN - CONDITION GOOD	Cat 3	23-Oct-2012
8m from 32 Dalmarnock Road				

Reference	Asset	Report	Defect Category	Date Recorded
11_015				
Safety Inspection - Statagic of 11_015 A749 - Dalmarnock Rd on 29 November 2012				
Dalmarnock Road				
LT115250-1	CARRIAGEWAY	POTHOLES	Remote/ Non Perm Harm < 1m	29-Nov-2012
DALMARNOCK RD & DUNN ST 500MM\500MM & 400MM\400MM POTHOLES (TRAFFIC LIGHTS)				
LT115250-2	CARRIAGEWAY	POTHOLES	Remote/ Non Perm Harm < 1m	29-Nov-2012
OP SPRINGFIELD RD (BESIDE TRAFFIC LIGHTS 500MM\500MM POTHOLE (BESIDE MANHOLE COVER)				
LT115250-3	CARRIAGEWAY	POTHOLES	Remote/ Non Perm Harm < 1m	29-Nov-2012
OP SRINGFIELD RD (COLUMN R36 BESIDE PED CROSSING 500MM\500MM POTHOLE (BESIDE TRAFFIC LIGHTS)				
LT115250-4	CARRIAGEWAY	POTHOLES	Remote/ Non Perm Harm < 1m	29-Nov-2012
BUILDING NO783 (OP BIRKWOOD ST 300MM\300MM POTHOLE (BESIDE PED CROSSING)				
LT115250-5	FOOTWAY	POTHOLES	Cat 2 Low	29-Nov-2012
BESIDE BARTHOLOMEW ST 200MM\200MM POTHOLE (BESIDE BUS STOP)				
LT115250-6	FOOTWAY	POLE REMAINS	Cat 2 Low	29-Nov-2012
ENT BARTHLOMEW ST REMOVE 50MM POLE BASE				

Reference	Asset	Report	Defect Category	Date Recorded
03_HP_06				
Safety Inspection - HP Footways of 03_HP_06 Calton E Centre ped route 6 - Bridgeton on 20 November 2012				
Dalmarnock Road				
LT115381-2	FOOTWAY	POTHLES	Cat 2 Low	20-Nov-2012
NO49 SHOP SMART STORE TWO 1M\400MM POTHOLE				
LT115381-3	FOOTWAY	POTHLES	Cat 2 Low	20-Nov-2012
BUILDING NO60 VERIOUS 300MM\300MM POTHLES (BESIDE KERB				

Reference	Asset	Report	Defect Category	Date Recorded
-----------	-------	--------	-----------------	---------------