

Effective: 01/11/2015 to 29/02/2016
Street: Ardingly Road (25600147)

Display Action Officer: Yes

Street: Ardingly Road (25600147)

Locality: West Hoathly Ward, West Hoathly, West Sussex

Area: WEST HOATHLY

Customer Services

Service: Love West Sussex	Logged by: Love Clean Streets	on: 10/02/2016 11:03	Officer: Mid-Sussex Pothole Stack
Desc.: Large pithole	Subject: Pothole	Classification: Request for service	
Extra information supplied by the user Which of the following best describes the location? : Driving lane The width of the pothole is best descr bed as being similar to... : A dinner plate (15-30cm/6-12") The depth of the pothole is similar to... : A can of beans or larger (more than 10cm/4")			
Location: Ardingly Road, West Hoathly, RH19 4	Contact:		
Service: Carriageway	Logged by: Contact Centre	on: 09/02/2016 12:05	Officer: Mid-Sussex Pothole Stack
Desc.: Heavy vehicle impact, (15-30cm/6-12ins)	Subject: Potholes	Classification: Request for service	#DEEP : 2. Up to TENNIS BALL (4-10 cm) #WIDE : 2. Up to DINNER PLATE size
Location: n/b just south of West Lodge leading to Stonelands.	Contact:		
Plot Number: 9,999.00	Feature Id - Location:	Feature Type: Whole Street Feature	
Service: Love West Sussex	Logged by: Love Clean Streets	on: 08/02/2016 20:38	Officer: Clive Buckler(HS-Mid Sussex)
Desc.: Pothole near of road	Subject: Pothole	Classification: Request for service	
Extra information supplied by the user Which of the following best describes the location? : Driving lane The width of the pothole is best descr bed as being similar to... : A car tyre (30-60cm/12-24") The depth of the pothole is similar to... : A can of beans or larger (more than 10cm/4")			
Location: Ardingly Road, West Hoathly, RH19 4	Contact:		
Service: Carriageway	Logged by: Contact Centre	on: 08/02/2016 15:47	Officer: Mid-Sussex Pothole Stack
Desc.: Pothole has already been filled	Subject: Potholes	Classification: Request for service	#DEEP : 2. Up to TENNIS BALL (4-10 cm) #WIDE : 2. Up to DINNER PLATE size (15-30cm/6-12ins)
Location: On the Ardingly Road 200 yards before selsfield common.	Contact:		
Service: Love West Sussex	Logged by: Love Clean Streets	on: 06/02/2016 09:10	Officer: Clive Buckler(HS-Mid Sussex)
Desc.: Previously reported	Subject: Pothole	Classification: Request for service	The work has not been completed, it has not even been
touched and the pot hole is getting deeper.			
Pot hole following left bend, very hard to miss with on coming traffic. Just prior to the Selsfield Road junction.			
Extra information supplied by the user Which of the following best describes the location? : Driving lane The width of the pothole is best descr bed as being similar to... : A dinner plate (15-30cm/6-12") The depth of the pothole is similar to... : A can of beans or larger (more than 10cm/4")			
Location: Ardingly Road, West Hoathly, RH19 4	Contact:		
Service: Love West Sussex	Logged by: Love Clean Streets	on: 05/02/2016 11:27	Officer: Clive Buckler(HS-Mid Sussex)
Desc.: Northbound carriageway on the passenger side - a pothole appeared over a week ago and is gradually getting bigger and bigger by the day. It is opposite a previously repaired pothole on the other side of the road. Traffic has to swerve into the opposite carriageway to avoid it.	Subject: Pothole	Classification: Request for service	
Extra information supplied by the user Which of the following best describes the location? : Driving lane The width of the pothole is best descr bed as being similar to... : A car tyre (30-60cm/12-24") The depth of the pothole is similar to... : A can of beans or larger (more than 10cm/4")			
Location: Ardingly Road, West Hoathly, RH19 4	Contact:		

Effective: 01/11/2015 to 29/02/2016
 Street: Ardingly Road (25600147)

Display Action Officer: Yes

Customer Services

		Logged by: Love Clean Streets	on: 05/02/2016 08:43	Officer: Mid-Sussex Pothole Stack
Service:	Love West Sussex	Subject: Pothole	Classification: Request for service	
Desc.:	Road repair has sunk. you need to drive on the wrong side of the road to avoid hole. This is northbound towards Turners Hill and almost opposite traffic code on side of road. Extra information supplied by the user Which of the following best describes the location? : Driving lane The width of the pothole is best descr bed as being similar to... : A car tyre (30-60cm/12-24") The depth of the pothole is similar to... : A can of beans or larger (more than 10cm/4")			
Location:	Ardingly Road, West Hoathly, RH19 4		Contact:	
		Logged by: Love Clean Streets	on: 05/02/2016 08:00	Officer: Mid-Sussex Pothole Stack
Service:	Love West Sussex	Subject: Pothole	Classification: Request for service	
Desc.:	The only way to avoid the pothole is to swerve into on coming traffic Extra information supplied by the user Which of the following best describes the location? : Please select The width of the pothole is best descr bed as being similar to... : A dinner plate (15-30cm/6-12") The depth of the pothole is similar to... : A can of beans or larger (more than 10cm/4")			
Location:	Ardingly Road, West Hoathly, RH19 4		Contact:	
		Logged by: Love Clean Streets	on: 04/02/2016 09:24	Officer: Mid-Sussex Pothole Stack
Service:	Love West Sussex	Subject: Pothole	Classification: Request for service	
Desc.:	This is a large & fairly deep pothole on the Ardingly Road coming from Ardingly on the left hand sidenot far before the turning left into Selsfield Road. It is impossible to avoid without going onto the other side of the road which is very DANGEROUS due to oncoming traffic. Extra information supplied by the user Which of the following best describes the location? : Driving lane The width of the pothole is best descr bed as being similar to... : A car tyre (30-60cm/12-24") The depth of the pothole is similar to... : A can of beans or larger (more than 10cm/4")			
Location:	Ardingly Road, West Hoathly, RH19 4		Contact:	
Plot Number:	9,999.00	Feature Id - Location:	Feature Type: Whole Street Feature	
		Logged by: Love Clean Streets	on: 03/02/2016 16:38	Officer: Mid-Sussex Pothole Stack
Service:	Love West Sussex	Subject: Pothole	Classification: Request for service	
Desc.:	hole is on the side of the Ardingly Road when heading from Ardingly towards Turners Hill, approx. 300 yds before the junction with Selsfield Road. It is from the kerbside, but extends across the driving lane so that it cannot be avoided unless crossing into the opposite lane Extra information supplied by the user Which of the following best describes the location? : Driving lane The width of the pothole is best descr bed as being similar to... : A car tyre (30-60cm/12-24") The depth of the pothole is similar to... : A can of beans or larger (more than 10cm/4")			
Location:	Ardingly Road, West Hoathly, RH19 4		Contact:	
		Logged by: Contact Centre	on: 03/02/2016 09:38	Officer: Balfour Beatty Living Places
Service:	Carriageway	Subject: Potholes	Classification: Request for service	
Desc.:	it is on the left hand side of the road, looks as if it has already been reported however there are lots of building materials on the side of the road opposite the pot hole, #DEEP : 2. Up to TENNIS BALL (4-10 cm) #WIDE : 2. Up to DINNER PLATE size (15-30cm/6-12ins)			
Location:	100 meters up form the pub.		Contact:	

Effective: 01/11/2015 to 29/02/2016
Street: Ardingly Road (25600147)

Display Action Officer: Yes

Customer Services

<p>Service: Love West Sussex</p> <p>Desc.: There is a very large pothole on the road heading from Ardingly to Turners Hill which is exactly in the driving position, cars are now swerving to avoid it. Extra information supplied by the user Which of the following best describes the location? : Driving lane The width of the pothole is best descr bed as being similar to... : A dinner plate (15-30cm/6-12") The depth of the pothole is similar to... : A tennis ball (4-10cm/1.5-4")</p> <p>Location: Ardingly Road, turners hill</p>	<p>Logged by: Love Clean Streets</p> <p>Subject: Pothole</p>	<p>on: 03/02/2016 08:41</p> <p>Classification: Request for service</p>	<p>Officer: Mid-Sussex Pothole Stack</p>
Plot Number: .50	Feature Id - Location: B2028/10110	Feature Type: Single 2-Lane Carriageway	
<p>Service: Love West Sussex</p> <p>Desc.: This is dangerous! There is a very deep pothole (6 inches) in the Northbound carriageway of the B2028 South of Selsfield. The damage is about 100 metres South of the "Slow" sign that is painted on the road South of the turning going to Turners Hill. It is as a direct result of very poor reinstatement after works on a road opening. [REDACTED] It is impossible to see the damage as you approach, but it is clear where it is from 2 manhole covers in the verge, and a gap in the fence where something has been dug or moledrained through from the adjoining field. Extra information supplied by the user Which of the following best describes the location? : Driving lane The width of the pothole is best descr bed as being similar to... : A car tyre (30-60cm/12-24") The depth of the pothole is similar to... : A can of beans or larger (more than 10cm/4")</p> <p>Location: Ardingly Road, West Hoathly, RH19 4</p>	<p>Logged by: Love Clean Streets</p> <p>Subject: Pothole</p>	<p>on: 02/02/2016 09:50</p> <p>Classification: Request for service</p>	<p>Officer: Clive Buckler(HS-Mid Sussex)</p>
<p>Service: Love West Sussex</p> <p>Desc.: North bound side, near vertical edge facing south I kely to cause damage to tyres/suspension Extra information supplied by the user Which of the following best describes the location? : Kerbside The width of the pothole is best descr bed as being similar to... : A dinner plate (15-30cm/6-12") The depth of the pothole is similar to... : A can of beans or larger (more than 10cm/4")</p> <p>Location: Ardingly Road, West Hoathly, RH19 4</p>	<p>Logged by: Love Clean Streets</p> <p>Subject: Pothole</p>	<p>on: 01/02/2016 14:22</p> <p>Classification: Request for service</p>	<p>Officer: Clive Buckler(HS-Mid Sussex)</p>
<p>Service: Love West Sussex</p> <p>Desc.: [REDACTED] massive pothole [REDACTED] Extra information supplied by the user Which of the following best describes the location? : Centre of road The width of the pothole is best descr bed as being similar to... : A car tyre (30-60cm/12-24") The depth of the pothole is similar to... : A can of beans or larger (more than 10cm/4")</p> <p>Location: Ardingly Road, West Hoathly, RH19 4</p>	<p>Logged by: Love Clean Streets</p> <p>Subject: Pothole</p>	<p>on: 31/01/2016 18:37</p> <p>Classification: Request for service</p>	<p>Officer: Clive Buckler(HS-Mid Sussex)</p>
<p>Service: Carriageway</p> <p>Desc.: # #DEEP : 2. Up to TENNIS BALL (4-10 cm) #WIDE : 2. Up to DINNER PLATE size (15-30cm/6-12ins)</p> <p>Location: [REDACTED] . pothole was repaired few days later.</p>	<p>Logged by: Contact Centre</p> <p>Subject: Potholes</p>	<p>on: 29/01/2016 15:43</p> <p>Classification: Request for service</p>	<p>Officer: Clive Buckler(HS-Mid Sussex)</p>

Effective: 01/11/2015 to 29/02/2016

Display Action Officer: Yes

Street: Ardingly Road (25600147)

Customer Services

Service: Emergency Desc.: 2-3 ft long Location: near to yew tree cottages	Logged by: Contact Centre Subject: Pothole #DEEP : 3. Larger than TIN OF BEANS (over 10 cm) #WIDE : 4. Larger than CAR TYRE (60cm/24ins)	on: 28/01/2016 11:05 Classification: Request for service Contact:	Officer: Mid-Sussex Pothole Stack
Service: Carriageway Desc.: Location:	Logged by: Contact Centre Subject: Potholes #DEEP : 2. Up to TENNIS BALL (4-10 cm) #WIDE : 2. Up to DINNER PLATE size (15-30cm/6-12ins)	on: 28/01/2016 10:15 Classification: Request for service Contact:	Officer: Mid-Sussex Pothole Stack
Service: Carriageway Desc.: big pothole Location: about half a mile turning off down this road. before you get to the white hart.	Logged by: Contact Centre Subject: Potholes #DEEP : 2. Up to TENNIS BALL (4-10 cm) #WIDE : 3. Up to CAR TYRE size(30-60cm/12-24ins)	on: 28/01/2016 09:06 Classification: Request for service Contact:	Officer: Mid-Sussex Pothole Stack
Service: Love West Sussex Desc.: Large pothole on southbound side of road might cause damage to vehicles Extra information supplied by the user Which of the following best describes the location? : Driving lane The width of the pothole is best descr bed as being similar to... : A car tyre (30-60cm/12-24") The depth of the pothole is similar to... : A tennis ball (4-10cm/1.5-4")	Logged by: Love Clean Streets Subject: Pothole	on: 27/01/2016 22:11 Classification: Request for service Contact:	Officer: Mid-Sussex Pothole Stack

Display Action Officer: Yes

Service: Love West Sussex
Subject: Pothole
Classification: Request for service
Desc.: [REDACTED] a large and deep pothole (about 2ft long by 1ft wide and 4 inches deep) which was located on Ardingly Road, coming from Turners Hill direction, just past the Selsfield Road junction and on the approach to a large house on the left.
[REDACTED]
[REDACTED]
[REDACTED]
[REDACTED]
[REDACTED]
[REDACTED]
[REDACTED]
[REDACTED]
Extra information supplied by the user Which of the following best describes the location? : Driving lane
The width of the pothole is best descr bed as being similar to... : A car tyre (30-60cm/12-24")
The depth of the pothole is similar to... : A can of beans or larger (more than 10cm/4")

Location: Ardingly Road, West Hoathly, RH19 4

Contact:

Service: Love West Sussex **Subject:** Pothole **Classification:** Request for service **Officer:** Mid-Sussex Pothole Stack

Desc.: A massive pot hole on the south heading carriageway on the B2028 south of Turners Hill towards Ardingly, approx. 1metre in length, app 0.8mtr in width and app 6inches deep, [REDACTED]

[REDACTED]

Extra information supplied by the user Which of the following best describes the location? : Driving lane
The width of the pothole is best descr bed as being similar to... : A car tyre (30-60cm/12-24")
The depth of the pothole is similar to... : A can of beans or larger (more than 10cm/4")

Location: Ardingly Road, West Hoathly, RH19 4 **Contact:**

Location: Ardingly Road, West Hoathly, RH19 4

Contact:

Service:	Love West Sussex	Logged by:	Love Clean Streets	on:	27/01/2016 20:21	Officer:	Mid-Sussex Pothole Stack
Desc.:	Deep pothole likely to cause damage to car wheels northbound Extra information supplied by the user Which of the following best describes the location? : Driving lane The width of the pothole is best descr bed as being similar to... : A car tyre (30-60cm/12-24") The depth of the pothole is similar to... : A can of beans or larger (more than 10cm/4")						
Location:	Ardingly Road, West Hoathly, RH19 4			Contact:			

Location: Ardingly Road, West Hoathly, RH19 4

Contact:

Effective: 01/11/2015 to 29/02/2016
Street: Ardingly Road (25600147)

Display Action Officer: Yes

Customer Services

Service: Love West Sussex	Logged by: Love Clean Streets	on: 27/01/2016 20:06	Officer: Mid-Sussex Pothole Stack
Subject: Pothole	Classification: Request for service		
Desc.: Not sure if this just a pothole or a collapsed drain but it has a vertical face to it when you drive over it which will undoubtedly cause damage to cars Extra information supplied by the user Which of the following best describes the location? : Driving lane The width of the pothole is best descr bed as being similar to... : A car tyre (30-60cm/12-24") The depth of the pothole is similar to... : A tennis ball (4-10cm/1.5-4")			
Location: Ardingly Road, West Hoathly, RH19 4	Contact:		
Service: Love West Sussex	Logged by: Love Clean Streets	on: 25/01/2016 19:46	Officer: Mid-Sussex Pothole Stack
Subject: Pothole	Classification: Request for service		
Desc.: A trench/pothole on the left hand side of the road driving North about 100 metres South of the "slow" sign. Looks like work has previously been carried out Extra information supplied by the user Which of the following best describes the location? : Driving lane The width of the pothole is best descr bed as being similar to... : A car tyre (30-60cm/12-24") The depth of the pothole is similar to... : A tennis ball (4-10cm/1.5-4")			
Location: Ardingly Road, West Hoathly, RH19 4	Contact:		
Service: Love West Sussex	Logged by: Love Clean Streets	on: 25/01/2016 18:48	Officer: Clive Buckler(HS-Mid Sussex)
Subject: Pothole	Classification: Request for service		
Desc.: road subsided in area of previous water works repair, very sharp edges Extra information supplied by the user Which of the following best describes the location? : Driving lane The width of the pothole is best descr bed as being similar to... : A dinner plate (15-30cm/6-12") The depth of the pothole is similar to... : A tennis ball (4-10cm/1.5-4")			
Location: Ardingly Road, West Hoathly, RH19 4	Contact:		
Service: Love West Sussex	Logged by: Love Clean Streets	on: 24/01/2016 16:15	Officer: Mid-Sussex Pothole Stack
Subject: Pothole	Classification: Request for service		
Desc.: Pot hole following left bend, very hard to miss with on coming traffic. Just prior to the Selsfield Road junction. Extra information supplied by the user Which of the following best describes the location? : Driving lane The width of the pothole is best descr bed as being similar to... : A dinner plate (15-30cm/6-12") The depth of the pothole is similar to... : A can of beans or larger (more than 10cm/4")			
Location: Ardingly Road, West Hoathly, RH19 4	Contact:		
Plot Number: 9,999.00	Feature Id - Location:	Feature Type: Whole Street Feature	
Service: Carriageway	Logged by: Contact Centre	on: 22/01/2016 11:34	Officer: Mid-Sussex Pothole Stack
Subject: Potholes	Classification: Request for service		
Desc.: POTHOLE #DEEP : 2. Up to TENNIS BALL (4-10 cm) #WIDE : 3. Up to CAR TYRE size(30-60cm/12-24ins)			
Location: About 400 yards south of the T junction	Contact:		
Service: Carriageway	Logged by: Contact Centre	on: 11/01/2016 14:09	Officer: Mid-Sussex Pothole Stack
Subject: Potholes	Classification: Request for service		
Desc.: pothole it was reapirod on the 8th jan and has now broken out again please can we get this repaired. #DEEP : 2. Up to TENNIS BALL (4-10 cm) #WIDE : 2. Up to DINNER PLATE size (15-30cm/6-12ins)			
Location: between Cleveland cottages and Yew tree cottages approx position	Contact:		
Plot Number: 9,999.00	Feature Id - Location:	Feature Type: Whole Street Feature	

Effective: 01/11/2015 to 29/02/2016
Street: Ardingly Road (25600147)

Display Action Officer: Yes

Customer Services

<p>Service: Carriageway Desc.: This pothole has already been reported due to be repaired on or before 13th January 2016. OVRD : Already on job list for repair on or before 13th January 2016 #DEEP : 3. Larger than TIN OF BEANS (over 10 cm) #WIDE : 2. Up to DINNER PLATE size (15-30cm/6-12ins) Location: Just south of the junction with Selsfield Road before Wakehurst Place travelling South from Junction.</p>	<p>Logged by: Contact Centre Subject: Potholes</p>	<p>on: 11/01/2016 10:34 Classification: Request for service</p>	<p>Officer: Mid-Sussex Pothole Stack</p>
<p>Service: Love West Sussex Desc.: very large pothole very dangerous, increasing debris field around it with large stones etc, was previously marked for repair but has deteriorated badly. photo imposs ble to busy Extra information supplied by the user Which of the following best describes the location? : Driving lane The width of the pothole is best descr bed as being similar to... : A car tyre (30-60cm/12-24") The depth of the pothole is similar to... : A tennis ball (4-10cm/1.5-4") Location: Ardingly Road, West Hoathly, RH19 4</p>	<p>Logged by: Love Clean Streets Subject: Pothole</p>	<p>on: 09/01/2016 21:47 Classification: Request for service</p>	<p>Officer: Crawley Pothole Stack</p>
<p>Service: Carriageway Desc.: Heavy vehicle impact to DINNER PLATE size (15-30cm/6-12ins) Location: approve 200-300 yards south of Selsfield Road junction. Submitting photograph.</p>	<p>Logged by: Contact Centre Subject: Potholes</p>	<p>on: 08/01/2016 09:46 Classification: Request for service</p>	<p>Officer: Mid-Sussex Pothole Stack</p>
<p>Service: Love West Sussex Desc.: Going South, less than two miles, after turning left from Selsfield Road onto Ardingly Road, there is a pothole or a manhole without cover on the left side of the driving lane. Extra information supplied by the user Which of the following best describes the location? : Driving lane The width of the pothole is best descr bed as being similar to... : A car tyre (30-60cm/12-24") The depth of the pothole is similar to... : A can of beans or larger (more than 10cm/4") Location: Ardingly Road, West Hoathly, RH19 4</p>	<p>Logged by: Love Clean Streets Subject: Pothole</p>	<p>on: 07/01/2016 23:43 Classification: Request for service</p>	<p>Officer: Clive Buckler(HS-Mid Sussex)</p>
<p>Service: Love West Sussex Desc.: There is a large, deep pothole on the B2028 Ardingly Road heading south towards Ardingly Village. It is approximately 400m after the junction with Selsfield Road and approx 400m before the old White Hart Pub which has recently been renovated into houses. Due to the position of the pothole and oncoming traffic it is quite difficult to avoid Extra information supplied by the user Which of the following best describes the location? : Driving lane The width of the pothole is best descr bed as being similar to... : A car tyre (30-60cm/12-24") The depth of the pothole is similar to... : A can of beans or larger (more than 10cm/4") Location: Ardingly Road, West Hoathly, RH19 4</p>	<p>Logged by: Love Clean Streets Subject: Pothole</p>	<p>on: 07/01/2016 19:42 Classification: Request for service</p>	<p>Officer: Mid-Sussex Pothole Stack</p>

Plot Number: 9,999.00

Feature Id - Location:

Feature Type: Whole Street Feature

Effective: 01/11/2015 to 29/02/2016
Street: Ardingly Road (25600147)

Display Action Officer: Yes

Customer Services

Service: Love West Sussex	Logged by: Love Clean Streets	on: 06/01/2016 22:37	Officer: Mid-Sussex Pothole Stack
Subject: Pothole	Classification: Request for service		
Desc.: Pothole on Northbound lane towards Turners Hill before turning to Wych Cross. There are no landmarks to be able to pinpoint the exact location but the hole appears to stretch horizontally across the driving lane and is not easy to avoid without driving on wrong side of road Extra information supplied by the user Which of the following best describes the location? : Driving lane The width of the pothole is best descr bed as being similar to... : A car tyre (30-60cm/12-24") The depth of the pothole is similar to... : A can of beans or larger (more than 10cm/4")			
Location: Ardingly Road, West Hoathly, RH19 4	Contact:		
Plot Number: 9,999.00	Feature Id - Location:	Feature Type: Whole Street Feature	
Enquiry No.: 2083215	Logged by: Love Clean Streets	on: 06/01/2016 16:26	Officer: Mid-Sussex District
Service: Love West Sussex	Subject: Sign Problem	Classification: Request for service	
Desc.: The various signs directing to Ardingly, Turners Hill and Wakehurst Place located at the junction of the B2028 and Selsfield Road at Selsfield Common (just south of Turners Hill) appear to have been hit in a collision that has knocked them to the ground at least six months ago and although they have had a strand of red and white tape attached to them for some time, they are sitting bent and broken on the ground pointing in the wrong directions. When will these be fixed? Extra information supplied by the user The sign is... : Blue directional sign The problem with the sign is best described as... : Damaged or broken			
Location: Ardingly Road, West Hoathly, RH19 4	Contact:		
Service: Love West Sussex	Logged by: Love Clean Streets	on: 01/01/2016 20:12	Officer: Clive Buckler(HS-Mid Sussex)
Subject: Sign Problem	Classification: Request for service		
Desc.: Direction signs have been knocked by a vehicle at junction of ardingly road and selsfield road Extra information supplied by the user The sign is... : Blue directional sign The problem with the sign is best described as... : Damaged or broken			
Location: Ardingly Road, West Hoathly, RH19 4	Contact:		
Service: Carriageway	Logged by: Contact Centre	on: 22/12/2015 14:37	Officer: James Turner (HS-Mid Sussex)
Subject: Condition	Classification: Request for service		
Desc.: there is a crease in the north carriageway and needs to be filled and ist is a hazzard. cep cc #Issue Type : Uneven surface			
Location: very near to property called Wayside	Contact:		
Service: Emergency	Logged by: Contact Centre	on: 22/12/2015 12:59	Officer: Mid-Sussex District
Subject: Trees	Classification: Request for service		
Desc.: there isw a broken branch hanging down touching raod and blocking 1 lane near to the junction. no other info. cep cc #OVRD : branch touching road #Issue type : Broken branch #Is it obstructing visibility? : Yes #Is it touching overhead cables? : No #Size of tree or branch : 4 to 5 feet long			
Location: near to junction turners hill road and ardingly road	Contact:		
Plot Number: 9,999.00	Feature Id - Location:	Feature Type: Whole Street Feature	
Service: Carriageway	Logged by: Carrie Anne Beaton	on: 12/02/2016 12:47	Officer: Mid-Sussex Pothole Stack
Subject: Potholes	Classification: Request for service		
Desc.: northbound along Ardingly Road, between Wakefield Place and Selsfield Road, deep pot hole.			
Location: Ardingly Road, between Wakefield Place and Selsfield Road	Contact:		
Plot Number: .00	Feature Id - Location:	Feature Type:	

Effective: 01/11/2015 to 29/02/2016
Street: Ardingly Road (25600147)

Display Action Officer: Yes

Customer Services

[REDACTED]	[REDACTED]	Logged by: Abigail Holdsworth	on: 12/02/2016 12:39	Officer: Mid-Sussex Pothole Stack
Service: Carriageway	Subject: Potholes	Classification: Request for service		
Desc.: [REDACTED] on the b2028 Ardingly Road. Heading southbound, [REDACTED] close to the junction of Stone Lands.				
[REDACTED] as it has been filled in. [REDACTED]				
Location: on the b2028 Ardingly Road. Heading southbound, close to the junction of Stone Lands.		Contact:		
Plot Number: 9,999.00	Feature Id - Location:	Feature Type: Whole Street Feature		
[REDACTED]	[REDACTED]	Logged by: Abigail Holdsworth	on: 05/02/2016 09:31	Officer: Mid-Sussex Pothole Stack
Service: Carriageway	Subject: Potholes	Classification: Request for service		
Desc.: Large pothole, with a very sharp edge that my tyre caught tonight. Large, sharp edged pothole. Easting/Northing: 534831/133701 Latitude: 51.086789 Longitude: -0.076267				
Location: Ardingly Road, West Hoathly		Contact:		
Plot Number: 9,999.00	Feature Id - Location:	Feature Type: Whole Street Feature		
[REDACTED]	[REDACTED]	Logged by: Carrie Anne Beaton	on: 04/02/2016 09:50	Officer: Clive Buckler(HS-Mid Sussex)
Service: Carriageway	Subject: Potholes	Classification: Request for service		
Desc.: Hole in north bound side. Sharp edge				
Location: Ardingly Road, West Sussex, England, RH19		Contact:		
Plot Number: 9,999.00	Feature Id - Location:	Feature Type: Whole Street Feature		
[REDACTED]	[REDACTED]	Logged by: Sally Trent	on: 03/02/2016 10:36	Officer: Clive Buckler(HS-Mid Sussex)
Service: Carriageway	Subject: Potholes	Classification: Request for service		
Desc.: [REDACTED] a pot hole in ardingly road, which is located opposite a cottage and a barn in west hoathly in West Sussex. [REDACTED]				
[REDACTED]				
[REDACTED]				
[REDACTED]				
[REDACTED]				
[REDACTED]				
[REDACTED]				
[REDACTED]				
Location: Ardingly Road, West Hoathly		Contact:		
Plot Number: 9,999.00	Feature Id - Location:	Feature Type: Whole Street Feature		

Effective: 01/11/2015 to 29/02/2016

Display Action Officer: Yes

Street: Ardingly Road (25600147)

Customer Services

[REDACTED]	[REDACTED]	Logged by: Carrie Anne Beaton	on: 13/01/2016 13:12	Officer: Mid-Sussex District
Service:	Carriageway	Subject: Condition	Classification: Request for service	
Desc.:	Driving from Ardingly towards Turners Hill on the LHS of the road just as you come round the last right bend before arriving at the junction with Selsfield Road			
Location:	HAZARD TYPE: Unevenness due to rut or gully APPROX. SIZE: 40 cm APPROX. DEPTH: 3 cm APPROX. DISTANCE FROM KERB: 30 cm DATE ENCOUNTERED: 2016-01-12 DEFECT DESCRIPTION: Sunken area in road			
Contact:				
Plot Number: 9,999.00	Feature Id - Location:	Feature Type: Whole Street Feature		
[REDACTED]	[REDACTED]	Logged by: Sally Trent	on: 12/01/2016 11:03	Officer: Mid-Sussex Pothole Stack
Service:	Carriageway	Subject: Potholes	Classification: Request for service	
Desc.:	[REDACTED] There is a dangerous pothole in Ardingly Road approx 300 yards in a southerly direction from junction with Selsfield Road [REDACTED]			
Location:	Ardingly Road	Contact:		
Plot Number: 9,999.00	Feature Id - Location:	Feature Type: Whole Street Feature		
[REDACTED]	[REDACTED]	Logged by: Jackie Boxall	on: 16/02/2016 17:22	Officer: Mid-Sussex Pothole Stack
Service:	Carriageway	Subject: Potholes	Classification: Request for service	
Desc.:	[REDACTED] a very deep pot hole on the Ardingly Road- just before the Selsfield Road Junction.			
Location:	Ardingly Road- just before the Selsfield Road Junction	Contact:		
[REDACTED]	[REDACTED]	Logged by: Catrin Jones	on: 16/02/2016 15:44	Officer: Mid-Sussex Pothole Stack
Service:	Carriageway	Subject: Potholes	Classification: Request for service	
Desc.:	[REDACTED] pothole [REDACTED]			
Location:		Contact:		
[REDACTED]	[REDACTED]	Logged by: Catrin Jones	on: 15/02/2016 11:30	Officer: Mid-Sussex Pothole Stack
Service:	Carriageway	Subject: Potholes	Classification: Request for service	
Desc.:	[REDACTED] pothole [REDACTED]			
Location:		Contact:		

Effective: 01/11/2015 to 29/02/2016
 Street: Ardingly Road (25600147)

Display Action Officer: Yes

Customer Services

<p>Service: Carriageway Desc.: pothole Location:</p>	<p>Logged by: Catrin Jones Subject: Potholes</p>	<p>on: 15/02/2016 10:05 Classification: Request for service Contact:</p>	<p>Officer: Mid-Sussex Pothole Stack</p>
<p>Enquiry No.: 321648 Service: Complaints Desc.: Under the general requirements of the Freedom of Information Act 2000, I would be grateful if you would provide the following information in relation to Ardingly Road West Hoathly, and in particular the section between Selsfield Road and Wakehurst Place.</p> <p>Dates of all safety inspections undertaken on the carriageway in the two years preceding 10/1/16 Details of all carriageway defects identified during safety inspections in the two years preceding 10/1/16 Details of how carriageway safety inspections are undertaken, including whether walked or driven, the speed of the inspection vehicle and the number of persons in the vehicle. The intended frequency of carriageway safety inspections. Details of all complaints and/or enquiries relating to the carriageway, received in the two years preceding 10/1/16. The hierarchy classification. The road/section number. The defect intervention criteria adopted in relation to the identification of all categories of carriageway potholes (in other words, this means how they define a pothole as requiring attention) The time period(s) adopted between identification and repair (temporary and permanent) of all categories of carriageway defects. Whether or not the authority has formally adopted all or part of the standards contained within the national code of practice for highways maintenance</p> <p>Location: Ardingly Road</p>	<p>Logged by: Paula Buckland Subject: Freedom of information request</p>	<p>on: 01/02/2016 16:02 Classification: Request for information Contact:</p>	<p>Officer: CSHub FOI's</p>
<p>Service: Carriageway Desc.: Pothole 1.9m x 0.9m x 0.2m Location: Southbound 300m south of Selsfield Road junction, 50m north of Wayside</p>	<p>Logged by: Clive Buckler Subject: Potholes</p>	<p>on: 11/01/2016 14:27 Classification: Request for service Contact:</p>	<p>Officer: Clive Buckler(HS-Mid Sussex)</p>
<p>Plot Number: 9,999.00</p>	<p>Feature Id - Location:</p>		<p>Feature Type: Whole Street Feature</p>

Effective: 01/11/2015 to 29/02/2016
Street: Ardingly Road (25600147)

Display Action Officer: Yes

Customer Services

Service: Information request
Desc.: [REDACTED] to request information under the Freedom of Information Act relating to a road your authority is responsible for maintaining. Specifically, my query relates to the Ardingly road, West Sussex, specifically the stretch between Turners Hill and Ardingly. Please can you send me:

1) A copy of your current road maintenance policy relating to that road. Please send me the full policy, but this should include details of the intended frequency of road safety inspections, how these inspections should be conducted and the maximum time between identification of a defect and repairs being carried out.

2) A copy of the road repair history for that road over the past year. Again, please send me the full road repair history, but this should include:

- dates of all safety inspections between 12th November until 11th January
- details of how safety inspections were undertaken (walked or driven, speed of inspection vehicle etc)
- details of all carriageway defects identified, with description, date and time
- details of how the authority handled these defects, what repairs were undertaken and the time between the identification of each defect and a repair being carried out.

Logged by: Catherine Caparo

on: 09/02/2016 14:20

Officer: CSHub FOI's

Subject: Email response requested

Classification: Request for information

Location: [REDACTED] to request information under the Freedom of Information Act relating to a road your authority is responsible for maintaining. Specifically, my query relates to the Ardingly road, West Sussex, specifically the stretch between Turners Hill and Ardingly. Please can you send me:

Contact:

1) A copy of your current road maintenance policy relating to that road. Please send me the full policy, but this should include details of the intended frequency of road safety inspections, how these inspections should be conducted and the maximum time between identification of a defect and repairs being carried out.

2) A copy of the road repair history for that road over the past year. Again, please send me the full road repair history, but this should include:

- dates of all safety inspections between 12th November until 11th January
- details of how safety inspections were undertaken (walked or driven, speed of inspection vehicle etc)
- details of all carriageway defects identified, with description, date and time
- details of how the authority handled these defects, what repairs were undertaken and the time between the identification of each defect and a repair being carried out.

Logged by: Jane Richards

on: 13/11/2015 20:44

Officer: Emergency Response Southern C

Service: Emergency

Subject: Rubbish and spillages

Classification: Request for service

Desc.: red paint spilled across the carriageway

Location: ardingly rd a just before/after the junction with stonecross lane

Contact:

Plot Number: 9,999.00

Feature Id - Location:

Feature Type: Whole Street Feature

Logged by: Tracey Scott-Muncey

on: 03/02/2016 14:33

Officer: Mid-Sussex Pothole Stack

Service: Carriageway

Subject: Potholes

Classification: Request for service

Desc.: [REDACTED]

Location: B2028 - Ardingly Road, Between Selsfield Road and Wakehurst Place

Contact:

Plot Number: 9,999.00

Feature Id - Location:

Feature Type: Whole Street Feature

Effective: 01/11/2015 to 29/02/2016
Street: Ardingly Road (25600147)

Display Action Officer: Yes

Customer Services

Service: Carriageway
Desc.:
Logged by: Tracey Scott-Muncey
Subject: Potholes
on: 15/01/2016 13:45
Classification: Request for service
Officer: Mid-Sussex District

t a pothole on Ardingly road (B2028) -

Location: Ardingly road (B2028)

Contact:

Plot Number: 9,999.00

Feature Id - Location:

Feature Type: Whole Street Feature

Service: Carriageway
Desc.:
Location:
Logged by: Tracey Scott-Muncey
Subject: Potholes
on: 13/01/2016 13:11
Classification: Request for service
Officer: Mid-Sussex District

Plot Number: 9,999.00

Feature Id - Location:

Feature Type: Whole Street Feature