



PAS/VAS Vehicle Quality Assurance Inspection

Date:	21 st October 2016	Location:	O/S Wat Gen A&E
PAS/VAS Company:	UKSAS	EEAST Callsign:	
Vehicle Registration:	██████████	Vehicle Skill Mix:	IHCD TECHNICIAN / ECA
Inspected by:	██████████		
Immediate Actions (if any):	Nil identified		

Description	Evidence	KLOE	Positive / Negative
UKSAS vehicle on operational duties was inspected on arrival at Watford General Hospital. The crew consisted of an ambulance Technician and an ECA. The crew stated that they have to identify any training needs and that they hadn't had any CPD or mandatory training this year. The ECA had a portfolio that he is working through and usually works with a Technician who is capable of signing the portfolio off as and when the skills are covered.			
All units inspected on the vehicle are within servicing dates.			

Date:	21 st October 2016	Location:	O/S Wat Gen A&E
PAS/VAS Company:	UKSAS	EEAST Callsign:	
Vehicle Registration:	██████	Vehicle Skill Mix:	IHCD TECHNICIAN / ECA
Inspected by:	██████		
Immediate Actions (if any):	Nil identified		

Description	Evidence	KLOE	Positive / Negative
<p>In line with the skill level of the crew, there were no controlled drugs on board. The crew were happy to allow their drugs bag to be inspected. They explained the restocking process which was in line with the process demonstrated at the UKSAS base in Essex.</p>	