

**Code/Seq:** Sgl/4  
**Ref:** 218000

**Location:** Edgware (A)  
**Site:** Windsor Avenue, Edgware

**House/Locn:** Outside 40  
**Description:** Windsor Avenue

**Species:** Malus sp.  
**Common:** Apple species  
**Owner:** Highways

**Tree-works visit** 10/03/2017 **at:** 12:39

**Contractor** G&T

**Height:** 7.5m  
**Spread:** 5.5m  
**Trunk:** 32cm  
**Age:** Mature

**Condition:** Good  
**Trunk:** Single  
**Type:** Broadleaf  
**FuncVal:** No Reduction  
**SLE:** 20-40 years

**Features:** Tarmac

**Tree works carried out:**

**Conditions:** Basal and trunk suckers  
Large flush cuts  
Other - See memo - mistletoe  
Raised roots/buttreassing

Grind Stump with Pit Creation (Ordered)

**Recommendations:**  
Plant Tree in Pre-Prepared Tree Pit

**Priority:** Urgent

**Tree-works visit** 23/02/2017 **at:** 18:00

**Contractor** GLE

**Height:** 7.5m  
**Spread:** 5.5m  
**Trunk:** 32cm  
**Age:** Mature

**Condition:** Good  
**Trunk:** Single  
**Type:** Broadleaf  
**FuncVal:** No Reduction  
**SLE:** 20-40 years

**Features:** Tarmac

**Tree works carried out:**

**Conditions:** Basal and trunk suckers  
Large flush cuts  
Other - See memo - mistletoe  
Raised roots/buttreassing

Remove Fallen Tree

**Recommendations:**  
Grind Stump with Pit Creation  
Plant Tree in Pre-Prepared Tree Pit

**Priority:** Urgent

**Previous Inspection** 23/02/2017 **at:** 14:50

**Inspector** AHT

**Height:** 7.5m  
**Spread:** 5.5m  
**Trunk:** 32cm  
**Age:** Mature

**Condition:** Good  
**Trunk:** Single  
**Type:** Broadleaf  
**FuncVal:** No Reduction  
**SLE:** 20-40 years

**Features:** Tarmac

**Recommendations:**

**Conditions:** Basal and trunk suckers  
Large flush cuts

Remove Fallen Tree

Plant Tree in Pre-Prepared Tree PitGrind Stump with Pit

Creation

Other - See memo - mistletoe  
Raised roots/buttreassing

**Priority:** Urgent

**Tree-works visit** 22/07/2016 **at:** 18:00**Contractor** GLE

**Height:** 7.5m  
**Spread:** 5.5m  
**Trunk:** 32cm  
**Age:** Mature

**Features:** Tarmac

**Conditions:** Basal and trunk suckers  
Large flush cuts  
Other - See memo - mistletoe  
Raised roots/buttreassing

**Priority:** No action required

**Condition:** Good  
**Trunk:** Single  
**Type:** Broadleaf  
**FuncVal:** No Reduction  
**SLE:** 20-40 years

**Tree works carried out:**

Remove Basal Growth - Ornamental & Other Species  
(Awaiting)

**Recommendations:**  
None recorded..

**Previous Inspection** 07/06/2016 **at:** 11:13**Inspector** ADI

**Height:** 7.5m  
**Spread:** 5.5m  
**Trunk:** 32cm  
**Age:** Mature

**Features:** Tarmac

**Conditions:** Basal and trunk suckers  
Large flush cuts  
Other - See memo - mistletoe  
Raised roots/buttreassing

**Priority:** Regime

**Condition:** Good  
**Trunk:** Single  
**Type:** Broadleaf  
**FuncVal:** No Reduction  
**SLE:** 20-40 years

**Recommendations:**

Remove Basal Growth - Ornamental & Other Species

**Previous Inspection** 01/12/2015 **at:** 11:22**Inspector** AJH

**Height:** 7.5m  
**Spread:** 5.5m  
**Trunk:** 32cm  
**Age:** Mature

**Features:** Tarmac

**Conditions:** Basal and trunk suckers  
Large flush cuts  
Other - See memo - mistletoe  
Raised roots/buttreassing

**Priority:** No action required

**Condition:** Good  
**Trunk:** Single  
**Type:** Broadleaf  
**FuncVal:** No Reduction  
**SLE:** 20-40 years

**Recommendations:**

None recorded..

**Tree-works visit** 18/06/2015 **at:** 18:14**Contractor** CSU

**Height:** 7.5m  
**Spread:** 5.5m  
**Trunk:** 32cm  
**Age:** Mature

**Features:** Tarmac

**Conditions:** Basal and trunk suckers  
Large flush cuts  
Other - See memo - mistletoe  
Raised roots/buttreassing

**Priority:** No action required

**Condition:** Good  
**Trunk:** Single  
**Type:** Broadleaf  
**FuncVal:** 25% Reduction  
**SLE:** 80+ years

**Tree works carried out:**

Remove Basal Growth - Ornamental & Other Species

**Recommendations:**  
None recorded..

**Previous Inspection** 13/05/2015 **at:** 16:48**Inspector** ADI

**Height:** 7.5m  
**Spread:** 5.5m  
**Trunk:** 32cm  
**Age:** Mature

**Features:** Tarmac

**Conditions:** Basal and trunk suckers  
Large flush cuts  
Other - See memo - mistletoe  
Raised roots/buttreassing

**Priority:** Regime

**Condition:** Good  
**Trunk:** Single  
**Type:** Broadleaf  
**FuncVal:** 25% Reduction  
**SLE:** 80+ years

**Recommendations:**

Remove Basal Growth - Ornamental &amp; Other Species

**Tree-works visit** 23/06/2014 **at:** 12:00**Contractor** CSU

**Height:** 7.5m  
**Spread:** 5.5m  
**Trunk:** 32cm  
**Age:** Mature

**Features:** Tarmac

**Conditions:** Basal and trunk suckers  
Large flush cuts  
Other - See memo - mistletoe  
Raised roots/buttreassing

**Priority:** No action required

**Condition:** Good  
**Trunk:** Single  
**Type:** Broadleaf  
**FuncVal:** 25% Reduction  
**SLE:** 80+ years

**Tree works carried out:**

Remove Basal Growth - Ornamental &amp; Other Species

**Recommendations:**

None recorded..

**Previous Inspection** 05/06/2014 **at:** 15:28**Inspector** FGM

**Height:** 7.5m  
**Spread:** 5.5m  
**Trunk:** 32cm  
**Age:** Mature

**Features:** Tarmac

**Conditions:** Basal and trunk suckers  
Large flush cuts  
Other - See memo - mistletoe  
Raised roots/buttreassing

**Priority:** Regime

**Condition:** Good  
**Trunk:** Single  
**Type:** Broadleaf  
**FuncVal:** 25% Reduction  
**SLE:** 80+ years

**Recommendations:**

Remove Basal Growth - Ornamental &amp; Other Species

**Tree-works visit** 03/06/2013 **at:** 12:00**Contractor** CSU

**Height:** 7.5m  
**Spread:** 5.5m  
**Trunk:** 32cm  
**Age:** Mature

**Features:** Tarmac

**Conditions:** Basal and trunk suckers  
Large flush cuts  
Other - See memo - mistletoe  
Raised roots/buttreassing

**Priority:** No action required

**Condition:** Good  
**Trunk:** Single  
**Type:** Broadleaf  
**FuncVal:** 25% Reduction  
**SLE:** 80+ years

**Tree works carried out:**

Remove Basal Growth - Ornamental &amp; Other Species

**Recommendations:**

None recorded..

**Tree-works visit** 29/05/2013 **at:** 17:03**Contractor** CSU

**Height:** 7.5m  
**Spread:** 5.5m  
**Trunk:** 32cm  
**Age:** Mature

**Features:** Tarmac

**Conditions:** Basal and trunk suckers  
Large flush cuts  
Other - See memo - mistletoe  
Raised roots/buttreassing

**Priority:** Regime

**Condition:** Good  
**Trunk:** Single  
**Type:** Broadleaf  
**FuncVal:** 25% Reduction  
**SLE:** 80+ years

**Tree works carried out:**

None recorded..

**Recommendations:**

Remove Basal Growth - Ornamental &amp; Other Species

**Tree-works visit** 29/03/2013 **at:** 17:30**Contractor** CSU

**Height:** 7.5m  
**Spread:** 5.5m  
**Trunk:** 32cm  
**Age:** Mature

**Features:** Tarmac

**Conditions:** Basal and trunk suckers  
Large flush cuts  
Other - See memo - mistletoe  
Raised roots/buttreassing

**Priority:** No action required

**Condition:** Good  
**Trunk:** Single  
**Type:** Broadleaf  
**FuncVal:** 25% Reduction  
**SLE:** 80+ years

**Tree works carried out:**

Crown Lift to 3m

**Recommendations:**

None recorded..

**Previous Inspection** 23/10/2012 **at:** 13:06**Inspector** PAM

**Height:** 7.5m  
**Spread:** 5.5m  
**Trunk:** 32cm  
**Age:** Mature

**Features:** Tarmac

**Conditions:** Basal and trunk suckers  
Large flush cuts  
Other - See memo - mistletoe  
Raised roots/buttreassing

**Priority:** Cyclical

**Condition:** Good  
**Trunk:** Single  
**Type:** Broadleaf  
**FuncVal:** 25% Reduction  
**SLE:** 80+ years

**Recommendations:**

Crown Lift to 3m

**Tree-works visit** 31/08/2012 **at:** 13:59**Contractor** CSU

**Height:**  
**Spread:** 7.5m  
**Trunk:** 32cm  
**Age:** Mature

**Features:** Tarmac**Conditions:** None recorded..**Priority:** No action required

**Condition:** Good  
**Trunk:** Single  
**Type:** Broadleaf  
**FuncVal:**  
**SLE:**

**Tree works carried out:**

Remove Basal Growth - Ornamental &amp; Other Species

**Recommendations:**

None recorded..

**Tree-works visit** 13/06/2011 **at:** 15:15**Contractor** CSU

**Height:**  
**Spread:** 7.5m  
**Trunk:** 32cm  
**Age:** Mature

**Features:** Tarmac**Conditions:** None recorded..**Priority:** Regime

**Condition:** Good  
**Trunk:** Single  
**Type:** Broadleaf  
**FuncVal:**  
**SLE:**

**Tree works carried out:**

Remove Basal Growth - Ornamental &amp; Other Species

**Recommendations:**

Remove Basal Growth - Ornamental &amp; Other Species

**Tree-works visit** 18/02/2010 **at:** 12:00**Contractor** CSU

**Height:**  
**Spread:** 7.5m  
**Trunk:** 32cm  
**Age:** Mature

**Features:** Tarmac**Conditions:** None recorded..**Priority:** No action required

**Condition:** Good  
**Trunk:** Single  
**Type:** Broadleaf  
**FuncVal:**  
**SLE:**

**Tree works carried out:**

Crown reduce 30% - Reduce 1

**Recommendations:**

None recorded..

**Inspectors Comments:**

Basal Growth  
n.b. mistletoe in crown

**Previous Inspection** 19/01/2010 **at:** 12:00**Inspector** PH

**Height:**  
**Spread:** 7.5m  
**Trunk:** 32cm  
**Age:** Mature

**Features:** Tarmac**Conditions:** None recorded..**Priority:** No action required

**Condition:** Good  
**Trunk:** Single  
**Type:** Broadleaf  
**FuncVal:**  
**SLE:**

**Recommendations:**

None recorded..

**Inspectors Comments:**

Basal Growth  
n.b. mistletoe in crown

**Tree-works visit** 15/06/2006 **at:** 12:00**Contractor** G&T

**Height:**  
**Spread:** 7.5m  
**Trunk:** 32cm  
**Age:** Mature

**Features:** Tarmac**Conditions:** None recorded..**Priority:** No action required

**Condition:** Good  
**Trunk:** Single  
**Type:** Broadleaf  
**FuncVal:**  
**SLE:**

**Tree works carried out:**

STANDARD CYLICAL PRUNE (LARGE) - A1-SCP

**Recommendations:**

None recorded..

**Inspectors Comments:**

Basal Growth  
n.b. mistletoe in crown

40 Windsor Avenue, HA8

