

Effective: 10/03/2012 to 10/03/2014
Street: Gatwick Road (9700110)

Display Action Officer: No

Street: Gatwick Road (9700110)

Locality: Industrial, Crawley, West Sussex

Area: CRAWLEY

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Section:	1.00	Road No. - Locn.:	C207/805	C/Way Type: Single 2-Lane Carriageway			Area: CRAWLEY	
Batch: 345221 - Ad Hoc Inspection Batch			Route: Ad-Hoc Northern				Date: 06/11/2013	
3051243	Previous patch around cover is failing. Please break out previous repair and redo1.5m x 1.5m sq (Enquiry 2007430)	06/11/2013	Under the bridge near Churchill Court where Napier Way joins road from Hazelwick Flyover 528145, 138268	C/W Covs/Gulls broken /miss	Internal		Committed	933096
Section:	9,999.00	Road No. - Locn.:		C/Way Type: Whole Street Feature			Area: CRAWLEY	
Batch: 404712 - Ad Hoc Inspection Batch			Route: Ad Hoc Prog Mangmnt				Date: 22/01/2014	
20004796	OOH Clear broken glass from carriageway	22/01/2014	Gatwick Road nr Nissan Garage	WS Obst flood,spill,tree,hedge	Internal		Committed	6001324
Batch: 403095 - Inspection Batch			Route: Ad Hoc Prog Mangmnt				Date: 22/10/2013	
20003179	Please fill pot hole prior to patching outside Nissan garage 5m x0.5m in bus lane	22/10/2013	Gatwick Road, Crawley, RH10 9	Potholes	Internal		Committed	69688
Batch: 403094 - Inspection Batch			Route: Ad Hoc Prog Mangmnt				Date: 22/10/2013	
20003178	Please fill pothole 1.2m x 0.5m	22/10/2013	Gatwick Road, Crawley, RH10 9	Potholes	Internal		Committed	69687
Batch: 402673 - Ad Hoc Inspection Batch			Route: Ad Hoc Prog Mangmnt				Date: 17/09/2013	
20002757	Damaged PGR - 3No X 2M 'V4' Visirail panels and 1no corner post (Enquiry 296217)	17/09/2013	At j/w Flemming Way opp Sussex Manor Business Park EN 528364, 138857	Planned Fencing Works	Internal		Uncommitt	69276
Batch: 401329 - Inspection Batch			Route: Ad Hoc Prog Mangmnt				Date: 09/07/2013	
20001407	3.7 x 0.9 x 100mm	09/07/2013	Gatwick Road, Crawley, RH10 9 30mtrs before roundabout outside Nissan garage in bus lane	Potholes	Internal		Committed	67932
Batch: 401313 - Inspection Batch			Route: Ad Hoc Prog Mangmnt				Date: 08/07/2013	
20001388	3m x 95mm x 0.7m	08/07/2013	os nissan dealership before roundabout	Potholes	Internal		Committed	67911
Batch: 400252 - Ad Hoc Inspection Batch			Route: Ad Hoc Prog Mangmnt				Date: 08/05/2013	
20000253	damaged section of Guardrail by pelican crossing (Enquiry 308477)	08/05/2013	on splitter island to south of Radford Road Roundabout	Planned Fencing Works	Internal		Uncommitt	66759
Batch: 352338 - Inspection Batch			Route: Crawley 6 Mthly Walked				Date: 26/02/2014	
3056242	Patch 1m2 hole at rear edge of bellmouth access to industrial estate	26/02/2014	On access to Forgewood Industrial Estate (southbound side approx 150m north of Fleming Way)	Potholes	Internal		Committed	938292
3056243	Patch 0.5 x 0.25m hole at rear edge of bellmouth access to industrial estate	26/02/2014	Access to Forgewood Industrial Estate (southbound side approx 150m north of Fleming Way)	Potholes	Internal		Committed	938293
3056241	Patch 0.6 x 0.3m pothole in southbound carriageway by bus stop to temporary repair deep hole in large patchy area (n.b. bus lane adjacent)	26/02/2014	Outside Mitsubishi Dealers (between lamp column nos.44 & 46 south of Tinsley Lane)	Potholes	Internal		Committed	938291
3056245	Cut square & renew 1.0 x 1.0m surround to mh cover in southbound bus lane	26/02/2014	Outside Motorline Nissan Dealers (50m north of Manor Royal)	Potholes	Internal		Committed	938295

Effective: 10/03/2012 to 10/03/2014
Street: Gatwick Road (9700110)

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Section:	9,999.00	Road No. - Locn.:	C/Way Type: Whole Street Feature			Area: CRAWLEY		
Batch:	352338 - Inspection Batch		Route: Crawley 6 Mthly Walked				Date: 26/02/2014	
3056239	Cut square & renew 2.4 x 1.2m surround to mh cover at start of southbound bus lane immediately to south of roundabout	26/02/2014	5m south of Radford Road	Potholes	Internal		Committed	938289
3056236	Possible water leak from water main in verge to rear of footway	26/02/2014	Adjacent to lamp column no.70	Any 3rd Party defect	External	WCO -NAO	Unactioned	
3056246	Cut square & patch 3.0 x 1.25m holed area in southbound carriageway (n.b. alongside designated bus lane)	26/02/2014	Adjacent to lamp column no.46 (outside Mitsubishi Dealers 120m south of Tinsley Lane)	Potholes	Internal		Committed	938296
3056247	Cut square & renew 1.2 x 1.2m surround to mh cover in southbound bus lane by entrance to British Rail New Yard	26/02/2014	Adjacent to lamp column no.70 (opposite southern end of service road adjoining Rutherford Way)	Potholes	Internal		Committed	938287
3056237	Broken/ sunken cover in southbound bus lane by entrance to British Rail New Yard	26/02/2014	Adjacent to lamp column no.72	Any 3rd Party defect	External		Unactioned	
3056240	Cut square & renew 1.0 x 0.6m surround to carriageway gulley at edge of northbound carriageway	26/02/2014	Opposite Motorline Nissan Dealers (60m north of Manor Royal)	Potholes	Internal		Committed	938290
3056244	Patch 2m2 holed area at rear edge of bellmouth access to industrial yard	26/02/2014	Entrance to British Rail New Yard (by lamp column no.70)	Potholes	Internal		Committed	938294
3056238	Cut square & renew 1.2 x 1.2m surround to mh cover in southbound bus lane by Pelican Crossing to south of roundabout	26/02/2014	30m south of Radford Road	Potholes	Internal		Committed	938288
Batch:	352309 - Ad Hoc Inspection Batch		Route: Ad-Hoc Northern				Date: 26/02/2014	
3056216	Pothole 30cm x 25cm x 160mm deep	26/02/2014	528309, 138713 Gatwick Road Industrial, Crawley	Potholes	Internal		Committed	938266
Batch:	352291 - Inspection Batch		Route: Ad-Hoc Northern				Date: 26/02/2014	
3056205		26/02/2014	Opposite Side of Garage. 528167, 138446 jst north of manor royal	Kerb missing - misaligned	Internal		Uncommitt	938255
Batch:	352290 - Inspection Batch		Route: Ad-Hoc Northern				Date: 26/02/2014	
3056204	Perm repair c/way pot hole sound gully patch 900mm x 1200mm approx constraint HGV's	26/02/2014	Opposite Side of Nissan Garage. 528167, 138446 jst north of manor royal	Potholes	Internal		Committed	938254
Batch:	351960 - Inspection Batch		Route: Ad-Hoc Northern				Date: 19/02/2014	
3055922	Cut out and patch pothole .6 x .5m x 115mm	19/02/2014	Between forgewood industrial estate and roundabout jw manor royal by col 64 opp Magellan terrace office units. Crossing into bus lane	Potholes	Internal		Committed	937952
Batch:	351313 - Inspection Batch		Route: Crawley A+B Reverse				Date: 11/02/2014	
3055491	DBM pothole - 0.6m x 0.4m x 50mm	11/02/2014	100m north of Fleming Way roundabout - busy industrial traffic	Potholes	Internal		Committed	937505
3055493	DBM pothole - 0.4m x 0.4m x 60mm	11/02/2014	Outside Kia garage - busy industrial traffic	Potholes	Internal		Committed	937503
3055492	DBM pothole - 0.5m x 0.4m x 50mm	11/02/2014	80m north of Fleming Way roundabout - busy industrial traffic	Potholes	Internal		Committed	937506

Effective: 10/03/2012 to 10/03/2014

Display Action Officer: No

Street: Gatwick Road (9700110)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Section:	9,999.00	Road No. - Locn.:	C/Way Type: Whole Street Feature			Area: CRAWLEY		
Batch:	351313 - Inspection Batch			Route: Crawley A+B Reverse			Date: 11/02/2014	
3055490	DBM patch - 4m x 2m x 45mm	11/02/2014	Just south of Kia garage - southbound - busy industrial traffic	Potholes	Internal		Committed	937504
Batch:	350727 - Inspection Batch			Route: Ad-Hoc Northern			Date: 05/02/2014	
3055231	Repair 2 adjacent c/way pot holes patch 450mm sq x 50mm incorporating both, constraints frequent HGV's	05/02/2014	O/s p & p motorcycle	Potholes	Internal		Committed	937239
Batch:	350726 - Inspection Batch			Route: Ad-Hoc Northern			Date: 05/02/2014	
3055230	Repair old failing trench approx 1.5m x .75m x .006m. Constraint, frequent HGV's	05/02/2014	O/s P&H Motorcycles, edge of bus Lane near bus stop	Potholes	Internal		Committed	937238
Batch:	349916 - Inspection Batch			Route: Ad-Hoc Northern			Date: 21/01/2014	
3054496	Section 81. Thames water cover and frame loose and rattling. Causing Tarmac to break out 120mm. Was phoned through. Urgent	21/01/2014	Near jw Napier way under footbridge and near dreams bed shop	Defective utility owned plant	External	STREETWK	Unactioned	
Batch:	349679 - Inspection Batch			Route: Ad-Hoc Northern			Date: 16/01/2014	
3054297	Permanent repair pothole 0.5m x 0.5m x 0.04m	16/01/2014	outside the Nissan dealership on Gatwick Road in centre carriageway outside of bus lane	Potholes	Internal		Committed	936282
Batch:	349223 - Inspection Batch			Route: Ad-Hoc Northern			Date: 09/01/2014	
3053955	Cut out and patch pothole .6m x .6m x 70mm	09/01/2014	In lane one as you head northbound on gatwick road from roundabout jw Fleming way	Potholes	Internal		Committed	935919
Batch:	349135 - Inspection Batch			Route: A + B Crawley			Date: 09/01/2014	
3053942	Pothole at edge of cover - .6x.2x.08 dbm, junction (11:26)	09/01/2014	By end of Gatwick Road Northbound Slip (528137,138287)	Potholes	Internal		Committed	935909
3053944	Subsidence - 6x1.5x40-100mm deep (11:34)	09/01/2014	o/s Nissan Garage (528168,138436)	Heave/ Subsidence	Internal		Committed	935908
3053941	Bollard 33g dislodged - passed to s/l ref no 272439	09/01/2014	Junction Radford Road	Any 3rd Party defect	External		Unactioned	
3053943	Pothole repair - .6x.4x.05 dbm, junction (11:34)	09/01/2014	20m right of L col 34 - outside lane (528190,138403)	Potholes	Internal		Committed	935910
Batch:	347385 - Inspection Batch			Route: Crawley A+B Reverse			Date: 09/12/2013	
3052468	Patch 0.4 x 0.3m pothole in northbound carriageway approx 10m north of roundabout (n.b. northbound side of splitter island)	09/12/2013	North of Fleming Way	Potholes	Internal		Committed	934404
3052469	Patch 0.4 x 0.3m pothole in northbound carriageway	09/12/2013	Adjacent to Gatwick Road Service Road (north of access road to Rutherford Way)	Potholes	Internal		Committed	934403
Batch:	345792 - Inspection Batch			Route: Ad-Hoc Northern			Date: 13/11/2013	
3051493	Temporary patch 6.0 x 0.5m holed area in southbound carriageway by end of bus lane on approach to roundabout	13/11/2013	Southbound approach to Manor Royal Roundabout	Potholes	Internal		Committed	933351

Effective: 10/03/2012 to 10/03/2014

Display Action Officer: No

Street: Gatwick Road (9700110)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Section:	9,999.00	Road No. - Locn.:		C/Way Type:	Whole Street Feature		Area:	CRAWLEY
Batch:	345586 - Inspection Batch			Route:	A + B Crawley			Date: 11/11/2013
	No actionable defects found							
Batch:	343314 - Inspection Batch			Route:	Crawley A+B Reverse			Date: 10/10/2013
	No actionable defects found							
Batch:	341824 - Ad Hoc Inspection Batch			Route:	Ad-Hoc Northern			Date: 24/09/2013
3049105	WORKS TBC Programme Year 3-5 Carriageway Resurfacing	24/09/2013	EN 528319,140077 - 528205,138020 Near Whittle Way	Planned Carriageway Works	Internal		Uncommitt	930879
Batch:	341607 - Inspection Batch			Route:	Ad-Hoc Northern			Date: 19/09/2013
3049015	Patch 0.6 x 0.2m area of holes in northbound carriageway on approach to junction with Whittle Way (n.b. separate bus lane alongside)	19/09/2013	Adjacent to Whittle Way	Potholes	Internal		Committed	930785
Batch:	341605 - Inspection Batch			Route:	Ad-Hoc Northern			Date: 19/09/2013
3049013	Patch 1.4 x 0.1m holed strip of carriageway around edge of twin cover (n.b heavily trafficked road & close to end of guided bus lane & splitter island) (see also job no.923906)	19/09/2013	Northbound approach to Fleming Way	Potholes	Internal		Committed	930782
Batch:	341159 - Inspection Batch			Route:	Ad-Hoc Northern			Date: 13/09/2013
3048756	Cut square, excavate 200mm, add stone & patch 4.8 x 1.0m sunken area in southbound carriageway by end of bus lane on southbound approach to roundabout	13/09/2013	50m north of roundabout at junction with Manor Royal	Potholes	Internal		Committed	930504
Batch:	341143 - Inspection Batch			Route:	A + B Crawley			Date: 12/09/2013
	No actionable defects found							
Batch:	340720 - Inspection Batch			Route:	Ad-Hoc Northern			Date: 10/09/2013
3048574	Cut out and patch pothole 3m x .75 x 100mm	10/09/2013	Between entrance to Mercedes and Napier way on service road. Be aware bus route and large lorries use this route in industrial area.	Potholes	Internal		Committed	930318
Batch:	339939 - Inspection Batch			Route:	Crawley 6 Mthly Walked			Date: 21/08/2013
	No actionable defects found							
Batch:	339337 - Inspection Batch			Route:	Crawley A+B Reverse			Date: 08/08/2013
	No actionable defects found							
Batch:	338850 - Ad Hoc Inspection Batch			Route:	Ad-Hoc Northern			Date: 29/07/2013
3047154	Refurb all WHITE AND YELLOW ROAD MARKINGS	29/07/2013	Between (and including) Gatwick Road Roundabout and Radford Road Roundabout	Lining / Studs Planned	Internal		Committed	928888

Effective: 10/03/2012 to 10/03/2014
Street: Gatwick Road (9700110)

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Section:	9,999.00	Road No. - Locn.:		C/Way Type:	Whole Street Feature		Area:	CRAWLEY
Batch:	338234 - Inspection Batch			Route:	A + B Crawley			Date: 11/07/2013
	No actionable defects found							
Batch:	337830 - Inspection Batch			Route:	Crawley A+B Reverse			Date: 14/06/2013
	No actionable defects found							
Batch:	337670 - Inspection Batch			Route:	Ad-Hoc Northern			Date: 05/06/2013
3045824	cut square & patch 0.8 x 0.6m hole in southbound carriageway	05/06/2013	opposite entrance to Magellan Terrace (40m north of Fleming Way)	Potholes	Internal		Committed	927562
Batch:	337265 - Inspection Batch			Route:	A + B Crawley			Date: 10/05/2013
	No actionable defects found							
Batch:	336632 - Inspection Batch			Route:	Crawley A+B Reverse			Date: 11/04/2013
3043669	old 1.5 x 0.5m patch starting to break up in nearside lane (see job no.923891)	11/04/2013	southbound carriageway on approach to Roundabout by Manor Royal	Planned Carriageway	for WCO	Internal	Uncommitt	925289
3043671	crazing/depression starting to show in northbound carriageway	11/04/2013	adjacent to lamp column no.111 (between Radford Road Roundabout & Airport Roundabout)	Planned Carriageway	for WCO	Internal	Uncommitt	925287
3043670	cut square & patch 0.5 x 0.4m pothole in southbound carriageway	11/04/2013	opposite Magdallen Terrace (50m north of Fleming Way)	Potholes		Internal	Committed	925288
Batch:	336127 - Inspection Batch			Route:	A + B Crawley			Date: 15/03/2013
	No actionable defects found							
Batch:	336065 - Inspection Batch			Route:	Crawley 6 Mthly Walked			Date: 13/03/2013
3042444	cut square & patch 0.8 x 0.25m holed area by mh cover in southbound bus lane to south of bellmouth (n.b. bus lane closure needed)	13/03/2013	adjacent to Tinsley Lane (south of Fleming Way Roundabout)	Potholes		Internal	Uncommitt	923911
3042442	cut square & patch 2.0 x 0.4m hole along joint in southbound carriageway adjacent to bellmouth (n.b. bus lane nearside)	13/03/2013	adjacent to Tinsley Lane (south of Fleming Way Roundabout)	Potholes		Internal	Uncommitt	923909
3042445	cut square & patch 0.6 x 0.3m hole by mh cover in southbound carriageway (n.b. bus lane nearside)	13/03/2013	adjacent to Nissan Car Dealers (50m north of Manor Royal)	Potholes		Internal	Uncommitt	923912
3042443	cut square & patch 2.5 x 1.0m holed/uneven area in southbound carriageway to southside of bellmouth (n.b. bus lane nearside)	13/03/2013	adjacent to Tinsley Lane (south of Fleming Way Roundabout)(adjacent to lamp column no.50)	Potholes		Internal	Uncommitt	923910
3042441	cut square & patch 0.8 x 0.3m shallow surface erosion in southbound carriageway adjacent to bellmouth (n.b. bus lane nearside)	13/03/2013	adjacent to Tinsley Lane	Potholes		Internal	Uncommitt	923908
3042440	cut square & patch 1.4 x 0.25m holed strip along joint in southbound carriageway adjacent to bellmouth (n.b. bus lane nearside)	13/03/2013	adjacent to Tinsley Lane (south of Fleming Way Roundabout)	Potholes		Internal	Uncommitt	923907

Effective: 10/03/2012 to 10/03/2014
Street: Gatwick Road (9700110)

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Section:	9,999.00	Road No. - Locn.:		C/Way Type:	Whole Street Feature		Area: CRAWLEY	
Batch:	336065 - Inspection Batch		Route: Crawley 6 Mthly Walked				Date: 13/03/2013	
3042439	patch 0.8 x 0.2m hole by edge of mh cover in carriageway on northbound approach to Roundabout (n.b. offside lane by end of splitter island & guided bus lane)	13/03/2013	20m south of Fleming Way Roundabout	Potholes	Internal		Uncommitt	923906
3042437	patch 0.8 x 0.3m hole on joint in northbound carriageway (n.b. bus lane along nearside)	13/03/2013	opposite Northwood Park Trading Estate (by lamp column no.41)	Potholes	Internal		Uncommitt	923904
3042436	patch 0.6 x 0.2m hole on joint in northbound carriageway (n.b. bus lane along nearside)	13/03/2013	opposite Autoglass (approx 160m north of Manor Royal)	Potholes	Internal		Uncommitt	923903
3042435	patch 0.3 x 0.2m hole on joint in northbound carriageway (n.b. bus lane along nearside)	13/03/2013	opposite Autoglass (approx 150m north of Manor Royal) (opposite lamp column no.38)	Potholes	Internal		Uncommitt	923902
3042433	shallow surface erosion & patchy surface in southbound carriageway - possible 10.0 x 1.5m patch needed adjacent to bus stop (n.b. bus lane nearside)	13/03/2013	adjacent to Hyundai Dealers (south of Tinsley Lane)	Planned Carriageway for WCO	Internal		Unactioned	
3042432	cut square & patch 1.4 x 1.4m surround breaking out around W.O. covers at edge of northbound carriageway (n.b. bus lane nearside)	13/03/2013	12m south of Whittle Way	Planned Carriageway for WCO	Internal		Committed	924026
3042438	patch 0.4 x 0.1m hole on joint at edge of northbound carriageway (n.b. alongside guided bus lane)	13/03/2013	60m south of Fleming Way Roundabout	Potholes	Internal		Uncommitt	923905
3042434	patch 0.4 x 0.1m hole on joint in northbound carriageway (n.b. bus lane along nearside)	13/03/2013	opposite Autoglass (north of Oakwood Trading Estate) approx 150m north of Manor Royal) (opposite lamp column no.38)	Potholes	Internal		Uncommitt	923901
Batch:	336059 - Inspection Batch		Route: Ad-Hoc Northern				Date: 13/03/2013	
3042426	4.0 x 0.5m fretted strip along joint in northbound carriageway (passed to OMC for 2-hour response)	13/03/2013	opposite Thales (by lamp column no.39) (between Manor Royal & Fleming Way)	Potholes	Internal		Uncommitt	923890
3042425	various holes in southbound carriageway (passed to OMC for temporary 2-hour response)	13/03/2013	adjacent to Tinsley Lane (approx 50m south of Fleming Way Roundabout)	Planned Carriageway for WCO	Internal		Unactioned	
3042424	cut square & patch 2.0 x 0.4m hole in nearside lane of southbound carriageway (by end of bus lane) (passed to OMC for 2-hour response)	13/03/2013	adjacent to Nissan Dealers 50m north of Manor Royal Roundabout	Potholes	Internal		Uncommitt	923891
Batch:	336004 - Inspection Batch		Route: Ad-Hoc Northern				Date: 08/03/2013	
3042298	patch 0.3 x 0.2m hole by edge of mh cover in northbound carriageway	08/03/2013	opposite lamp column no.68 (adjacent to southern end of Gatwick Road Service Road)	Potholes	Internal		Uncommitt	923741

Effective: 10/03/2012 to 10/03/2014
Street: Gatwick Road (9700110)

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Section:	9,999.00	Road No. - Locn.:		C/Way Type: Whole Street Feature			Area: CRAWLEY	
Batch: 336004 - Inspection Batch		Route: Ad-Hoc Northern						Date: 08/03/2013
3042296	surface water over cover in northbound carriageway - check level	08/03/2013	opposite lamp column no.68 (adjacent to southern end of Gatwick Road Service Road	Planned Carriageway	for WCO	Internal	Unactioned	
3042295	surface water over cover in northbound carriageway - check level	08/03/2013	south of Whittle Way (by lamp column no.85)	Planned Carriageway	for WCO	Internal	Unactioned	
3042294	cut square & patch 0.8 x 0.5m pothole in northbound carriageway (n.b. 2 way road with bus lanes nearside both ways)	08/03/2013	10m north of Whittle Way (opposite lamp column no.86)	Potholes		Internal	Uncommitt	923740
3042292	patch 0.4 x 0.3m hole in southbound carriageway between roundabout & pelican crossing (n.b. divided by splitter island with bus lane to nearside of main carriageway)	08/03/2013	5m south of Radford Road Roundabout	Potholes		Internal	Uncommitt	923738
3042291	cut square & patch 0.8 x 0.5m hole in southbound carriageway (n.b. two-way road with bus lanes running nearside both ways)	08/03/2013	north of Cobham Way (between lamp column nos.92 & 90)	Potholes		Internal	Uncommitt	923737
3042290	cut square & patch 0.5 x 0.2m pothole in southbound carriageway (n.b. bus lane nearside)	08/03/2013	100m north of Fleming Way Roundabout (10m north of entrance to Magdalen Terrace) (opposite lamp column no.65)	Potholes		Internal	Uncommitt	923736
3042289	cut square & patch 0.4 x 0.3m pothole in southbound carriageway (n.b. bus lane nearside)	08/03/2013	90m north of Fleming Way Roundabout (opposite entrance to Magdalen Terrace)	Potholes		Internal	Uncommitt	923735
3042288	cut square & patch 0.4 x 0.4m pothole in southbound carriageway (n.b. bus lane nearside)	08/03/2013	60m north of Fleming Way Roundabout (by entrance to Volkswagen Car Showrooms)	Potholes		Internal	Uncommitt	923734
3042293	cut square & patch 0.6 x 0.4m pothole in northbound carriageway (n.b. 2 way road with bus lanes nearside both ways)	08/03/2013	5m south of Whittle Way	Potholes		Internal	Uncommitt	923739
3042287	patch holes in carriageway across bellmouth access	08/03/2013	entrance to Forgewood Industrial Estate (southbound side 150m north of Fleming Way Roundabout / opposite no.39)	Planned Carriageway	for WCO	Internal	Unactioned	
3042297	surface water at edge of carriageway - check gully	08/03/2013	opposite lamp column no.68	Planned Carriageway	for WCO	Internal	Unactioned	
Batch: 335505 - Inspection Batch		Route: Crawley A+B Reverse						Date: 11/02/2013
3041393	DBM pothole - 0.6m x 0.6m x 70mm	11/02/2013	o/s Northwood park - southbound	Potholes		Internal	Uncommitt	922631
Batch: 335466 - Ad Hoc Inspection Batch		Route: Ad-Hoc Northern						Date: 08/02/2013
3041325	Make safe c/w pot approx 150cm x 32cm x 150mm deep	08/02/2013	Out side garage mitsubishi BCL Group	WS Obst flood,spill,tree,hedge		Internal	Uncommitt	922561
Batch: 335121 - Inspection Batch		Route: Ad-Hoc Northern						Date: 22/01/2013
3040632	cut square & patch 2.0 x 1.0m area of carriageway adjacent to gully at edge of northbound carriageway	22/01/2013	opposite lamp column no.110 (between James Watt Way & Airport Roundabout to north of traffic signals by Beehive Ring Road)	Potholes		Internal	Uncommitt	921780

Effective: 10/03/2012 to 10/03/2014
Street: Gatwick Road (9700110)

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Section:	9,999.00	Road No. - Locn.:		C/Way Type:	Whole Street Feature		Area: CRAWLEY	
Batch:	335067 - Ad Hoc Inspection Batch			Route:	Ad-Hoc Northern			Date: 18/01/2013
3040538	Repair c/w pot 300mm dia x 75mm deep(Enquiry 272753)	18/01/2013	Opposite Thales. Pothole is on left hand side near Mitsubishi/Hyundai Garage.	Potholes	Internal		Uncommitt	921683
Batch:	334921 - Inspection Batch			Route:	A + B Crawley			Date: 11/01/2013
3040251	cut square & patch 1.2 x 0.4m hole in northbound carriageway	11/01/2013	opposite Autoglass (by lamp column no.37 approx 200m north of Gatwick Road Roundabout (Manor Royal)	Potholes	Internal		Uncommitt	921325
Batch:	334431 - Inspection Batch			Route:	Crawley A+B Reverse			Date: 17/12/2012
	No actionable defects found							
Batch:	333851 - Inspection Batch			Route:	A + B Crawley			Date: 08/11/2012
	No actionable defects found							
Batch:	333767 - Ad Hoc Inspection Batch			Route:	Ad-Hoc Northern			Date: 02/11/2012
3038086	maek safe collapsed man hole cover outside the nat west bank. Third building on the left south of the footbridge. ref 718 02/11/2012 (Enquiry 264297)	02/11/2012	third building on the left south of the footbridge.	WS Obst flood,spill,tree,hedge	Internal		Uncommitt	918765
Batch:	333551 - Ad Hoc Inspection Batch			Route:	Ad-Hoc Northern			Date: 17/10/2012
3037620	Police report (ref: 1130 todays date) oil spillage outside motor cycle shop. Beleived van oil sump has broken. Starting to spread. No other details. (Enquiry 262681)	17/10/2012	o/s P & H Motorcycles, number 63	WS Obst flood,spill,tree,hedge	Internal		Uncommitt	918193
Batch:	333457 - Inspection Batch			Route:	Crawley A+B Reverse			Date: 10/10/2012
	No actionable defects found							
Batch:	333101 - Inspection Batch			Route:	A + B Crawley			Date: 12/09/2012
	No actionable defects found							
Batch:	332884 - Inspection Batch			Route:	Ad-Hoc Northern			Date: 20/08/2012
3036231	lid missing from electrical connection pillar along rear edge of footway by edge of development site adjacent to pelican crossing (crossing ref:3665)	20/08/2012	opposite Oakwood Trade Park	Defective utility owned plant	External	STREETWK	Unactioned	
Batch:	332875 - Inspection Batch			Route:	Crawley 6 Mthly Walked			Date: 17/08/2012
3036217	fretted footway surface - possible overlay 5.0 x 1.6m area	17/08/2012	adjacent to lamp column no.10 (London Road-Radford Road)	Planned Footway for WCO	Internal		Unactioned	
3036216	clear overgrown vegetation from around "Clearway" sign alongside southbound carriageway	17/08/2012	50m south of Airport Roundabout (London Road)	Any 3rd Party defect	External	CUST-NAO	Unactioned	
3036215	carriageway breaking out & bouncing adjacent to gulley along edge of northbound carriageway - 1.4 x 1.0m area	17/08/2012	opposite lamp column no.110 (London Road-Radford Road)	Planned Carriageway for WCO	Internal		Unactioned	

Effective: 10/03/2012 to 10/03/2014

Display Action Officer: No

Street: Gatwick Road (9700110)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Section:	9,999.00	Road No. - Locn.:		C/Way Type:	Whole Street Feature		Area:	CRAWLEY
Batch:	332875 - Inspection Batch		Route:	Crawley 6 Mthly Walked			Date:	17/08/2012
3036214	root burst in footway surface - possible overlay 9.0 x 1.6m area	17/08/2012	between lc.108 & lc.110 (London Road - Radford Road)	Planned Footway for WCO	Internal		Uncommitt	916758
Batch:	332871 - Inspection Batch		Route:	Ad-Hoc Northern			Date:	17/08/2012
3036194	patch 0.5 x 0.4m hole in carriageway by corner of surround to mh cover in northside of bellmouth	17/08/2012	entrance to Forgewoid Industrial Estate	Potholes	Internal		Uncommitt	916422
3036193	12 x 1.25m crazed concrete area across entrance in line with adjacent footway (check status)	17/08/2012	entrance to Magellan Terrace (50m north of Fleming Way)	Planned Carriageway for WCO	Internal		Uncommitt	916759
3036192	sinking mh cover in southbound bus lane	17/08/2012	by entrance to British Rail New Yard (adjacent to lamp column no.72)	Planned Carriageway for WCO	Internal		Unactioned	
3036204	o/g vegetation - approx 30-40m length	17/08/2012	adjacent to The Office Building (opposite lamp column no.77)	Any 3rd Party defect	External	CUST-NAO	Unactioned	
3036203	remove 0.6 x 0.4m area of surplus hardened cement left stuck to surface of asphalt footway	17/08/2012	adjacent to lamp column no.89 (opposite Cobham Way)	F/W hazard trip/depression	Internal		Uncommitt	916421
3036202	sunken W.O & S.V covers in northbound carriageway - lid of adjacent mh cover in bus lane banging	17/08/2012	25m north of Rutherford Way (by lamp column no.85)	Defective utility owned plant	External	STREETWK	Unactioned	
3036201	o/g veg encroaching over footway - approx 25m length	17/08/2012	north of Rutherford Way (by lc.85)	Any 3rd Party defect	External	CUST-NAO	Unactioned	
3036200	patch 0.4 x 0.2m pothole by mh cover in northbound carriageway	17/08/2012	adjacent to southern end of service road adjoining Rutherford Way	Potholes	Internal		Uncommitt	916423
3036199	patch 0.5 x 0.3m hole by mh cover in southbound bus lane	17/08/2012	adjacent to Tinsley Lane	Potholes	Internal		Uncommitt	916419
3036198	patch 2.0 x 0.2m strip of holes in join between southbound carriageway & bus lane	17/08/2012	adjacent to Tinsley Lane	Potholes	Internal		Uncommitt	916418
3036197	patch 1.0 x 0.2m hole in southbound carriageway	17/08/2012	opposite bus stop by lamp column no.43 (by Gatwick Hyundai)	Potholes	Internal		Uncommitt	916417
3036196	missing lid from electrical connection box at rear of footway adjacent to Pelican Crossing no.3665	17/08/2012	opposite Oakwood Trade Park	Any 3rd Party defect	External	WCO -NAO	Unactioned	
3036195	patch 1m2 hole in carriageway adjacent to tactile crossing point to southside of bellmouth	17/08/2012	entrance to British Rail New Yard	Planned Carriageway for WCO	Internal		Uncommitt	916450
Batch:	332815 - Inspection Batch		Route:	Crawley A+B Reverse			Date:	09/08/2012
3035958	DBM pothole - 0.4m x 0.2m x 70mm	09/08/2012	20m south of Gatwick Ind. Est entrance - west side by cover	Potholes	Internal		Uncommitt	916132
Batch:	332594 - Inspection Batch		Route:	Ad-Hoc Northern			Date:	18/07/2012
3035428	DBM POTHOLE - 0.6m x 0.4m x 110mm	18/07/2012	bus lay-by - northbound side - almost opposite Tinsley Lane North	Potholes	Internal		Uncommitt	915448

Effective: 10/03/2012 to 10/03/2014

Display Action Officer: No

Street: Gatwick Road (9700110)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Section:	9,999.00	Road No. - Locn.:		C/Way Type:	Whole Street Feature		Area:	CRAWLEY
Batch:	332532 - Inspection Batch			Route:	A + B Crawley			Date: 12/07/2012
	No actionable defects found							
Batch:	332301 - Ad Hoc Inspection Batch			Route:	Ad-Hoc Northern			Date: 21/06/2012
3034786	Please investigate surcharging gully D37492	21/06/2012	o/s P&H Motorcycles HONDA on main c/way. 528474,139101	Drainage investigation needed	External 3800		Unactioned	
Batch:	332209 - Inspection Batch			Route:	Crawley A+B Reverse			Date: 13/06/2012
3034588	1 x post with missing sign & 1 x sign slipped to base of post by bus lay-by alongside southbound carriageway	13/06/2012	north of Radford Road	Any 3rd Party defect	External CUST-NAO		Unactioned	
3034587	cut square & patch 1.2 x 1.2m carriageway surround to mh cover in southbound carriageway adjacent to pelican crossing by lamp column no.36 (n.b. within designated bus lane)	13/06/2012	adjacent to Oakwood Trading Estate	Potholes	Internal		Uncommitt	914337
3034586	cut square & patch 1m2 hole in northbound carriageway (n.b. in outside lane of two lane carriageway with nearside lane designated as bus lane)	13/06/2012	opposite Oakwood Trading Estate	Potholes	Internal		Uncommitt	914338
Batch:	332184 - Ad Hoc Inspection Batch			Route:	Ad-Hoc Northern			Date: 12/06/2012
3034539	BT frame and cover loose in carriageway, surround breaking up.	12/06/2012	At Puffin crossing no 3665, nr Oakwood Industrial Park. 528216,138495	Defective utility owned plant	External STREETWK		Unactioned	
Batch:	331747 - Inspection Batch			Route:	A + B Crawley			Date: 10/05/2012
	No actionable defects found							
Batch:	331446 - Inspection Batch			Route:	Crawley A+B Reverse			Date: 12/04/2012
	No actionable defects found							
Batch:	229093 - Ad Hoc Inspection Batch			Route:	Ad-Hoc Southern			Date: 09/01/2013
2054550	Pothole 16 inches long x 8 inch wide x 3 inch deep.	09/01/2013	Opposite AutoGlass nr junc Oakwood Industrial Park	Potholes	Internal		Uncommitt	828505
Batch:	228198 - Ad Hoc Inspection Batch			Route:	Ad-Hoc Southern			Date: 20/09/2012
2052280	Police reports oil spillage at above location on north bound carriageway, about 2 foot wide.	20/09/2012	Between Rutherford Way and James Watt Way. Located between Rutherford Way and the RADFORD ROAD ROUNDABOUT. Incident No:0502/20/09/2012 (Enquiry 259721)	WS Obst flood,spill,tree,hedge	Internal		Uncommitt	825827
Batch:	227973 - Ad Hoc Inspection Batch			Route:	Ad-Hoc Southern			Date: 29/08/2012
2051511	Approx 2 foot wide by 2 foot deep. lots of loose tarmac surrounding it. Pls repair and clear debris LS.CC - (Enquiry 257553)	29/08/2012	On the roundabout just after the flyover	WS Obst flood,spill,tree,hedge	Internal		Uncommitt	825028

Effective: 10/03/2012 to 10/03/2014
Street: Gatwick Road (9700110)

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Section:	9,999.00	Road No. - Locn.:		C/Way Type:	Whole Street Feature		Area: CRAWLEY	
Batch:	227114 - Ad Hoc Inspection Batch			Route:	Ad-Hoc Southern			Date: 11/06/2012
2049308	Collapsed drain, has no lid, in a bus lane. could cause problems for vehicles. (Enquiry 248979)	11/06/2012	Outside Toyota Dealership	WS Obst flood,spill,tree,hedge	Internal		Uncommitt	822402
Batch:	130382 - Ad Hoc Inspection Batch			Route:	Ad-Hoc Western			Date: 22/01/2014
10125807	Patch 1m sq around Thames water cover Tarmac 120mm deep. (see defect 3054496)	22/01/2014	Near jw Napier way under footbridge and near dreams bed shop	WS Obst flood,spill,tree,hedge	Internal		Committed	707650
Batch:	130381 - Ad Hoc Inspection Batch			Route:	Ad-Hoc Western			Date: 22/01/2014
10125806	Patch 1m sq around Thames water cover Tarmac 120mm deep. (see defect 3054496)	22/01/2014	Near jw Napier way under footbridge and near dreams bed shop	WS Obst flood,spill,tree,hedge	Internal		Unactioned	
Batch:	120545 - Ad Hoc Inspection Batch			Route:	Ad-Hoc Western			Date: 03/05/2013
10118856	Make safe cspot adjacent to MHC 2ftx2ft and 4 inches deep, in wheel track, in lane 1 (Enquiry 289054)	03/05/2013	N/bound, Under the footbridge near Churchill Court , approx 5 mtrs south of Gatwick Road N/bound slip 528145, 138268	Potholes	Internal		Committed	700472

Customer Services

Enquiry No: 2027639
Service: Carriageway
Desc.: Lots of potholes all along road deepest is about 4incs
Location: Between Fleming Way and Manor Royle 528402, 138912

Logged by: Contact Centre
Subject: Potholes

on: 10/03/2014 12:25
Classification: Request for service

Contact: [REDACTED]

Plot Number: 9,999.00

Feature Id - Location:

Feature Type: Whole Street Feature

Job Number: 939097

Defect Number: 3057040

Enquiry No: 2027433
Service: Carriageway

Logged by: Contact Centre
Subject: Potholes

on: 07/03/2014 15:46
Classification: Request for service

Desc.: Between Beehive Ring Road and the Roundabout on left side of road coming from the Airport. Large pothole which has been repaired. Caller has damaged vehicle this occurred a week last thursday. New tyre and wheel. Claim requested fj/cc (Claim Requested)

Location: 528517, 139776, C207 location may not match grid ref but grid ref is correct.

Contact: [REDACTED]

Enquiry No: 2026946

Logged by: Contact Centre

on: 05/03/2014 13:43

Service: Carriageway

Subject: Potholes

Classification: Request for service

Desc.: Damage received to vehicle due to pothole. Pothole is approx 2ft length, Width 1ft, Depth 2 to 3 inches. Damage to vehicle was off set tracking and blew out tyre. Incident happened Friday 28th Febuary 2014 approx 18:30pm. (Claim Requested)

Location: Opposite Kia Motors 528302, 138720

Contact: [REDACTED]

Enquiry No: 2026751

Logged by: Contact Centre

on: 04/03/2014 15:57

Service: Carriageway

Subject: Potholes

Classification: Request for service

Desc.: Went over pothole on 4.3.14 about 2pm may have damaged the car.

Location: Northbound side by garage 528188, 138464

Contact: [REDACTED]

Effective: 10/03/2012 to 10/03/2014
Street: Gatwick Road (9700110)

Display Action Officer: No

Customer Services

Enquiry No: 2026536	Logged by: Love Clean Streets	on: 04/03/2014 00:36
Service: Carriageway	Subject: Potholes	Classification: Request for service
Desc.: Numerous potholes Gatwick road nr Oakwood industrial park		
Location: Gatwick Road, Crawley, RH10 9	Contact:	
Enquiry No: 2026335	Logged by: Love Clean Streets	on: 03/03/2014 10:56
Service: Carriageway	Subject: Potholes	Classification: Request for service
Desc.: Massive deep and dangerous pot hole surrounded by deep crumbling road surface for atleast 10ft of the road!! Causing great damage to cars !!!		
Location: Gatwick Road, Crawley, RH10 9	Contact:	
Enquiry No: 2026177	Logged by: Love Clean Streets	on: 01/03/2014 15:57
Service: Carriageway	Subject: Potholes	Classification: Request for service
Desc.: severe pot hole		
Location: 11 Gatwick Road, Magellan Ter, Crawley, West Sussex RH10 9PJ, UK	Contact:	
Enquiry No: 2026140	Logged by: Love Clean Streets	on: 28/02/2014 21:12
Service: Carriageway	Subject: Condition	Classification: Request for service
Desc.: Significant wear, poor surface and numerous dangerpus pot holes along the length of this road from the Hazelwick Flyover to the James Watt Way roundabout. Very dangerous and I have had numerous reports from businesses.		
Location: gatwick road crawley	Contact:	
Enquiry No: 2026089	Logged by: Contact Centre	on: 28/02/2014 15:23
Service: Carriageway	Subject: Potholes	Classification: Request for service
Desc.: 13cm deep, width two foot and length about two foot. Damaged her car. (Claim Requested)		
Location: 528325, 138747 near side of road. Between Tinsley lane and the bus stop.	Contact: [REDACTED]	
Enquiry No: 2025982	Logged by: Contact Centre	on: 28/02/2014 10:58
Service: Carriageway	Subject: Potholes	Classification: Request for service
Desc.: Went over potohle on 28.2.14 about 5:50am damaged front and back nearside tyres pothole about 5-8 incs deep. (Claim Requested)		
Location: Gatwick Road Industrial southbound side 200yrs from Fleming Way Roundabout near bus stop 528353, 138822	Contact: [REDACTED]	
Enquiry No: 2025850	Logged by: Contact Centre	on: 27/02/2014 15:30
Service: Carriageway	Subject: Potholes	Classification: Request for service
Desc.: 528300, 138685 by bus shelter by kerb pothole 6 in deep dustbin lid size. Has damage front alloy wheel and tyre also damage to back tyre. (Claim Requested)		
Location: 528300, 138685 by bus shelter by kerb	Contact: [REDACTED]	
Enquiry No: 2025755	Logged by: Contact Centre	on: 27/02/2014 11:28
Service: Emergency	Subject: Pothole	Classification: Request for service
Desc.: caller reporting large pothole close to ind est has damaged vehicle tyre exploded is currently waiting for recovery truck. is going to get photos of hole. (Claim Requested)		
Location: 528511, 139400 by manor royal ind est mr speedy	Contact: [REDACTED]	
Enquiry No: 2025554	Logged by: Contact Centre	on: 26/02/2014 12:37
Service: Carriageway	Subject: Potholes	Classification: Request for service
Desc.: Outside the Kia Garage heading from North to South is a crater, depth 5/6 inches, Length of 1 foot and width 9 inches Severe damage to brand new Golf Vaulkswagon GTD Puncture tyre & pound;253.00 and the 19 inch alloy wheel & pound;800 appx will be getting all the rest of the details off of Vaulkswagon garage when works complete. [REDACTED] states the crater is very dangerous and if a bike hits this it would cause terrible damage to property and life. cc dh 26.02.2014 (Claim Requested)		
Location: 528309, 138713 Gatwick Road Industrial, Crawley	Contact: [REDACTED]	
Plot Number: 9,999.00	Feature Id - Location:	Feature Type: Whole Street Feature
Job Number: 938266	Defect Number: 3056216	

Effective: 10/03/2012 to 10/03/2014
Street: Gatwick Road (9700110)

Display Action Officer: No

Customer Services

Enquiry No: 2025498	Logged by: Contact Centre	on: 26/02/2014 10:04
Service: Carriageway	Subject: Potholes	Classification: Request for service
Desc.: Caller reports damage to front and rear tyre on nearside due to hole. Located at above. Approx 16 inch diam x 6 inch deep. (Claim Requested)		
Location: Near Northwood Park entrance. 528297, 138679	Contact: [REDACTED]	
Enquiry No: 2025497	Logged by: Love Clean Streets	on: 26/02/2014 10:05
Service: Carriageway	Subject: Potholes	Classification: Request for service
Desc.: The 2 broken up patches on the road have been previously repaired. Now a large and deep pothole has appeared in the first patched up area. Urgent repair is needed.		
Location: 11 Gatwick Road, Magellan Ter, Crawley, West Sussex RH10 9PJ, UK	Contact:	
Enquiry No: 2025074	Logged by: Contact Centre	on: 24/02/2014 13:54
Service: Carriageway	Subject: Potholes	Classification: Request for service
Desc.: large pothole on left hand side by the bus lane. Approx 16 inches wide callers front wheel went into it . Approx 4/5 inches deep. has caused damage to both nearside tyres. fj/cc (Claim Requested)		
Location: 528443, 138967, C207 just past junction with Industrial Estate towards roundabout	Contact: [REDACTED]	
Enquiry No: 2025065	Logged by: Contact Centre	on: 24/02/2014 13:35
Service: Carriageway	Subject: Potholes	Classification: Request for service
Desc.: caller hit a large pothole outside the garage and has damaged his tyre. its about 48 inches long and 20 wide and about 4 inches deep. wants a claim form. (Claim Requested)		
Location: outside the kia garage. 528308, 138716	Contact: [REDACTED]	
Enquiry No: 2025000	Logged by: Contact Centre	on: 24/02/2014 11:39
Service: Carriageway	Subject: Potholes	Classification: Request for service
Desc.: This lady has hit a pot hole about 12/15inch and about 4/5 inch deep. She will be claiming and sending in pictures (Claim Requested)		
Location: 528262, 138603 about half way	Contact: [REDACTED]	
Enquiry No: 2024903	Logged by: Love Clean Streets	on: 24/02/2014 08:59
Service: Carriageway	Subject: Potholes	Classification: Request for service
Desc.: A deep pothole in the main part of the carriageway jon the Gatwick Road, Crawley just adjacent to the Kia Showroom going away from gatwick Airport towards Crawley		
Location: 11 Gatwick Road, Magellan Ter, Crawley, West Sussex RH10 9PJ, UK	Contact:	
Enquiry No: 2024885	Logged by: Love Clean Streets	on: 24/02/2014 03:13
Service: Carriageway	Subject: Condition	Classification: Request for service
Desc.: Massive pot hole and pretty much the entire road is crumbling !!!		
Location: 1 Gatwick Road, Crawley, RH10 9	Contact:	
Enquiry No: 2024563	Logged by: Contact Centre	on: 21/02/2014 09:37
Service: Bridges and Subways	Subject: Potholes	Classification: Request for service
Desc.: caller hit a large pothole this morning by garage and has damaged front tyre. approx size unknown but was large and wants a claims form. cep cc (Claim Requested)		
Location: by the garage just before manor royal 528155, 138421	Contact: [REDACTED]	
Enquiry No: 2024544	Logged by: Love Clean Streets	on: 21/02/2014 09:09
Service: Carriageway	Subject: Potholes	Classification: Request for service
Desc.: Massive crater on southbound side		
Location: 11 Gatwick Road, Magellan Ter, Crawley, West Sussex RH10 9PJ, UK	Contact:	
Enquiry No: 2024316	Logged by: Love Clean Streets	on: 20/02/2014 11:29
Service: Carriageway	Subject: Potholes	Classification: Request for service
Desc.: Large pothole opened outside Lookers Mercedes entrance - was recently filled in but is now open again and at least 10 inches deep.		
Location: 2 Gatwick Road, Bank Precinct, Crawley, West Sussex RH10 9RF, UK	Contact:	

Effective: 10/03/2012 to 10/03/2014

Display Action Officer: No

Street: Gatwick Road (9700110)

Customer Services

Enquiry No: 2023821	Logged by: Love Clean Streets	on: 18/02/2014 15:47
Service: Carriageway	Subject: Potholes	Classification: Request for service
Desc.: Potholes in Road from Fleming Way upto Manor Royal by the nissan garage.		
Location: 11 Gatwick Road, Magellan Ter, Crawley, West Sussex RH10 9PJ, UK	Contact:	
Enquiry No: 2023707	Logged by: Contact Centre	on: 18/02/2014 12:21
Service: Carriageway	Subject: Potholes	Classification: Request for service
Desc.: On the left hand side near the Thales / Toyota building. About 3ft long, 1ft wide and about 5-6 inches deep. Looks like a failed repair, or may have been repaired but hole appeared again. (Claim Requested)		
Location: 528306, 138708 On the left hand side near the Thales / Toyota building.	Contact: [REDACTED]	
Enquiry No: 2023521	Logged by: Contact Centre	on: 17/02/2014 15:19
Service: Carriageway	Subject: Potholes	Classification: Request for service
Desc.: Heading down from North to South on the Gatwick Road just before it gets to the Hazelwick Avenue there is a large pothole that [REDACTED] hit. He pulled over near the Hazelwick Roundabout and found that the damage is a scratched alloy and big bulge in the tyre and Mr Wyatt will also be getting the tracking checked. He has not got the size of the pothole. Many thanks cc dh 17/02/2014 (Claim Requested)		
Location: 528171, 138173 Gatwick Road, Crawley	Contact: [REDACTED]	
Enquiry No: 2023451	Logged by: Contact Centre	on: 17/02/2014 13:54
Service: Carriageway	Subject: Drainage	Classification: Request for service
Desc.: Blocked drain causes a huge puddle when it rains heavy. When it does puddle traffic drives in the middle of road to get past it.		
Location: Opposite Aviareps House. 528477, 139064	Contact: [REDACTED]	
Enquiry No: 2023444	Logged by: Contact Centre	on: 17/02/2014 13:52
Service: Carriageway	Subject: Drainage	Classification: Request for service
Desc.: Blocked Gully Drain when it rains heavy the drain is not taking away water and causing puddling in the road.		
Location: Opposite Side of Garage. 528167, 138446 jst north of manor royal	Contact: [REDACTED]	
Plot Number: 9,999.00	Feature Id - Location:	Feature Type: Whole Street Feature
Job Number: 938254	Defect Number: 3056204	
Enquiry No: 2023433	Logged by: Contact Centre	on: 17/02/2014 13:41
Service: Footways and Cycleways	Subject: Overgrown vegetation	Classification: Request for service
Desc.: Ivy is now encroaching on footpath. Half of footpath is covered in ivy. Height is approx 6 inches.		
Location: By Street Light Numbers 67, 71, 85. 123456, 123456	Contact: [REDACTED]	
Enquiry No: 2023130	Logged by: Love Clean Streets	on: 15/02/2014 21:38
Service: Carriageway	Subject: Condition	Classification: Request for service
Desc.: Break in road surface just past traffic lights heading towards crawley		
Location: null	Contact:	
Enquiry No: 2021798	Logged by: Love Clean Streets	on: 11/02/2014 08:36
Service: Carriageway	Subject: Potholes	Classification: Request for service
Desc.: This road is becoming a total nightmare. The entire road is full of deep potholes and gullies from the Radford Road end to the roundabout before the Three Bridges flyover		
Location: 71 Gatwick Road, Crawley, West Sussex RH10 9RD, UK	Contact:	
Enquiry No: 2021108	Logged by: Contact Centre	on: 07/02/2014 08:56
Service: Carriageway	Subject: Potholes	Classification: Request for service
Desc.: Series of potholes which vary in size across both sides of the carriageway. Large to small potholes which are full of water.		
Location: From the Roundabout at Manor Royal up to James Watt Way. 123456, 123456	Contact: [REDACTED]	

Effective: 10/03/2012 to 10/03/2014
Street: Gatwick Road (9700110)

Display Action Officer: No

Customer Services

Enquiry No: 2021107	Logged by: Contact Centre	on: 07/02/2014 08:52
Service: Carriageway	Subject: Drainage	Classification: Request for service
Desc.: blocked gully drain on left hand corner as you turn left of roundabout from the junction of fleming way.		
Location: As you turn left on roundabout from Fleming Way. 528399, 138917	Contact:	
Enquiry No: 2020513	Logged by: Love Clean Streets	on: 05/02/2014 08:40
Service: Carriageway	Subject: Potholes	Classification: Request for service
Desc.: The whole of the section of this road between the two roundabouts is full of pot holes on both sides. It is dangerous and people are driving to avoid the holes in the road and not looking where they are driving.		
Location: between manor royal & flemming way	Contact:	
Enquiry No: 2020508	Logged by: Love Clean Streets	on: 05/02/2014 08:22
Service: Carriageway	Subject: Condition	Classification: Request for service
Desc.: Large dip/crater in road just after speed camera		
Location: Gatwick Road, Crawley, RH10 9	Contact:	
Plot Number: 9,999.00	Feature Id - Location:	Feature Type: Whole Street Feature
Job Number: 937239		
Enquiry No: 2020115	Logged by: Love Clean Streets	on: 03/02/2014 15:23
Service: Carriageway	Subject: Potholes	Classification: Request for service
Desc.: Two large potholes have appeared on the exit to this roundabout, could cause damage to cars and buses. Very dangerous cycles/motorcycles		
Location: Gatwick Road, Crawley, RH10 9	Contact:	
Enquiry No: 2020002	Logged by: Love Clean Streets	on: 03/02/2014 08:38
Service: Footways and Cycleways	Subject: Overgrown vegetation	Classification: Request for service
Desc.: Opposite Plumbase, Gatwick Road, Crawley footplate overgrown making you walk in cycle lane.		
Location: Opp Plumbase	Contact:	
Enquiry No: 2019925	Logged by: Love Clean Streets	on: 03/02/2014 10:03
Service: Bridges and Subways	Subject: Condition	Classification: Request for information
Desc.: To large pot holes have appeared on the exit to the roundabout.		
Location: junc Fleming Way	Contact:	
Enquiry No: 2019560	Logged by: Contact Centre	on: 31/01/2014 09:05
Service: Carriageway	Subject: Potholes	Classification: Request for service
Desc.: Lots of deep pothole all along road could not give any size road needs to be resurfaced.		
Location: All along road 528512, 139341	Contact:	
Plot Number: 9,999.00	Feature Id - Location:	Feature Type: Whole Street Feature
Job Number: 935910		
Enquiry No: 2016787	Logged by: Contact Centre	on: 17/01/2014 09:30
Service: Emergency	Subject: Drainage	Classification: Request for service
Desc.: Sussex Police have closed off the road due to flooding and need highways to attend asap to close. Incident No:21717/01/2014		
Location: From A23 roundabout to Beehive Ring road 528357, 139993	Contact: SUSSEX POLICE 2014	

Effective: 10/03/2012 to 10/03/2014
Street: Gatwick Road (9700110)

Display Action Officer: No

Customer Services

Enquiry No: 2016333 **Logged by:** Contact Centre **on:** 15/01/2014 12:56
Service: Information request **Subject:** Callback requested **Classification:** Request for information
Desc.: Customer referring to case ref: 1 [REDACTED] 88, carriageway around manhole cover under footbridge near Churchill Court. Customer says this has been repaired 3 times and each time the defect has returned. Customer wishes to be called back to discuss why the repairs are only temporary and kepp recurring. Customer has been told the repairs cost &#pound;50 a time and says it is a waste that by this information it has now cost &#pound;150 for the problem to keep reappearing. (Call Back Requested)
Location: 528145, 138268 under footbridge near Churchill Court **Contact:** [REDACTED]

Enquiry No: 2016281 **Logged by:** Love Clean Streets **on:** 15/01/2014 10:58
Service: Carriageway **Subject:** Potholes **Classification:** Request for service
Desc.: I am writing to inform you of a very large and dangerous pothole outside the Nissan dealership on Gatwick Road (Crawters Brook) in Crawley, just as you come to the roundabout.
Location: Gatwick Road, Crawley, RH10 9 **Contact:**

Enquiry No: 2016257 **Logged by:** Love Clean Streets **on:** 15/01/2014 10:16
Service: Carriageway **Subject:** Potholes **Classification:** Request for service
Desc.: VERY LARGE POTHOLE!! Extremely dangerous as its a very busy junction onto a busy roundabout - I unfortunately drove into it as it was raining very hard and could not see it in the road!
Location: Gatwick Road, Crawley, RH10 9 **Contact:**

Enquiry No: 2016009 **Logged by:** Contact Centre **on:** 14/01/2014 09:35
Service: Carriageway **Subject:** Potholes **Classification:** Request for service
Desc.: Pothole reported to Sussex Police. Information is that Pothole is deep and very bad. Dangerous. Incident No:299/14/01/14
Location: Opposite Nissan Garage. 528404, 138917 **Contact:** SUSSEX POLICE 2014

Plot Number: 9,999.00 **Feature Id - Location:** **Feature Type:** Whole Street Feature
Job Number: 936282

Enquiry No: 2015362 **Logged by:** Contact Centre **on:** 09/01/2014 12:45
Service: Carriageway **Subject:** Potholes **Classification:** Request for service
Desc.: This pot hole is in the middle of two lanes roughly 4-5 inches deep and width is about a ft, When Mr Davies hit the pot hole it instantly bgurst his new tyre that was fitted only 3 months ago, he took the car to the garage and he has had to buy a new tyre again (Claim Requested)
Location: as you come out of Fleming road and meet the roundabout turn left into gatwick road and its in the middle of the road near the traffic lights **Contact:** [REDACTED]

Plot Number: 9,999.00 **Feature Id - Location:** **Feature Type:** Whole Street Feature
Job Number: 935919 **Defect Number:** 3053955

Enquiry No: 2014304 **Logged by:** Love Clean Streets **on:** 06/01/2014 09:09
Service: Carriageway **Subject:** Condition **Classification:** Request for service
Desc.: Large dips/holes in road both directions of travel which cause cars to avoid by using bus lane.....
Location: 56 Gatwick Road, Crawley, RH10 9 **Contact:**

Enquiry No: 2014051 **Logged by:** Love Clean Streets **on:** 03/01/2014 13:01
Service: Carriageway **Subject:** Potholes **Classification:** Request for service
Desc.: There is a very large pothole in the bus lane, this has now been reported and repaired several times over the last few months and has again broken up. This has now caused damage to our buses and we are currently having to avoid using this lane. Please could this be reapiored properly this time.
Location: Gatwick Road, Crawley, RH10 9 **Contact:**

Enquiry No: 2011997 **Logged by:** Love Clean Streets **on:** 16/12/2013 13:43
Service: Carriageway **Subject:** Condition **Classification:** Request for service
Desc.: this was filled in really badly back in Aug/Sept. It is now worse than ever
Location: Gatwick Road, Crawley, RH10 9 **Contact:**

Effective: 10/03/2012 to 10/03/2014
Street: Gatwick Road (9700110)

Display Action Officer: No

Customer Services

Enquiry No: 2009546 **Logged by:** Love Clean Streets **on:** 14/11/2013 15:21
Service: Footways and Cycleways **Subject:** Trees **Classification:** Request for service
Desc.: Tree is overhanging cycle path so low that you are struck in the face by branches if you do not duck. High risk of personal injury to cyclist.
Location: Gatwick Road, Crawley, RH10 9 **Contact:**

Enquiry No: 2008822 **Logged by:** Contact Centre **on:** 08/11/2013 09:41
Service: Carriageway **Subject:** Potholes **Classification:** Request for service
Desc.: caller reporting large pothole at the edge of the road which is approx 5 inches deep and dustbin lid in size looks as if the road has sunk. pothole is currently full of water
Location: outside the garage approaching the roundabout 528169, 138441 **Contact:** [REDACTED]

Enquiry No: 2008208 **Logged by:** Love Clean Streets **on:** 04/11/2013 12:11
Service: Carriageway **Subject:** Ironworks **Classification:** Request for service
Desc.: Manhole surround breaking up. This was repaired a couple of months ago but is bad once more and needs repair again. This is heading North, where the left filter lane joins the main on Gatwick road just after the flyover.
Location: , at junction with Churchill Ct. **Contact:**

Enquiry No: 2007618 **Logged by:** Love Clean Streets **on:** 29/10/2013 22:34
Service: Footways and Cycleways **Subject:** Condition **Classification:** Request for service
Desc.: There is a lot of grit, stones and mud on the pavement / cycle path here making it extremely dangerous for cyclists coming round the corner or just to maintain grip at all. There is a lot of mud as well where cars have parked half on the grass and paved area. Please could it be swept / cleaned in some way.
Location: Gatwick Road, Crawley **Contact:**

Enquiry No: 2007430 **Logged by:** Contact Centre **on:** 29/10/2013 09:09
Service: Carriageway **Subject:** Ironworks **Classification:** Request for service
Desc.: Tarmac around manhole cover has come away was previously done ref 1334188, but customer said a really bad job was done and it needs looking at.
Location: Under the bridge near Churchill Court 528145, 138268 **Contact:** [REDACTED]

Plot Number: 1.00 **Feature Id - Location:** C207/805 **Feature Type:** Single 2-Lane Carriageway
Job Number: 933096 **Defect Number:** 3051243

Enquiry No: 2007418 **Logged by:** Love Clean Streets **on:** 29/10/2013 07:28
Service: Carriageway **Subject:** Lining **Classification:** Request for service
Desc.: White lines on road almost gone very dangerous due to bus lanes etc. it's almost the whole length of the road.
Location: 47 Gatwick Road, Crawley **Contact:**

Enquiry No: 2006485 **Logged by:** Love Clean Streets **on:** 22/10/2013 06:54
Service: Carriageway **Subject:** Potholes **Classification:** Request for service
Desc.: The pot hole at this location has now reappeared. It is in the lane where the bus lane finishes and the cars move over making it unavoidable. It is quite a deep hole.
Location: Gatwick Road, Crawley, RH10 9 **Contact:**

Plot Number: 9,999.00 **Feature Id - Location:** **Feature Type:** Whole Street Feature
Job Number: 69688 **Defect Number:** 20003179

Enquiry No: 2006417 **Logged by:** Love Clean Streets **on:** 21/10/2013 12:13
Service: Carriageway **Subject:** Condition **Classification:** Request for service
Desc.: Potholes along the jointing lines which have spread along the boundary between the bus lane and the traffic lane in several places on Gatwick Road between Fleming Way and Manor Royal. Have been present for months. Estimate holes up to 60cm wide and several metres long, up to approx 60 mm depth. Edward Smith, Upper Beeding, Community Highway Volunteer.
Location: Gatwick Road, Crawley, RH10 9 **Contact:**

Plot Number: 9,999.00 **Feature Id - Location:** **Feature Type:** Whole Street Feature
Job Number: 69687 **Defect Number:** 20003178

Effective: 10/03/2012 to 10/03/2014
Street: Gatwick Road (9700110)

Display Action Officer: No

Customer Services

Enquiry No: 2004261	Logged by: Love Clean Streets	on: 26/09/2013 08:12
Service: Carriageway	Subject: Potholes	Classification: Request for service
Desc.: Hole in road , opposite Northwood Park		
Location: Northwood Park, Crawley, RH10 9		Contact:
Enquiry No: 2004021	Logged by: Love Clean Streets	on: 23/09/2013 22:33
Service: Carriageway	Subject: Lining	Classification: Request for service
Desc.: Most of Gatwick road is devoid of white lines.this shows bus lane and North and south bound traffic. Quite dangerous as i found an hour ago (2210hrs)		
Location: Gatwick Road, Crawley, RH10 9		Contact:
Plot Number: 9,999.00	Feature Id - Location:	Feature Type: Whole Street Feature
Job Number: 928888		
Enquiry No: 2002561	Logged by: Love Clean Streets	on: 09/09/2013 14:33
Service: Carriageway	Subject: Condition	Classification: Request for service
Desc.: Largo pothole in road directly outside the new Lookers Mercedes dealership. It is very deep at least 20 inches and needs filling.		
Location: 78 Gatwick Road, Crawley, RH10 9		Contact:
Enquiry No: 2002417	Logged by: Love Clean Streets	on: 07/09/2013 08:26
Service: Carriageway	Subject: Potholes	Classification: Request for service
Desc.: Potholes and general poor road condition		
Location: Gatwick Road, Crawley, RH10 9		Contact:
Enquiry No: 2002416	Logged by: Love Clean Streets	on: 07/09/2013 08:22
Service: Carriageway	Subject: Condition	Classification: Request for service
Desc.: Break in road causes damage to vehicle when driving speed limit just after traffic lights going towards manor royal		
Location: Gatwick Road, Gatwick, RH6 0		Contact:
Enquiry No: 2001065	Logged by: Love Clean Streets	on: 22/08/2013 19:02
Service: Carriageway	Subject: Lining	Classification: Request for service
Desc.: Line markings from Fleming way to Tinsley lane north have completely disappeared making it dangerous, especially after the filter at the Fleming way roundabout		
Location: 50 Gatwick Road, Crawley, RH10 9		Contact:
Enquiry No: 2000736	Logged by: Contact Centre	on: 20/08/2013 09:10
Service: Information request	Subject: Callback requested	Classification: Request for information
Desc.: confirm 297268 caller says that this is still not cut back difficult for one person to walk on this path now		
Location: gatwick road 528497, 139282		Contact: [REDACTED]
Enquiry No: 610551	Logged by: Faith Talbott	on: 07/03/2014 08:53
Service: Carriageway	Subject: Third party claims	Classification: Request for service
Desc.: The pothole is 110mm deep and 1.5 meters long - PLEASE SEND CLAIM FORM		
Location: Gatwick road on the Crawley industrial estate - map attached		Contact:
Enquiry No: 610486	Logged by: Faith Talbott	on: 03/03/2014 12:21
Service: Carriageway	Subject: Third party claims	Classification: Request for service
Desc.: I'm reporting this and also want to claim for a new wheel as mine is completely damaged - PLEASE SEND CLAIM FORM		
Location: The address is [REDACTED]		Contact:
Outside the Mitsubishi car garage by the bus stop		

Effective: 10/03/2012 to 10/03/2014
Street: Gatwick Road (9700110)

Display Action Officer: No

Customer Services

Enquiry No: 610394 **Logged by:** Faith Talbott **on:** 24/02/2014 10:04
Service: Carriageway **Subject:** Potholes **Classification:** Request for service
Desc.: Pothole.
Location: South bound Gatwick Road, outside Mitsubishi Motors, Manor Royal, Crawley **Contact:**

Enquiry No: 609848 **Logged by:** Faith Talbott **on:** 30/01/2014 10:16
Service: Footways and Cycleways **Subject:** Potholes **Classification:** Request for service
Desc.: APPROX. SIZE: 40 holes of 20cm
APPROX. DEPTH: 10cm
APPROX. DISTANCE FROM KERB: 0
DATE ENCOUNTERED: 2014-01-29
DEFECT DESCRIPTION:
Cycle path is in a terrible state. Amongst the cyclists at work, we call it the "car park of death". It's got multiple potholes, broken surface, gaps in the concrete.
FURTHER INFORMATION:
<http://www.fillthathole.org.uk/hazard/96042>

Location: OS GRID REFERENCE: TQ 28705 40198 . Gatwick to Manor Royal Cycle Path **Contact:**
DISTRICT: Crawley
WARD: Northgate
ROAD NAME: Not Known. Gatwick to Manor Royal Cycle Path
LOCATION DESCRIPTION:
In the car park (on the cycle path part of it)
LOCATION MAP:
<http://www.fillthathole.org.uk/hazard/96042/map>

Enquiry No: 609846 **Logged by:** Faith Talbott **on:** 30/01/2014 09:53
Service: Carriageway **Subject:** Potholes **Classification:** Request for service
Desc.: Big pothole on gatwick road
Location: Big pothole on Gatwick road, near P&H Motorcycles, been there for ages, never repaired. Easily avoidable **Contact:**

Plot Number: 9,999.00 **Feature Id - Location:** **Feature Type:** Whole Street Feature
Job Number: 937238 **Defect Number:** 3055230

Enquiry No: 609352 **Logged by:** Jackie Ferguson **on:** 16/01/2014 08:46
Service: Carriageway **Subject:** Potholes **Classification:** Request for service
Desc.: I am writing to inform you of a very large and dangerous pothole
Location: outside the Nissan dealership on Gatwick Road **Contact:**

Plot Number: 9,999.00 **Feature Id - Location:** **Feature Type:** Whole Street Feature
Job Number: 936282 **Defect Number:** 3054297

Effective: 10/03/2012 to 10/03/2014
Street: Gatwick Road (9700110)

Display Action Officer: No

Customer Services

Enquiry No: 608501 **Logged by:** Vikki Atfield **on:** 15/11/2013 11:55
Service: Information request **Subject:** Email response requested **Classification:** Request for information
Desc.: I am a Crawley resident, and I am after some info regarding where a particular road stops, and in turn becomes another named road.

The road in question is Gatwick Road, on the Industrial estate, where it enters the flyover and becomes Hazelwick Avenue, heading in a southerly direction, towards Three Bridges.

I need to know the EXACT point at which this change happens.

If this is the incorrect e-mail address for this info, I would appreciate either you forward this on to the correct persons, or let me know whom I should be contacting.

I very much appreciate any help you can provide.

Location: Gatwick Road, on the Industrial estate, where it enters the flyover and becomes Hazelwick Avenue, heading in a southerly direction, towards Three Bridges **Contact:**

Enquiry No: 608006 **Logged by:** Jackie Ferguson **on:** 16/10/2013 10:03
Service: Carriageway **Subject:** Other **Classification:** Request for service
Desc.:) Meeting at Crawters Brook went well. Looking to get some dates in the diary and let you know when they are taking place. A question came out of today's meeting you might be able to help with. It relates to permission to cross and use land owned by WSCC at the front of Crawler's Brook to create the park. I attach Land Registry info and another map for your information showing the WSCC ownership. I'm trying to find out who we need to speak to about the relevant permissions to use this land. Can you help? Hopefully it wont be too much of a problem as the area in question is already been used as an informal picnic area.

Location: crawters brook **Contact:**

Enquiry No: 607623 **Logged by:** Karen Patten **on:** 23/09/2013 11:26
Service: Carriageway **Subject:** Street furniture **Classification:** Request for service
Desc.: Pedestrian railings damaged
Location: E: 528362, N: 138860 **Contact:**

Enquiry No: 607593 **Logged by:** Oliver Monnery **on:** 17/09/2013 15:25
Service: Carriageway **Subject:** Condition **Classification:** Request for service
Desc.: Following a meeting (13 Sept 2013) with Cllr. Peter Lamb and local businesses it was raised and observed severe damage to public highway, please see pictures. This included missing kerbs, potholes, damaged footway and verge rutting. Just so you are aware long term solution by way of a TRO is being investigated to protect the highway from such damage, however, in the short term please assess and rectify the current situation.

Location: Location: D174 Gatwick Road Service Road – NSG: 9701088 / 528476-139225 & 528469-139194 **Contact:**
 Location : D174 Rutherford Way – NSG: 9701087 / 528465-13934

Enquiry No: 607426 **Logged by:** Oliver Monnery **on:** 02/09/2013 11:56
Service: Footways and Cycleways **Subject:** Overgrown vegetation **Classification:** Request for service
Desc.: I am contacting you regarding the bushes located at the front of the building where I work - address as above. The bushes are very overgrown (blackberries) and is hindering people walking along the public footpath (the pathway in question leads to the bus stop) opposite from Subway/Topps Tiles.
Location: O/S The Office Building, opp subway and topps tiles **Contact:**

Enquiry No: 607375 **Logged by:** Alisa Gorringe **on:** 29/08/2013 11:41
Service: Footways and Cycleways **Subject:** Overgrown vegetation **Classification:** Request for service
Desc.: Please see below email trail. Are you able to assist in resolving the overgrown bushes located outside 'The Office Building', Gatwick Road, Crawley, West Sussex RH10 9RZ. I attach a photo for your reference - as you can see it is extremely difficult to walk along this pathway due to the bushes being so overgrown.
Location: Located outside 'The Office Building', Gatwick Road, Crawley **Contact:**

Effective: 10/03/2012 to 10/03/2014
Street: Gatwick Road (9700110)

Display Action Officer: No

Customer Services

Enquiry No: 607298 **Logged by:** Oliver Monnery **on:** 22/08/2013 16:02
Service: Footways and Cycleways **Subject:** Overgrown vegetation **Classification:** Request for service
Desc.: Overgrown bushes mean I have to step into a busy road to make my way to/from the bus stop
Location: Bus Stop in Gatwick Rd heading east after Tinsley Lane North & Goods Yard/Forge Wood **Contact:**

Enquiry No: 606620 **Logged by:** Oliver Monnery **on:** 12/07/2013 12:13
Service: Footways and Cycleways **Subject:** Overgrown vegetation **Classification:** Request for service
Desc.: Case ID: 131001844400 - reply to help point - footpath obstruction due to overgrown shrubs & grass opposite the Nissan Garage on other side of the road - land mark could be a weeping willow tree which we think belongs to CBC
Location: Gatwick road opposite the Nissan Garage on other side of the road **Contact:**

Enquiry No: 606546 **Logged by:** Oliver Monnery **on:** 09/07/2013 14:21
Service: Carriageway **Subject:** Lining **Classification:** Request for service
Desc.: the white lines in particular are very worn, it is difficult to see where the road lines and bus lines are difficult to see, i have seen cars drifting around as they can not see the white lines, if it is possible and comes under your control would it be possible to have the white lines replaced, thanks for your time
Location: gatwick road between fleming way and james watt way, crawley ind eas **Contact:**

Plot Number: 9,999.00 **Feature Id - Location:** **Feature Type:** Whole Street Feature
Job Number: 928888

Enquiry No: 606521 **Logged by:** Alisa Gorringer **on:** 08/07/2013 11:16
Service: Footways and Cycleways **Subject:** Overgrown vegetation **Classification:** Request for service
Desc.: 'm enquiring about an area to the front/Side of my business premises that has become extremely over grown. The garden maintenance team for the group of buildings on Bank Precinct haven't tackle this part because its not part of the grounds for this property but it's affecting the appearance of the front of the building. I've attached some pictures for your reference. Would it be possible for someone to look into this and to let me know whether this area is scheduled in to be maintained? [REDACTED]. " i have the photos in my inbox if anyone wants them, please let me know and I will send them to you.
Location: [REDACTED] **Contact:**

Enquiry No: 605551 **Logged by:** Jackie Ferguson **on:** 07/05/2013 14:18
Service: Carriageway **Subject:** Trees **Classification:** Request for service
Desc.:
The photograph shows an oak tree which fell on the building we manage at unit 5 [REDACTED], which has now been removed. There remains an urgent requirement to attend to the adjacent oak tree, which looks like it may fall similarly, representing a danger to passing traffic on Gatwick Road, pedestrians on the pavement and the building itself.
The plan attached from our Land Registry searches shows an asterisk with a circle, the tree now removed, while the asterisk to the north without the circle shows the tree requiring inspection please. I would be grateful if you could investigate and report back to me as to the state of the tree and the best way to proceed, including whether we/you at West Sussex County Council could remove the tree given that it is protected by a TPO.
Location: [REDACTED] **Contact:**

Enquiry No: 605440 **Logged by:** Jackie Ferguson **on:** 26/04/2013 07:43
Service: Carriageway **Subject:** Lining **Classification:** Request for service
Desc.: requesting double yellow lines
Location: [REDACTED] **Contact:**

Enquiry No: 604248 **Logged by:** Jackie Ferguson **on:** 24/01/2013 10:24
Service: Carriageway **Subject:** Condition **Classification:** Request for service
Desc.: please can something be done about the road condition on the Building Site in Gatwick Road Crawley. It's the site for the new Mercedes Garage. The road is in dreadful condition and the footpath is also causing problems. There has been a roadsweeper in attendance from yesterday but does not seem to be having any effect. I know the conditions of the last week have been dire but this is an on going problem. The road is often left covered in stones and debris. This is a bus route and is used by cars and lorries for access to offices and buildings.
Location: gatwick road **Contact:**

Effective: 10/03/2012 to 10/03/2014
Street: Gatwick Road (9700110)

Display Action Officer: No

Customer Services

Enquiry No: 311375 **Logged by:** Jackie Ferguson **on:** 10/03/2014 10:42
Service: Carriageway **Subject:** Parking **Classification:** Request for service
Desc.: [REDACTED] is a 'service road' of sorts.

They have been in contact with the Police and apparently are having a meeting with someone on the 12th to discuss the problems of parking in general.

Having looked on the TRO I want to know as the highway boundary is up to their 'driveways' can we enforce the DYL marked on the main road parallel to this service road it is in fact Gatwick Road.

I am asking as I said I would to try and find a solution to the problems there.

Has anyone any idea about the problems here?

Location: [REDACTED] **Contact:**

Enquiry No: 311331 **Logged by:** Jackie Ferguson **on:** 06/03/2014 09:32
Service: Carriageway **Subject:** Lining **Classification:** Request for service
Desc.: What action might be taken regarding the confusion that might be solved by new "arrow" road markings pointed out be [REDACTED]

His concern being that road users tend to be confused by the solid white line of the bus lane and end up travelling northwards along Gatwick Road but in the southern side – so into on-coming traffic. Arrows directing people to the right side of the road may help. He attaches a useful drawing.

Location: gatwick road **Contact:**

Enquiry No: 311190 **Logged by:** Ian Brett (SAO) **on:** 26/02/2014 18:14
Service: Carriageway **Subject:** Condition **Classification:** Request for service
Desc.: Numerous potholes in carriageway - pothole Patrol needed - approx 20 holes in total loosely marked
Location: Throughout - most notably between Manor Royal & Fleming Way **Contact:**

Plot Number: 9,999.00 **Feature Id - Location:** **Feature Type:** Whole Street Feature

Enquiry No: 311188 **Logged by:** Ian Brett (SAO) **on:** 26/02/2014 17:36
Service: Carriageway **Subject:** Condition **Classification:** Request for service
Desc.: Approx 12 x 2m patchy/uneven area in northbound carriageway & 1.4 x 1.4m patchy area around adjacent W.O. Valves
Location: 5m & 15m south of Whittle Way **Contact:**

Plot Number: 9,999.00 **Feature Id - Location:** **Feature Type:** Whole Street Feature

Enquiry No: 311187 **Logged by:** Ian Brett (SAO) **on:** 26/02/2014 17:35
Service: Carriageway **Subject:** Condition **Classification:** Request for service
Desc.: Approx 15 x 1.2m patchy area in southbound carriageway by bus stop between lamp column nos.44 & 46
Location: Adjacent to Mitsubishi Dealers (approx 200m south of Tinsley Lane) **Contact:**

Plot Number: 9,999.00 **Feature Id - Location:** **Feature Type:** Whole Street Feature

Enquiry No: 311186 **Logged by:** Ian Brett (SAO) **on:** 26/02/2014 17:33
Service: Carriageway **Subject:** Condition **Classification:** Request for service
Desc.: Approx 7 x 1m sunken/crazed area in northbound carriageway to north of Traffic Signals
Location: By lamp column no.111 (60m north of Beehive Ring Road) **Contact:**

Plot Number: 9,999.00 **Feature Id - Location:** **Feature Type:** Whole Street Feature

Effective: 10/03/2012 to 10/03/2014
Street: Gatwick Road (9700110)

Display Action Officer: No

Customer Services

Enquiry No: 310515 **Logged by:** Adam Malski **on:** 14/01/2014 09:52
Service: Carriageway **Subject:** Potholes **Classification:** Request for service
Desc.: Police report of dangerous pot hole. ref: 299 14/1/14
Location: o/s Nissan garage **Contact:**

Enquiry No: 310248 **Logged by:** Ian Brett (SAO) **on:** 09/12/2013 16:06
Service: Carriageway **Subject:** Condition **Classification:** Request for service
Desc.: Patchy area with various small holes in southbound carriageway
Location: Outside KIA Motors (South of Tinsley Lane) **Contact:**

Plot Number: 9,999.00 **Feature Id - Location:** **Feature Type:** Whole Street Feature

Enquiry No: 310031 **Logged by:** Paula Buckland **on:** 07/11/2013 15:54
Service: Carriageway **Subject:** Other **Classification:** Request for service
Desc.: Would like to know the exact point where Gatwick Road becomes Hazelwick Avenue
Location: At flyover **Contact:**

Enquiry No: 309986 **Logged by:** Paula Buckland **on:** 05/11/2013 16:00
Service: Carriageway **Subject:** Lining **Classification:** Request for service
Desc.: Complaining about the state of the road markings, almost completely invisible in the dark.
Location: Between Fleming Way and Radford Road **Contact:**

Enquiry No: 309893 **Logged by:** Maureen Vaughey **on:** 22/10/2013 11:10
Service: Carriageway **Subject:** Third party claims **Classification:** Request for service
Desc.: damage caused to vehicle on 1st Oct due to a large pothole
Location: Gatwick Road heading towards town centre **Contact:**

Enquiry No: 309889 **Logged by:** Eleanor Harries **on:** 21/10/2013 16:08
Service: Carriageway **Subject:** Condition **Classification:** Request for service
Desc.: previous repair failing
Location: o/s Nissan - approaching Manor Royal Roundabout **Contact:**

Enquiry No: 309725 **Logged by:** Lidia Gage **on:** 20/09/2013 13:58
Service: Carriageway **Subject:** Lining **Classification:** Request for service
Desc.: Description of issue: It has been brought to my attention that this area of Manor Royal where the road markings are so faded that they are difficult to see and that this is a safety issue. These issues have been previously highlighted following visuals audits on December 2011, December 2012 and again in April 2013. I provide extracts from those reports below. Sometime ago I was informed that the Gatwick Road lines were programmed for repainting. However, no action has been taken and the issue has been reported to me again in my capacity as Executive Director. I provide photographs of both these areas.
Please can you look into this as a matter of urgency as it is a real safety issue, as the photos from Priestley Way/Rutherford Way highlight, and let me know of when action will be taken to remedy this problem.
Location: Rutherford Way **Contact:**

Effective: 10/03/2012 to 10/03/2014
Street: Gatwick Road (9700110)

Display Action Officer: No

Customer Services

Enquiry No: 309723 **Logged by:** Lidia Gage **on:** 20/09/2013 13:44
Service: Carriageway **Subject:** Lining **Classification:** Request for service

Desc.: Description of issue: It has been brought to my attention that there are areas of Manor Royal where the road markings are so faded that they are difficult to see and that this is a safety issue. Two areas in particular have been highlighted:

- Gatwick Road: north side of the Hazelwick Flyover to the roundabout at Manor Royal (road) and the stretch of road between the Fleming Way roundabout and James Watt Way roundabout

Location: north side of the Hazelwick Flyover to the roundabout at Manor Royal (road) and the stretch of road between the Fleming Way roundabout and James Watt Way roundabout **Contact:**

Enquiry No: 309667 **Logged by:** Ian Brett (SAO) **on:** 17/09/2013 16:28
Service: Carriageway **Subject:** Condition **Classification:** Request for service
Desc.: Various old patching works & recent sunken area on line of surface water drainage pipe along near side (bus lane) of southbound carriageway - possible drainage investigation needed? (See also job no.925289 & 923891)
Location: Southbound carriageway 50m north of roundabout junction with Manor Royal **Contact:**

Plot Number: 9,999.00 **Feature Id - Location:** **Feature Type:** Whole Street Feature
Job Number: 930946

Enquiry No: 309664 **Logged by:** Eleanor Harries **on:** 17/09/2013 15:25
Service: Carriageway **Subject:** Drainage **Classification:** Request for service

Desc.: Gully not draining

Location: By col 71 opp forwood **Contact:**

Plot Number: 9,999.00 **Feature Id - Location:** **Feature Type:** Whole Street Feature

Enquiry No: 309621 **Logged by:** Ian Brett (SAO) **on:** 12/09/2013 20:47
Service: Carriageway **Subject:** Condition **Classification:** Request for service

Desc.: Holed area in northbound carriageway

Location: Adjacent to Whittle Way **Contact:**

Plot Number: 9,999.00 **Feature Id - Location:** **Feature Type:** Whole Street Feature
Job Number: 930785 **Defect Number:** 3049015

Enquiry No: 309620 **Logged by:** Ian Brett (SAO) **on:** 12/09/2013 20:46
Service: Carriageway **Subject:** Condition **Classification:** Request for service

Desc.: 1.4 x 0.1m holed area at edge of cover in northbound carriageway on approach to roundabout

Location: Northbound approach to Fleming Way **Contact:**

Plot Number: 9,999.00 **Feature Id - Location:** **Feature Type:** Whole Street Feature
Job Number: 930782 **Defect Number:** 3049013

Enquiry No: 309537 **Logged by:** Eleanor Harries **on:** 29/08/2013 16:03
Service: Carriageway **Subject:** Drainage **Classification:** Request for service

Desc.: Gully ponding even though it hasn't rained

Location: On gatwick road northbound opp sterling park **Contact:**

Plot Number: 9,999.00 **Feature Id - Location:** **Feature Type:** Whole Street Feature

Enquiry No: 309133 **Logged by:** Maureen Vaughey **on:** 05/06/2013 08:05
Service: Licences **Subject:** Cross overs **Classification:** Request for information

Desc.: vco request via Hugh Davies in legal

Location: vco request via Hugh Davies in legal **Contact:**

Effective: 10/03/2012 to 10/03/2014
Street: Gatwick Road (9700110)

Display Action Officer: No

Customer Services

Enquiry No: 308477 **Logged by:** Ian Brett (SAO) **on:** 08/03/2013 13:43
Service: Footways and Cycleways **Subject:** Street furniture **Classification:** Request for service
Desc.: damaged section of Guardrail by pelican crossing
Location: on splitter island to south of Radford Road Roundabout **Contact:**

Plot Number: 9,999.00 **Feature Id - Location:** **Feature Type:** Whole Street Feature
Job Number: 66759 **Defect Number:** 20000253

Enquiry No: 308188 **Logged by:** Catrin Jones **on:** 29/01/2013 13:31
Service: Carriageway **Subject:** Potholes **Classification:** Request for service
Desc.: On Thursday 24th January as I finished work I was on my way home and came into contact with a pot hole. 2 weeks earlier on the Monday 7th January I had already hit a pothole on that same stretch. It seems to have been filled in temporarily. However there is a rough section of road just after that first repair and just before it also there is a growing pot hole which I unfortunately went in during rush hour at about 6 in the evening. I sustained a substantial scuff to my rear left wheel and to the front wheel my wheel alignment seems to have been completely knocked out of place. When I brake my car also pulls to one side immediately as a result.

I would like to put in a claim as I hardly find it fitting that a busy road like this should be subject to pot holes which have quite clearly damaged my car and now repairs are needed.

Location: **Contact:**

Enquiry No: 308018 **Logged by:** Maureen Vaughey **on:** 09/01/2013 11:58
Service: Carriageway **Subject:** Condition **Classification:** Request for service
Desc.: I would like to ask if you could send out your survey team, or "rangers" as I believe they are now called, to look at the section of road in Crawley, it Gatwick Road, the sector between Manor Royal and Fleming Way, north and outhbound side.

Location: This section has extremely high traffic flow and heavy weight lorries, and potholes and wear is now appearing please can it be dealt with before damage to our vehicles, or worse an accident .
 I would like to ask if you could send out your survey team, or "rangers" as I believe they are now called, to look at the section of road in Crawley, it Gatwick Road, the sector between Manor Royal and Fleming Way, north and outhbound side. **Contact:**

This section has extremely high traffic flow and heavy weight lorries, and potholes and wear is now appearing please can it be dealt with before damage to our vehicles, or worse an accident .

Enquiry No: 307575 **Logged by:** Ian Brett (SAO) **on:** 10/10/2012 13:06
Service: Carriageway **Subject:** Signs **Classification:** Request for service
Desc.: leaning signpost alongside southbound carriageway
Location: adjacent to Kia Motors (approx 70m south of Fleming Way) **Contact:**

Plot Number: 9,999.00 **Feature Id - Location:** **Feature Type:** Whole Street Feature

Enquiry No: 307198 **Logged by:** Ian Brett (SAO) **on:** 17/08/2012 08:30
Service: Footways and Cycleways **Subject:** Signs **Classification:** Request for service
Desc.: bus lane sign damaged
Location: os Kia Motors (opposite lamp column no.45) **Contact:**

Plot Number: 9,999.00 **Feature Id - Location:** **Feature Type:** Whole Street Feature
Job Number: 916789

Effective: 10/03/2012 to 10/03/2014

Display Action Officer: No

Street: Gatwick Road (9700110)

Customer Services**Enquiry No:** 306510**Logged by:** NAO ADMIN**on:** 08/05/2012 13:14**Service:** Carriageway**Subject:** Drainage**Classification:** Request for service**Desc.:** Repaired drain, now sunken. On pedestrian crossing, at cycling distance from kerb

Status Reported

Location TQ 28222 38486

Location Description 1 Gatwick Rd, RH10 9DE

Road Name

Hazard Type Surface poorly restored after roadworks

Hazard Description Repaired drain, now sunken. On pedestrian crossing, at cycling distance from kerb

Approximate Size 1m

Approximate Depth 10cm

Approximate distance from Kerb 30cm

Date Encountered 28 Apr 2012

Date Added 28 Apr 2012

Planned Fix Date Unknown

Highway Authority West Sussex County Council

District / Ward / Parish Crawley / Three Bridges

DISTRICT: Crawley

WARD: Three Bridges

LOCATION DESCRIPTION:

1 Gatwick Rd, RH10 9DE

GRID REFERENCE: TQ 28222 38486

Location: Repaired drain, now sunken. On pedestrian crossing, at cycling distance from kerb**Contact:**

Status Reported

Location TQ 28222 38486

Location Description 1 Gatwick Rd, RH10 9DE

Road Name

Hazard Type Surface poorly restored after roadworks

Hazard Description Repaired drain, now sunken. On pedestrian crossing, at cycling distance from kerb

Approximate Size 1m

Approximate Depth 10cm

Approximate distance from Kerb 30cm

Date Encountered 28 Apr 2012

Date Added 28 Apr 2012

Planned Fix Date Unknown

Highway Authority West Sussex County Council

District / Ward / Parish Crawley / Three Bridges

DISTRICT: Crawley

WARD: Three Bridges

LOCATION DESCRIPTION:

1 Gatwick Rd, RH10 9DE

GRID REFERENCE: TQ 28222 38486

Plot Number: 9,999.00**Feature Id - Location:****Feature Type:** Whole Street Feature

Effective: 10/03/2012 to 10/03/2014
Street: Gatwick Road (9700110)

Display Action Officer: No

Customer Services

Enquiry No: 306427	Logged by: Eleanor Harries	on: 25/04/2012 13:54
Service: Carriageway	Subject: Condition	Classification: Request for service
Desc.: 1cover subsidence around cover looks like recent repair failing sunk 80mm		
Location: by pedestrian crossing north of nissan garage		Contact:
Enquiry No: 306426	Logged by: Eleanor Harries	on: 25/04/2012 14:04
Service: Carriageway	Subject: Ironworks	Classification: Request for service
Desc.: thames water cover sunk 40mm do section 81		
Location: slip road gatwick road to crawley avenue opp ramada		Contact:
Enquiry No: 306344	Logged by: Eleanor Harries	on: 30/03/2012 13:25
Service: Carriageway	Subject: Lining	Classification: Request for service
Desc.: painted on carriageway		
Location: o/s remercco and italian pizza at end of service road		Contact:
Enquiry No: 299456	Logged by: Love Clean Streets	on: 06/08/2013 11:25
Service: Footways and Cycleways	Subject: Overgrown vegetation	Classification: Request for service
Desc.: Despite getting a report back from Love West sussex to say this job has been completed, the brambles and nettles are still overgrown on this stretch of path. People are having to walk into a very busy bus lane to avoid the bushes. The exact location of this is between the Bus stop on Gatwick Road and Tinsley Lane. Please could you get somebody out to this asap before someone is injured or damage is caused to clothing		
Location: Gatwick Road, Crawley, RH10 9		Contact:
Enquiry No: 299209	Logged by: Love Clean Streets	on: 02/08/2013 15:39
Service: Carriageway	Subject: Condition	Classification: Request for service
Desc.: Poor road condition gatwick road Crawley		
Location: Gatwick Road, Crawley, RH10 9		Contact:
Enquiry No: 299172	Logged by: Love Clean Streets	on: 03/08/2013 00:23
Service: Carriageway	Subject: Condition	Classification: Request for service
Desc.: More holes gatwick road Crawley		
Location: Gatwick Road, Crawley, RH10 9		Contact:
Enquiry No: 299170	Logged by: Love Clean Streets	on: 03/08/2013 00:21
Service: Carriageway	Subject: Condition	Classification: Request for service
Desc.: Loads of holes like this down gatwick road Crawley poor repair work dangerous to motorcycles !!!		
Location: Gatwick Road, Crawley, RH10 9		Contact:
Enquiry No: 299000	Logged by: Love Clean Streets	on: 01/08/2013 08:10
Service: Footways and Cycleways	Subject: Overgrown vegetation	Classification: Request for service
Desc.: There are brambles and stinging nettles overgrown at this location, spreading out over the path. We are getting complaints from passengers using the buses and staff.		
Location: Gatwick Road, Crawley, RH10 9		Contact:
Enquiry No: 298897	Logged by: Contact Centre	on: 31/07/2013 10:59
Service: Carriageway	Subject: Potholes	Classification: Request for service
Desc.: Number of potholes along the length of the road. Vehicles straddle bus lane to avoid the potholes and as such kick up stones. This has resulted in 4 windscreens being broken and serious concerns regarding the safety of staff and customers at his site and those people who may be waiting at the bus shelter there also. Please could [REDACTED] be contacted to arrange a site visit to discuss with him. (Call Back Requested)		
Location: 528313, 138711 Along the length of the road, but particularly in front of Gatwick Mitsubishi		Contact: [REDACTED]

Effective: 10/03/2012 to 10/03/2014
Street: Gatwick Road (9700110)

Display Action Officer: No

Customer Services

Enquiry No: 297797 **Logged by:** Love Clean Streets **on:** 18/07/2013 13:03
Service: Footways and Cycleways **Subject:** Overgrown vegetation **Classification:** Request for service
Desc.: Hedge row is overgrown and obstructing pavement. This is on a blind bend of a cycle route/pathway or the corner fo a busy road. Vegetation is blocking payment and line of sight if not cleared soon their will be an accident.
Location: Gatwick Road, Gatwick, RH6 0 nr rbt James Watt Way **Contact:**

Enquiry No: 297268 **Logged by:** Contact Centre **on:** 15/07/2013 08:33
Service: Carriageway **Subject:** Overgrown vegetation **Classification:** Request for service
Desc.: From junction of Tinsley Lane North heading south on to Gatwick road, there si around a 100 yards of overgrown vegetation forcing people into the road... caller states that only one person can walk on the pavement.
Location: 528497, 139282 **Contact:** [REDACTED]

Enquiry No: 295994 **Logged by:** Contact Centre **on:** 02/07/2013 16:04
Service: Information request **Subject:** Callback requested **Classification:** Request for information
Desc.: Call back requested to justify painting bus lane lines on a road surface in desperate need of resurfacing. WHY waste such public fundsw when potholes still have to be repaired. Not happy with potholes, some claimed to be nearly 1ft deep now covered in fresh paint. Demanding call back asap. (Call Back Requested)
Location: by Fleming Way; 528552, 139651 **Contact:** [REDACTED]

Enquiry No: 295928 **Logged by:** Love Clean Streets **on:** 02/07/2013 10:39
Service: Carriageway **Subject:** Condition **Classification:** Request for service
Desc.: Pothole, at the roundabout junction of Gatwick road, just after the bus lane stops.
Location: Gatwick Road, Crawley, RH10 9 **Contact:**

Enquiry No: 295522 **Logged by:** Contact Centre **on:** 27/06/2013 12:55
Service: Information request **Subject:** Callback requested **Classification:** Request for information
Desc.: [REDACTED]. She has a driver who is insured with them who was driving through a bus lane. Would like to know the hours drivers can drive through a bus lane if thats something they can do or not. I have located the co-ordinates as best as i can, had very little information on location. Please call to discuss on [REDACTED] and quote ref number [REDACTED]3 (Call Back Requested)
Location: By a Toyota and VW garage, between Rutherford Way and Gatwick Road. 528485, 139205 **Contact:** [REDACTED]

Enquiry No: 295408 **Logged by:** Love Clean Streets **on:** 26/06/2013 16:45
Service: Carriageway **Subject:** Condition **Classification:** Request for service
Desc.: newish manhole cover ,surrounding surface breaking up on 2 sides
Location: Gatwick Road, Crawley, RH10 9 **Contact:**

Enquiry No: 295147 **Logged by:** Love Clean Streets **on:** 25/06/2013 08:32
Service: Carriageway **Subject:** Condition **Classification:** Request for service
Desc.: There is a very large and deep pot hole in the bus lane, we are starting to get repoets of damage to tyres on the buses. Please could someone look at this as soon as possible.
Location: Gatwick Road, Crawley, RH10 9 **Contact:**

Plot Number: 9,999.00 **Feature Id - Location:** **Feature Type:** Whole Street Feature
Job Number: 67932 **Defect Number:** 20001407

Enquiry No: 295090 **Logged by:** Love Clean Streets **on:** 24/06/2013 14:36
Service: Carriageway **Subject:** Condition **Classification:** Request for service
Desc.: very deep pothole, left hand lane, at the end of the bus lane heading towards Hazelwick. extreamly dangerous for cyclists and motorcyclists
Location: Gatwick Road, Crawley, RH10 9 **Contact:**

Effective: 10/03/2012 to 10/03/2014
Street: Gatwick Road (9700110)

Display Action Officer: No

Customer Services

Enquiry No: 295060 **Logged by:** Love Clean Streets **on:** 24/06/2013 12:37
Service: Carriageway **Subject:** Condition **Classification:** Request for service
Desc.: large deep hole with mud coming out
Location: Gatwick Road, Crawley, RH10 9 **Contact:**

Plot Number: 9,999.00 **Feature Id - Location:** **Feature Type:** Whole Street Feature
Job Number: 67911 **Defect Number:** 20001388

Enquiry No: 292480 **Logged by:** Love Clean Streets **on:** 03/06/2013 13:09
Service: Carriageway **Subject:** Potholes **Classification:** Request for service
Desc.: Deep pothole on busy road - Magellan Terrace, Gatwick Road, Crawley RH10 9PJ
Location: Gatwick Road, Crawley, RH10 9 **Contact:**

Enquiry No: 292473 **Logged by:** Love Clean Streets **on:** 03/06/2013 12:57
Service: Carriageway **Subject:** Potholes **Classification:** Request for service
Desc.: Deep pothole on the busy road
Location: Gatwick Road, Crawley, RH10 9 **Contact:**

Enquiry No: 292253 **Logged by:** Love Clean Streets **on:** 31/05/2013 14:38
Service: Carriageway **Subject:** Ironworks **Classification:** Request for service
Desc.: cover dropped below road surface
Location: Gatwick Road, Crawley, RH10 9 **Contact:**

Enquiry No: 292252 **Logged by:** Love Clean Streets **on:** 31/05/2013 14:36
Service: Carriageway **Subject:** Ironworks **Classification:** Request for service
Desc.: cover dropped below road surface
Location: 1 Gatwick Road, Crawley, RH10 9 **Contact:**

Enquiry No: 289054 **Logged by:** Contact Centre **on:** 03/05/2013 10:37
Service: Emergency **Subject:** Pothole **Classification:** Request for service
Desc.: The road surface has broken away around the manhole cover causing a hole of approx 2ftx2ft and 4 inches deep.
Location: Under the footbridge near Churchill Court 528145, 138268 **Contact:** [REDACTED]

Plot Number: 9,999.00 **Feature Id - Location:** **Feature Type:** Whole Street Feature
Job Number: 700472 **Defect Number:** 10118856

Enquiry No: 288992 **Logged by:** Contact Centre **on:** 02/05/2013 15:59
Service: Verges and grass **Subject:** Trees **Classification:** Request for service
Desc.: A tree is leaning over possibly towards the road, it may have been like this for a bit but if the winds pick up it could fall over onto the road. Can someone please caome and have look at this asap.
Also can someone please call Henry regarding this tree. (Call Back Requested)
Location: 528485, 139068 on the side of the road **Contact:** [REDACTED]

Enquiry No: 286831 **Logged by:** Love Clean Streets **on:** 16/04/2013 17:24
Service: Carriageway **Subject:** Potholes **Classification:** Request for service
Desc.: Numerous potholes varying sizes along Gatwick Road from junction with Manor Royal north to A23 London Road road surface is breaking up in places requiring resurfacing
Location: 58 Gatwick Road, Crawley, RH10 9 **Contact:**

Enquiry No: 286830 **Logged by:** Love Clean Streets **on:** 16/04/2013 17:23
Service: Carriageway **Subject:** Potholes **Classification:** Request for service
Desc.: Numerous potholes varying sizes along Gatwick Road from junction with Manor Royal north to A23 London Road road surface is breaking up in places requiring resurfacing
Location: Gatwick Road, Crawley, RH10 9 **Contact:**

Effective: 10/03/2012 to 10/03/2014
Street: Gatwick Road (9700110)

Display Action Officer: No

Customer Services

Enquiry No: 286829 **Logged by:** Love Clean Streets **on:** 16/04/2013 17:22
Service: Carriageway **Subject:** Potholes **Classification:** Request for service
Desc.: Numerous potholes varying sizes along Gatwick Road from junction with Manor Royal north to A23 London Road road surface is breaking up in places requiring resurfacing
Location: 52 Gatwick Road, Crawley, RH10 9 **Contact:**

Enquiry No: 286828 **Logged by:** Love Clean Streets **on:** 16/04/2013 17:21
Service: Carriageway **Subject:** Potholes **Classification:** Request for service
Desc.: Numerous potholes varying sizes along Gatwick Road from junction with Manor Royal north to A23 London Road road surface is breaking up in places requiring resurfacing
Location: Gatwick Road, Crawley, RH10 9 **Contact:**

Enquiry No: 286827 **Logged by:** Love Clean Streets **on:** 16/04/2013 17:20
Service: Carriageway **Subject:** Potholes **Classification:** Request for service
Desc.: Numerous potholes varying sizes along Gatwick Road from junction with Manor Royal north to A23 London Road road surface is breaking up in places requiring resurfacing
Location: Gatwick Road, Crawley, RH10 9 **Contact:**

Enquiry No: 286758 **Logged by:** Contact Centre **on:** 16/04/2013 14:55
Service: Carriageway **Subject:** Potholes **Classification:** Request for service
Desc.: Cluster of potholes across width of road. Depth estimated. Depth approx 3- 5 inches.
Location: junction with Manor Royal; 528122, 138338 **Contact:** [REDACTED]

Enquiry No: 285734 **Logged by:** Contact Centre **on:** 10/04/2013 09:35
Service: Information request **Subject:** Callback requested **Classification:** Request for information
Desc.: Client works for Sussex Air, and they are wanting to put some air quality modelling on this roundabout they want to know if a Hazzard Assessment has been done for this roundabout so they can proceed with this display. Call back requested. (Call Back Requested)
Location: On the Hazelwick Roundabout
528219, 137961 **Contact:** [REDACTED]

Enquiry No: 284619 **Logged by:** Love Clean Streets **on:** 28/03/2013 23:08
Service: Carriageway **Subject:** Condition **Classification:** Request for service
Desc.: Numerous potholes on Gatwick Road between Fleming way and roundabout
Location: Gatwick Road, Crawley, RH10 9 **Contact:**

Enquiry No: 284000 **Logged by:** Contact Centre **on:** 26/03/2013 11:21
Service: Carriageway **Subject:** Potholes **Classification:** Request for service
Desc.: Caller reporting a large pothole around 2ft wide and about 2-3 inches. Northbound lane, between Whittle Way and Cobham Way . Please investigate
Location: Northbound lane, between Whittle Way and Cobham Way. 528509, 139479 **Contact:** [REDACTED]

Enquiry No: 282056 **Logged by:** Love Clean Streets **on:** 17/03/2013 12:14
Service: Bridges and Subways **Subject:** Condition **Classification:** Request for information
Desc.: Potholes on carriageway by Kia/Hyundai car dealership.
Location: 1 Gatwick Road, Crawley, RH10 9 **Contact:**

Enquiry No: 281647 **Logged by:** Love Clean Streets **on:** 14/03/2013 08:29
Service: Carriageway **Subject:** Potholes **Classification:** Request for service
Desc.: Numerous potholes along 100m stretch
Location: 1 Gatwick Road, Crawley, RH10 9 **Contact:**

Enquiry No: 281645 **Logged by:** Love Clean Streets **on:** 14/03/2013 08:26
Service: Carriageway **Subject:** Potholes **Classification:** Request for service
Desc.: Pothole
Location: Gatwick Road, Crawley, RH10 9 **Contact:**

Effective: 10/03/2012 to 10/03/2014
Street: Gatwick Road (9700110)

Display Action Officer: No

Customer Services

Enquiry No: 281644	Logged by: Love Clean Streets	on: 14/03/2013 08:25
Service: Carriageway	Subject: Potholes	Classification: Request for service
Desc.: Pothole at pedestrian lights		
Location: Gatwick Road, Crawley, RH10 9	Contact:	
Enquiry No: 281058	Logged by: Love Clean Streets	on: 10/03/2013 20:27
Service: Bridges and Subways	Subject: Condition	Classification: Request for information
Desc.: Potholes on both sides of carriageway		
Location: Gatwick Road, Crawley, RH10 9	Contact:	
Enquiry No: 280318	Logged by: Contact Centre	on: 04/03/2013 10:35
Service: Carriageway	Subject: Potholes	Classification: Request for service
Desc.: Caller hit a pothole yesterday and have had to have a tyre replaced. Pothole at estimate is as deep as a coke can and a little bigger then a dinner plate. Please call back to discuss plan of action. (Call Back Requested)		
Location: Heading north on gatwick road from the roundabout of James Watt wat and Radford road towards the roundabout to get onto the London Road. 528426, 528426	Contact: [REDACTED]	
Enquiry No: 279948	Logged by: Contact Centre	on: 28/02/2013 09:33
Service: Carriageway	Subject: Condition	Classification: Request for service
Desc.: Caller is reporting the whole of gatwick road is littered with potholes big and small ,deep and not so deep. There are also sunken manhole covers. Needs looking at as its a bus route with bus lanes and people are driving around the potholes to avoid them		
Location: all the way along Gatwick road particularly at the junction of Fleming way onto Gatwick road 528413, 138924	Contact: [REDACTED]	
Enquiry No: 279759	Logged by: Contact Centre	on: 26/02/2013 16:12
Service: Carriageway	Subject: Potholes	Classification: Request for service
Desc.: caller hit a pothole on the 14 Jan and has damaged his tracking and 2 tyres size unknow and he did report to Surrey who took a time to reply to you. caller would like to make a claim. cep cc (Claim Requested)		
Location: By Oakwood Industrial Park 528218, 138502	Contact: [REDACTED]	
Enquiry No: 279726	Logged by: Love Clean Streets	on: 26/02/2013 14:46
Service: Carriageway	Subject: Condition	Classification: Request for service
Desc.: The current construcion work that is taking place at the new Lookers Mercedes Garage on Gatwick Road is causing a massive amount of mud and stones being deposited on the highway from many large lorries entering and exiting the site. The road is not cleaned at any part of the day. Today it is raining on and off and it is extremely dangerous and a huge skid risk.		
Location: Gatwick Road, Crawley, RH10 9	Contact:	
Enquiry No: 278229	Logged by: Love Clean Streets	on: 15/02/2013 20:30
Service: Carriageway	Subject: Condition	Classification: Request for service
Desc.: 20cm pothole on Gatwick road before Cobham way, going towards Crawley		
Location: Gatwick Road, Crawley, RH10 9	Contact:	
Enquiry No: 278140	Logged by: Love Clean Streets	on: 15/02/2013 13:39
Service: Carriageway	Subject: Condition	Classification: Request for service
Desc.: Sunken man holes - opposite unnamed side road between Stirling Park and roundabout.		
Location: Gatwick Road, Crawley, RH10 9	Contact:	
Enquiry No: 278137	Logged by: Love Clean Streets	on: 15/02/2013 13:35
Service: Carriageway	Subject: Condition	Classification: Request for service
Desc.: 2 large potholes on Gatwick Road, one of them ~5cm deep 30 x 5 cm wide.		
Location: Gatwick Road & Tinsley Lane, Crawley, RH10 9	Contact:	

Effective: 10/03/2012 to 10/03/2014
Street: Gatwick Road (9700110)

Display Action Officer: No

Customer Services

Enquiry No: 276718 **Logged by:** Contact Centre **on:** 08/02/2013 09:45
Service: Emergency **Subject:** Pothole **Classification:** Request for service
Desc.: 2 potholes largest is 4-6incs deep stones are coming out of it and going on to there cars.cc.lh.8.2.13
Location: Out side garage **Contact:** [REDACTED]

Plot Number: 9,999.00 **Feature Id - Location:** **Feature Type:** Whole Street Feature
Job Number: 922561 **Defect Number:** 3041325

Enquiry No: 275413 **Logged by:** Contact Centre **on:** 01/02/2013 09:36
Service: Footways and Cycleways **Subject:** Obstruction **Classification:** Request for service
Desc.: Cafe are putting A bourds on pathway and verge causing people to walk into the road. (Call Back Requested)
Location: Charles Deli-100 yards south of 57 **Contact:** [REDACTED]

Enquiry No: 274947 **Logged by:** Love Clean Streets **on:** 30/01/2013 12:39
Service: Carriageway **Subject:** Potholes **Classification:** Request for service
Desc.: Potholes and damage to carriage way.
Location: Gatwick Road, Crawley, RH10 9 **Contact:**

Enquiry No: 274714 **Logged by:** Contact Centre **on:** 29/01/2013 14:27
Service: Footways and Cycleways **Subject:** Obstruction **Classification:** Request for service
Desc.: Wishes to discuss the problem of heavy lorries parking on the footway forcing pedestrians into the road and creating an obstruction to vehicles wishing to access the site. (Call Back Requested)
Location: rear entrance to DX Ltd **Contact:** [REDACTED]

Enquiry No: 273860 **Logged by:** Contact Centre **on:** 24/01/2013 15:04
Service: Footways and Cycleways **Subject:** Rubbish or Spillages **Classification:** Request for service
Desc.: The customer is report that the slip road at the location is covered with yellow clay mud at the site where there is buiding work going on.It looks like the vehicle are leaving the site and not cleaning down.The customer says that her shoes are covered with mud each time she uses the path,she is saying that it is a slip hazard.
Location: Jun Gatwick Road and Napier Road at the Mecades Benz sale garage. **Contact:** [REDACTED]

Enquiry No: 273767 **Logged by:** Love Clean Streets **on:** 24/01/2013 09:31
Service: Carriageway **Subject:** Condition **Classification:** Request for service
Desc.: Construction mud adding to already wet roads from snow
Location: 78 Gatwick Road, Crawley, RH10 9 **Contact:**

Enquiry No: 273084 **Logged by:** Contact Centre **on:** 18/01/2013 10:14
Service: Carriageway **Subject:** Potholes **Classification:** Request for service
Desc.: Three large pot holes not sure on size as thought they were shadows., to side of Junction
Location: northbound carriageway after the south terminal then theres a bus stop on lh side, over several meters there s three large pot hole on os lane before you get to a set of traffic lights **Contact:** SUSSEX POLICE 2013

Enquiry No: 272753 **Logged by:** Contact Centre **on:** 16/01/2013 13:14
Service: Emergency **Subject:** Pothole **Classification:** Request for service
Desc.: Just over dinner plate sized and about 2-3 inches deep. She, and a number of her work colleagues, have hit this pothole. (Call Back Requested)
Location: Opposite Thales. Pothole is on left hand side near Mitsubishi/Hyundai Garage. **Contact:** [REDACTED]

Plot Number: 9,999.00 **Feature Id - Location:** **Feature Type:** Whole Street Feature
Job Number: 921683 **Defect Number:** 3040538

Effective: 10/03/2012 to 10/03/2014
Street: Gatwick Road (9700110)

Display Action Officer: No

Customer Services

Enquiry No: 271438 **Logged by:** Contact Centre **on:** 08/01/2013 10:12
Service: Carriageway **Subject:** Potholes **Classification:** Request for service
Desc.: Caller reports damage to wheel and tyre due to hole. Near entrance to Oakwood indus Park. Happened on 07/01/2013, at about 7.00pm.
Approx 16 inches long x 8 inch wide x 3 inch deep. (Claim Requested)
Location: Opposite AutoGlass. **Contact:** [REDACTED]

Plot Number: 9,999.00 **Feature Id - Location:** **Feature Type:** Whole Street Feature
Job Number: 828505 **Defect Number:** 2054550

Enquiry No: 270444 **Logged by:** Love Clean Streets **on:** 02/01/2013 18:27
Service: Carriageway **Subject:** Ironworks **Classification:** Request for service
Desc.: manhole cover and surrounds sinking into road near roundabout outside car garage
Location: Gatwick Road, Crawley, RH10 9 **Contact:**

Plot Number: 9,999.00 **Feature Id - Location:** **Feature Type:** Whole Street Feature
Job Number: 923891 **Defect Number:** 3042424

Enquiry No: 270286 **Logged by:** Love Clean Streets **on:** 02/01/2013 11:58
Service: Carriageway **Subject:** Potholes **Classification:** Request for service
Desc.: Very deep pothole in crease in the road - very hard to see and extremely dangerous and caused damage to my tyre - I could not take a photograph due to busy traffic
Location: Gatwick Road, Crawley, RH10 9 **Contact:**

Enquiry No: 268193 **Logged by:** Love Clean Streets **on:** 14/12/2012 09:51
Service: Street Lighting **Subject:** Traffic Lights **Classification:** Request for information
Desc.: The traffic lights at this junction are not working.
Location: Gatwick Road & arterial, Crawley, RH10 9 **Contact:**

Enquiry No: 264799 **Logged by:** Contact Centre **on:** 08/11/2012 09:26
Service: Carriageway **Subject:** Traffic conditions **Classification:** Request for service
Desc.: Road work cones that have been there for a few days and no work has been done. They are causing long tail backs. Nothing on the roadworks site to say any works to be done. Nothing at the roadworks to say who is doing them. (Call Back Requested)
Location: Going to wards the roundabout at Victoria House **Contact:** [REDACTED]

Enquiry No: 264325 **Logged by:** Contact Centre **on:** 02/11/2012 15:38
Service: Emergency **Subject:** Ironworks **Classification:** Request for service
Desc.: Collaped man hole cover pls investigate
Location: Os Victory House **Contact:** [REDACTED]

Plot Number: 9,999.00 **Feature Id - Location:** **Feature Type:** Whole Street Feature
Job Number: 826857

Enquiry No: 264297 **Logged by:** Contact Centre **on:** 02/11/2012 13:25
Service: Emergency **Subject:** Ironworks **Classification:** Request for service
Desc.: there is a collapsed man hole cover outside the nat west bank.
Third building on the left south of the footbridge. ref 718 02/11/2012
Location: third building on the left south of the footbridge. **Contact:** SUSSEX POLICE 2012

Plot Number: 9,999.00 **Feature Id - Location:** **Feature Type:** Whole Street Feature
Job Number: 918765 **Defect Number:** 3038086

Effective: 10/03/2012 to 10/03/2014
Street: Gatwick Road (9700110)

Display Action Officer: No

Customer Services

Enquiry No: 263556 **Logged by:** Love Clean Streets **on:** 25/10/2012 12:27
Service: Footways and Cycleways **Subject:** Signs **Classification:** Request for service
Desc.: 30mph terminal sign n/side s/bound missing. Also o/side 30 / 40mph terminal signs do not conform to TSM Ch 4 Fig 14.14 page 113. Speed camera enforcement in Gatwick Road will therefore be suspended.
Location: Gatwick Road, Crawley, RH6 0 **Contact:**

Plot Number: 9,999.00 **Feature Id - Location:** **Feature Type:** Whole Street Feature
Job Number: 919555

Enquiry No: 262681 **Logged by:** Contact Centre **on:** 17/10/2012 15:33
Service: Emergency **Subject:** Rubbish and spillages **Classification:** Request for service
Desc.: Police report (ref: 1130 todays date) oil spillage outside motor cycle shop. Beleived van oil sump has broken. Starting to spread. No other details.
Location: o/s P & H Motorcycles, number 63 **Contact:** SUSSEX POLICE 2012

Plot Number: 9,999.00 **Feature Id - Location:** **Feature Type:** Whole Street Feature
Job Number: 918193 **Defect Number:** 3037620

Enquiry No: 260931 **Logged by:** Contact Centre **on:** 02/10/2012 10:45
Service: Carriageway **Subject:** Signs **Classification:** Request for service
Desc.: caller would like to speak to someone re the speed limits on this stretch of road. pls call asap as was not happy that couldnt speak to anyone today (Call Back Requested)
Location: manor royal by ind estate **Contact:** [REDACTED]

Plot Number: 9,999.00 **Feature Id - Location:** **Feature Type:** Whole Street Feature

Enquiry No: 259721 **Logged by:** Contact Centre **on:** 20/09/2012 11:22
Service: Carriageway **Subject:** Rubbish and spillages **Classification:** Request for service
Desc.: Police reports oil spillage at above location on north bound carriageway, about 2 foot wide. Located between Rutherford Way and the RADFORD ROAD ROUNDABOUT.
Incident No:0502/20/09/2012
Location: Between Rutherford Way and James Watt Way. **Contact:** SUSSEX POLICE 2012

Plot Number: 9,999.00 **Feature Id - Location:** **Feature Type:** Whole Street Feature
Job Number: 825827 **Defect Number:** 2052280

Enquiry No: 258756 **Logged by:** Contact Centre **on:** 11/09/2012 11:07
Service: Emergency **Subject:** Pothole **Classification:** Request for service
Desc.: The caller is sending photos via email. Several holes in a cluster in the pavement. 4 inches in depth.
Location: Outside Magellan Terrace, next to the crossing point. **Contact:** [REDACTED]

Enquiry No: 257553 **Logged by:** Contact Centre **on:** 29/08/2012 09:14
Service: Emergency **Subject:** Pothole **Classification:** Request for service
Desc.: Extract from email:
Approx 2 foot wide by 2 foot deep. Appeared yesterday, lots of loose tarmac surrounding it.
LS.CC - approx coordinates as cannot see flyover on mapping. Identifies as Gatwick Rd, Industrial, Crawley but no option for this.
Location: On the roundabout just after the flyover **Contact:** [REDACTED]

Plot Number: 9,999.00 **Feature Id - Location:** **Feature Type:** Whole Street Feature
Job Number: 825028 **Defect Number:** 2051511

Enquiry No: 254445 **Logged by:** Contact Centre **on:** 23/07/2012 17:39
Service: Carriageway **Subject:** Signs **Classification:** Request for service
Desc.: Caller would like to know the exact speed limit for Gatwick road on 08/03/2012 as he got a speeding ticket at 39mph but there is a sign in the background of the photographic evidence that states it is a 40mph zone. Please can we contact him to confirm this. (Call Back Requested)
Location: Would like to know the exact speed limit for Gatwick Road. **Contact:** [REDACTED]

Plot Number: 9,999.00 **Feature Id - Location:** **Feature Type:** Whole Street Feature

Effective: 10/03/2012 to 10/03/2014
Street: Gatwick Road (9700110)

Display Action Officer: No

Customer Services

Enquiry No: 248979
Service: Carriageway
Desc.: Collapsed drain, has no lid, in a bus lane. could cause problems for vehicles.
Location: Outside Toyota Dealership

Logged by: Contact Centre
Subject: Drainage

on: 11/06/2012 11:40
Classification: Request for service

Contact: [REDACTED]

Plot Number: 9,999.00
Job Number: 822402

Feature Id - Location:
Defect Number: 2049308

Feature Type: Whole Street Feature

Enquiry No: 243291
Service: Carriageway
Desc.: The customer wants information on lines and parking bays. (Call Back Requested)
Location: gatwick road

Logged by: Contact Centre
Subject: Lining

on: 16/04/2012 11:03
Classification: Request for service

Contact: [REDACTED]

Plot Number: 9,999.00

Feature Id - Location:

Feature Type: Whole Street Feature

Enquiry No: 241246
Service: Carriageway
Desc.: Caller had spoken to Norman Perryman regarding getting parking bays put in outside his business, he was told that it was public parking so he could not do that, he has now noticed that parking bays have been painted outside other business with reserved on, he would like to know if they have permission. RM CC (Call Back Requested)
Location: [REDACTED]

Logged by: Contact Centre
Subject: Lining

on: 14/03/2012 10:20
Classification: Request for service

Contact: [REDACTED]

Plot Number: 9,999.00

Feature Id - Location:

Feature Type: Whole Street Feature

Enquiry No: 241244
Service: Carriageway
Desc.: Caller reports that a food outlet has placed at least 6 A boards on the grass and an umbrella which is attached to a lamp post, but is not very secure on the grass verge, he has reported this before but nothing was done and the boards have been out everyday. RM CC (Call Back Requested)
Location: Opposite Forge Wood Industrial Estate and up the road towards Gatwick

Logged by: Contact Centre
Subject: Obstruction

on: 14/03/2012 10:14
Classification: Request for service

Contact: [REDACTED]

Plot Number: 9,999.00

Feature Id - Location:

Feature Type: Whole Street Feature

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Section: 1.00		Road No. - Locn.: C207/805		C/Way Type: Single 2-Lane Carriageway		Area: CRAWLEY	
933096	Previous patch around cover is failing. Please break out previous repair and redo 1.5m x 1.5m sq (Enquiry 2007430) (C/W Cows/Gulls broken /miss)	Under the bridge near Churchill Court where Napier Way joins road from Hazelwick Flyover 528145, 138268	28 Days - BB	Works Closed	06/11/2013	29/11/2013	Act. BB01/903161
Section: 9,999.00		Road No. - Locn.:		C/Way Type: Whole Street Feature		Area: CRAWLEY	
66759	See MASTER JOB No. 65214 Remove and replace 1no 2m & 1no 0.9m panel of V4 Visi Rail, 1no End post & 1no g (Enquiry 308477) (Planned Fencing Works)	on splitter island to south of Radford Road Roundabout EN 528535, 139614	2 Weeks Contractor Assessment	Works Closed	08/05/2013	08/01/2014	Act.
67911	3m x 95mm x 0.7m (Potholes)	os nissan dealership before roundabout	5 Days - BB	Works Closed	08/07/2013	12/07/2013	Act. BB01/1500675
67932	3.7 x 0.9 x 100mm (Potholes)	Gatwick Road, Crawley, RH10 9 30mtrs before roundabout outside Nissan garage in bus lane	5 Days - BB	Works Closed	09/07/2013	12/07/2013	Act. BB01/1500688

Effective: 10/03/2012 to 10/03/2014
Street: Gatwick Road (9700110)

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Section:	9,999.00	Road No. - Locn.:	C/Way Type: Whole Street Feature			Area: CRAWLEY	
69276	REFER TO MASTER JOB NO. 68240. RECHARGE Damaged PGR - 3No X 2M 'V4' Visirail panels and 1no corner post (Enquiry 296217) (Planned Fencing Works)	At j/w Flemming Way opp Sussex Manor Business Park EN 528364, 138857	2 Weeks Contractor Assessment	Works Closed	17/09/2013	07/02/2014	Act.
69687	Please fill pothole 1.2m x 0.5m (Potholes)	Gatwick Road, Crawley, RH10 9	28 Days - BB	Works Closed	22/10/2013	24/10/2013	Act. BB01/1501662
69688	Please fill pot hole prior to patching outside Nissan garage 5m x0.5m in bus lane (Potholes)	Gatwick Road, Crawley, RH10 9	5 Days - BB	Works Closed	22/10/2013	24/10/2013	Act. BB01/1501663
700472	Make safe cspot adjacent to MHC 2ftx2ft and 4-6 inches deep, in wheel track, in lane 1 (Enquiry 289054) (Potholes)	N/bound, Under the footbridge near Churchill Court , approx 5 mtrs south of Gatwick Road N/bound slip 528145, 138268	2 Hours - BB	Works Closed	03/05/2013	03/05/2013	Act. BB01/300719
707650	Patch 1m sq around Thames water cover Tarmac 120mm deep. (see defect 3054496) (WS Obst flood,spill,tree,hedge)	Near jw Napier way under footbridge and near dreams bed shop	2 Hours - BB	Works Closed	22/01/2014	22/01/2014	Act. BB01/305028
821669	OUT OF HOURS Sand c/w diesel spill.	London Rd - A23 - Beehive roundabout.	2 Hours - BB	Scheduled	14/05/2012	12/05/2012	Act.
822402	Collapsed drain, has no lid, in a bus lane. could cause problems for vehicles. (Enquiry 248979) (WS Obst flood,spill,tree,hedge)	Outside Toyota Dealership	2 Hours - BB	Works Closed	11/06/2012	11/06/2012	Act.
825028	Approx 2 foot wide by 2 foot deep. lots of loose tarmac surrounding it. Pls repair and clear debris LS.CC - (Enquiry 257553) (WS Obst flood,spill,tree,hedge)	On the roundabout just after the flyover	2 Hours - BB	Works Closed	29/08/2012	29/08/2012	Act.
825827	Police reports oil spillage at above location on north bound carriageway, about 2 foot wide. (WS Obst flood,spill,tree,hedge)	Between Rutherford Way and James Watt Way. Located between Rutherford Way and the RADFORD ROAD ROUNDABOUT. Incident No:0502/20/09/2012 (Enquiry 259721)	2 Hours - BB	Site Clear - Permanent	20/09/2012	20/09/2012	Act.
826857	Collapsed man hole cover, make safe and reset (Enquiry 264325)	Os Victory House	2 Hours - BB	Job Cancelled no Transfer	02/11/2012	02/11/2012	Est.
827050	Out of Hours - Plave out Traffic Lights not worksing boards	J/W Flemming Way	2 Hours - BB	Works Closed	12/11/2012	11/11/2012	Act.
828505	Pothole 16 inches long x 8 inch wide x 3 inch deep. (Potholes)	Opposite AutoGlass nr junc Oakwood Industrial Park	28 Days - BB	Works Closed	09/01/2013	05/02/2013	Act.
904225	BATCH 910418. resecure bus lane sign using 76mm clips.	just north of James Watt roundabout	2 Weeks Contractor Assessment	Works Closed	19/10/2011	15/02/2013	Act.

Effective: 10/03/2012 to 10/03/2014
Street: Gatwick Road (9700110)

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Section:	9,999.00	Road No. - Locn.:	C/Way Type: Whole Street Feature		Area: CRAWLEY		
906815	Batch 11 Crawley & Mid Sussex Lining - refresh all white lining	throughout the whole road	28 Days - BB	Works Closed	15/12/2011	22/03/2012	Act.
909849	fill at edge - .5x.3x.04 dbm ,junction [lane closure] (Potholes)	near Gatwick Road r/about ,by L col 28 - at Brunel cover	28 Days - BB	Works Started	21/02/2012	20/03/2012	Act.
909851	Pothole Repair - .5x.5x.05 dbm ,junction (Potholes)	opposite KIA Motors	28 Days - BB	Site Clear - Permanent	21/02/2012	19/03/2012	Act.
909852	patch required - 1.8x.6x.04 dbm ,junction (Potholes)	o/s KIA Motors	28 Days - BB	Site Clear - Permanent	21/02/2012	19/03/2012	Act.
909853	Pothole Repair - 1x.3x.04 dbm ,junction (Potholes)	junction Rutherford Way spur - by L col 75	28 Days - BB	Site Clear - Permanent	21/02/2012	14/03/2012	Act.
910636	patch 0.5 x 0.5m pothole in centre of northbound carriageway (Potholes)	adjacent to lamp column no.46	5 Days - BB	Works Closed	08/03/2012	22/03/2012	Act.
910648	cut square & patch 2.0 x 1.0m by 40mm pothole in southbound carriageway (Potholes)	adjacent to Kia Motors	28 Days - BB	Works Closed	09/03/2012	28/03/2012	Act.
914337	cut square & patch 1.2 x 1.2m carriageway surround to mh cover in southbound carriageway adjacent to pelican crossing by lamp column no.36 (n.b. within designated bus lane) (Potholes)	adjacent to Oakwood Trading Estate	28 Days - BB	Site Clear - Permanent	13/06/2012	02/07/2012	Act.
914338	cut square & patch 1m2 hole in northbound carriageway (n.b. in outside lane of two lane carriageway with nearside lane designated as bus lane) (Potholes)	opposite Oakwood Trading Estate	28 Days - BB	Works Closed	13/06/2012	02/07/2012	Act.
915448	DBM POTHOLE - 0.6m x 0.4m x 110mm (Potholes)	bus lay-by - northbound side - almost opposite Tinsley Lane North	5 Days - BB	Site Clear - Permanent	18/07/2012	20/07/2012	Act.
916132	DBM pothole - 0.4m x 0.2m x 70mm (Potholes)	20m south of Gatwick Ind. Est entrance - west side by cover	28 Days - BB	Site Clear - Permanent	09/08/2012	29/08/2012	Act.
916417	patch 1.0 x 0.2m hole in southbound carriageway (Potholes)	opposite bus stop by lamp column no.43 (by Gatwick Hyundai)	28 Days - BB	Works Closed	17/08/2012	03/09/2012	Act.
916418	patch 2.0 x 0.2m strip of holes in join between southbound carriageway & bus lane (Potholes)	adjacent to Tinsley Lane	28 Days - BB	Site Clear - Permanent	17/08/2012	03/09/2012	Act.
916419	patch 0.5 x 0.3m hole by mh cover in southbound bus lane (Potholes)	adjacent to Tinsley Lane	28 Days - BB	Works Closed	17/08/2012	03/09/2012	Act.

Effective: 10/03/2012 to 10/03/2014
Street: Gatwick Road (9700110)

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Section:	9,999.00	Road No. - Locn.:		C/Way Type: Whole Street Feature		Area: CRAWLEY	
916421	remove 0.6 x 0.4m area of surplus hardened cement left stuck to surface of asphalt footway (F/W hazard trip/depression)	adjacent to lamp column no.89 (opposite Cobham Way)	28 Days - BB	Site Clear - Permanent	17/08/2012	05/09/2012	Act.
916422	patch 0.5 x 0.4m hole in carriageway by corner of surround to mh cover in northside of bellmouth (Potholes)	entrance to Forgewoid Industrial Estate	28 Days - BB	Site Clear - Permanent	17/08/2012	05/09/2012	Act.
916423	patch 0.4 x 0.2m pothole by mh cover in northbound carriageway (Potholes)	adjacent to southern end of service road adjoining Rutherford Way	28 Days - BB	Site Clear - Permanent	17/08/2012	05/09/2012	Act.
916450	patch 1m2 hole in carriageway adjacent to tactile crossing point to southside of bellmouth (Planned Carriageway for WCO)	entrance to British Rail New Yard	28 Days - BB	Site Clear - Permanent	20/08/2012	10/09/2012	Act.
916758	Footway patch as marked as per site specific sheet approx 35m2	opp lc 111 to lc 110 528391,139966 to 528453,139886	28 Days - BB	Works Closed	31/08/2012	28/11/2012	Act.
916759	C/way patch as marked as per site specific sheet approx 13m2	entrance to Magellan Terrace (50m north of Fleming Way) 528437,138979	28 Days - BB	Works Closed	31/08/2012	28/09/2012	Act.
916789	Signs batch 49 (916839) - GD Remove 1 x damaged post. Install 1 x new 3300mm post. Re-use existing BUS LANE sign, serving southbound traffic	Outside Kia Motors	28 Days - BB	Works Closed	04/09/2012	23/10/2012	Act.
917427	OUT OF HOURS - Sand carriageway following oil spillage	Junction with London Road (Police ref: 234)	2 Hours - BB	Works Closed	24/09/2012	22/09/2012	Act.
918193	Police report (ref: 1130 today's date) oil spillage outside motor cycle shop. Beleived van oil sump has broken. Starting to spread. No other details. (Enquiry 262681) (WS Obst flood,spill,tree,hedge)	o/s P & H Motorcycles, number 63	2 Hours - BB	Works Closed	17/10/2012	17/10/2012	Act.
918765	maek safe collasped man hole cover outside the nat west bank. Third building on the left south of the footbridge. ref 718 02/11/2012 (Enquiry 264297) (WS Obst flood,spill,tree,hedge)	third building on the left south of the footbridge.	2 Hours - BB	Site Clear - Permanent	02/11/2012	02/11/2012	Act.

Effective: 10/03/2012 to 10/03/2014
Street: Gatwick Road (9700110)

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Section:	9,999.00	Road No. - Locn.:	C/Way Type: Whole Street Feature		Area: CRAWLEY		
919555	Signs Batch 70 (920450) - GD 1. At junction with Radford Road Roundabout Install 1 x new 4400mm post (inc 600mm under ground) and 1 new x YELLOW-BACKED 30MPH & IND AREA sign (diag.670 and diag.2402.1v) (1415mm x 810mm) and 1 x new PEDAL CYCLES & PEDS ONLY sign (diag.956) (300mm), both serving southbound traffic. Install 1 x new 40MPH sign (diag.670) (600mm) and 1 x new PEDAL CYCLES & PEDS ONLY sign (diag.956) (300mm), both serving northbound traffic. 2. Install 1 x 30MPH sign (diag.670) (600mm) to existing post, serving southbound traffic.		28 Days - BB	Works Closed	26/11/2012	27/02/2013	Act.
921325	cut square & patch 1.2 x 0.4m hole in northbound carriageway (Potholes)	opposite Autoglass (by lamp column no.37 approx 200m north of Gatwick Road Roundabout) (Manor Royal)	28 Days - BB	Works Closed	11/01/2013	24/01/2013	Act.
921683	Repair c/w pot 300mm dia x 75mm deep(Enquiry 272753) (Potholes)	Opposite Thales on left hand side near Mitsubishi/Hyundai Garage.	28 Days - BB	Site Clear - Permanent	18/01/2013	14/02/2013	Act.
921780	cut square & patch 2.0 x 1.0m area of carriageway adjacent to gully at edge of northbound carriageway (Potholes)	opposite lamp column no.110 (between James Watt Way & Airport Roundabout to north of traffic signals by Beehive Ring Road)	28 Days - BB	Site Clear - Permanent	22/01/2013	16/02/2013	Act.
922561	Make safe c/w pot approx 150cm x 32cm x 150mm deep (WS Obst flood,spill,tree,hedge)	Out side garage mitsubishi BCL Group	2 Hours - BB	Works Closed	08/02/2013	08/02/2013	Act.
922631	DBM pothole - 0.6m x 0.6m x 70mm (Potholes)	o/s Northwood park - southbound	28 Days - BB	Works Closed	11/02/2013	07/03/2013	Act.
923734	cut square & patch 0.4 x 0.4m pothole in southbound carriageway (n.b. bus lane nearside) (Potholes)	60m north of Fleming Way Roundabout (by entrance to Volkswagen Car Showrooms)	28 Days - BB	Works Closed	08/03/2013	04/04/2013	Act.
923735	cut square & patch 0.4 x 0.3m pothole in southbound carriageway (n.b. bus lane nearside) (Potholes)	90m north of Fleming Way Roundabout (opposite entrance to Magdalen Terrace)	28 Days - BB	Works Closed	08/03/2013	04/04/2013	Act.
923736	cut square & patch 0.5 x 0.2m pothole in southbound carriageway (n.b. bus lane nearside) (Potholes)	100m north of Fleming Way Roundabout (10m north of entrance to Magdalen Terrace) (opposite lamp column no.65)	28 Days - BB	Works Closed	08/03/2013	04/04/2013	Act.

Effective: 10/03/2012 to 10/03/2014
Street: Gatwick Road (9700110)

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Section:	9,999.00	Road No. - Locn.:		C/Way Type: Whole Street Feature		Area: CRAWLEY	
923737	cut square & patch 0.8 x 0.5m hole in southbound carriageway (n.b. two-way road with bus lanes running nearside both ways) (Potholes)	north of Cobham Way (between lamp column nos.92 & 90)	28 Days - BB	Works Closed	08/03/2013	04/04/2013	Act.
923738	patch 0.4 x 0.3m hole in southbound carriageway between roundabout & pelican crossing (n.b. divided by splitter island with bus lane to nearside of main carriageway) (Potholes)	5m south of Radford Road Roundabout	28 Days - BB	Works Closed	08/03/2013	04/04/2013	Act.
923739	cut square & patch 0.6 x 0.4m pothole in northbound carriageway (n.b. 2 way road with bus lanes nearside both ways) (Potholes)	5m south of Whittle Way	28 Days - BB	Works Closed	08/03/2013	04/04/2013	Act.
923740	cut square & patch 0.8 x 0.5m pothole in northbound carriageway (n.b. 2 way road with bus lanes nearside both ways) (Potholes)	10m north of Whittle Way (opposite lamp column no.86)	28 Days - BB	Works Closed	08/03/2013	04/04/2013	Act.
923741	patch 0.3 x 0.2m hole by edge of mh cover in northbound carriageway (Potholes)	opposite lamp column no.68 (adjacent to southern end of Gatwick Road Service Road)	28 Days - BB	Works Closed	08/03/2013	04/04/2013	Act.
923890	4.0 x 0.5m fretted strip along joint in northbound carriageway (passed to OMC for 2-hour response) (Potholes)	opposite Thales (by lamp column no.39) (between Manor Royal & Fleming Way)	28 Days - BB	Works Closed	13/03/2013	08/04/2013	Act.
923891	cut square & patch 2.0 x 0.4m hole in nearside lane of southbound carriageway (by end of bus lane) (passed to OMC for 2-hour response) (Potholes)	adjacent to Nissan Dealers 50m north of Manor Royal Roundabout	28 Days - BB	Passed To Contractor To Start	13/03/2013	10/04/2013	Est.
923901	patch 0.4 x 0.1m hole on joint in northbound carriageway (n.b. bus lane along nearside) (Potholes)	opposite Autoglass (north of Oakwood Trading Estate) approx 150m north of Manor Royal (opposite lamp column no.38)	28 Days - BB	Works Closed	13/03/2013	09/04/2013	Act.
923902	patch 0.3 x 0.2m hole on joint in northbound carriageway (n.b. bus lane along nearside) (Potholes)	opposite Autoglass (approx 150m north of Manor Royal) (opposite lamp column no.38)	28 Days - BB	Works Closed	13/03/2013	09/04/2013	Act.
923903	patch 0.6 x 0.2m hole on joint in northbound carriageway (n.b. bus lane along nearside) (Potholes)	opposite Autoglass (approx 160m north of Manor Royal)	28 Days - BB	Works Closed	13/03/2013	09/04/2013	Act.

Effective: 10/03/2012 to 10/03/2014
Street: Gatwick Road (9700110)

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Section:	9,999.00	Road No. - Locn.:	C/Way Type: Whole Street Feature		Area: CRAWLEY		
923904	patch 0.8 x 0.3m hole on joint in northbound carriageway (n.b. bus lane along nearside) (Potholes)	opposite Northwood Park Trading Estate (by lamp column no.41)	28 Days - BB	Works Closed	13/03/2013	09/04/2013	Act.
923905	patch 0.4 x 0.1m hole on joint at edge of northbound carriageway (n.b. alongside guided bus lane) (Potholes)	60m south of Fleming Way Roundabout	28 Days - BB	Works Closed	13/03/2013	09/04/2013	Act.
923906	patch 0.8 x 0.2m hole by edge of mh cover in carriageway on northbound approach to Roundabout (n.b. offside lane by end of splitter island & guided bus lane) (Potholes)	20m south of Fleming Way Roundabout	28 Days - BB	Works Closed	13/03/2013	09/04/2013	Act.
923907	cut square & patch 1.4 x 0.25m holed strip along joint in southbound carriageway adjacent to bellmouth (n.b. bus lane nearside) (Potholes)	adjacent to Tinsley Lane (south of Fleming Way Roundabout)	28 Days - BB	Works Closed	13/03/2013	02/04/2013	Act.
923908	cut square & patch 0.8 x 0.3m shallow surface erosion in southbound carriageway adjacent to bellmouth (n.b. bus lane nearside) (Potholes)	adjacent to Tinsley Lane	28 Days - BB	Works Closed	13/03/2013	02/04/2013	Act.
923909	cut square & patch 2.0 x 0.4m hole along joint in southbound carriageway adjacent to bellmouth (n.b. bus lane nearside) (Potholes)	adjacent to Tinsley Lane (south of Fleming Way Roundabout)	28 Days - BB	Works Closed	13/03/2013	02/04/2013	Act.
923910	cut square & patch 2.5 x 1.0m holed/uneven area in southbound carriageway to southside of bellmouth (n.b. bus lane nearside) (Potholes)	adjacent to Tinsley Lane (south of Fleming Way Roundabout)(adjacent to lamp column no.50)	28 Days - BB	Works Closed	13/03/2013	02/04/2013	Act.
923911	cut square & patch 0.8 x 0.25m holed area by mh cover in southbound bus lane to south of bellmouth (n.b. bus lane closure needed) (Potholes)	adjacent to Tinsley Lane (south of Fleming Way Roundabout)	28 Days - BB	Works Closed	13/03/2013	02/04/2013	Act.
923912	cut square & patch 0.6 x 0.3m hole by mh cover in southbound carriageway (n.b. bus lane nearside) (Potholes)	adjacent to Nissan Car Dealers (50m north of Manor Royal)	28 Days - BB	Works Closed	13/03/2013	02/04/2013	Act.

Effective: 10/03/2012 to 10/03/2014
Street: Gatwick Road (9700110)

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Section:	9,999.00	Road No. - Locn.:	C/Way Type: Whole Street Feature		Area: CRAWLEY		
924026	cut square & patch 1.4 x 1.4m surround breaking out around W.O. covers at edge of northbound carriageway (n.b. bus lane nearside) (Planned Carriageway for WCO)	12m south of Whittle Way	28 Days - BB	Works Closed	14/03/2013	15/04/2013	Act. BB01/80
924443	Lining Batch 63 (924073) - GD Refurb ALL WHITE MARKINGS along road, including all GIVE WAYS at connecting junctions.	From Fleming Way Roundabout to Gatwick Road Roundabout	28 Days - BB	Works Closed	21/03/2013	26/04/2013	Act. BB04/200894
925287	crazing/depression starting to show in northbound carriageway (Planned Carriageway for WCO)	adjacent to lamp column no.111 (between Radford Road Roundabout & Airport Roundabout)	zzFix required within 3 months	Job Raised	11/04/2013	09/07/2013	Est.
925288	cut square & patch 0.5 x 0.4m pothole in southbound carriageway (Potholes)	opposite Magdallen Terrace (50m north of Fleming Way)	28 Days - BB	Works Closed	11/04/2013	09/05/2013	Act. BB01/900101
925289	old 1.5 x 0.5m patch starting to break up in nearside lane (see job no.923891) (Planned Carriageway for WCO)	southbound carriageway on approach to Roundabout by Manor Royal	zzFix required within 3 months	Job Raised	11/04/2013	09/07/2013	Est.
927562	cut square & patch 0.8 x 0.6m hole in southbound carriageway (Potholes)	opposite entrance to Magellan Terrace (40m north of Fleming Way)	28 Days - BB	Works Closed	05/06/2013	25/06/2013	Act. BB01/900937
928888	Batch_83_(930219)_GD_Lining Refurb all WHITE AND YELLOW ROAD MARKINGS (Lining / Studs Planned)	Between (and including) Gatwick Road Roundabout and Radford Road Roundabout	28 Days - BB	Works Closed	29/07/2013	14/01/2014	Act. BB04/1100985
930318	Cut out and patch pothole 3m x .75 x 100mm (Potholes)	Between entrance to Mercedes and Napier way on service road. Be aware bus route and large lorries use this route in industrial area.	5 Days - BB	Works Closed	10/09/2013	12/09/2013	Act. BB01/902060
930363	Repair cpot adjacent to MHC 2ftx2ft and 4-6 inches deep, in wheel track, in lane 1 (Enquiry 289054) (Potholes)	N/bound, Under the footbridge near Churchill Court , approx 5 mtrs south of Gatwick Road N/bound slip 528145, 138268 just north of MAXwell way	2 Hours - BB	Works Closed	10/09/2013	10/09/2013	Act. BB01/902091
930504	Cut square, excavate 200mm, add stone & patch 4.8 x 1.0m sunken area in southbound carriageway by end of bus lane on southbound approach to roundabout (Potholes)	50m north of roundabout at junction with Manor Royal	28 Days - BB	Works Closed	13/09/2013	08/10/2013	Act. BB01/902151

Effective: 10/03/2012 to 10/03/2014
Street: Gatwick Road (9700110)

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Section:	9,999.00	Road No. - Locn.:	C/Way Type: Whole Street Feature			Area: CRAWLEY	
930782	Patch 1.4 x 0.1m holed strip of carriageway around edge of twin cover (n.b heavily trafficked road & close to end of guided bus lane & splitter island) (see also job no.923906) (Potholes)	Northbound approach to Fleming Way	28 Days - BB	Works Closed	19/09/2013	08/10/2013	Act. BB01/902237
930785	Patch 0.6 x 0.2m area of holes in northbound carriageway on approach to junction with Whittle Way (n.b. separate bus lane alongside) (Potholes)	Adjacent to Whittle Way	28 Days - BB	Works Closed	19/09/2013	09/10/2013	Act. BB01/902240
930879	WORKS TBC* Programme Year TBC Carriageway Resurfacing (Planned Carriageway Works) CD: WORKS TBC Programme Year 3-5 Carriageway Surface Dressing	EN 528319,140077 - 528205,138020 Near Whittle Way CD: Airport Roundabout to Gatwick Road Southbound EN: 528163, 138180 TO 528316, 140080	Planned Works - Forward Prog.	Asset Mgmt Team only	24/09/2013		
930946	Trial excavation up to 5m x 1m to locate source of water pumping through surface.	o/s Toyota Garage 528155,138419	28 Days - BB	Job Cancelled - No action req.	24/09/2013	22/10/2013	Est. BB05/1870397
933351	Temporary patch 6.0 x 0.5m holed area in southbound carriageway by end of bus lane on approach to roundabout (Potholes)	Southbound approach to Manor Royal Roundabout	2 Hours - BB	Works Closed	13/11/2013	13/11/2013	Act. BB01/903312
933353	Repair subsidence in c/way	s/bound approach to manor royal roundabout	2 Hours - BB	Works Closed	13/11/2013	13/11/2013	Act. BB01/903313
934403	Patch 0.4 x 0.3m pothole in northbound carriageway (Potholes)	Adjacent to Gatwick Road Service Road (north of access road to Rutherford Way)	28 Days - BB	Works Closed	09/12/2013	06/01/2014	Act. BB01/903863
934404	Patch 0.4 x 0.3m pothole in northbound carriageway approx 10m north of roundabout (n.b. northbound side of splitter island) (Potholes)	North of Fleming Way	28 Days - BB	Works Closed	09/12/2013	06/01/2013	Act. BB01/903863
935908	Subsidence - 6x1.5x40-100mm deep (11:34) (Heave/ Subsidence)	o/s Nissan Garage (528168,138436)	5 Days - BB	Works Closed	09/01/2014	14/01/2014	Act. BB01/904522
935909	Pothole at edge of cover - .6x.2x.08 dbm, junction (11:26) (Potholes)	By end of Gatwick Road Northbound Slip (528137,138287)	28 Days - BB	Works Closed	09/01/2014	15/01/2014	Act. BB01/904523
935910	Pothole repair - .6x.4x.05 dbm, junction (11:34) (Potholes)	20m right of L col 34 - outside lane (528190,138403)	28 Days - BB	Works Closed	09/01/2014	05/02/2014	Act. BB01/904523
935919	Cut out and patch pothole .6m x .6m x 70mm (Potholes)	In lane one as you head northbound on gatwick road from roundabout jw Fleming way	28 Days - BB	Works Closed	09/01/2014	05/02/2014	Act. BB01/904531

Effective: 10/03/2012 to 10/03/2014
Street: Gatwick Road (9700110)

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Section:	9,999.00	Road No. - Locn.:	C/Way Type: Whole Street Feature		Area: CRAWLEY		
936282	Permanent repair pothole 0.5m x 0.5m x 0.04m (Potholes)	outside the Nissan dealership on Gatwick Road in centre carriageway outside of bus lane	28 Days - BB	Works Closed	16/01/2014	11/02/2014	Act. BB01/904715
936333	Police have closed Rd, request assistance to clear flooding RefL 217 17/1/14	South of Airport Roundabout on London Rd	28 Days - BB	Works Closed	17/01/2014	14/01/2014	Act. BB01/603851
937238	Repair old failing trench approx 1.5m x .75m x .006m. Constraint, frequent HGV's (Potholes)	O/s P&H Motorcycles, edge of bus Lane near bus stop	28 Days - BB	Works Closed	05/02/2014	22/02/2014	Act. BB01/905243
937239	Repair 2 adjacent c/way pot holes patch 450mm sq x 50mm incorporating both, constraints frequent HGV's (Potholes)	O/s p & p motorcycle	28 Days - BB	Works Closed	05/02/2014	28/02/2014	Act. BB01/905244
937503	DBM pothole - 0.4m x 0.4m x 60mm (Potholes)	Outside Kia garage - busy industrial traffic	28 Days - BB	Works Closed	11/02/2014	07/03/2014	Act. BB01/905451
937504	DBM patch - 4m x 2m x 45mm (Potholes)	Just south of Kia garage - southbound - busy industrial traffic	28 Days - BB	Works Closed	11/02/2014	07/03/2014	Act. BB01/905451
937505	DBM pothole - 0.6m x 0.4m x 50mm (Potholes)	100m north of Fleming Way roundabout - busy industrial traffic	28 Days - BB	Works Closed	11/02/2014	07/03/2014	Act. BB01/905451
937506	DBM pothole - 0.5m x 0.4m x 50mm (Potholes)	80m north of Fleming Way roundabout - busy industrial traffic	28 Days - BB	Works Closed	11/02/2014	07/03/2014	Act. BB01/905451
937540	DBM pothole - 1 of 2 approx 300mm dia x d 80mm	N/Bound Just off roundabout opp VW Garage	28 Days - BB	Works Closed	11/02/2014	07/03/2014	Act. BB01/905476
937541	DBM pothole - 2nd of 2 approx 300mm dia x d 80mm (Busy industrial area)	N/Bound Just off roundabout opp VW Garage	28 Days - BB	Works Closed	11/02/2014	07/03/2014	Act. BB01/905477
937542	DBM pothole - 1 of 2 approx 200mm dia x d 50mm (Busy industrial area)	South/Bound Just off roundabout opp VW Garage	28 Days - BB	Works Closed	11/02/2014	07/03/2014	Act. BB01/905478
937543	DBM pothole - 2nd of 2 approx 200mm dia x d 50mm (Busy industrial area)	South/Bound Just off roundabout opp VW Garage	28 Days - BB	Works Closed	11/02/2014	07/03/2014	Act. BB01/905479
937952	Cut out and patch pothole .6 x .5m x 115mm (Potholes)	Between forgewood industrial estate and roundabout jw manor royal by col 64 opp Magellan terrace office units. Crossing into bus lane	5 Days - BB	Works Closed	19/02/2014	24/02/2014	Act. BB01/905779
938254	Perm repair c/way pot hole sound gully patch 900mm x 1200mm approx constraint HGV's (Potholes)	Opposite Side of Nissan Garage. 528167, 138446 jst north of manor royal	28 Days - BB	Passed To Contractor To Start	26/02/2014	26/03/2014	Est. BB01/905987
938255	Kerb missing - misaligned	Opposite Side of Garage. 528167, 138446 jst north of manor royal	28 Days - BB	Job Raised	26/02/2014	26/03/2014	Est.

Effective: 10/03/2012 to 10/03/2014
Street: Gatwick Road (9700110)

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Section:	9,999.00	Road No. - Locn.:		C/Way Type: Whole Street Feature		Area: CRAWLEY	
938266	Pothole 30cm x 25cm x 160mm deep (Potholes)	528309, 138713 Gatwick Road Industrial, Crawley	5 Days - BB	Works Closed	26/02/2014	03/03/2014	Act. BB01/905998
938287	Cut square & renew 1.2 x 1.2m surround to mh cover in southbound bus lane by entrance to British Rail New Yard (Potholes)	Adjacent to lamp column no.70 (opposite southern end of service road adjoining Rutherford Way)	28 Days - BB	Passed To Contractor To Start	27/02/2014	26/03/2014	Est. BB01/906013
938288	Cut square & renew 1.2 x 1.2m surround to mh cover in southbound bus lane by Pelican Crossing to south of roundabout (Potholes)	30m south of Radford Road	28 Days - BB	Passed To Contractor To Start	27/02/2014	26/03/2014	Est. BB01/906013
938289	Cut square & renew 2.4 x 1.2m surround to mh cover at start of southbound bus lane immediately to south of roundabout (Potholes)	5m south of Radford Road	28 Days - BB	Passed To Contractor To Start	27/02/2014	26/03/2014	Est. BB01/906013
938290	Cut square & renew 1.0 x 0.6m surround to carriageway gully at edge of northbound carriageway (Potholes)	Opposite Motorline Nissan Dealers (60m north of Manor Royal)	28 Days - BB	Passed To Contractor To Start	27/02/2014	26/03/2014	Est. BB01/906013
938291	Patch 0.6 x 0.3m pothole in southbound carriageway by bus stop to temporary repair deep hole in large patchy area (n.b. bus lane adjacent) (Potholes)	Outside Mitsubishi Dealers (between lamp column nos.44 & 46 south of Tinsley Lane)	5 Days - BB	Works Closed	27/02/2014	03/03/2014	Act. BB01/906012
938292	Patch 1m2 hole at rear edge of bellmouth access to industrial estate (Potholes)	On access to Forgewood Industrial Estate (southbound side approx 150m north of Fleming Way)	28 Days - BB	Passed To Contractor To Start	27/02/2014	26/03/2014	Est. BB01/906013
938293	Patch 0.5 x 0.25m hole at rear edge of bellmouth access to industrial estate (Potholes)	Access to Forgewood Industrial Estate (southbound side approx 150m north of Fleming Way)	28 Days - BB	Passed To Contractor To Start	27/02/2014	26/03/2014	Est. BB01/906013
938294	Patch 2m2 holed area at rear edge of bellmouth access to industrial yard (Potholes)	Entrance to British Rail New Yard (by lamp column no.70)	28 Days - BB	Passed To Contractor To Start	27/02/2014	26/03/2014	Est. BB01/906013
938295	Cut square & renew 1.0 x 1.0m surround to mh cover in southbound bus lane (Potholes)	Outside Motorline Nissan Dealers (50m north of Manor Royal)	28 Days - BB	Passed To Contractor To Start	27/02/2014	26/03/2014	Est. BB01/906013
938296	Cut square & patch 3.0 x 1.25m holed area in southbound carriageway (n.b. alongside designated bus lane) (Potholes)	Adjacent to lamp column no.46 (outside Mitsubishi Dealers 120m south of Tinsley Lane)	5 Days - BB	Works Closed	27/02/2014	01/03/2014	Act. BB01/906012
6000741	Trial excavation up to 5m x 1m to locate source of water pumping through surface.	o/s Toyota Garage 528155,138419	28 Days - BB	Passed To Contractor To Start	16/12/2013	13/01/2014	Est. BB04/1700118

Effective: 10/03/2012 to 10/03/2014

Street: Gatwick Road (9700110)

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Section: 9,999.00		Road No. - Locn.:		C/Way Type: Whole Street Feature		Area: CRAWLEY	
6001324	OOH Clear broken glass from carriageway (WS Obst flood,spill,tree,hedge)	Gatwick Road nr Nissan Garage	2 Hours - BB	Works Closed	22/01/2014	11/01/2014	Act. BB01/1502275